



U.S. Department
of Transportation

**National Highway
Traffic Safety
Administration**

400 Seventh Street, S.W.
Washington, D.C. 20590

Dear Crash Data Researchers/Users:

Thank you for choosing crash data from the National Highway Traffic Safety Administration (NHTSA) for your research or other use. The information contained in this motor vehicle crash report is collected, maintained and distributed in accordance with Public Law 89-564. In accordance with this Public Law, NHTSA is required not to release any case information until completion of quality control procedures. These procedures include a review of the case material to extract all names, licenses and registration numbers, non-coded interview material, non-research related researcher comments in the margins, non-factual data, and the production number portion of the vehicle identification number (VIN).

If you requested NHTSA to query its database files in order to identify a specific crash, then that query was made using non-personal descriptors you provided for use in our search. This motor vehicle crash may have been identified from a data search and matches the general, non-personal descriptors you provided, but we cannot confirm that this is the specific crash report you requested.

If you have any questions with regard to the above procedures, please contact the Field Operations Branch, Crash Investigation Division, National Center for Statistics and Analysis at 202-366-4820. Again, please be advised that we cannot confirm that this is the case that you have specifically requested nor can we certify the information to be correct.

*** *** ***



AUTO SAFETY HOTLINE
(800) 424-9393
Wash. D.C. Area 366-0123

DYNAMIC SCIENCE, INC.
In-Depth Accident Investigation

Contract Number DTNH22-94-D-27058
Case Number DSI-94-AB-006

 1994

TECHNICAL SUMMARY

CONTRACTOR: Dynamic Science, Inc.
CONTRACT NUMBER: DTNH22-94-D-27058
CASE NUMBER: DSI-94-AB-006

[REDACTED]
This three vehicle collision occurred on a two-lane, undivided, urban roadway in [REDACTED] Maryland during the afternoon hours of a winter weekend [REDACTED] 94).

Vehicle 1, a 1990 Cadillac Sedan deVille, was being driven south in the southbound travel lane by the unrestrained 77 year old female driver (the case occupant) at a speed estimated to have been between 56 and 64 KPH (35 and 40 MPH). Occupant 2, an 80 year old male, was sitting unrestrained in the right front seating position of Vehicle 1.

Vehicle 2, a 1991 Toyota SR-5 4WD pickup, was being driven north in the northbound travel lane at a speed estimated to have been between 56 and 64 KPH (35 and 40 MPH) by the 26 year old male driver. The driver was restrained by the available three-point manual lap/shoulder safety restraints. Occupant 2, a 1 year old male, was properly restrained in a child safety seat in the right front seating position. Occupant 3, an 11 year old female, was sitting in the left rear seating position and was wearing the available three-point manual lap/shoulder safety restraints.

Vehicle 3, a 1990 Mercury Cougar 2-door, was being driven north in the northbound travel lane by the 22 year old female driver at a speed estimated to have been between 56 and 64 KPH (35 and 40 MPH). Vehicle 3 was to the rear of Vehicle 2. Occupant 2, a 21 year old female, was seated in the right front seating position. Police report that both occupants of Vehicle 3 were restrained by three-point manual lap/shoulder safety restraints.

As Vehicle 1 was being driven in a right turning curve, the vehicle crossed the double yellow painted center lines, entered the northbound travel lane and the left front plane of Vehicle 1 impacted the left front plane of Vehicle 2 in a head-on configuration.

The Delta V for Vehicle 1 was computed, using CRASH III PC, as 39 KPH (24 MPH) using a CDC of 92FYEW4 and a PDOF of 355 degrees. The combined direct and induced damage width was 160 cm (63 in), and the maximum crush depth was 105 cm (41 in) at C₁. The Delta V for Vehicle 2 was computed, using CRASH III PC, as 37 KPH (23 MPH) using a CDC of 92FYEW4 and a PDOF of 355 degrees. The combined direct and induced damage width was 156 cm (61 in), and the maximum crush depth was 77 cm (30 in) at C₁. The forces in this impact exceeded the manufacturer's threshold in the supplemental restraint system of Vehicle 1 and the airbag deployed.

After impact, Vehicle 1 rotated counter-clockwise and came to final rest facing east. Vehicle 2, after impact rotated counter-clockwise and the left rear bumper corner was impacted by the front plane of Vehicle 3. The Delta V could not be computed for this impact, but the CDC for Vehicle 2 was 09LBLE1 using a PDOF of 255 degrees. The combined direct and induced damage width was 43 cm (17 in), and the maximum crush depth was approximately 4 cm (2 in) at the bumper corner. Vehicle 2 continued its counterclockwise rotation and came to final rest facing west. Vehicle 3 appears not to have rotated and came to final rest facing northeast.

The driver of Vehicle 1 (the case occupant) sustained moderate injuries consisting of fractures, rupture, avulsion and a closed head injury with loss of consciousness; maximum AIS = AIS-3. She was transported by air to a [REDACTED] where she was admitted for treatment. Occupant 2 sustained major injuries consisting of fractures, rupture, abrasion, sprain and a closed head injury with loss of consciousness; maximum AIS = AIS-4. He was also transported to a regional trauma center where he was admitted for treatment.

The driver of Vehicle 2 sustained major injuries consisting of a closed head injury with loss of consciousness, lacerations and strains; maximum AIS = AIS-4. He was transported to a [REDACTED] hospital where he was admitted for treatment. Occupant 2 sustained a minor closed head injury without loss of consciousness; maximum AIS = AIS-1. He was transported to a [REDACTED] where he was treated and released. Occupant 3 sustained minor injury consisting of a fracture; maximum AIS = AIS-1. She was also transported to a local hospital where she was treated and released.

The driver of Vehicle 3 was reported to have sustained non-incapacitating injuries of an unknown nature or severity. Her course of treatment could not be determined. Occupant 2 reportedly sustained incapacitating injuries of an unknown nature or severity. Her course of treatment could not be determined.

Both Vehicles 1 and 2 were towed from the scene due to damage sustained in this crash. Vehicle 3 was towed from the scene for unknown reasons.

This research was supported (in part) by the National Highway Traffic Safety Administration (NHTSA), U.S. Department of Transportation, under contract number DTNH22-94-D-27058. The opinions, findings, and recommendations contained herein are those of the authors, and do not necessarily represent those of NHTSA.

This document is disseminated under the sponsorship of the Department of Transportation in the interest of information exchange. The United States Government assumes no liability for the contents or use thereof.

The opinions, findings, and conclusions expressed in this publication are those of the authors and not necessarily those of the National Highway Traffic Safety Administration.

The crash investigation process is an inexact science which requires that physical evidence such as skid marks, vehicular damage measurements, and occupant contact points be coupled with the investigator's expert knowledge and experience of vehicle dynamics and occupant kinematics in order to determine the pre-crash, crash, and post-crash movements of involved vehicles and occupants.

Because each crash is a unique sequence of events, generalized conclusions cannot be made concerning the crashworthiness performance of the involved vehicle(s) or their safety systems.

DYNAMIC SCIENCE, INC.
ACCIDENT INVESTIGATION
CASE NUMBER: DSI-94-AB-006

TABLE OF CONTENTS

Accident Data	1
Ambience	1
Roadway	2
Traffic Controls	4
Vehicles	6
Vehicle Damage and Velocity Estimates	8
Collision Sequence	10
Occupant Kinematics	12
Supplemental Restraint System	13
Emergency Rescue Response	14
Occupant Data	16
Injuries	19
List of Abbreviations	22
Case Occupant Supplement	23
Accident Schematic	26
Collision Measurement Table	27
Photo Index and Photos	28
Slide Index and Slides	29
Appendices:	
A. NASS Field Forms	
B. Police Accident Report	

**Dynamic Science, Inc.
In-Depth Investigation
Case Number: DSI-94-AB-06**

ACCIDENT DATA:

Location: [REDACTED] Maryland
Area/Type: Urban/residential
Date/Time: Winter/afternoon
Accident Type: Car/pick-up/car - Head-on

INJURY SEVERITY:

Vehicle 1: Driver (case occupant): AIS-3
R/F Occupant: AIS-4

Vehicle 2: Driver: AIS-4
R/F Occupant: AIS-1
L/R Occupant: AIS-1

Vehicle 3: Driver: Reportedly sustained
non-incapacitating
injuries of unknown
nature or severity
R/F Occupant: Reportedly sustained
incapacitating injuries
of unknown nature or
severity

AMBIENCE:

Viewing Conditions: No viewing restrictions
Cloud Cover: Clear
Precipitation: None
Temperature: 2-4° C (35-40° F)
Road Surface: Dry

Dynamic Science, Inc.
In-Depth Investigation
Case Number: DSI-94-AB-06

ROADWAY:

	VEHICLE 1	VEHICLE 2
Type:	2-lane, undivided	2-lane, undivided
Width:	12.8 m (41.9 ft)	12.8 m (41.9 ft)
Traffic Density:	Moderate	Moderate
Median:	None	None
Edge:	2.7 m (8.8 ft) asphalt paved shoulder	2.9 m (9.5 ft) asphalt paved shoulder
Surface:	Asphalt	Asphalt
Reported Defects:	None	None
Co-efficient of Friction (est.):	.90	.90
Vertical Alignment:	Upgrade - positive 5%	Downgrade - negative 5%
Horizontal Alignment:	Right turning curve, R = 190.8 m (626 ft)	Left turning curve, R = 254.2 m (834.1 ft)

Dynamic Science, Inc.
In-Depth Investigation
Case Number: DSI-94-AB-06

ROADWAY:

VEHICLE 3

Type:	2-lane, undivided
Width:	12.8 m (41.9 ft)
Traffic Density:	Moderate
Median:	None
Edge:	2.9 m (9.5 ft) asphalt paved shoulder
Surface:	Asphalt
Reported Defects:	None
Co-efficient of Friction (est.):	.90
Vertical Alignment:	Downgrade - negative 5 %
Horizontal Alignment:	Left turning curve, R = 254.2 m (834.1 ft)

Dynamic Science, Inc.
In-Depth Investigation
Case Number: DSI-94-AB-06

TRAFFIC CONTROLS:

	VEHICLE 1	VEHICLE 2
Signals:	None	None
Signs:	None	None
Speed Limit:	64 KPH (40 MPH)	64 KPH (40 MPH)
Markings:	Single, solid, white painted line separates west shoulder and S/B travel lane. Double, solid, yellow painted lines separate S/B and N/B travel lanes. Single, solid, white painted line separates east shoulder and N/B travel lane.	Single, solid, white painted line separates N/B travel lane and east shoulder. Double, solid, yellow painted lines separate N/B and S/B travel lanes. Single, solid, white painted line separates S/B travel lane and west shoulder.

Dynamic Science, Inc.
In-Depth Investigation
Case Number: DSI-94-AB-06

TRAFFIC CONTROLS:

VEHICLE 3

Signals:

None

Signs:

None

Speed Limit:

64 KPH (40 MPH)

Markings:

Single, solid, white painted line separates N/B travel lane and east shoulder. Double, solid, yellow painted lines separate N/B and S/B travel lanes. Single, solid, white painted line separates S/B travel lane and west shoulder.

Dynamic Science, Inc.
In-Depth Investigation
Case Number: DSI-94-AB-06

VEHICLES:

	VEHICLE 1	VEHICLE 2
Description:	1990 Cadillac Sedan deVille, 4-door	1991 Toyota SR5 4WD pickup truck
Odometer:	67,983 km (42,244 mi)	50,085 km (31,122 mi)
Engine:	V8 / 4.5L	V6 / 3.0L
Vehicle Modifications:	None	None
Tire Condition:	Good - 25 % treadwear, no abnormal tread wear patterns	Fair - 60 % to 65 % treadwear, no abnormal tread wear patterns
Manual Restraints:	3-point, manual lap/shoulder restraints at L/F, R/F, L/R and R/R seating positions. 2-point manual lap belts at C/F and C/R seating positions.	3-point, manual lap/shoulder restraints at L/F, R/F, L/R and R/R seating positions.
Automatic Restraints:	Driver's side airbag	None
Reported Defects:	None	None
Cargo:	None	None
Windshield Damage:	Unknown, cut and removed for occupant extrication	Cracked from impact forces
Fleet:	None	None
Tow Status:	Towed due to crash damage	Towed due to crash damage

Dynamic Science, Inc.
In-Depth Investigation
Case Number: DSI-94-AB-06

VEHICLES (Con't.):

VEHICLE 3

Description:	1990 Mercury Cougar, 2-door
Odometer:	Unknown - Vehicle could not be located for inspection
Engine:	Unknown
Vehicle Modifications:	Unknown
Tire Condition:	Unknown
Manual Restraints:	Unknown
Automatic Restraints:	None
Reported Defects:	None
Cargo:	Unknown
Windshield Damage:	Unknown
Fleet:	None
Tow Status:	Towed from scene, reason unknown

Dynamic Science, Inc.
In-Depth Investigation
Case Number: DSI-94-AB-06

VEHICLE DAMAGE:

	<u>VEHICLE 1</u>	<u>VEHICLE 2</u>	
Object Struck:	Vehicle 2	Vehicle 1	Vehicle 3
Event Number:	01	01	02
CDC:	92FYEW4	92FYEW4	09LBLE1
Maximum Crush:	104.5 cm (41.2 in) @ C ₁	77.1 cm (30.4 in) @ C ₁	approximately 4 cm (1.6 in) @ L/R bumper corner

VEHICLE VELOCITY ESTIMATES:

	<u>VEHICLE 1</u>	<u>VEHICLE 2</u>	
Impact Speed:	56 to 64 KPH (35 to 40 MPH)	56 to 64 KPH (35 to 40 MPH)	8 to 16 KPH (5 to 10 MPH)
Total Delta V:	38.5 KPH (23.9 MPH)	37.2 KPH (23.1 MPH)	Not computed
Longitudinal Delta V:	-38.4 KPH (-23.9 MPH)	-37.1 KPH (-23.0 MPH)	Insufficient information
Lateral Delta V:	3.4 KPH (2.1 MPH)	3.2 KPH (2.0 MPH)	
Energy Dissipation:	133,340 j (98,333.3 ft-lb)	87,076.3 j (64,215.6 ft-lb)	

Calculations based upon: Delta V: Crash III PC - damage only

$$\text{Radius: } R = \frac{C^2}{8 \cdot M} + \frac{M}{2}$$

Southbound: C = 100 ft, M = 2.0 ft
Northbound: C = 100 ft, M = 1.5 ft

**Dynamic Science, Inc.
In-Depth Investigation
Case Number: DSI-94-AB-06**

VEHICLE DAMAGE:

VEHICLE 3

Object Struck: Vehicle 2
Event Number: 02
CDC: Unknown - Vehicle
not inspected
Maximum Crush:

VEHICLE VELOCITY ESTIMATES:

VEHICLE 3

Impact Speed (estimated): 16 to 24 KPH
(10 to 15 MPH)
Total Delta V: Not computed
Longitudinal Delta V: Insufficient information
Lateral Delta V: Vehicle not located
Energy Dissipation: for inspection

Calculations based upon: None for this impact, insufficient information

Dynamic Science, Inc.
In-Depth Investigation
Case Number: DSI-94-AB-06

COLLISION SEQUENCE:

PRE-CRASH: This three vehicle crash occurred during the afternoon hours of a winter weekend on a two-lane, undivided, asphalt paved, urban/residential roadway in [REDACTED] Maryland. The weather was clear, there were no viewing restrictions, and the road surface was dry and free of defects. Traffic volume was moderate, and there is a posted speed limit of 64 KPH (45 MPH).

The roadway configuration is a 2.7 m (8.8 ft) asphalt paved shoulder separated from the southbound travel lane by a single, solid, white painted line. The southbound travel lane is separated from the northbound travel lane by double, solid, yellow painted lines. The northbound travel lane is separated from the east 2.9 m (9.5 ft) asphalt paved shoulder by a single, solid, white painted line.

The southbound travel lane is a right turning curve with a radius of 190.8 m (626.0 ft) computed at the west edge of the travel lane. The northbound travel lane is a left turning curve with a radius of 254.2 m (834.1 ft) computed at the east edge of the travel lane. In addition, the southbound travel lane has a positive five percent upgrade.

Vehicle 1, a 1990 Cadillac Sedan deVille, was being driven south in the southbound travel lane by the 77 year old female driver (the case occupant) who was not restrained by the available three-point manual lap/shoulder safety restraints. Occupant 2, an 80 year old male, was sitting in the right front seating position and was not wearing the available three-point manual lap/shoulder safety restraints. The speed of Vehicle 1 was estimated to have been between 56 and 64 KPH (35 and 40 MPH).

Vehicle 2, a 1991 Toyota SR-5 4WD extended cab pickup truck, was being driven north in the northbound travel lane by the 26 year old male driver at a speed estimated to have been between 56 and 64 KPH (35 and 40 MPH). The driver was wearing the available three-point manual lap/shoulder safety restraints in a normal and proper manner. Occupant 2, a 1 year old male, was secured by the available harness and shield of an Evenflo Champion I, forward facing, convertible child safety seat that was properly secured in the right front seating position

Dynamic Science, Inc.
In-Depth Investigation
Case Number: DSI-94-AB-06

by the available three-point manual lap/shoulder safety restraint. Occupant 3, an 11 year old female, was sitting in the left rear seating position and was wearing the available three-point manual lap/shoulder safety restraints.

Vehicle 3, 1990 Mercury Cougar 2-door, was being driven north in the northbound travel lane, immediately behind Vehicle 2, by the 22 year old female driver at a speed estimated to have been between 56 and 64 KPH (35 and 40 MPH). Occupant 2, a 21 year old female, was seated in the right front seating position. Police indicate that both occupants of this vehicle were restrained, but this could not be verified as the vehicle could not be located for inspection and the driver refused to cooperate in this investigation.

As Vehicle 1 neared the center of the right turning curve, the driver's attention was apparently diverted and the vehicle drifted left across the double yellow center lines into the travel path of Vehicle 2 in the northbound travel lane.

CRASH:

The left front plane of Vehicle 1 impacted the left front plane of Vehicle 2 in a head-on configuration. The Delta V for Vehicle 1 was computed, using CRASH III PC, as 38.5 KPH (23.9 MPH) using a CDC of 92FYEW4 and a PDOF of 355 degrees. The combined direct and induced damage width was 160 cm (63 in), and the maximum crush depth was 104.5 cm (41.2 in) at C₁. The Delta V for Vehicle 2 was computed, using CRASH III PC, as 37.2 KPH (23.1 MPH) using a CDC of 92FYEW4 and a PDOF of 355 degrees. The combined direct and induced damage width was 156 cm (61.4 in), and the maximum crush depth was 77.1 cm (30.4 in) at C₁. The forces in this impact exceeded the manufacturer's threshold in the supplemental restraint system of Vehicle 1 and the driver's side airbag deployed.

POST CRASH:

At impact, Vehicle 1 began a 110 degree counter-clockwise rotation and came to final rest facing east with the right front wheel at the double yellow center lines and the right and left rear wheels in the southbound travel lane.

Vehicle 2 also began a counter-clockwise rotation at impact and had rotated approximately 50 degrees when the front plane of Vehicle 3 impacted the left rear bumper corner of Vehicle 2 in a near right angle

Dynamic Science, Inc.
In-Depth Investigation
Case Number: DSI-94-AB-06

configuration. Vehicle 2 continued the counterclockwise rotation for an additional 20 degrees and came to final rest facing northwest with the right and left front wheels in the northbound travel lane and the right and left rear wheels on the east shoulder of the roadway. Vehicle 3 came to final rest facing northeast with the right front wheel on the east shoulder of the roadway and the left front wheel, left rear wheel and right rear wheel in the northbound travel lane. The driver of Vehicle 3 appears to have steered right and braked prior to impact with Vehicle 2 and the FRP of Vehicle 3 appears to be at the approximate POI with Vehicle 2.

The CDC for Vehicle 2 in impact two was 09LBLE1 using a PDOF of 255 degrees. The combined direct and induced damage width was 43 cm (17 in), and the maximum crush depth was approximately 4 cm (2 in) at the left rear bumper corner. A more thorough reconstruction of this secondary impact could not be completed due to the inability to locate Vehicle 3 for inspection and the lack of cooperation from the owner of Vehicle 3.

DRIVER KINEMATICS:

The 77 year old female driver of Vehicle 1 (the case occupant) was seated on a split bench seat with separate backs in a normal, upright seated position. The driver, who was 160 cm (63 in) in height and weighed 68 kg (150 lb), had the electric seat adjusted to the full forward position and to its maximum height. The seat back support was in the normal, upright configuration. The driver was not wearing the available three-point, manual lap/shoulder safety restraints.

At impact, the unrestrained driver (the case occupant) was projected forward, upward and to the left. This movement caused her to override the deploying airbag and her head impacted the left "A" pillar and left front door glazing resulting in a closed head injury with loss of consciousness of undetermined duration. At the same time, her right hand was projected from the steering wheel rim into the upper left instrument panel resulting in a colles fracture of the right wrist.

The driver's left foot was on the floor/toe pan at impact, and as she was projected forward and upward, her left knee impacted the lower left instrument panel resulting in axial loading of the left femur causing

Dynamic Science, Inc.
In-Depth Investigation
Case Number: DSI-94-AB-06

an intertrochanteric femur fracture. Simultaneously, she sustained an open fracture and ruptured tendon of the left patella.

At impact it appears that the driver was in the process of moving her right foot from the accelerator to the brake pedal. The impact force projected her foot onto the brake pedal as the floor/toe pan intruded longitudinally resulting in a right calcaneus fracture. In addition, her right knee impacted the lower left instrument panel and she sustained a closed fracture of the right patella and an avulsion of the right knee.

The driver's forward and upward movement also caused her abdomen to load and deform the lower steering wheel rim. There were no reported injuries from this contact.

Occupant 2, an 80 year old male, was seated on a split bench seat with separate backs that was adjusted to its forward most position and which appeared to be at its maximum height. He was not restrained by the available three-point manual lap/shoulder safety restraints. At impact he was projected forward, slightly downward and to the left. This movement caused his head to strike the right top of the instrument panel resulting in a closed head injury with loss of consciousness for an undetermined duration and a right forehead laceration. His chest and upper abdomen impacted the right instrument panel resulting in a ruptured spleen with massive parenchymal disruption and fractures of multiple left ribs. His lower abdomen and lower extremities impacted the lower right instrument panel resulting in a hemoperitoneum and a thoracic back sprain.

SUPPLEMENTAL RESTRAINT SYSTEM:

The case vehicle was equipped with a driver's side airbag that deployed as a result of a head-on collision. There were no manufacturer's identifying numbers, marks or tags on the airbag, or airbag module, at the time of Dynamic Science's on-site inspection which occurred 17 days post crash and within 24 hours of notification.

The airbag was not damaged during the crash sequence and did not yield evidence of occupant contact. The bag measured approximately 71 cm (28 in) in diameter in its deflated, post crash state. The airbag was vented by two vent ports on the back side of the bag (away from

Dynamic Science, Inc.
In-Depth Investigation
Case Number: DSI-94-AB-06

the driver). The 3.5 cm (1.4 in) diameter vent ports were located at the 10:00 and 2:00 o'clock positions. The airbag was not tethered.

At the time of Dynamic Science's on-site inspection the airbag contained five horizontal and four vertical fold creases. The fold creases were oriented to the top of the steering wheel.

SCENE CLEARANCE:

The driver of Vehicle 1 (the case occupant) sustained moderate injuries consisting of fractures, rupture, avulsion and a closed head injury with loss of consciousness; maximum AIS = AIS-3. Occupant 2 sustained major injuries consisting of fractures, rupture, abrasion, sprain and a closed head injury with loss of consciousness; maximum AIS = AIS-4. Neither occupant of Vehicle 1 was entrapped, but extensive extrication procedures were used to extricate the occupants. The extrication procedures included cutting the "A" pillars and "B" pillars, removing the windshield and folding the top back. The left front and rear doors were also removed. Once extricated from Vehicle 1, both occupants were transported by air to a [REDACTED] center where they were admitted for treatment.

The driver of Vehicle 2 sustained major injuries consisting of a closed head injury with loss of consciousness, lacerations and strains; maximum AIS = AIS-4. He was transported by land to a [REDACTED] where he was admitted for treatment. Occupant 2 sustained minor injuries consisting of a closed head injury without loss of consciousness; maximum AIS = AIS-1. He was transported by land to a local hospital where he was treated and released. Occupant 3 sustained minor injury consisting of a fracture; maximum AIS = AIS-1. She was transported to a [REDACTED] where she was treated and released. None of the occupants in Vehicle 2 were entrapped, but a "Hurst tool" was required to open a jammed door to facilitate extrication.

The driver of Vehicle 3 refused to cooperate with this investigation. However, police reported that she sustained non-incapacitating injuries of an unknown nature or severity. Her course of treatment could not be determined. Police also reported that Occupant 2 sustained incapacitating injuries of an unknown nature or severity. Her course of treatment could not be determined.

Dynamic Science, Inc.
In-Depth Investigation
Case Number: DSI-94-AB-06

Vehicles 1 and 2 were towed from the scene due to damage sustained in this crash. Vehicle 3 was towed from the scene for unknown reasons.

SAFETY STANDARDS:

There were no violations of the Federal Motor Vehicle Safety Standards identified during the on-site inspections of Vehicles 1 and 2.

**Dynamic Science, Inc.
In-Depth Investigation
Case Number: DSI-94-AB-06**

DRIVER AND OTHER OCCUPANTS:

VEHICLE 1

	<u>DRIVER (case occupant)</u>	<u>OCCUPANT 2</u>
Age/Sex:	77 years old/female	80 years old/male
Seated Position:	Left front	Right front
Seat Type:	Split bench with separate backs	Split bench with separate backs
Height:	160 cm (63 in)	173 cm (68 in)
Weight:	68 kg (150 lb)	75 kg (165 lb)
Occupation:	Not reported	Retired
Pre-existing Medical Condition:	None known	None known
Alcohol/Drug Involvement:	Unspecified opiates in blood sample	None reported
Driving Experience:	40+ years	N/A
Body Posture:	Normal, upright seated position	Normal, upright seated position
Hand Position:	Both hands on steering wheel rim, exact positions unknown	Unknown
Foot Position:	Left foot on floor/toe pan, right foot moving from accelerator to brake	Both feet on floor/toe pan
Restraint Usage:	None	None
Additional Occupants:	1	None

Dynamic Science, Inc.
In-Depth Investigation
Case Number: DSI-94-AB-06

DRIVER AND OTHER OCCUPANTS (con't):

VEHICLE 2

	<u>DRIVER</u>	<u>OCCUPANT 2</u>	<u>OCCUPANT 3</u>
Age/Sex:	26 years old/male	1 year old/male	11 years old/female
Seated Position:	Left front	Right front	Left rear
Seat Type:	Bucket with folding back	Child safety seat, secured in bucket with folding back	Folding "jump" seat
Height:	183 cm (72 in)	79 cm (31 in)	137 cm (54 in)
Weight:	82 kg (180 lb)	15 kg (32 lb)	41 kg (90 lb)
Occupation:	Not reported	Pre-school child	Student
Pre-existing Medical Condition:	None reported	None reported	None reported
Alcohol/Drug Involvement:	None	None	None
Driving Experience:	9 years	N/A	N/A
Body Posture:	Normal, upright seated position	Upright, secured with harness and shield in forward facing child safety seat	Normal, upright seated position
Hand Position:	Both hands on steering wheel rim, positions unknown	Unknown	Unknown
Foot Position:	Right foot on accelerator, left foot on floor/toe pan	Unknown	Both feet on floor
Restraint Usage:	3-point manual lap/shoulder restraints	3-point manual lap/shoulder restraint secured child safety seat	3-point manual lap/shoulder restraint
Additional Occupants:	2	1	None

Dynamic Science, Inc.
In-Depth Investigation
Case Number: DSI-94-AB-06

DRIVER AND OTHER OCCUPANTS (con't):

VEHICLE 3

	<u>DRIVER</u>	<u>OCCUPANT 2</u>
Age/Sex:	22 years old/female	21 years old/female
Seated Position:	Left front	Right front
Seat Type:	Unknown	Unknown
Height:	Refused	Unknown
Weight:	Refused	Unknown
Occupation:	Refused	Unknown
Pre-existing Medical Condition:	None known	None known
Alcohol/Drug Involvement:	None	None
Driving Experience:	Unknown	N/A
Body Posture:	Unknown	Unknown
Hand Position:	Unknown	Unknown
Foot Position:	Unknown	Unknown
Restraint Usage:	Unknown	Unknown
Additional Occupants:	1	None

Dynamic Science, Inc.
In-Depth Investigation
Case Number: DSI-94-AB-06

INJURIES:

Vehicle 1

	<u>INJURY</u>	<u>AIS/OIC CODE</u>	<u>ICD-9</u>	<u>SOURCE</u>
DRIVER: (case occupant)	Fracture, L. femur (interchanteric)	2851810.3,2091202	820.21	L. Inst. panel
	Fracture, open - L. Patella	2852400.2,2091102	822.1	L. Inst. panel
	Rupture, tendon, L. Patella	2840802.2,2091102	844.8	L. Inst. panel
	Fracture, R. Patella	2852400.2,1091102	822.0	L. Inst. panel
	Fracture, R. Calcaneus	2851400.2,1561101	825.0	Floor/brake pedal
	Fracture, Wrist (colles fracture)	2752802.2,1091100	813.41	L. Inst. panel
	Closed head injury with loss of consciousness	160406.2,0262100	850.5	L. side window glass and "A" pillar
	Avulsion, R. Knee	2890800.1,1091102	891.0	L. Inst. panel
R/F Occupant:	Rupture, spleen w/massive parenchymal disruption	2544226.4,2111100	865.04	R. Inst. panel
	Fractures, multiple L. Ribs	2450220.2,2111100	807.09	R. Inst. panel
	Closed head injury with loss of consciousness	2160406.2,0111100	850.5	R. Inst. panel
	Abrasion, R. Forehead	2290202.1,7111100	910.0	R. Inst. panel
	Hemoperitoneum	2590402.1,9111100	868.03	R. Inst. panel
	Sprain, back (thoracic)	2640478.1,7921300	847.1	Inertial force

**Dynamic Science, Inc.
In-Depth Investigation
Case Number: DSI-94-AB-06**

INJURIES:

Vehicle 2

	<u>INJURY</u>	<u>AIS/OIC CODE</u>	<u>ICD-9</u>	<u>SOURCE</u>
DRIVER:	Closed head injury with loss of consciousness (intercranial bleeding)	7140629.4,2041100	853.06	Steering wheel rim
	Laceration, L. eyebrow	7290602.1,2041100	873.42	Steering wheel rim
	Strain, neck	7640278.1,6921300	847.0	Inertial force
	Strain, back	7640478.1,7921300	847.1	Inertial force
R/F Occupant:	Closed head injury without loss of consciousness	7160499.1,0481100	850.9	Shield, child safety seat
L/R Occupant:	Fracture, Nose	7251002.1,4401100	802.0	L/F seat back support

**Dynamic Science, Inc.
In-Depth Investigation
Case Number: DSI-94-AB-06**

INJURIES:

Vehicle 3

	<u>INJURY</u>	<u>AIS/OIC CODE</u>	<u>ICD-9</u>	<u>SOURCE</u>
DRIVER:	Reported by police to have sustained non-incapacitating injuries of unknown nature or severity			

R/F Occupant:	Reported by police to have sustain incapacitating injuries of unknown nature or severity			
--------------------------	--	--	--	--

Abbreviations Used In Scene And Photographic Documentation

ft.	Feet
in.	Inches
AIS	Abbreviated Injury Scale
BLF	Begin Left Front
BLR	Begin Left Rear
BRF	Begin Right Front
BRR	Begin Right Rear
CBE	Cab Behind Engine
CCW	Counterclockwise
CDC	Collision Deformation Classification
CG	Center of Gravity
CM	Centimeter
COE	Cab Over Engine
CW	Clockwise
E, EB	East, Eastbound
ELF	End Left Front
ELR	End Left Rear
ERF	End Right Front
ERR	End Right Rear
FRP	Final Rest Position
I	Interstate Highway
IP	Intermediate Point
KG	Kilogram
KPH	Kilometers Per Hour
LF	Left Front
LR	Left Rear
M	Meter
N, NB	North, Northbound
NE	Northeast
NW	Northwest
PDOF	Principal Direction of Force
POI	Point of Impact
R	Radius of Curvature
RF	Right Front
RL	Reference Line
RP	Reference Point
RR	Right Rear
S, SB	South, Southbound
SE	Southeast
SW	Southwest
T	Time or Elapsed Time (in seconds)
U.S.	United States Highway
V1	Vehicle Number 1
W, WB	West, Westbound

FRONT INTRUSIONS

Case Number DSL-94-AB-001


VEHICLE Ø1

Seat adjusted to:

Forward X
Midpoint _____
Rearward _____

Seat Type:

Electric X
Manual _____




Left Side

A-B	<u>48.6</u>	cm	<u>19.1</u>	in
B-C	<u>-6.0</u>	cm	<u>-2.4</u>	in
B-D	<u>38.0</u>	cm	<u>15.0</u>	in
A-B-C	<u>86.6</u>	cm	<u>34.1</u>	in
C-E	<u>43.0</u>	cm	<u>16.9</u>	in
B-E	<u>23.0</u>	cm	<u>9.1</u>	in

Right Side

A-B	<u>48.6</u>	cm	<u>19.1</u>	in
B-C	<u>7.0</u>	cm	<u>2.8</u>	in
B-D	<u>48.0</u>	cm	<u>18.9</u>	in
A-B-C	<u>96.6</u>	cm	<u>38.0</u>	in
C-E	<u>51.0</u>	cm	<u>20.1</u>	in
B-E	<u>28.0</u>	cm	<u>11.0</u>	in




Left Side

G-I	<u>104.6</u>	cm	<u>41.2</u>	in
H-J	<u>80.0</u>	cm	<u>31.5</u>	in


Right Side

G-I	<u>109.6</u>	cm	<u>42.8</u>	in
H-J	<u>75.0</u>	cm	<u>29.5</u>	in




PEDAL MOVEMENT

DAMACE OVERLAP



47%




48%

STEERING COLUMN WORKING DIAGRAMS

STEERING COLUMN COLLAPSE

Steering Column Shear Module Movement




SHEAR CAPSULE

COMPLETE COLLAPSE
PRIMARY IMPACT CRUSH


SOME DRIVER
LOADING

Left —




Right — V = —"

Direction and Magnitude of Steering Column Movement




STEERING COLUMN MOVEMENT


Vertical Movement



Lateral Movement



Longitudinal Movement




ALL MEASUREMENTS APPROXIMATE DUE TO EXTRICATION DAMAGE

	COMPARISON VALUE	—	DAMAGED VALUE	=	MOVEMENT
VERTICAL					+ MOVEMENT - UNMEASURABLE - ESTIMATED = + 14 cm (4.6")
LATERAL					+ MOVEMENT - UNMEASURABLE - ESTIMATED = + 7.6 cm (3.0")
LONGITUDINAL					φ - 22.4 cm (-8.7 in) = -22.4 cm (-8.7 in)

STEERING RIM/SPOKE DEFORMATION

COMPARISON VALUE	—	DAMAGED VALUE	=	DEFORMATION
12.4 cm (4.7 in)	—	8.4 cm (3.1")	=	4.4 cm (1.6 in)
—	—	—	=	—



COLLISION MEASUREMENTS**Case Number DSI-94-AB-06**

Reference Point: Wood utility pole, 1.5 m (5 ft) east of east edge of roadway

Reference Line: East edge of roadway

DATA POINT	LONGITUDINALS	LATERALS
East edge of roadway	0	0
Single white line (east shoulder)	0	2.9 m (9.5 ft) W
Double yellow line (N/B travel lane)	0	6.6 m (21.7 ft) W
Single white line (S/B travel lane)	0	10.1 m (33.1 ft) W
West edge of roadway (west shoulder)	0	12.8 m (41.9 ft) W
POI - V1 and V2	7.3 m (23.8 ft) S	5.4 m (17.8 ft) W
Approximate POI - V2 and V3	10.1 m (33.1 ft) S	3.1 m (10.2 ft) W
FRP - V1		
R/F wheel	10.1 m (33.1 ft) S	6.2 m (20.5 ft) W
L/R wheel	9.2 m (30.3 ft) S	9.9 m (32.5 ft) W
R/R wheel	11.2 m (36.9 ft) S	9.1 m (29.8 ft) W
FRP - V2		
L/F wheel	6.8 m (22.3 ft) S	4.5 m (14.8 ft) W
R/F wheel	4.7 m (15.3 ft) S	4.7 m (15.4 ft) W
L/R wheel	7.6 m (25 ft) S	2.2 m (7.1 ft) W
R/R wheel	5.9 m (19.2 ft) S	1.6 m (5.1 ft) W
FRP - V3		
L/F wheel	10.1 m (33.1 ft) S	3.1 m (10.2 ft) W
R/F wheel	11.1 m (36.4 ft) S	1.6 m (5.1 ft) W
R/R wheel	13.7 m (45.0 ft) S	2.6 m (8.4 ft) W
L/R wheel	12.8 m (42.0 ft) S	4.5 m (14.6 ft) W

PHOTO INDEX

Case No. DSI-94-AB-06

PHOTO NO.	VEHICLE NO.	ORIENTATION	SUBJECT MATTER
1	Vehicle 1	NW	Approach path, Vehicle 1
2-4	Vehicle 1	SE	Travel path, Vehicle 1
5-6	Vehicle 1	SE	POI, Vehicle 1 and Vehicle 2
7	Vehicle 1	S	Travel path, POI to FRP, Vehicle 1
8	Vehicle 1	N	FRP and Reverse travel path to POI, Vehicle 1
9	Vehicle 1	NW	Reverse travel path, Vehicle 1
10	Vehicle 2/3	SE	Approach path, Vehicles 2 and 3
11-13	Vehicle 2/3	NW	Travel path and POI, Vehicles 2 and 3
14-15	Vehicle 2	NW	POI, Vehicles 2 and 1
16	Vehicle 2	W	FRP, Vehicle 2
17-18	Vehicle 2	E	FRP, Vehicle 2 and POI Vehicles 2 and 1
19	Vehicle 3	S	FRP, Vehicle 3
20	Vehicle 2/3	SE	Reverse travel path, Vehicles 2 and 3
21-31	Vehicle 1	CCW	Exterior views, Vehicle 1
32-51	Vehicle 1	---	Interior views, Vehicle 1
52-63	Vehicle 2	CCW	Exterior views, Vehicle 2
64-83	Vehicle 2	---	Interior views, Vehicle 2









AB06-9



AB06-10






















































































SLIDE INDEX

Case No. DSI-94-AB-06

SLIDE NO.	VEHICLE NO.	ORIENTATION	SUBJECT MATTER
1	Vehicle 1	NW	Approach path
2-5	Vehicle 1	SE	Travel path
6-7	Vehicle 1	SE	POI
8	Vehicle 1	W	Travel path to FRP
9	Vehicle 1	E	FRP
10	Vehicle 1	NW	Reverse travel path
11	Vehicle 2/3	SE	Approach path
12-14	Vehicle 2/3	NW	Travel path
15-16	Vehicle 2	NW	POI, Vehicles 2 and 1
17	Vehicle 2	W	FRP
18	Vehicle 2/3	E	FRP, Vehicle 2 and POI Vehicles 2 and 3
19	Vehicle 2/3	E	FRP, Vehicle 3
20	Vehicle 2/3	SE	Reverse travel path, Vehicles 2 and 3
21-32	Vehicle 1	CCW	Exterior views
33-54	Vehicle 1	---	Interior views
55-67	Vehicle 2	CCW	Exterior views
68-88	Vehicle 2	---	Interior views











RJF



















































































































TOYOTA

SR5

VB

4WD



TOYOTA

SR5

V6

4WD



TOYOTA

SR5

4WD
























































ACCIDENT FORM

1. Primary Sampling Unit Number _____

2. Case Number - Stratum DSI-94-AB-006

IDENTIFICATION

3. Number of General Vehicle
Forms Submitted 034. Date of Accident
(Month, Day, Year) WINTER / WEEKEND / 9 45. Time of Accident AFTERNOON

Code reported military time of accident.

NOTE: Midnight = 2400
Unknown = 9999

SPECIAL STUDIES - INDICATORS

Check (✓) each special study (SS14-SS18 below) that has been completed; code 1 for the checked special studies and 0 for the special studies not checked.

6. 0 SS15 Administrative Use 07. 0 SS16 Pedestrian Crash Data Study 08. 0 SS17 Impact Fires 09. 0 SS18 _____ 010. 0 SS19 _____ 0

NUMBER OF EVENTS

11. Number of Recorded Events
in This Accident 02Code the number of events which occurred
in this accident.

ACCIDENT EVENTS

For each event that occurred in the accident, code the lowest numbered vehicle in the left columns and the other involved vehicle or object on the right.

Accident Event Sequence Number	Vehicle Number	Class Of Vehicle	General Area of Damage	Vehicle Number or Object Contacted	Class Of Vehicle	General Area of Damage
12. <u>0 1</u>	13. <u>0 1</u>	14. <u>0 4</u>	15. <u>F</u>	16. <u>0 2</u>	17. <u>1 5</u>	18. <u>F</u>
19. <u>0 2</u>	20. <u>0 2</u>	21. <u>1 5</u>	22. <u>L</u>	23. <u>0 3</u>	24. <u>0 3</u>	25. <u>F</u>
26. <u>0 3</u>	27. _____	28. _____	29. _____	30. _____	31. _____	32. _____
33. <u>0 4</u>	34. _____	35. _____	36. _____	37. _____	38. _____	39. _____
40. <u>0 5</u>	41. _____	42. _____	43. _____	44. _____	45. _____	46. _____

IF GREATER THAN FIVE EVENTS, CONTINUE CODING ON THE ACCIDENT EVENT SUPPLEMENT

CODES FOR CLASS OF VEHICLE

- (00) Not a motor vehicle
- (01) Subcompact/mini (wheelbase < 254 cm)
- (02) Compact (wheelbase ≥ 254 but < 265 cm)
- (03) Intermediate (wheelbase ≥ 265 but < 278 cm)
- (04) Full size (wheelbase ≥ 278 but < 291 cm)
- (05) Largest (wheelbase ≥ 291 cm)
- (09) Unknown passenger car size
- (11) Compact utility vehicle
- (12) Large utility vehicle (≤ 4,500 kgs GVWR)
- (13) Passenger van (≤ 4,500 kgs GVWR)
- (14) Other van (≤ 4,500 kgs GVWR)
- (15) Pickup truck (≤ 4,500 kgs GVWR)
- (18) Other truck (≤ 4,500 kgs GVWR)
- (19) Unknown light truck type
- (20) School bus
- (21) Other bus
- (22) Truck (> 4,500 kgs GVWR)
- (23) Tractor without trailer
- (24) Tractor-trailer(s)
- (25) Motored cycle
- (28) Other vehicle
- (99) Unknown

CODES FOR GENERAL AREA OF DAMAGE (GAD)

CDS APPLICABLE AND OTHER VEHICLES

- (O) Not a motor vehicle
- (N) Noncollision
- (F) Front
- (R) Right side
- (L) Left side
- (B) Back
- (T) Top
- (U) Undercarriage
- (9) Unknown

TDC APPLICABLE VEHICLES

- (O) Not a motor vehicle
- (N) Noncollision
- (F) Front
- (R) Right side
- (L) Left side
- (B) Back of unit with cargo area (rear of trailer or straight truck)
- (D) Back (rear of tractor)
- (C) Rear of cab
- (V) Front of cargo area
- (T) Top
- (U) Undercarriage
- (9) Unknown

CODES FOR VEHICLE NUMBER OR OBJECT CONTACTED

(01-30) — Vehicle Number

Noncollision

- (31) Overturn — rollover
- (32) Fire or explosion
- (33) Jackknife
- (34) Other intraunit damage (specify): _____

(35) Noncollision injury

(38) Other noncollision (specify): _____

(39) Noncollision — details unknown

Collision With Fixed Object

- (41) Tree (≤ 10 cm in diameter)
- (42) Tree (> 10 cm in diameter)
- (43) Shrubbery or bush
- (44) Embankment

(45) Breakaway pole or post (any diameter)

Nonbreakaway Pole or Post

- (50) Pole or post (≤ 10 cm in diameter)
- (51) Pole or post (> 10 cm but ≤ 30 cm in diameter)
- (52) Pole or post (> 30 cm in diameter)
- (53) Pole or post (diameter unknown)

(54) Concrete traffic barrier

(55) Impact attenuator

(56) Other traffic barrier (includes guardrail)
(specify): _____

(57) Fence

(58) Wall

(59) Building

(60) Ditch or culvert

(61) Ground

(62) Fire hydrant

(63) Curb

(64) Bridge

(68) Other fixed object (specify): _____

(69) Unknown fixed object

Collision with Nonfixed Object

(71) Motor vehicle not in-transport

(72) Pedestrian

(73) Cyclist or cycle

(74) Other nonmotorist or conveyance

(75) Vehicle occupant

(76) Animal

(77) Train

(78) Trailer, disconnected in transport

(79) Object fell from vehicle in-transport

(88) Other nonfixed object (specify): _____

(89) Unknown nonfixed object

(98) Other event (specify): _____

(99) Unknown event or object

National Highway Traffic Safety
Administration

GENERAL VEHICLE FORM

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

1. Primary Sampling Unit Number

2. Case Number - Stratum D3I-94-AB-0063. Vehicle Number 01

VEHICLE IDENTIFICATION

4. Vehicle Model Year 9 0
Code the last two digits of the model year
(99) Unknown5. Vehicle Make (specify): 1 9
CADILLAC
Applicable codes are found in your
NASS Data Collection, Coding and
Editing Manual.
(99) Unknown6. Vehicle Model (specify): 0 0 3
SEDAN DEVILLE
Applicable codes are found in your
NASS Data Collection, Coding and
Editing Manual.
(999) Unknown7. Body Type 0 4
Note: Applicable codes may be found on
the back of this page.

8. Vehicle Identification Number

1 9 6 C D 5 3 3 B L 4 X X X X X
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16Left justify; Slash zeros and letter Z (0 and Z)
No VIN—Code all zeros
Unknown—Code all nines

OFFICIAL RECORDS

9. Police Reported Vehicle Disposition 1
(0) Not towed due to vehicle damage
(1) Towed due to vehicle damage
(9) Unknown10. Police Reported Travel Speed 9 9 9Code to the nearest kph (NOTE: 000 means
less than 0.5 kph)
(160) 159.5 kph and above
(999) Unknown mph X 1.6093 = kph11. Police Reported Alcohol Presence 0
(0) No alcohol present
(1) Yes (alcohol present)
(7) Not reported
(8) No driver present
(9) UnknownNote: See variables 37 through 55
(Page 4) for information on Other Drugs12. Alcohol Test Result For Driver 9 6
Code actual value (decimal implied
before first digit—0.xx)
(95) Test refused
(96) None given
(97) AC test performed, results unknown
(98) No driver present
(99) UnknownSource: PAR

ACCIDENT RELATED

13. Speed Limit 0 6 4
(000) No statutory limit
Code posted or statutory speed limit
in kph
(999) Unknown4 0 mph X 1.6093 = 0 6 4 kph14. Attempted Avoidance Maneuver 0 2
(01) No avoidance actions
(02) Braking (no lockup)
(03) Braking (lockup)
(04) Braking (lockup unknown)
(05) Releasing brakes
(06) Steering left
(07) Steering right
(08) Braking and steering left
(09) Braking and steering right
(10) Accelerating
(11) Accelerating and steering left
(12) Accelerating and steering right
(97) No driver present
(98) Other action (specify):
(99) Unknown15. Accident Type 5 0
Applicable codes may be found on the
back of page two of this field form
(00) No impact
Code the number of the diagram that
best describes the accident circumstance
(98) Other accident type (specify):
(99) Unknown

**** SKIP TO VARIABLE GV37 IF GV07 DOES NOT EQUAL 01-49 ****

CODES FOR BODY TYPE

CDS APPLICABLE VEHICLES

Automobiles

- (01) Convertible (excludes sun-roof, t-bar)
- (02) 2-door sedan, hardtop, coupe
- (03) 3-door/2-door hatchback
- (04) 4-door sedan, hardtop
- (05) 5-door/4-door hatchback
- (06) Station wagon (excluding van and truck based)
- (07) Hatchback, number of doors unknown
- (08) Other automobile type (specify): _____
- (09) Unknown automobile type

Automobile Derivatives

- (10) Auto based pickup (includes El Camino, Caballero, Ranchero, Brat, and Rabbit pickup)
- (11) Auto based panel (cargo station wagon, auto based ambulance/hearse)
- (12) Large limousine - more than four side doors or stretched chassis
- (13) Three-wheel automobile or automobile derivative

Utility Vehicles ($\leq 4,500$ kgs GVWR)

- (14) Compact utility (Jeep CJ-2 - CJ-7, Scrambler, Golden Eagle, Renegade, Laredo, Wrangler, Cherokee [84 and after], Dispatcher, Raider, Bronco II, Bronco [76 and before], Explorer, S-10 Blazer, Geo Tracker, Bravada, S-15 Jimmy, Thing, Pathfinder, Trooper, Trooper II, Rodeo, Amigo, Navajo, 4-Runner, Montero, Samurai, Sidekick, Rocky)
- (15) Large utility (includes Jeep Cherokee [83 and before], Ramcharger, Trailduster, Bronco-fullsize [78 and after], fullsize Blazer, fullsize Jimmy, Landcruiser, Rover, Scout)
- (16) Utility station wagon (Chevy Suburban, GMC Suburban, Travelall, Grand Wagoneer, includes suburban limousine)
- (19) Utility, unknown body type

Van Based Light Trucks ($\leq 4,500$ kgs GVWR)

- (20) Minivan (Chrysler Town and Country, Caravan, Grand Caravan, Voyager, Grand Voyager, Mini-Ram, Dodge/Plymouth Vista, Aerostar, Villager, Lumina APV, Trans Sport, Silhouette, Astro, Safari, Toyota Van, Toyota Minivan, Previa, Nissan Minivan, Quest, Mitsubishi Minivan, Vanagon/Camper.)
- (21) Large van (B150-B350, Sportsman, Royal, Maxiwagon, Ram, Tradesman, Voyager [83 and before], E150-E350, Econoline, Clubwagon, Chateau, G10-G30, Chevy Van, Beauville, Sport Van, G15-G35, Rally Van, Vandura.)
- (22) Step van or walk-in van ($\leq 4,500$ kgs GVWR)
- (23) Van based motorhome ($\leq 4,500$ kgs GVWR)
- (24) Van based school bus ($\leq 4,500$ kgs GVWR)
- (25) Van based other bus ($\leq 4,500$ kgs GVWR)
- (28) Other van type (Hi-Cube Van, Kary) (specify): _____

- (29) Unknown van type

Light Conventional Trucks (Pickup style cab, $\leq 4,500$ kgs GVWR)

- (30) Compact pickup (D50, Colt P/U, Ram 50, Dakota, Arrow Pickup [foreign], Ranger, Courier, S-10, T-10, LUV, S-15, T-15, Sonoma, Datsun/Nissan Pickup, P'up, Mazda Pickup, Toyota Pickup, Mitsubishi Pickup)
- (31) Large Pickup (Jeep Pickup, Comanche, Ram Pickup, D100-D350, W100-W350, F100-F350, C10-C35, K10-K35, R10-R35, V10-V35, Silverado, Sierra, R100-R500,)

- (32) Pickup with slide-in camper
- (33) Convertible pickup
- (39) Unknown pickup style light conventional truck type

Other Light Trucks ($\leq 4,500$ kgs GVWR)

- (40) Cab chassis based (includes rescue vehicles, light stake, dump, and tow truck)
- (41) Truck based panel
- (42) Light truck based motorhome (chassis mounted)
- (45) Other light conventional truck type
- (48) Unknown light truck type
- (49) Unknown light vehicle type (automobile, utility, van, or light truck)

OTHER VEHICLES

Buses (Excludes Van Based)

- (50) School bus (designed to carry students, not cross country or transit)
- (58) Other bus type (e.g., transit, intercity, bus based motorhome) (specify): _____
- (59) Unknown bus type

Medium/Heavy Trucks ($> 4,500$ kgs GVWR)

- (60) Step van ($> 4,500$ kgs GVWR)
- (61) Single unit straight truck ($4,500$ kgs $<$ GVWR $\leq 8,850$ kgs)
- (62) Single unit straight truck ($8,850$ kgs $<$ GVWR $\leq 12,000$ kgs)
- (63) Single unit straight truck ($> 12,000$ kgs GVWR)
- (64) Single unit straight truck, GVWR unknown
- (65) Medium/heavy truck based motorhome
- (67) Truck-tractor with no cargo trailer
- (68) Truck-tractor pulling one trailer
- (69) Truck-tractor pulling two or more trailers
- (70) Truck-tractor (unknown if pulling trailer)
- (78) Unknown medium/heavy truck type
- (79) Unknown truck type (light/medium/heavy)

Motored Cycles (Does Not Include All-Terrain Vehicles/Cycles)

- (80) Motorcycle
- (81) Moped (motorized bicycle)
- (82) Three-wheel motorcycle or moped
- (88) Other motored cycle (minibike, motorscooter) (specify): _____
- (89) Unknown motored cycle type

Other Vehicles

- (90) ATV (All-Terrain Vehicle) and ATC (All-Terrain Cycle)
- (91) Snowmobile
- (92) Farm equipment other than trucks
- (93) Construction equipment other than trucks
- (97) Other vehicle type
- (99) Unknown body type

OCCUPANT RELATED

16. Driver Presence in Vehicle 1
 (0) Driver not present
 (1) Driver present
 (9) Unknown
17. Number of Occupants This Vehicle 2
 (00-96) Code actual number of occupants for this vehicle
 (97) 97 or more
 (99) Unknown
18. Number of Occupant Forms Submitted 2

VEHICLE WEIGHT ITEMS

19. Vehicle Curb Weight 1,610
 Code weight to nearest 10 kilograms.
 (045) Less than 450 kilograms
 (610) 6,100 kilograms or more
 (999) Unknown
3,546 lbs X .4536 = 1,608 kgs
 Source: [REDACTED]
20. Vehicle Cargo Weight 0
 Code weight to nearest 10 kilograms.
 (000) Less than 5 kilograms
 (450) 4,500 kilograms or more
 (999) Unknown
 _____ lbs X .4536 = _____ kgs

RECONSTRUCTION DATA

21. Towed Trailing Unit 0
 (0) No towed unit
 (1) Yes—towed trailing unit
 (9) Unknown
22. Documentation of Trajectory Data for This Vehicle 1
 (0) No
 (1) Yes
23. Post Collision Condition of Tree or Pole (For Highest Delta V) 0
 (0) Not collision (for highest delta V) with tree or pole
 (1) Not damaged
 (2) Cracked/sheared
 (3) Tilted <45 degrees
 (4) Tilted ≥45 degrees
 (5) Uprooted tree
 (6) Separated pole from base
 (7) Pole replaced
 (8) Other (specify): _____
 (9) Unknown


































































24. Rollover 0
 (0) No rollover (no overturning)
Rollover (primarily about the longitudinal axis)
 (1) Rollover, 1 quarter turn only
 (2) Rollover, 2 quarter turns
 (3) Rollover, 3 quarter turns
 (4) Rollover, 4 or more quarter turns (specify): _____
 (5) Rollover--end-over-end (i.e., primarily about the lateral axis)
 (9) Rollover (overturn), details unknown

OVERRIDE/UNDERRIDE (THIS VEHICLE)

25. Front Override/Underride (this Vehicle) 0
26. Rear Override/Underride (this Vehicle) 0
 (0) No override/underride, or not an end-to-end impact
Override (see specific CDC)
 (1) 1st CDC
 (2) 2nd CDC
 (3) Other not automated CDC (specify): _____
Underride (see specific CDC)
 (4) 1st CDC
 (5) 2nd CDC
 (6) Other not automated CDC (specify): _____
 (7) Medium/heavy truck or bus override
 (9) Unknown

HEADING ANGLE AT IMPACT FOR HIGHEST DELTA V

- Values: (000)-(359) Code actual value
 (997) Noncollision
 (998) Impact with object
 (999) Unknown
27. Heading Angle For This Vehicle 210
28. Heading Angle For Other Vehicle 030

Category	Configuration	ACCIDENT TYPES (Includes Intent)				
I. Single Driver	A. Right Roadside Departure	 01 DRIVE OFF ROAD	 02 CONTROL/ TRACTION LOSS	 03 AVOID COLLISION WITH VEH., PED., ANIM.	04 SPECIFICS OTHER	05 SPECIFICS UNKNOWN
	B. Left Roadside Departure	 06 DRIVE OFF ROAD	 07 CONTROL/ TRACTION LOSS	 08 AVOID COLLISION WITH VEH., PED., ANIM.	09 SPECIFICS OTHER	10 SPECIFICS UNKNOWN
	C. Forward Impact	 11 PARKED VEH.	 12 STA. OBJECT	 13 PEDESTRIAN/ ANIMAL	 14 END DEPARTURE	15 SPECIFICS OTHER 16 SPECIFICS UNKNOWN
II. Same Trafficway Same Direction	D. Rear-End	 20 STOPPED 21, 22, 23	 22 SLOWER 24, 25, 26, 27	 26 DECEL. 28, 29, 30, 31	 30 SPECIFICS OTHER	 31 SPECIFICS UNKNOWN
	E. Forward Impact	 34 CONTROL/ TRACTION LOSS	 36 CONTROL/ TRACTION LOSS	 38 AVOID COLLISION WITH VEH.	 40 AVOID COLLISION WITH OBJECT	 41 SPECIFICS OTHER  42 SPECIFICS UNKNOWN
	F. Sideswipe Angle	 44 SPECIFICS OTHER	 45 SPECIFICS UNKNOWN	 46 SPECIFICS OTHER	 47 SPECIFICS UNKNOWN	 48 SPECIFICS OTHER  49 SPECIFICS UNKNOWN
III. Same Trafficway Opposite Direction	G. Head-On	 50 LATERAL MOVE	 51 SPECIFICS OTHER	 52 SPECIFICS OTHER	 53 SPECIFICS UNKNOWN	 54 SPECIFICS OTHER
	H. Forward Impact	 54 CONTROL/ TRACTION LOSS	 56 CONTROL/ TRACTION LOSS	 58 AVOID COLLISION WITH VEH.	 60 AVOID COLLISION WITH OBJECT	 61 SPECIFICS OTHER  62 SPECIFICS UNKNOWN
	I. Sideswipe Angle	 64 LATERAL MOVE	 65 SPECIFICS OTHER	 66 SPECIFICS OTHER	 67 SPECIFICS UNKNOWN	 68 SPECIFICS OTHER
IV. Change Trafficway Vehicle Turning	J. Turn Across Path	 68 INITIAL OPPOSITE DIRECTIONS	 70 INITIAL SAME DIRECTIONS	 72 SPECIFICS OTHER	 73 SPECIFICS UNKNOWN	 74 SPECIFICS OTHER  75 SPECIFICS UNKNOWN
	K. Turn Into Path	 76 TURN INTO SAME DIRECTION	 78 TURN INTO OPPOSITE DIRECTIONS	 80 SPECIFICS OTHER	 81 SPECIFICS UNKNOWN	 82 SPECIFICS OTHER  83 SPECIFICS UNKNOWN
V. Intersecting Paths (Vehicle Damage)	L. Straight Paths	 86 SPECIFICS OTHER	 88 SPECIFICS UNKNOWN	 89 SPECIFICS OTHER	 90 SPECIFICS OTHER	 91 SPECIFICS UNKNOWN
VI. Miscellaneous	M. Backing Etc.	 92 BACKING VEH.	 93 OTHER VEH. OR OBJECT	 94 OTHER ACCIDENT TYPE	 95 UNKNOWN ACCIDENT TYPE	 96 NO IMPACT

29. Basis for Total Delta V (highest) 1*Delta V Calculated*

- (1) CRASH program—damage only routine
- (2) CRASH program—damage and trajectory routine
- (3) Missing vehicle algorithm

Delta V Not Calculated

- (4) At least one vehicle (which may be this vehicle) is beyond the scope of an acceptable reconstruction program, regardless of collision conditions.
- (5) All vehicles within scope (CDC applicable) of CRASH program but one of the collision conditions is beyond the scope of the CRASH program or other acceptable reconstruction technique, regardless of adequacy of damage data.
- (6) All vehicle and collision conditions are within scope of one of the acceptable reconstruction programs, but there is insufficient data available.

COMPUTER GENERATED DELTA V

30. Total Delta V

Highest

38.5 Nearest kph (highest) 24 mph
(23.9 mph)

Nearest kph (secondary)

(NOTE: 000 means less than
0.5 kph)
(160) 159.5 kph and above
(999) Unknown

31. Longitudinal Component of
Delta V

+
- 38 5 8

-38.5 Nearest kph (highest) -24 mph
(-23.9 mph)

Nearest kph (secondary)

(NOTE: 000 means greater than
-0.5 kph and less than +0.5 kph)
(±160) ±159.5 kph and above
(999) Unknown

Highest

32. Lateral Component of Delta V +

3.4 Nearest kph (highest) 3
(2.1 mph)

Nearest kph (secondary)

(NOTE: 000 means greater than
-0.5 kph and less than +0.5 kph)
(±160) ±159.5 kph and above
(999) Unknown

33. Energy Absorption

1 3 3 3 0 0
(98,300 ft/lbs)

133,340 Nearest 100 joules (highest)

(98,333.3 ft/lbs)

Nearest 100 joules (secondary)

(NOTE: 0000 means less than 50 joules)
(9997) 999,650 joules or more
(9999) Unknown

34. Confidence In Reconstruction Program
Results (For Highest Delta V)

(0) No reconstruction

(1) Collision fits model — results appear reasonable

(2) Collision fits model — results appear high

(3) Collision fits model — results appear low

(4) Borderline reconstruction — results appear reasonable

35. Type of Vehicle Inspection

(0) No inspection

(1) Complete inspection

(2) Partial inspection (specify):

36. Is this an AOPS Vehicle?

(0) No

(1) Yes - researcher determined

(2) VIN determined air bag system

(3) VIN determined automatic (passive) belts

(4) VIN determined air bag and automatic (passive) belts

IS OLDMISS APPLICABLE FOR THIS VEHICLE? [] YES [X] NO

IF YES: IS A COMPLETED OLDMISS PROGRAM SUMMARY INCLUDED? [] YES [] NO

37. Police Reported Other Drug Presence ϕ

- (0) No other drug(s) present
- (1) Yes [other drug(s) present]
- (7) Not reported
- (8) No driver present
- (9) Unknown

38. Police Reported Drug Evaluation Classification (DEC) Test For Driver ϕ

- (0) No DEC process available or given
- (1) DEC process given, results known
- (2) DEC process given, results unknown
- (3) DEC process available, unknown if given
- (8) No driver present

39. Other Drug Specimen Test Type For Driver 1

- (0) No specimen test given
- (1) Blood test
- (2) Urine test
- (3) Other specimen tests (specify): _____
- (7) Unspecified specimen test
- (8) No driver present
- (9) Unknown if specimen test given

DRUG EVALUATION CLASSIFICATION

OTHER DRUGS TEST RESULTS FOR DRIVER

	DEC Test Results	Specimen Test Results
Narcotic Drug	40. <u> ϕ </u>	41. <u> 2 </u>
Depressant Drug	42. <u> ϕ </u>	43. <u> 1 </u>
Stimulant Drug	44. <u> ϕ </u>	45. <u> 1 </u>
Hallucinogen Drug	46. <u> ϕ </u>	47. <u> 1 </u>
Cannabinoid Drug	48. <u> ϕ </u>	49. <u> 1 </u>
Phencyclidine (PCP)	50. <u> ϕ </u>	51. <u> 1 </u>
Inhalant Drug	52. <u> ϕ </u>	53. <u> 1 </u>
Other Drug (Excluding Nicotine, Aspirin, Alcohol, Drugs Administered Post-Crash)	54. <u> ϕ </u>	55. <u> 1 </u>

Codes For DEC Test Results

- (0) No DEC test given
- (1) Passed DEC test
- (2) Failed DEC test
- (3) DEC test given—results unknown
- (8) No driver present
- (9) Unknown if DEC test given

Codes for Specimen Test Results

- (0) No specimen test given
- (1) Drug not found in specimen
- (2) Drug found in specimen
- (7) Specimen test given, results unknown or not obtained
- (8) No driver present
- (9) Unknown if specimen test given

OTHER DATA

56. Driver's Zip Code

- (00000) Driver not present
 (00001) Driver not a resident of U.S. or territories
 Code actual 5-digit zip code
 (99999) Unknown

57. Driver's Race/Ethnic Origin

- (0) Driver not present
 (1) White (non-Hispanic)
 (2) Black (non-Hispanic)
 (3) White (Hispanic)
 (4) Black (Hispanic)
 (5) American Indian, Eskimo or Aleut
 (6) Asian or Pacific Islander
 (8) Other (specify):
 (9) Unknown

58. Vehicle Special Use (This Trip)

- (0) No special use
 (1) Taxi
 (2) Vehicle used as school bus
 (3) Vehicle used as other bus
 (4) Military
 (5) Police
 (6) Ambulance
 (7) Fire truck or car
 (8) Other (specify):
 (9) Unknown

ROLLOVER DATA

If GV07 (Body Type) \neq 1-49, leave GV59-GV63 blank.
 If GV24 (Rollover) = 0, then GV59-GV63 must equal 0.
 If GV24 = 9, then GV59-GV63 must equal 9.

59. Rollover Initiation Type

- (0) No rollover
 (1) Trip-over
 (2) Flip-over
 (3) Turn-over
 (4) Climb-over
 (5) Fall-over
 (6) Bounce-over
 (7) Collision with another vehicle
 (8) Other rollover initiation type (specify):
 (9) Unknown rollover initiation type

60. Location of Rollover Initiation

- (0) No rollover
 (1) On roadway
 (2) On shoulder—paved
 (3) On shoulder—unpaved
 (4) On roadside or divided trafficway median
 (9) Unknown

61. Rollover Initiation Object Contacted

 ϕ ϕ

62. Location on Vehicle Where Initial Principal Tripping Force Is Applied

 ϕ

- (0) No rollover
 (1) Wheels/tires
 (2) Side plane
 (3) End plane
 (4) Undercarriage
 (5) Other location on vehicle (specify):
 (8) Non-contact rollover forces (specify):
 (9) Unknown

63. Direction of Initial Roll

 ϕ

- (0) No rollover
 (1) Roll right - primarily about the longitudinal axis
 (2) Roll left - primarily about the longitudinal axis
 (5) End-over-end (i.e., primarily about the lateral axis)
 (9) Unknown roll direction

PRECRASH DATA

64. Pre-Event Movement (Prior to Recognition of Critical Event)

1 3

- (01) Going straight
 (02) Slowing or stopping in traffic lane
 (03) Starting in traffic lane
 (04) Stopped in traffic lane
 (05) Passing or overtaking another vehicle
 (06) Disabled or parked in travel lane
 (07) Leaving a parking position
 (08) Entering a parking position
 (09) Turning right
 (10) Turning left
 (11) Making a U-turn
 (12) Backing up (other than for parking position)
 (13) Negotiating a curve
 (14) Changing lanes
 (15) Merging
 (16) Successful avoidance maneuver to a previous critical event
 (97) Other (specify):
 (98) No driver present
 (99) Unknown

CODES FOR ROLLOVER INITIATION OBJECT CONTACTED

- (00) No rollover
- (01-30) — Vehicle Number

Noncollision

- (31) Turn-over — fall-over
- (33) Jackknife

Collision With Fixed Object

- (41) Tree (≤ 10 cm in diameter)
- (42) Tree (> 10 cm in diameter)
- (43) Shrubbery or bush
- (44) Embankment

- (45) Breakaway pole or post (any diameter)

Nonbreakaway Pole or Post

- (50) Pole or post (≤ 10 cm in diameter)
- (51) Pole or post (> 10 cm but ≤ 30 cm in diameter)
- (52) Pole or post (> 30 cm in diameter)
- (53) Pole or post (diameter unknown)

- (54) Concrete traffic barrier
- (55) Impact attenuator
- (56) Other traffic barrier (includes guardrail)
(specify): _____

- (57) Fence
- (58) Wall
- (59) Building
- (60) Ditch or culvert
- (61) Ground
- (62) Fire hydrant
- (63) Curb
- (64) Bridge
- (68) Other fixed object (specify): _____

- (69) Unknown fixed object

Collision with Nonfixed Object

- (71) Motor vehicle not in-transport
- (76) Animal
- (77) Train
- (78) Trailer, disconnected in transport
- (79) Object fell from vehicle in-transport
- (88) Other nonfixed object (specify): _____

- (89) Unknown nonfixed object

- (98) Other event (specify): _____

- (99) Unknown event or object

PRECRASH DATA (Continued)

65. Critical Precrash Event 1 φ*This Vehicle Loss of Control Due To:*

- (01) Blow out or flat tire
- (02) Stalled engine
- (03) Disabling vehicle failure (e.g., wheel fell off) (specify): _____
- (04) Non-disabling vehicle problem (e.g., hood flew up) (specify): _____
- (05) Poor road conditions (puddle, pot hole, ice, etc.) (specify): _____
- (06) Traveling too fast for conditions
- (08) Other cause of control loss (specify): _____
- (09) Unknown cause of control loss

This Vehicle Traveling

- (10) Over the lane line on left side of travel lane
- (11) Over the lane line on right side of travel lane
- (12) Off the edge of the road on the left side
- (13) Off the edge of the road on the right side
- (14) End departure
- (15) Turning left at intersection
- (16) Turning right at intersection
- (17) Crossing over (passing through) intersection
- (19) Unknown travel direction

Other Motor Vehicle In Lane

- (50) Stopped
- (51) Traveling in same direction with lower speed (i.e., lower steady speed or decelerating)
- (52) Traveling in same direction with higher speed
- (53) Traveling in opposite direction
- (54) In crossover
- (55) Backing
- (59) Unknown travel direction of other motor vehicle in lane

Other Motor Vehicle Encroaching Into Lane

- (60) From adjacent lane (same direction)—over left lane line
- (61) From adjacent lane (same direction)—over right lane line
- (62) From opposite direction—over left lane line
- (63) From opposite direction—over right lane line
- (64) From parking lane
- (65) From crossing street, turning into same direction
- (66) From crossing street, across path
- (67) From crossing street, turning into opposite direction
- (68) From crossing street, intended path not known
- (70) From driveway, turning into same direction
- (71) From driveway, across path
- (72) From driveway, turning into opposite direction
- (73) From driveway, intended path not known
- (74) From entrance to limited access highway
- (78) Encroachment by other vehicle—details unknown

Pedestrian or Pedalcyclist, or Other Nonmotorist

- (80) Pedestrian in roadway
- (81) Pedestrian approaching roadway
- (82) Pedestrian—unknown location
- (83) Pedalcyclist or other nonmotorist in roadway (specify): _____
- (84) Pedalcyclist or other nonmotorist approaching roadway (specify): _____
- (85) Pedalcyclist or other nonmotorist—unknown location (specify): _____

Object or Animal

- (87) Animal in roadway
- (88) Animal approaching roadway
- (89) Animal—unknown location
- (90) Object in roadway
- (91) Object approaching roadway
- (92) Object—unknown location

(98) Other critical precrash event (specify): _____

(99) Unknown

For Corrective Actions Attempted see variable GV14 (Attempted Avoidance Manuever)

66. Precrash Stability After Avoidance Maneuver 1

- (0) No avoidance maneuver
- (1) Tracking
- (2) Skidding longitudinally—rotation less than 30 degrees
- (3) Skidding laterally—clockwise rotation
- (4) Skidding laterally—counterclockwise rotation
- (7) Other vehicle loss-of-control (specify): _____
- (8) No driver present
- (9) Precrash stability unknown

67. Precrash Directional Consequences of Avoidance Maneuver (Corrective Action) 1

- (0) No avoidance maneuver
- (1) Vehicle stayed in travel lane where avoidance maneuver was initiated
- (2) Vehicle stayed on roadway but left travel lane where avoidance maneuver was initiated
- (3) Vehicle stayed on roadway, not known if left travel lane where avoidance maneuver was initiated
- (4) Vehicle departed roadway
- (5) Avoidance maneuver initiated off roadway
- (8) No driver present
- (9) Directional consequences unknown

*** IF THE CDS APPLICABLE VEHICLE WAS NOT INSPECTED (I.E., GV35 = 0), ***
DO NOT COMPLETE THE EXTERIOR AND INTERIOR VEHICLE FORMS.

*** IF GV07 DOES NOT EQUAL 01-49, DO NOT COMPLETE ***
THE EXTERIOR VEHICLE, INTERIOR VEHICLE,
OCCUPANT ASSESSMENT, AND OCCUPANT INJURY FORMS.

ORIGINAL SPECIFICATIONS WORK SHEET


Wheelbase	<u>1</u> <u>1</u> <u>4</u> . <u>0</u> inches	x 2.54 =	<u>2</u> <u>9</u> <u>0</u> cm
Overall Length	<u>2</u> <u>0</u> <u>5</u> . <u>5</u> inches	x 2.54 =	<u>5</u> <u>2</u> <u>2</u> cm
Maximum Width	<u>0</u> <u>7</u> <u>1</u> . <u>7</u> inches	x 2.54 =	<u>1</u> <u>8</u> <u>2</u> cm
Curb Weight	<u>0</u> <u>3</u> . <u>5</u> <u>4</u> <u>6</u> pounds	x .4536 =	<u>1</u> . <u>6</u> <u>0</u> <u>8</u> kg
Average Track	<u>0</u> <u>6</u> <u>0</u> . <u>1</u> inches	x 2.54 =	<u>1</u> <u>5</u> <u>3</u> cm
Front Overhang	<u>0</u> <u>4</u> <u>4</u> . <u>0</u> inches	x 2.54 =	<u>1</u> <u>1</u> <u>2</u> cm
Rear Overhang	<u>0</u> <u>4</u> <u>7</u> . <u>5</u> inches	x 2.54 =	<u>1</u> <u>2</u> <u>1</u> cm
Undeformed End Width	<u>0</u> <u>6</u> <u>3</u> . <u>0</u> inches	x 2.54 =	<u>1</u> <u>6</u> <u>0</u> cm
Engine Size: cyl./displ.	<u>4</u> <u>5</u> <u>0</u> <u>0</u> cc	x .001 =	<u>4</u> . <u>5</u> L
	<u>2</u> <u>7</u> <u>4</u> CID	x .0164 =	<u>4</u> . <u>5</u> L

VEHICLE DAMAGE SKETCH

TIRE—WHEEL DAMAGE a. Rotation physically restricted b. Tire deflated RF <u>2</u> RF <u>2</u> LF <u>1</u> LF <u>1</u> RR <u>2</u> RR <u>2</u> LR <u>2</u> LR <u>2</u> (1) Yes (2) No (8) NA (9) Unk.		ORIGINAL SPECIFICATIONS Wheelbase <u>290</u> cm Overall Length <u>522</u> cm Maximum Width <u>182</u> cm Curb Weight <u>1,600</u> kg Average Track <u>153</u> cm Front Overhang <u>112</u> cm Rear Overhang <u>121</u> cm Undeformed End Width <u>160</u> cm Engine Size: cyl./displ. <u>V8/4.5</u> L		WHEEL STEER ANGLES (For locked front wheels or displaced rear axles only) RF \pm <u>—</u> ° LF \pm <u>0</u> ° RR \pm <u>—</u> ° LR \pm <u>—</u> ° Within \pm 5 degrees
TYPE OF TRANSMISSION <input type="checkbox"/> Manual <input checked="" type="checkbox"/> Automatic		DRIVE WHEELS <input checked="" type="checkbox"/> FWD <input type="checkbox"/> RWD <input type="checkbox"/> 4WD		
		Approximate Cargo Weight <u>0</u> kg		

GAUGE STANDS ADL

MEASUREMENTS IN CENTIMETERS



NOTES: Sketch new perimeter and cross hatch direct damage and single hatch induced damage on all views. Annotate observations which might be useful in reconstructing the accident (e.g., grass in tire bead, direction of striations, scuff on sidewalls, etc.). If pulling trailer, sketch type of trailer and damage received on the back of this page.

Annotate any damage caused by extrication such as component removal by torching, prying, or hydraulic shears.

CODES FOR OBJECT CONTACTED

(99) Unknown event or object

[illegible]

COLLISION DEFORMATION CLASSIFICATION

HIGHEST DELTA "V"

Accident Event Sequence Number	Object Contacted	(1) (2) Direction of Force	(3) Deformation Location	(4) Longitudinal or Lateral Location	(5) Vertical or Lateral Location	(6) Type of Damage Distribution	(7) Deformation Extent
4. <u>φ 1</u>	5. <u>φ 2</u>	6. <u>9 2</u>	7. <u>F</u>	8. <u>Y</u>	9. <u>E</u>	10. <u>W</u>	11. <u>φ 4</u>

Second Highest Delta "V"

12. _____	13. _____	14. _____	15. _____	16. _____	17. _____	18. _____	19. _____
-----------	-----------	-----------	-----------	-----------	-----------	-----------	-----------

CRUSH PROFILE IN CENTIMETERS

The crush profile for the damage described in the CDC(s) above should be documented in the appropriate space below. (ALL MEASUREMENTS ARE IN CENTIMETERS.)

HIGHEST DELTA "V"

20. <u>L</u>	21. <u>C₁</u>	<u>C₂</u>	<u>C₃</u>	<u>C₄</u>	<u>C₅</u>	<u>C₆</u>	22. <u>± D</u>
<u>1 6 φ</u> (63.0")	<u>1 φ 5</u> (41")	<u>φ 8 2</u> (32")	<u>φ 5 6</u> (22")	<u>φ 3 9</u> (15")	<u>φ 1 5</u> (46")	<u>φ φ φ</u> (φ)	<u>+ φ 4 3</u> (-17")

Second Highest Delta "V"

23. <u>L</u>	24. <u>C₁</u>	<u>C₂</u>	<u>C₃</u>	<u>C₄</u>	<u>C₅</u>	<u>C₆</u>	25. <u>± D</u>
_____	_____	_____	_____	_____	_____	_____	<u>+</u> <u>-</u>

26. Are CDCs Documented but Not Coded on The Automated File?
(0) No
(1) Yes

φ

27. Researcher's Assessment of Vehicle Disposition
(0) Not towed due to vehicle damage
(1) Towed due to vehicle damage
(9) Unknown

1

28. Original Wheelbase 2 9 φ
Code to the nearest centimeter
(999) Unknown

1 1 4 . φ inches X 2.54 = 2 9 φ centimeters

<p>29. Is This A Multi-Stage Manufactured Vehicle And/Or A Certified Altered Vehicle? <u>φ</u></p> <p>(0) No post manufacturer modifications (1) Yes - post manufacturer modifications (specify): _____</p> <p>_____ (Include photograph of CERTIFICATION PLACARD in case report)</p> <p>(9) Unknown if vehicle is modified</p>	<p>34. Fuel Tank-1 Location <u>1</u></p>
<p>30. Fire Occurrence <u>φ</u></p> <p>(0) No fire</p> <p>Yes, fire occurred</p> <p>(1) Minor (2) Major (9) Unknown</p>	<p>35. Fuel Tank-2 Location <u>φ</u></p> <p>(0) No fuel tank (1) Aft of center of the rear wheels (rear axle) centered (2) Aft of center of the rear wheels (rear axle) left side (3) Aft of center of the rear wheels (rear axle) right side (4) Forward of center of the rear wheels (rear axle) centered (5) Forward of center of the rear wheels (rear axle) left side (6) Forward of center of the rear wheels (rear axle) right side (7) Over center of the rear wheels (rear axle) (8) Other (specify): _____ (9) Unknown</p>
<p>31. Origin of Fire <u>φ</u></p> <p>(0) No fire (1) Vehicle exterior (front, side, back, top) (2) Exhaust system (3) Fuel tank (and other fuel retention system parts) (4) Engine compartment (5) Cargo/trunk compartment (6) Instrument panel (7) Passenger compartment area (8) Other location (specify): _____ (9) Unknown</p>	<p>36. Fuel Tank-1 Filler Cap Location <u>2</u></p>
<p>32. Type of Fuel Tank-1 <u>1</u></p>	<p>37. Fuel Tank-2 Filler Cap Location <u>φ</u></p> <p>(0) No fuel tank (1) On back plane (2) Aft of center of the rear wheels (rear axle) on left side plane (3) Aft of center of the rear wheels (rear axle) on right side plane (4) Forward of center of the rear wheels (rear axle) on left side plane (5) Forward of center of the rear wheels (rear axle) on right side plane (6) Over the center of the rear wheels (rear axle) on left side plane (7) Over the center of the rear wheels (rear axle) on right side plane (8) Other (specify): _____ (9) Unknown</p>
<p>33. Type of Fuel Tank-2 <u>φ</u></p> <p>(0) No fuel tank (electrical vehicle) (1) Metallic (2) Non-metallic (9) Unknown</p>	<p>38. Fuel Tank-1 Damage <u>1</u></p>
	<p>39. Fuel Tank-2 Damage <u>φ</u></p> <p>(0) No fuel tank (1) No damage to fuel tank (2) Deformed, no seam failure (3) Deformed, with a seam failure (4) Punctured (5) Lacerated (ripped) (6) Abraded (scraped) (7) Filler neck separation from the fuel tank (8) Other damage (specify): _____ (9) Unknown</p>

[illegible]



INTERIOR VEHICLE FORM

1. Primary Sampling Unit Number _____

2. Case Number - Stratum DSI-94-AB-4063. Vehicle Number 01

INTEGRITY

4. Passenger Compartment Integrity 9 9
(00) No integrity loss

Yes, Integrity Was Lost Through

- (01) Windshield
(02) Door (side)
(03) Door/hatch (back door)
(04) Roof
(05) Roof glass
(06) Side window
(07) Rear window (backlight)
(08) Roof and roof glass
(09) Windshield and door (side)
(10) Windshield and roof
(11) Side and rear window (side window and backlight)
(12) Windshield and side window
(13) Door and side window
(98) Other combination of above (specify):

(99) Unknown

Door, Tailgate or Hatch Opening

5. LF 9 6. RF 1 7. LR 1 8. RR 1 9. TG/H 0

- (0) No door/gate/hatch
(1) Door/gate/hatch remained closed and operational
(2) Door/gate/hatch came open during collision
(3) Door/gate/hatch jammed shut
(8) Other (specify):

(9) Unknown

Damage/Failure Associated with Door, Tailgate or Hatch
Opening in Collision. If IV05-IV09 \neq 2, Then code 010. LF 9 11. RF 0 12. LR 0 13. RR 0 14. TG/H 0

- (0) No door/gate/hatch or door not opened

Door, Tailgate or Hatch Came Open During Collision

- (1) Door operational (no damage)
(2) Latch/striker failure due to damage
(3) Hinge failure due to damage
(4) Door structure failure due to damage
(5) Door support (i.e., pillar, sill, roof side rail,
etc.) failure due to damage
(6) Latch/striker and hinge failure due to damage
(8) Other failure (specify):

(9) Unknown

GLAZING

Glazing Damage from Impact Forces

15. WS 9 16. LF 9 17. RF 0 18. LR 9 19. RR 0
20. BL 0 21. Roof 0 22. Other 0

- (0) No glazing damage from impact forces
(2) Glazing in place and cracked from impact forces
(3) Glazing in place and holed from impact forces
(4) Glazing out-of-place (cracked or not) and not holed from
impact forces
(5) Glazing out-of-place and holed from impact forces
(6) Glazing disintegrated from impact forces
(7) Glazing removed prior to accident
(8) No glazing
(9) Unknown if damaged

Glazing Damage from Occupant Contact

23. WS 9 24. LF 9 25. RF 0 26. LR 0 27. RR 0
28. BL 0 29. Roof 0 30. Other 0

- (0) No occupant contact to glazing or no glazing
(1) Glazing contacted by occupant but no glazing damage
(2) Glazing in place and cracked by occupant contact
(3) Glazing in place and holed by occupant contact
(4) Glazing out-of-place (cracked or not) by occupant
contact and not holed by occupant contact
(5) Glazing out-of-place by occupant contact and holed by
occupant contact
(6) Glazing disintegrated by occupant contact
(9) Unknown if contacted by occupant

If No Glazing Damage **And** No Occupant Contact or No
Glazing, Then Code IV31 Through IV46 As 0

Type of Window/Windshield Glazing

31. WS 1 32. LF 2 33. RF 0 34. LR 2 35. RR 0
36. BL 0 37. Roof 0 38. Other 0

- (0) No glazing contact and no damage, or no glazing
(1) AS-1 — Laminated
(2) AS-2 — Tempered
(3) AS-3 — Tempered-tinted
(4) AS-14 — Glass/Plastic
(8) Other (specify):

(9) Unknown


Window Precrash Glazing Status

39. WS 1 40. LF 2 41. RF 0 42. LR 2 43. RR 0
44. BL 0 45. Roof 0 46. Other 0

- (0) No glazing contact and no damage, or no glazing
(1) Fixed
(2) Closed
(3) Partially opened
(4) Fully opened
(9) Unknown

INTRUSION WORKSHEET

Note: Sketch intruded areas



LOCATION OF INTRUSION	INTRUDED COMPONENT	(All Measurements Are In Centimeters)			DOMINANT CRUSH DIRECTION
		COMPARISON VALUE	INTRUDED VALUE	INTRUSION	
11	TOE PAN	50.0cm (19.7")	25.0cm (9.8")	25.0cm (9.8")	LONG.
11	L. INST. PANEL	78.0cm (30.7")	56.0cm (22.0")	22.0cm (8.7")	LONG.
11	L. "A" PILLAR	88.0cm (34.6")	67.0cm (26.4")	21.0cm (8.3")	LONG.
		-		=	
		-		=	
		-		=	
		-		=	
		-		=	
		-		=	
		-		=	
		-		=	
		-		=	
		-		=	
		-		=	
		-		=	
		-		=	

OCCUPANT AREA INTRUSION

Note: If no intrusions, leave variables IV47-IV86 blank.

INTRUDING COMPONENT

	Location of Intrusion	Intruding Component	Magnitude of Intrusion	Dominant Crush Direction
1st	47. <u>1</u> <u>1</u>	48. <u>0</u> <u>5</u>	49. <u>3</u>	50. <u>2</u>
2nd	51. <u>1</u> <u>1</u>	52. <u>0</u> <u>2</u>	53. <u>3</u>	54. <u>2</u>
3rd	55. <u>1</u> <u>1</u>	56. <u>0</u> <u>6</u>	57. <u>3</u>	58. <u>2</u>
4th	59. _____	60. _____	61. _____	62. _____
5th	63. _____	64. _____	65. _____	66. _____
6th	67. _____	68. _____	69. _____	70. _____
7th	71. _____	72. _____	73. _____	74. _____
8th	75. _____	76. _____	77. _____	78. _____
9th	79. _____	80. _____	81. _____	82. _____
10th	83. _____	84. _____	85. _____	86. _____

Interior Components

- (01) Steering assembly
- (02) Instrument panel left
- (03) Instrument panel center
- (04) Instrument panel right
- (05) Toe pan
- (06) A (A1/A2)-pillar
- (07) B-pillar
- (08) C-pillar
- (09) D-pillar
- (10) Door panel (side)
- (12) Roof (or convertible top)
- (13) Roof side rail
- (14) Windshield
- (15) Windshield header
- (16) Window frame
- (17) Floor pan (includes sill)
- (18) Backlight header
- (19) Front seat back
- (20) Second seat back
- (21) Third seat back
- (22) Fourth seat back
- (23) Fifth seat back
- (24) Seat cushion
- (25) Back door/panel (e.g., tailgate)
- (26) Other interior component (specify): _____

- (27) Side panel - forward of the A (A2)-pillar
- (28) Side panel - rear of the A (A2)-pillar

Exterior Components

- (30) Hood
- (31) Outside surface of this vehicle (specify): _____
- (32) Other exterior object in the environment (specify): _____
- (33) Unknown exterior object
- (97) Catastrophic
- (98) Intrusion of unlisted component(s) (specify): _____
- (99) Unknown

LOCATION OF INTRUSION

Front Seat
 (11) Left
 (12) Middle
 (13) Right

Fourth Seat
 (41) Left
 (42) Middle
 (43) Right

Second Seat
 (21) Left
 (22) Middle
 (23) Right

(97) Catastrophic
 (98) Other enclosed area (specify) _____

(99) Unknown

Third Seat
 (31) Left
 (32) Middle
 (33) Right

MAGNITUDE OF INTRUSION

- (1) ≥ 3 centimeters but < 8 centimeters
- (2) ≥ 8 centimeters but < 15 centimeters
- (3) ≥ 15 centimeters but < 30 centimeters
- (4) ≥ 30 centimeters but < 46 centimeters
- (5) ≥ 46 centimeters but < 61 centimeters
- (6) ≥ 61 centimeters
- (7) Catastrophic
- (9) Unknown

DOMINANT CRUSH DIRECTION

- (1) Vertical
- (2) Longitudinal
- (3) Lateral
- (7) Catastrophic
- (9) Unknown

STEERING RIM/SPOKE DEFORMATION

(All Measurements Are in Centimeters)

COMPARISON VALUE	—	DAMAGE VALUE	=	DEFORMATION
12. ϕ cm (4.7")	—	8. ϕ cm (3.1")	=	4. ϕ cm (1.6")
	—		=	
	—		=	
	—		=	



STEERING COLUMN87. Steering Column Type 2

- (1) Fixed column
 (2) Tilt column
 (3) Telescoping column
 (4) Tilt and telescoping column
 (8) Other column type (specify): _____

(9) Unknown _____

88. Blank X X

(This variable is left blank so that numbering consistency can be maintained with the 1988-94 CDS.

89. Blank X X X

(This variable is left blank so that numbering consistency can be maintained with the 1988-94 CDS.

90. Blank X X X

(This variable is left blank so that numbering consistency can be maintained with the 1988-94 CDS.

91. Blank X X X

(This variable is left blank so that numbering consistency can be maintained with the 1988-94 CDS.

92. Steering Rim/Spoke Deformation 0 4

Code actual measured

- deformation to the nearest centimeter
 (00) No steering rim deformation
 (01-14) Actual measured value in centimeters
 (15) 15 centimeters or more
 (98) Observed deformation cannot be measured
 (99) Unknown


93. Location of Steering Rim/Spoke Deformation 0 6*Quarter Sections*

- (01) Section A
 (02) Section B
 (03) Section C
 (04) Section D

Half Sections

- (05) Upper half of rim/spoke
 (06) Lower half of rim/spoke
 (07) Left half of rim/spoke
 (08) Right half of rim/spoke

- (09) Complete steering wheel collapse
 (10) Undetermined location
 (99) Unknown

**INSTRUMENT PANEL**94. Odometer Reading 0 6 8,000

_____ kilometers—Code to the nearest 1,000 kilometers

- (000) No odometer
 (001) Less than 1,500 kilometers
 (500) 499,500 kilometers or more
 (999) Unknown

0 4 2. 2 4 4 miles X 1.6093 = 0 6 7. 9 8 3 kilometers

Source: INSPECTION

95. Instrument Panel Damage from Occupant Contact? 1

- (0) No
 (1) Yes
 (9) Unknown

96. Knee Bolsters Deformed from Occupant Contact? 8


- (0) No
 (1) Yes
 (8) Not present
 (9) Unknown

97. Did Glove Compartment Door Open During Collision(s)? 0

- (0) No
 (1) Yes
 (8) Not present
 (9) Unknown

VEHICLE INTERIOR SKETCHES

Note area of ejection/entrapment



Sketch windshield contact(s) and the damaged area(s) on the instrument panel outline (e.g., radio, glove compartment, damage to instrument panel structure).

Cross hatch contact points, draw spider webs or use other annotation as may be appropriate.

Annotate the contacted area with a letter (begin with A) and list on the Points of Occupant Contact page.

POINTS OF OCCUPANT CONTACT

Contact	Interior Component Contacted	Occupant No. If Known	Body Region If Known	Supporting Physical Evidence	Confidence Level of Contact Point
A	45	01	FACE, UPPER TORSO	AIR BAG DEPLOYED	1
B	09	01	L. KNEE	DEFORMATION	1
C	04	01	ABDOMEN	DEFORMATION / ABRASED	1
D	09	01	R. KNEE	DEFORMATION / ABRASED	1
E	56	01	R. FOOT	DEFORMATION	1
F	11	02	UPPER TORSO	DEFORMATION / ABRASED	1
G	11	02	ABDOMEN	DEFORMATION	1
H					
I					
J					
K					
L					
M					
N					

CODES FOR INTERIOR COMPONENTS

FRONT

- (01) Windshield
- (02) Mirror
- (03) Sunvisor
- (04) Steering wheel rim
- (05) Steering wheel hub/spoke
- (06) Steering wheel (combination of codes 04 and 05)
- (07) Steering column, transmission selector lever, other attachment
- (08) Add on equipment (e.g., CB, tape deck, air conditioner)
- (09) Left instrument panel and below
- (10) Center instrument panel and below
- (11) Right instrument panel and below
- (12) Glove compartment door
- (13) Knee bolster
- (14) Windshield including one or more of the following: front header, A (A1/A2)-pillar, instrument panel, mirror, or steering assembly (driver side only)
- (15) Windshield including one or more of the following: front header, A (A1/A2)-pillar, instrument panel, or mirror (passenger side only)
- (16) Driver side air bag compartment cover
- (17) Passenger side air bag compartment cover
- (18) Windshield reinforced by exterior object (specify): _____
- (19) Other front object (specify): _____

LEFT SIDE

- (20) Left side interior surface, excluding hardware or armrests
- (21) Left side hardware or armrest
- (22) Left A (A1/A2)-pillar

- (23) Left B-pillar
- (24) Other left pillar (specify): _____
- (25) Left side window glass or frame
- (26) Left side window glass including one or more of the following: frame, window sill, A (A1/A2)-pillar, B-pillar, or roof side rail.
- (27) Other left side object (specify): _____
- (28) Left side window sill

RIGHT SIDE

- (30) Right side interior surface, excluding hardware or armrests
- (31) Right side hardware or armrest
- (32) Right A (A1/A2)-pillar
- (33) Right B-pillar
- (34) Other right pillar (specify): _____
- (35) Right side window glass or frame
- (36) Right side window glass including one or more of the following: frame, window sill, A (A1/A2)-pillar, B pillar, or roof side rail.
- (37) Other right side object (specify): _____
- (38) Right side window sill

INTERIOR

- (40) Seat, back support
- (41) Belt restraint webbing/buckle
- (42) Belt restraint B-pillar attachment point
- (43) Other restraint system component (specify): _____
- (44) Head restraint system
- (45) Air bag (use codes "16" and "17" for injuries sustained from air bag compartment covers)

- (46) Other occupants (specify): _____

- (47) Interior loose objects
- (48) Child safety seat (specify): _____
- (49) Other interior object (specify): _____

ROOF

- (50) Front header
- (51) Rear header
- (52) Roof left side rail
- (53) Roof right side rail
- (54) Roof or convertible top

FLOOR

- (56) Floor (including toe pan)
- (57) Floor or console mounted transmission lever, including console
- (58) Parking brake handle
- (59) Foot controls including parking brake

REAR

- (60) Backlight (rear window)
- (61) Backlight storage rack, door, etc.
- (62) Other rear object (specify): _____

CONFIDENCE LEVEL OF CONTACT POINT

- (1) Certain
- (2) Probable
- (3) Possible
- (9) Unknown

AUTOMATIC RESTRAINTS

NOTES: Encode the data for each applicable front seat position. The attribute for the variables may be found below. Restraint systems should be assessed during the vehicle inspection then coded on the Occupant Assessment Form.

AIR BAGS

		Left	Right
F I R S T	Availability/Function	/	φ
	Deployment	/	φ
	Failure	/	φ

Air Bag System Availability/Function

- (0) Not equipped/not available
(1) Air bag

Non-functional

- (2) Air bag disconnected (specify): _____
(3) Air bag not reinstalled
(9) Unknown

Air Bag System Deployment

- (0) Not equipped/not available
(1) Air bag deployed during accident (as a result of impact)
(2) Air bag deployed inadvertently just prior to accident
(3) Air bag deployed, accident sequence undetermined
(4) Nondeployed
(5) Unknown if deployed
(6) Air bag deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)
(9) Unknown

Are There Indications of Air Bag System Failure?

- (0) Not equipped/not available
(1) No
(2) Yes (specify): _____
(9) Unknown

AUTOMATIC BELTS

		Left	Right
F I R S T	Availability/Function	φ	φ
	Use	φ	φ
	Type	φ	φ
	Proper Use	φ	φ
	Failure Modes	φ	φ

Automatic (Passive) Belt System Availability/Function

- (0) Not equipped/not available
(1) 2 point automatic belts
(2) 3 point automatic belts
(3) Automatic belts - type unknown

Non-functional

- (4) Automatic belts destroyed or rendered inoperative
(9) Unknown

Automatic (Passive) Belt System Use

- (0) Not equipped/not available/destroyed or rendered inoperative
(1) Automatic belt in use
(2) Automatic belt not in use (manually disconnected, motorized track inoperative)
(3) Automatic belt use unknown
(9) Unknown

Automatic (Passive) Belt System Type

- (0) Not equipped/not available
(1) Non-motorized system
(2) Motorized system
(9) Unknown

Proper Use of Automatic (Passive) Belt System

- (0) Not equipped/not available/not used
(1) Automatic belt used properly
(2) Automatic belt used properly with child safety seat

Automatic Belt Used Improperly

- (3) Automatic shoulder belt worn under arm
(4) Automatic shoulder belt worn behind back
(5) Automatic belt worn around more than one person
(6) Lap portion of automatic belt worn on abdomen
(7) Automatic lap and shoulder belt or automatic shoulder belt used improperly with child safety seat (specify): _____
(8) Other improper use of automatic belt system (specify): _____
(9) Unknown

Automatic (Passive) Belt Failure Modes During Accident

- (0) Not equipped/not available/not in use
(1) No automatic belt failure(s)
(2) Torn webbing (stretched webbing not included)
(3) Broken buckle or latchplate
(4) Upper anchorage separated
(5) Other anchorage separated (specify): _____
(6) Broken retractor
(7) Combination of above (specify): _____
(8) Other automatic belt failure (specify): _____
(9) Unknown

MANUAL RESTRAINTS

NOTES: Encode the applicable data for each seat position in the vehicle. The attribute for the variable may be found below. Restraint systems should be assessed during the vehicle inspection then coded on the Occupant Assessment Form.

If a Child safety seat is present, encode the data on the back of this page.

If the vehicle has automatic restraints available, encode the appropriate data on the back of the previous page.

		Left	Center	Right
FIRST	Availability	4	3	4
	Evidence of usage	NONE	—	NONE
	Used in this crash?	φ φ	φ φ	φ φ
	Proper Use	φ	φ	φ
	Failure Modes	φ	φ	φ
SECOND	Availability	4	3	4
	Evidence of usage	—	—	—
	Used in this crash?	φ φ	φ φ	φ φ
	Proper Use	φ	φ	φ
	Failure Modes	φ	φ	φ
OTHER	Availability			
	Evidence of usage			
	Used in this crash?			
	Proper Use			
	Failure Modes			

Manual (Active) Belt System Availability

- (0) None available
- (1) Belt removed/destroyed
- (2) Shoulder belt
- (3) Lap belt
- (4) Lap and shoulder belt
- (5) Belt available - type unknown

Integral Belt Partially Destroyed

- (6) Shoulder belt (lap belt destroyed/removed)
- (7) Lap belt (shoulder belt destroyed/removed)

(8) Other belt (specify):

(9) Unknown

Manual (Active) Belt System Use

- (00) None used, not available, or belt removed/destroyed
- (01) Inoperable (specify):
- (02) Shoulder belt
- (03) Lap belt
- (04) Lap and shoulder belt
- (05) Belt used - type unknown
- (08) Other belt used (specify):
- (12) Shoulder belt used with child safety seat
- (13) Lap belt used with child safety seat
- (14) Lap and shoulder belt used with child safety seat
- (15) Belt used with child safety seat - type unknown
- (18) Other belt used with child safety seat (specify):
- (99) Unknown if belt used

Proper Use of Manual (Active) Belts

- (0) None used or not available
- (1) Belt used properly
- (2) Belt used properly with child safety seat

Belt Used Improperly

- (3) Shoulder belt worn under arm
- (4) Shoulder belt worn behind back or seat
- (5) Belt worn around more than one person
- (6) Lap belt worn on abdomen
- (7) Lap belt or lap and shoulder belt used improperly with child safety seat (specify):

(8) Other improper use of manual belt system (specify):

(9) Unknown

Manual (Active) Belt Failure Modes During Accident

- (0) No manual belt used or not available
- (1) No manual belt failure(s)
- (2) Torn webbing (stretched webbing not included)
- (3) Broken buckle or latchplate
- (4) Upper anchorage separated
- (5) Other anchorage separated (specify):
- (6) Broken retractor
- (7) Combination of above (specify):
- (8) Other manual belt failure (specify):
- (9) Unknown

CHILD SAFETY SEAT FIELD ASSESSMENT

When a child safety seat is present enter the occupant's number in the first row and complete the column below the occupant's number using the codes listed below. Complete a column for each child safety seat present.

Occupant Number						
1. Type of Child Safety Seat						
2. Child Safety Seat Orientation						
3. Child Safety Seat Harness Usage			0			
4. Child Safety Seat Shield Usage						
5. Child Safety Seat Tether Usage						
6. Child Safety Seat Make/Model		Specify Below for Each Child Safety Seat				

1. Type of Child Safety Seat

- (0) No child safety seat
- (1) Infant seat
- (2) Toddler seat
- (3) Convertible seat
- (4) Booster seat
- (7) Other type child safety seat (specify):

- (8) Unknown child safety seat type
- (9) Unknown if child safety seat used

2. Child Safety Seat Orientation

- (00) No child safety seat
- Designed for Rear Facing for This Age/Weight
- (01) Rear facing
- (02) Forward facing
- (08) Other orientation (specify):
- (09) Unknown orientation

Designed for Forward Facing for This Age/Weight

- (11) Rear facing
- (12) Forward facing
- (18) Other orientation (specify):
- (19) Unknown orientation

Unknown Design or Orientation For This Age/Weight, or Unknown Age/Weight

- (21) Rear facing
- (22) Forward facing
- (28) Other orientation (specify):
- (29) Unknown orientation

- (99) Unknown if child safety seat used

3. Child Safety Seat Harness Usage

4. Child Safety Seat Shield Usage

5. Child Safety Seat Tether Usage

Note: Options Below Are Used for Variables 3-5.

- (00) No child safety seat

Not Designed with Harness/Shield/Tether

- (01) After market harness/shield/tether added, not used
- (02) After market harness/shield/tether used
- (03) Child safety seat used, but no after market harness/shield/tether added
- (09) Unknown if harness/shield/tether added or used

Designed With Harness/Shield/Tether

- (11) Harness/shield/tether not used
- (12) Harness/shield/tether used
- (19) Unknown if harness/shield/tether used

Unknown If Designed With Harness/Shield/Tether

- (21) Harness/shield/tether not used
- (22) Harness/shield/tether used
- (29) Unknown if harness/shield/tether used

- (99) Unknown if child safety seat used

6. Child Safety Seat Make/Model

(Specify make/model and occupant number)

HEAD RESTRAINTS/SEAT EVALUATION

NOTES: Encode the applicable data for each seat position in the vehicle. The attribute for these variables may be found at the bottom of the page. Head restraint type/damage and seat type/performance should be assessed during the vehicle inspection then coded on the Occupant Assessment Form.

		Left	Center	Right
FIRST	Head Restraint Type/Damage	3	4	3
	Seat Type	46	46	46
	Seat Performance	1	1	1
	Seat Orientation	1	1	1
SECOND	Head Restraint Type/Damage	1	4	1
	Seat Type	43	43	43
	Seat Performance	1	1	1
	Seat Orientation	1	1	1
THIRD	Head Restraint Type/Damage			
	Seat Type			
	Seat Performance			
	Seat Orientation			
OTHER	Head Restraint Type/Damage			
	Seat Type			
	Seat Performance			
	Seat Orientation			

Head Restraint Type/Damage by Occupant at This Occupant Position

- (0) No head restraints
- (1) Integral — no damage
- (2) Integral — damaged during accident
- (3) Adjustable — no damage
- (4) Adjustable — damaged during accident
- (5) Add-on — no damage
- (6) Add-on — damaged during accident
- (8) Other Specify: _____

(9) Unknown _____

Seat Type (this Occupant Position)

- (00) Occupant not seated or no seat
- (01) Bucket
- (02) Bucket with folding back
- (03) Bench
- (04) Bench with separate back cushions
- (05) Bench with folding back(s)
- (06) Split bench with separate back cushions
- (07) Split bench with folding back(s)
- (08) Pedestal (i.e., column supported)
- (09) Other seat type (specify): _____

(10) Box mounted seat (i.e., van type) _____

(99) Unknown _____

Seat Performance (this Occupant Position)

- (0) Occupant not seated or no seat
- (1) No seat performance failure(s)
- (2) Seat adjusters failed
- (3) Seat back folding locks or "seat back" failed specify: _____
- (4) Seat tracks/anchors failed
- (5) Deformed by impact of occupant
- (6) Deformed by passenger compartment intrusion (specify): _____

(7) Combination of above (specify): _____

(8) Other (specify): _____

(9) Unknown _____

Seat Orientation (this Occupant Position)

- (0) Occupant not seated or no seat
- (1) Forward facing seat
- (2) Rear facing seat
- (3) Side facing seat (inward)
- (4) Side facing seat (outward)
- (8) Other (specify): _____

(9) Unknown _____

DESCRIBE ANY INDICATION OF ABNORMAL OCCUPANT POSTURE (I.E., UNUSUAL OCCUPANT CONTACT PATTERN)

EJECTION/ENTRAPMENT DATA

Complete the following if the researcher has any indication that an occupant was either ejected from or entrapped in the vehicle. Code the appropriate data on the Occupant Assessment Form.

EJECTION No [☒] Yes []

Describe indications of ejection and body parts involved in partial ejection(s):

Occupant Number						
Ejection						
(Note on Vehicle Interior Sketch) Ejection Area						
Ejection Medium						
Medium Status						

Ejection

- (1) Complete ejection
- (2) Partial ejection
- (3) Ejection, Unknown degree
- (9) Unknown

Ejection Area

- (1) Windshield
- (2) Left front
- (3) Right front
- (4) Left rear
- (5) Right rear
- (6) Rear

(7) Roof

- (8) Other area (e.g., back of pickup, etc.) (specify):

(9) Unknown**Ejection Medium**

- (1) Door/hatch/tailgate
- (2) Nonfixed roof structure
- (3) Fixed glazing
- (4) Nonfixed glazing (specify):

(5) Integral structure

- (8) Other medium (specify):

(9) Unknown**Medium Status (Immediately Prior to Impact)**

- (1) Open
- (2) Closed
- (3) Integral structure
- (9) Unknown

ENTRAPMENT No [☒] Yes []

Describe entrapment mechanism: _____

Component(s): _____

(Note in vehicle interior diagram)

National Highway Traffic Safety
Administration

OCCUPANT ASSESSMENT FORM

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

OCCUPANT'S SEATING

1. Primary Sampling Unit Number _____
2. Case Number - Stratum DSI-94-AB-006
3. Vehicle Number 0 1
4. Occupant Number 0 1

OCCUPANT'S CHARACTERISTICS

5. Occupant's Age 7 7
Code actual age at time of accident.
(00) Less than one year old (specify by month): _____
(97) 97 years and older _____
(99) Unknown
6. Occupant's Sex 2
(1) Male
(2) Female
(9) Unknown
7. Occupant's Height 1 6 0
Code actual height to the nearest
centimeter.
(999) Unknown
6 3 inches X 2.54 = 1 6 0 centimeters
8. Occupant's Weight 0 6 8
Code actual weight to the nearest
kilogram.
(999) Unknown
1 5 0 pounds X .4536 = 0 6 8 kilograms
9. Occupant's Role 1
(1) Driver
(2) Passenger
(9) Unknown

10. Occupant's Seat Position 1 1
Front Seat
(11) Left side
(12) Middle
(13) Right side
(14) Other (specify): _____
(15) On or in the lap of another occupant
- Second Seat*
(21) Left side
(22) Middle
(23) Right side
(24) Other (specify): _____
(25) On or in the lap of another occupant
- Third Seat*
(31) Left side
(32) Middle
(33) Right side
(34) Other (specify): _____
(35) On or in the lap of another occupant
- Fourth Seat*
(41) Left side
(42) Middle
(43) Right side
(44) Other (specify): _____
(45) On or in the lap of another occupant
- (97) In or on unenclosed area
(98) Other seat (specify): _____
(99) Unknown
11. Occupant's Posture 0
(0) Normal posture
- Abnormal posture*
(1) Kneeling or standing on seat
(2) Lying on or across seat
(3) Kneeling, standing or sitting in front of seat
(4) Sitting sideways or turned to talk with another occupant or to look out a rear window
(5) Sitting on a console
(6) Lying back in a reclined seat position
(7) Bracing with feet or hands on a surface in front of seat
(8) Other abnormal posture (specify): _____
(9) Unknown

EJECTION/ENTRAPMENT

12. Ejection ϕ

- (0) No ejection
- (1) Complete ejection
- (2) Partial ejection
- (3) Ejection, unknown degree
- (9) Unknown

13. Ejection Area ϕ

- (0) No ejection
- (1) Windshield
- (2) Left front
- (3) Right front
- (4) Left rear
- (5) Right rear
- (6) Rear
- (7) Roof
- (8) Other area (e.g., back of pickup, etc.)
(specify): _____
- (9) Unknown

14. Ejection Medium ϕ

- (0) No ejection
- (1) Door/hatch/tailgate
- (2) Nonfixed roof structure
- (3) Fixed glazing
- (4) Nonfixed glazing (specify): _____
- (5) Integral structure
- (8) Other medium (specify): _____
- (9) Unknown

15. Medium Status (Immediately Prior To Impact) ϕ

- (0) No ejection
- (1) Open
- (2) Closed
- (3) Integral structure
- (9) Unknown

16. Entrapment ϕ

(NOTE: Entrapped means that part of the person was in the vehicle and mechanically restrained; jammed doors and immobilizing injuries by themselves are not sufficient to constitute entrapment.)

- (0) Not entrapped
- (1) Entrapped
- (9) Unknown

RESTRAINT SYSTEM EVALUATION

17. Manual (Active) Belt System Availability 4

- (0) None available
- (1) Belt removed/destroyed
- (2) Shoulder belt
- (3) Lap belt
- (4) Lap and shoulder belt
- (5) Belt available—type unknown

Integral Belt Partially Destroyed

- (6) Shoulder belt (lap belt destroyed/removed)
- (7) Lap belt (shoulder belt destroyed/removed)

(8) Other belt (specify): _____

(9) Unknown _____

18. Manual (Active) Belt System Use φ φ

- (00) None used, not available, or belt removed/destroyed
- (01) Inoperative (specify): _____

(02) Shoulder belt _____

(03) Lap belt _____

(04) Lap and shoulder belt _____

(05) Belt used—type unknown _____

(08) Other belt used (specify): _____

(12) Shoulder belt used with child safety seat _____

(13) Lap belt used with child safety seat _____

(14) Lap and shoulder belt used with child safety seat _____

(15) Belt used with child safety seat—type unknown _____

(18) Other belt used with child safety seat (specify): _____

(99) Unknown if belt used _____

19. Proper Use of Manual (Active) Belts φ

- (0) None used or not available
- (1) Belt used properly
- (2) Belt used properly with child safety seat

Belt Used Improperly

- (3) Shoulder belt worn under arm
- (4) Shoulder belt worn behind back or seat
- (5) Belt worn around more than one person
- (6) Lap belt worn on abdomen
- (7) Lap belt or lap and shoulder belt used improperly with child safety seat (specify): _____

(8) Other improper use of manual belt system (specify): _____

(9) Unknown _____

20. Manual (Active) Belt Failure Modes During Accident φ

- (0) No manual belt used
- (1) No manual belt failure(s)
- (2) Torn webbing (stretched webbing not included)
- (3) Broken buckle or latchplate
- (4) Upper anchorage separated
- (5) Other anchorage separated (specify): _____

(6) Broken retractor _____

(7) Combination of above (specify): _____

(8) Other manual belt failure (specify): _____

(9) Unknown _____

21. Air Bag System Availability/Function 1

- (0) Not equipped/not available
- (1) Air bag

Non-functional

(2) Air bag disconnected (specify): _____

(3) Air bag not reinstalled _____

(9) Unknown _____

22. Air Bag System Deployment 1

- (0) Not equipped/not available
- (1) Air bag deployed during accident (as a result of impact)
- (2) Air bag deployed inadvertently just prior to accident
- (3) Air bag deployed, accident sequence undetermined
- (4) Nondeployed
- (5) Unknown if deployed
- (6) Air bag deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)
- (9) Unknown

23. Are There Indications of Air Bag System Failure? 1

- (0) Not equipped/not available
- (1) No
- (2) Yes (specify): _____

(9) Unknown _____

Note: See Variables 44 through 48 (Page 5) for Information on Automatic Belts

24. Police Reported Restraint Use 9

- (0) None used
- (1) Police did not indicate restraint use
- (2) Shoulder belt
- (3) Lap belt
- (4) Lap and shoulder belt
- (5) Belt used, type not specified
- (6) Child safety seat
- (7) Other or automatic restraint (specify): _____

(8) Restrained, type unknown _____

(9) Police indicated "unknown"

HEAD RESTRAINT AND SEAT EVALUATION

25. Head Restraint Type/Damage by Occupant
at This Occupant Position3

- (0) No head restraints
- (1) Integral—no damage
- (2) Integral—damaged during accident
- (3) Adjustable—no damage
- (4) Adjustable—damaged during accident
- (5) Add-on—no damage
- (6) Add-on—damaged during accident
- (8) Other (specify):

(9) Unknown

26. Seat Type (this Occupant Position)

6

- (00) Occupant not seated or no seat
- (01) Bucket
- (02) Bucket with folding back
- (03) Bench
- (04) Bench with separate back cushions
- (05) Bench with folding back(s)
- (06) Split bench with separate back cushions
- (07) Split bench with folding back(s)
- (08) Pedestal (i.e., column supported)
- (09) Other seat type (specify):

(10) Box mounted seat (i.e., van type)

(99) Unknown

27. Seat Performance (this Occupant Position)

1

- (0) Occupant not seated or no seat
- (1) No seat performance failure(s)
- (2) Seat adjusters failed
- (3) Seat back folding locks or "seat back" failed (specify):
- (4) Seat track/anchors failed
- (5) Deformed by impact of occupant
- (6) Deformed by passenger compartment intrusion (specify):

(7) Combination of above (specify):

(8) Other (specify):

(9) Unknown

CHILD SAFETY SEAT

28. Child Safety Seat Make/Model ~~0~~ ~~0~~ ~~0~~
 (000) No child safety seat
 Applicable codes are found in your NASS CDS
 Data Collection, Coding and Editing
 (950) Built-in child safety seat
 (997) Other make/model (specify):

(998) Unknown make/model
 (999) Unknown if child safety seat used

29. Type of Child Safety Seat ~~0~~
 (0) No child safety seat
 (1) Infant seat
 (2) Toddler seat
 (3) Convertible seat
 (4) Booster seat
 (7) Other type child safety seat (specify):

(8) Unknown child safety seat type
 (9) Unknown if child safety seat used

30. Child Safety Seat Orientation ~~0~~ ~~0~~
 (00) No child safety seat

Designed for Rear Facing for This Age/Weight

(01) Rear facing
 (02) Forward facing
 (08) Other orientation (specify):

(09) Unknown orientation

Designed For Forward Facing for This Age/Weight

(11) Rear facing
 (12) Forward facing
 (18) Other orientation (specify):

(19) Unknown orientation

Unknown Design or Orientation For This Age/Weight, or Unknown Age/Weight

(21) Rear facing
 (22) Forward facing
 (28) Other orientation (specify):

(29) Unknown orientation

(99) Unknown if child safety seat used

31. Child Safety Seat Harness Usage ~~0~~ ~~0~~

32. Child Safety Seat Shield Usage ~~0~~ ~~0~~

33. Child Safety Seat Tether Usage ~~0~~ ~~0~~

Note: Options below applicable to
 Variables OA31-OA33.

(00) No child safety seat

Not Designed With Harness/Shield/Tether

(01) After market harness/shield/tether
 added, not used
 (02) After market harness/shield/tether used
 (03) Child safety seat used, but no after market
 harness/shield/tether added
 (09) Unknown if harness/shield/tether
 added or used

Designed With Harness/Shield/Tether

(11) Harness/shield/tether not used
 (12) Harness/shield/tether used
 (19) Unknown if harness/shield/tether used

Unknown If Designed With Harness/Shield/Tether

(21) Harness/shield/tether not used
 (22) Harness/shield/tether used
 (29) Unknown if harness/shield/tether used

(99) Unknown if child safety seat used

INJURY CONSEQUENCES34. Injury Severity (Police Rating) 3

- (0) O - No injury
- (1) C - Possible injury
- (2) B - Nonincapacitating injury
- (3) A - Incapacitating injury
- (4) K - Killed
- (5) U - Injury, severity unknown
- (6) Died prior to accident
- (9) Unknown

35. Treatment - Mortality 3

- (0) No treatment
- (1) Fatal
- (2) Fatal - ruled disease (specify):

Nonfatal

- (3) Hospitalization
- (4) Transported and released
- (5) Treatment at scene - nontransported
- (6) Treatment later
- (8) Treatment - other (specify):

(9) Unknown

36. Type Of Medical Facility (for Initial Treatment) 1

- (0) Not treated at a medical facility
- (1) Trauma center
- (2) Hospital
- (3) Medical clinic
- (4) Physician's office
- (5) Treatment later at medical facility
- (8) Other (specify):

(9) Unknown

37. Hospital Stay 1 9

(00) Not Hospitalized

Code the number of days (up through 60) that the occupant stayed in hospital.

- (61) 61 days or more
- (99) Unknown

99. Case Occupant 1

- (0) Not Case Occupant
- (1) This is the Case Occupant
- (2) This is the Case Occupant in another case

38. Working Days Lost 9 7

Code the number of days (up through 60) that the occupant lost from work due to the accident

- (00) No working days lost
- (61) 61 days or more
- (62) Fatally injured
- (97) Not working prior to accident
- (99) Unknown

STOP - GO TO VARIABLE 44 ON PAGE 7**VARIABLES 39 THROUGH 43 ARE COMPLETED BY THE ZONE CENTER**39. Time to Death 0 0

Code number of hours from time of accident to time of death up through 24 hours. If time of death is greater than 24 hours, code number of days. (Note: 1 day = 31, 2 days = 32, ... n days = 30 + n up through 30 days = 60)

- (00) Not fatal
- (96) Fatal - ruled disease
- (99) Unknown

40. 1st Medically Reported Cause of Death 0 041. 2nd Medically Reported Cause of Death 0 042. 3rd Medically Reported Cause of Death 0 0

Code the Occupant Injury from line number(s) for the medically reported injury(s) which reportedly contributed to this occupant's death

- (00) Not fatal or no additional causes
- (96) Mode of death given but specific injuries are not linked to cause of death. (specify):

(97) Other result (includes fatal ruled disease) (specify):

(99) Unknown

43. Number of Recorded Injuries for This Occupant 0 8

Code the actual number of injuries recorded for this occupant.

- (00) No recorded injuries
- (97) Injured, details unknown
- (99) Unknown if injured

AUTOMATIC BELT SYSTEM**44. Automatic (Passive) Belt System Availability/Function** φ

- (0) Not equipped/not available
- (1) 2 point automatic belts
- (2) 3 point automatic belts
- (3) Automatic belts - type unknown

Non-functional

- (4) Automatic belts destroyed or rendered inoperative
- (9) Unknown

45. Automatic (Passive) Belt System Use φ

- (0) Not equipped/not available/destroyed or rendered inoperative
- (1) Automatic belt in use
- (2) Automatic belt not in use (manually disconnected, motorized track inoperative) (specify): _____

- (3) Automatic belt use unknown
- (9) Unknown

46. Automatic (Passive) Belt System Type φ

- (0) Not equipped/not available
- (1) Non-motorized system
- (2) Motorized system
- (9) Unknown

47. Proper Use of Automatic (Passive) Belt System φ

- (0) Not equipped/not available/not used
- (1) Automatic belt used properly
- (2) Automatic belt used properly with child safety seat

Automatic Belt Used Improperly

- (3) Automatic shoulder belt worn under arm
- (4) Automatic shoulder belt worn behind back
- (5) Automatic belt worn around more than one person
- (6) Lap portion of automatic belt worn on abdomen
- (7) Automatic lap and shoulder belt or automatic shoulder belt used improperly with child safety seat (specify): _____

- (8) Other improper use of automatic belt system (specify): _____
- (9) Unknown

48. Automatic (Passive) Belt Failure Modes During Accident φ

- (0) Not equipped/not available/not in use
- (1) No automatic belt failure(s)
- (2) Torn webbing (stretched webbing not included)
- (3) Broken buckle or latchplate
- (4) Upper anchorage separated
- (5) Other anchorage separated (specify): _____

- (6) Broken retractor
- (7) Combination of above (specify): _____
- (8) Other automatic belt failure (specify): _____
- (9) Unknown

49. Seat Orientation (this Occupant Position) 1

- (0) Occupant not seated or no seat
- (1) Forward facing seat
- (2) Rear facing seat
- (3) Side facing seat (inward)
- (4) Side facing seat (outward)
- (8) Other (specify): _____

- (9) Unknown

Check the Primary Source Used In Determining Belt Use.

- [] Not equipped/not available/destroyed or rendered inoperative
- [X] Vehicle inspection
- [] Official injury data
- [] Driver/occupant interview
- [] Other (specify): _____

- [] Unknown if belt used

ARE ALL APPLICABLE MEDICAL RECORDS INCLUDED WITH INITIAL SUBMISSION?

NO [X] YES []

UPDATE CANDIDATE?

NO [X] YES []

**STOP - VARIABLES 50 THROUGH 53 ARE
COMPLETED BY THE ZONE CENTER****TRAUMA DATA**

50. Glasgow Coma Scale (GCS) Score 1 5
(at Medical Facility)
(00) Not injured
(01) Injured - not treated at medical facility
(02) No GCS Score at medical facility
(03-15) Code the actual value of the
initial GCS Score recorded at medical
facility.
(97) Injured, details unknown
(99) Unknown if injured
51. Was the Occupant Given Blood? 9
(1) No - blood not given
(2) Yes - blood given
(specify units): _____
(9) Unknown if blood given
52. Arterial Blood Gases (ABG) - HCO_3 ϕ 1
(00) Not injured
(01) Injured, ABGs not measured or reported
(02-50) Code the actual value of the HCO_3
(96) ABGs reported, HCO_3 unknown
(97) Injured, details unknown
(99) Unknown if injured

BELT USE DETERMINATION

53. Primary Source of Belt Use Determination 1
(0) Not equipped/not available/destroyed
or rendered inoperative
(1) Vehicle inspection
(2) Official injury data
(3) Driver/occupant interview
(8) Other (specify): _____
(9) Unknown if belt used



OCCUPANT INJURY FORM

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

1. Primary Sampling Unit Number _____

3. Vehicle Number 612. Case Number - Stratum DSI-94-AB-0064. Occupant Number 01

INJURY DATA

Record below the actual injuries sustained by this occupant that were identified from the official and unofficial data sources. Remember not to double count an injury just because it was identified from two different sources. If greater than ten injuries have been documented, encode the balance on the Occupant Injury Supplement.

	Source of Injury Data	Body Region	Type of Anatomic Structure	Specific Anatomic Structure	Level of Injury	A.I.S. Severity	Aspect	Injury Source	Injury Source Confidence Level	Direct/ Indirect Injury	Occupant Area Intrusion Number	ICD-9
1st	5. <u>2</u>	6. <u>8</u>	7. <u>5</u>	8. <u>1B</u>	9. <u>10</u>	10. <u>3</u>	11. <u>2</u>	12. <u>09</u>	13. <u>1</u>	14. <u>2</u>	15. <u>02</u>	820.21
2nd	16. <u>2</u>	17. <u>8</u>	18. <u>5</u>	19. <u>24</u>	20. <u>00</u>	21. <u>2</u>	22. <u>2</u>	23. <u>09</u>	24. <u>1</u>	25. <u>1</u>	26. <u>02</u>	822.1
3rd	27. <u>2</u>	28. <u>8</u>	29. <u>4</u>	30. <u>08</u>	31. <u>02</u>	32. <u>2</u>	33. <u>2</u>	34. <u>09</u>	35. <u>1</u>	36. <u>1</u>	37. <u>02</u>	844.8
4th	38. <u>2</u>	39. <u>8</u>	40. <u>5</u>	41. <u>24</u>	42. <u>00</u>	43. <u>2</u>	44. <u>1</u>	45. <u>09</u>	46. <u>1</u>	47. <u>1</u>	48. <u>02</u>	822.0
5th	49. <u>2</u>	50. <u>8</u>	51. <u>5</u>	52. <u>14</u>	53. <u>00</u>	54. <u>2</u>	55. <u>1</u>	56. <u>56</u>	57. <u>1</u>	58. <u>1</u>	59. <u>01</u>	825.0
6th	60. <u>2</u>	61. <u>7</u>	62. <u>5</u>	63. <u>28</u>	64. <u>02</u>	65. <u>2</u>	66. <u>1</u>	67. <u>09</u>	68. <u>1</u>	69. <u>1</u>	70. <u>00</u>	813.41
7th	71. <u>2</u>	72. <u>1</u>	73. <u>6</u>	74. <u>04</u>	75. <u>06</u>	76. <u>2</u>	77. <u>0</u>	78. <u>26</u>	79. <u>2</u>	80. <u>1</u>	81. <u>00</u>	850.5
8th	82. <u>2</u>	83. <u>8</u>	84. <u>9</u>	85. <u>08</u>	86. <u>00</u>	87. <u>1</u>	88. <u>1</u>	89. <u>09</u>	90. <u>1</u>	91. <u>1</u>	92. <u>02</u>	891.0
9th	93. <u> </u>	94. <u> </u>	95. <u> </u>	96. <u> </u>	97. <u> </u>	98. <u> </u>	99. <u> </u>	100. <u> </u>	101. <u> </u>	102. <u> </u>	103. <u> </u>	
10th	104. <u> </u>	105. <u> </u>	106. <u> </u>	107. <u> </u>	108. <u> </u>	109. <u> </u>	110. <u> </u>	111. <u> </u>	112. <u> </u>	113. <u> </u>	114. <u> </u>	



OCCUPANT INJURY DATA

	Source of Injury Data	A.I.S. - 90					Injury Source	Injury Source Confidence Level	Direct/ Indirect Injury	Occupant Area Intrusion Number
		Body Region	Type of Anatomic Structure	Specific Anatomic Structure	Level of Injury	A.I.S. Severity				
11th	---	---	---	---	---	---	---	---	---	---
12th	---	---	---	---	---	---	---	---	---	---
13th	---	---	---	---	---	---	---	---	---	---
14th	---	---	---	---	---	---	---	---	---	---
15th	---	---	---	---	---	---	---	---	---	---
16th	---	---	---	---	---	---	---	---	---	---
17th	---	---	---	---	---	---	---	---	---	---
18th	---	---	---	---	---	---	---	---	---	---
19th	---	---	---	---	---	---	---	---	---	---
20th	---	---	---	---	---	---	---	---	---	---
21st	---	---	---	---	---	---	---	---	---	---
22nd	---	---	---	---	---	---	---	---	---	---
23rd	---	---	---	---	---	---	---	---	---	---
24th	---	---	---	---	---	---	---	---	---	---
25th	---	---	---	---	---	---	---	---	---	---

ICD-9

OFFICIAL INJURY DATA — SOFT TISSUE INJURIES

Indicate the Location, Specific Anatomic Structure, Detail (size, depth, fracture type, head injury clinical signs and neurological deficits), and Source of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)



SOURCE OF INJURY DATA

OFFICIAL

- (1) Autopsy records with or without hospital/medical records
- (2) Hospital/medical records other than emergency room (e.g., discharge summary)
- (3) Emergency room records only (including associated X-rays or other lab reports)
- (4) Private physician, walk-in or emergency clinic

UNOFFICIAL

- (5) Lay coroner report
- (6) E.M.S. personnel
- (7) Interviewee
- (8) Other source (specify): _____
- (9) Police

INJURY SOURCE

FRONT

- (01) Windshield
- (02) Mirror
- (03) Sunvisor
- (04) Steering wheel rim
- (05) Steering wheel hub/spoke
- (06) Steering wheel (combination of codes 04 and 05)
- (07) Steering column, transmission selector lever, other attachment
- (08) Add on equipment (e.g., CB, tape deck, air conditioner)
- (09) Left instrument panel and below
- (10) Center instrument panel and below
- (11) Right instrument panel and below
- (12) Glove compartment door
- (13) Knee bolster
- (14) Windshield including one or more of the following: front header, A (A1/A2)-pillar, instrument panel, mirror, or steering assembly (driver side only)
- (15) Windshield including one or more of the following: front header, A (A1/A2)-pillar, instrument panel, or mirror (passenger side only)
- (16) Driver side air bag compartment cover
- (17) Passenger side air bag compartment cover
- (18) Windshield reinforced by exterior object (specify): _____
- (19) Other front object (specify): _____

LEFT SIDE

- (20) Left side interior surface, excluding hardware or armrests
- (21) Left side hardware or armrest
- (22) Left A (A1/A2)-pillar
- (23) Left B-pillar
- (24) Other left pillar (specify): _____

- (25) Left side window glass or frame
- (26) Left side window glass including one or more of the following: frame, window sill, A (A1/A2)-pillar, B-pillar, or roof side rail.
- (27) Other left side object (specify): _____
- (28) Left side window sill

RIGHT SIDE

- (30) Right side interior surface, excluding hardware or armrests
- (31) Right side hardware or armrest
- (32) Right A (A1/A2)-pillar
- (33) Right B-pillar
- (34) Other right pillar (specify): _____
- (35) Right side window glass or frame
- (36) Right side window glass including one or more of the following: frame, window sill, A (A1/A2)-pillar, B-pillar, or roof side rail.
- (37) Other right side object (specify): _____
- (38) Right side window sill

INTERIOR

- (40) Seat, back support
- (41) Belt restraint webbing/buckle
- (42) Belt restraint B-pillar or door frame attachment point
- (43) Other restraint system component (specify): _____
- (44) Head restraint system
- (45) Air bag (use codes "16" and "17" for injuries sustained from air bag compartment covers)
- (46) Other occupants (specify): _____
- (47) Interior loose objects
- (48) Child safety seat (specify): _____
- (49) Other interior object (specify): _____

ROOF

- (50) Front header
- (51) Rear header
- (52) Roof left side rail
- (53) Roof right side rail
- (54) Roof or convertible top

FLOOR

- (56) Floor (including toe pan)
- (57) Floor or console mounted transmission lever, including console
- (58) Parking brake handle
- (59) Foot controls including parking brake

REAR

- (60) Backlight (rear window)

- (61) Backlight storage rack, door, etc.
- (62) Other rear object (specify): _____

EXTERIOR of OCCUPANT'S VEHICLE

- (65) Hood
- (66) Outside hardware (e.g., outside mirror, antenna)
- (67) Other exterior surface or tires (specify): _____
- (68) Unknown exterior objects

EXTERIOR of OTHER MOTOR VEHICLE

- (70) Front bumper
- (71) Hood edge
- (72) Other front of vehicle (specify): _____

- (73) Hood
- (74) Hood ornament
- (75) Windshield, roof rail, A-pillar
- (76) Side surface
- (77) Side mirrors
- (78) Other side protrusions (specify) _____

- (79) Rear surface
- (80) Undercarriage
- (81) Tires and wheels
- (82) Other exterior of other motor vehicle (specify): _____

- (83) Unknown exterior of other motor vehicle

OTHER VEHICLE or OBJECT IN THE ENVIRONMENT

- (84) Ground
- (85) Other vehicle or object (specify) _____
- (86) Unknown vehicle or object

NONCONTACT INJURY

- (90) Fire in vehicle
- (91) Flying glass
- (92) Other noncontact injury source (specify): _____
- (93) Air bag exhaust gases
- (97) Injured, unknown source

INJURY SOURCE CONFIDENCE LEVEL

- (1) Certain
- (2) Probable
- (3) Possible
- (9) Unknown

DIRECT/INDIRECT INJURY

- (1) Direct contact injury
- (2) Indirect contact injury
- (3) Noncontact injury
- (7) Injured, unknown source

OCCUPANT INJURY CLASSIFICATION

Body Region

- (1) Head
- (2) Face
- (3) Neck
- (4) Thorax
- (5) Abdomen
- (6) Spine
- (7) Upper Extremity
- (8) Lower Extremity
- (9) Unspecified

Type of Anatomic Structure

- (1) Whole Area
- (2) Vessels
- (3) Nerves
- (4) Organs (includes muscles/ligaments)
- (5) Skeletal (includes joints)
- (6) Head - LOC
- (9) Skin

Specific Anatomic Structure

- Whole Area
- (02) Skin - Abrasion
 - (04) Skin - Contusion
 - (06) Skin - Laceration
 - (08) Skin - Avulsion
 - (10) Amputation
 - (20) Burn
 - (30) Crush
 - (40) Degloving
 - (50) Injury - NFS
 - (90) Trauma, other than mechanical

Head - LOC

- (02) Length of LOC
- (04, 06, 08) Level of Consciousness
- (10) Concussion

Spine

- (02) Cervical
- (04) Thoracic
- (06) Lumbar

Vessels, Nerves, Organs, Bones, Joints are assigned consecutive two digit numbers beginning with 02

Level of Injury

Specific injuries are assigned consecutive two-digit numbers beginning with 02.

To the extent possible, within the organizational framework of the AIS, 00 is assigned to an injury NFS as to severity or where only one injury is given in the dictionary for that anatomic structure. 99 is assigned to any injury NFS as to lesion or severity.

Abbreviated Injury Scale

- (1) Minor injury
- (2) Moderate injury
- (3) Serious injury
- (4) Severe injury
- (5) Critical injury
- (6) Maximum (untreatable)
- (7) Injured, unknown severity

Aspect

- (1) Right
- (2) Left
- (3) Bilateral
- (4) Central
- (5) Anterior
- (6) Posterior
- (7) Superior
- (8) Inferior
- (9) Unknown
- (0) Whole region

OFFICIAL INJURY DATA — SKELETAL INJURIES

Restrained?

☒ No

☐ Yes

Blood Alcohol Level
(mg/dl)

BAL = ϕ

Glasgow Coma
Scale Score

GCSS = 15

Units of Blood
Given

Units = LINK

Arterial Blood Gases


pH = 7.35

PO₂ = 100

PCO₂ = 40


HCO₃ = 24

Indicate the Location, Specific Anatomic Structure, Detail (size, depth, fracture type, head injury clinical signs and neurological deficits), and Source of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)



OFFICIAL INJURY DATA — INTERNAL INJURIES

Indicate the Location, Specific Anatomic Structure, Detail (size, depth, fracture type, head injury clinical signs and neurological deficits), and Source of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)



National Highway Traffic Safety
Administration

OCCUPANT ASSESSMENT FORM

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

OCCUPANT'S SEATING

1. Primary Sampling Unit Number _____
2. Case Number - Stratum DSI-94-AB-φφ6
3. Vehicle Number φ 1
4. Occupant Number φ 2

OCCUPANT'S CHARACTERISTICS

5. Occupant's Age 8 φ
Code actual age at time of accident.
(00) Less than one year old (specify by month): _____
(97) 97 years and older _____
(99) Unknown

6. Occupant's Sex 1
(1) Male
(2) Female
(9) Unknown

7. Occupant's Height 1 7 3
Code actual height to the nearest
centimeter.
(999) Unknown

6 8 inches X 2.54 = 1 7 3 centimeters

8. Occupant's Weight φ 7 5
Code actual weight to the nearest
kilogram.
(999) Unknown

1 6 5 pounds X .4536 = φ 7 5 kilograms

9. Occupant's Role 2
(1) Driver
(2) Passenger
(9) Unknown

10. Occupant's Seat Position 1 3
Front Seat
(11) Left side
(12) Middle
(13) Right side
(14) Other (specify): _____
(15) On or in the lap of another occupant

- Second Seat*
(21) Left side
(22) Middle
(23) Right side
(24) Other (specify): _____
(25) On or in the lap of another occupant

- Third Seat*
(31) Left side
(32) Middle
(33) Right side
(34) Other (specify): _____
(35) On or in the lap of another occupant

- Fourth Seat*
(41) Left side
(42) Middle
(43) Right side
(44) Other (specify): _____
(45) On or in the lap of another occupant

- (97) In or on unenclosed area
(98) Other seat (specify): _____
(99) Unknown

11. Occupant's Posture φ
(0) Normal posture

- Abnormal posture*
(1) Kneeling or standing on seat
(2) Lying on or across seat
(3) Kneeling, standing or sitting in front of seat
(4) Sitting sideways or turned to talk with another occupant or to look out a rear window
(5) Sitting on a console
(6) Lying back in a reclined seat position
(7) Bracing with feet or hands on a surface in front of seat
(8) Other abnormal posture (specify): _____
(9) Unknown

EJECTION/ENTRAPMENT

12. Ejection φ

- (0) No ejection
- (1) Complete ejection
- (2) Partial ejection
- (3) Ejection, unknown degree
- (9) Unknown

13. Ejection Area φ

- (0) No ejection
- (1) Windshield
- (2) Left front
- (3) Right front
- (4) Left rear
- (5) Right rear
- (6) Rear
- (7) Roof
- (8) Other area (e.g., back of pickup, etc.)
(specify): _____
- (9) Unknown

14. Ejection Medium φ

- (0) No ejection
- (1) Door/hatch/tailgate
- (2) Nonfixed roof structure
- (3) Fixed glazing
- (4) Nonfixed glazing (specify): _____
- (5) Integral structure
- (8) Other medium (specify): _____
- (9) Unknown

15. Medium Status (Immediately Prior To Impact) φ

- (0) No ejection
- (1) Open
- (2) Closed
- (3) Integral structure
- (9) Unknown

16. Entrapment φ

(NOTE: Entrapped means that part of the person was in the vehicle and mechanically restrained; jammed doors and immobilizing injuries by themselves are not sufficient to constitute entrapment.)

- (0) Not entrapped
- (1) Entrapped -
- (9) Unknown

RESTRAINT SYSTEM EVALUATION

17. Manual (Active) Belt System Availability 4

- (0) None available
- (1) Belt removed/destroyed
- (2) Shoulder belt
- (3) Lap belt
- (4) Lap and shoulder belt
- (5) Belt available—type unknown

Integral Belt Partially Destroyed

- (6) Shoulder belt (lap belt destroyed/removed)
- (7) Lap belt (shoulder belt destroyed/removed)

(8) Other belt (specify): _____

(9) Unknown _____

18. Manual (Active) Belt System Use ϕ ϕ

- (00) None used, not available, or belt removed/destroyed
- (01) Inoperative (specify): _____

(02) Shoulder belt _____

(03) Lap belt _____

(04) Lap and shoulder belt _____

(05) Belt used—type unknown _____

(08) Other belt used (specify): _____

(12) Shoulder belt used with child safety seat _____

(13) Lap belt used with child safety seat _____

(14) Lap and shoulder belt used with child safety seat _____

(15) Belt used with child safety seat—type unknown _____

(18) Other belt used with child safety seat (specify): _____

(99) Unknown if belt used _____

19. Proper Use of Manual (Active) Belts ϕ

- (0) None used or not available
- (1) Belt used properly
- (2) Belt used properly with child safety seat

Belt Used Improperly

- (3) Shoulder belt worn under arm
- (4) Shoulder belt worn behind back or seat
- (5) Belt worn around more than one person
- (6) Lap belt worn on abdomen
- (7) Lap belt or lap and shoulder belt used improperly with child safety seat (specify): _____

(8) Other improper use of manual belt system (specify): _____

(9) Unknown _____

20. Manual (Active) Belt Failure Modes During Accident ϕ

- (0) No manual belt used
- (1) No manual belt failure(s)
- (2) Torn webbing (stretched webbing not included)
- (3) Broken buckle or latchplate
- (4) Upper anchorage separated
- (5) Other anchorage separated (specify): _____

(6) Broken retractor _____

(7) Combination of above (specify): _____

(8) Other manual belt failure (specify): _____

(9) Unknown _____

21. Air Bag System Availability/Function ϕ

- (0) Not equipped/not available
- (1) Air bag

Non-functional

(2) Air bag disconnected (specify): _____

(3) Air bag not reinstalled _____

(9) Unknown _____

22. Air Bag System Deployment ϕ

- (0) Not equipped/not available
- (1) Air bag deployed during accident (as a result of impact)
- (2) Air bag deployed inadvertently just prior to accident
- (3) Air bag deployed, accident sequence undetermined
- (4) Nondeployed
- (5) Unknown if deployed
- (6) Air bag deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)
- (9) Unknown

23. Are There Indications of Air Bag System Failure? ϕ

- (0) Not equipped/not available
- (1) No
- (2) Yes (specify): _____

(9) Unknown _____

Note: See Variables 44 through 48 (Page 5) for Information on Automatic Belts

24. Police Reported Restraint Use 9

- (0) None used
- (1) Police did not indicate restraint use
- (2) Shoulder belt
- (3) Lap belt
- (4) Lap and shoulder belt
- (5) Belt used, type not specified
- (6) Child safety seat
- (7) Other or automatic restraint (specify): _____

(8) Restrained, type unknown _____

(9) Police indicated "unknown"

HEAD RESTRAINT AND SEAT EVALUATION

25. Head Restraint Type/Damage by Occupant at This Occupant Position 3

- (0) No head restraints
- (1) Integral—no damage
- (2) Integral—damaged during accident
- (3) Adjustable—no damage
- (4) Adjustable—damaged during accident
- (5) Add-on—no damage
- (6) Add-on—damaged during accident
- (8) Other (specify): _____
- (9) Unknown

26. Seat Type (this Occupant Position) 6

- (00) Occupant not seated or no seat
- (01) Bucket
- (02) Bucket with folding back
- (03) Bench
- (04) Bench with separate back cushions
- (05) Bench with folding back(s)
- (06) Split bench with separate back cushions
- (07) Split bench with folding back(s)
- (08) Pedestal (i.e., column supported)
- (09) Other seat type (specify): _____
- (10) Box mounted seat (i.e., van type)
- (99) Unknown

27. Seat Performance (this Occupant Position) 1

- (0) Occupant not seated or no seat
- (1) No seat performance failure(s)
- (2) Seat adjusters failed
- (3) Seat back folding locks or "seat back" failed (specify): _____
- (4) Seat track/anchors failed
- (5) Deformed by impact of occupant
- (6) Deformed by passenger compartment intrusion (specify): _____
- (7) Combination of above (specify): _____
- (8) Other (specify): _____
- (9) Unknown -

CHILD SAFETY SEAT

28. Child Safety Seat Make/Model ϕ ϕ ϕ
 (000) No child safety seat
 Applicable codes are found in your NASS CDS
 Data Collection, Coding and Editing
 (950) Built-in child safety seat
 (997) Other make/model (specify):

 (998) Unknown make/model
 (999) Unknown if child safety seat used

29. Type of Child Safety Seat ϕ
 (0) No child safety seat
 (1) Infant seat
 (2) Toddler seat
 (3) Convertible seat
 (4) Booster seat
 (7) Other type child safety seat (specify):

 (8) Unknown child safety seat type
 (9) Unknown if child safety seat used

30. Child Safety Seat Orientation ϕ ϕ
 (00) No child safety seat

Designed for Rear Facing for This Age/Weight
 (01) Rear facing
 (02) Forward facing
 (08) Other orientation (specify):

 (09) Unknown orientation

Designed For Forward Facing for This Age/Weight
 (11) Rear facing
 (12) Forward facing
 (18) Other orientation (specify):

 (19) Unknown orientation

Unknown Design or Orientation For This Age/Weight, or Unknown Age/Weight
 (21) Rear facing
 (22) Forward facing
 (28) Other orientation (specify):

 (29) Unknown orientation

 (99) Unknown if child safety seat used

31. Child Safety Seat Harness Usage ϕ ϕ

32. Child Safety Seat Shield Usage ϕ ϕ

33. Child Safety Seat Tether Usage ϕ ϕ

Note: Options below applicable to
 Variables OA31-OA33.
 (00) No child safety seat

Not Designed With Harness/Shield/Tether

(01) After market harness/shield/tether
 added, not used
 (02) After market harness/shield/tether used
 (03) Child safety seat used, but no after market
 harness/shield/tether added
 (09) Unknown if harness/shield/tether
 added or used

Designed With Harness/Shield/Tether

(11) Harness/shield/tether not used
 (12) Harness/shield/tether used
 (19) Unknown if harness/shield/tether used

Unknown If Designed With Harness/Shield/Tether

(21) Harness/shield/tether not used
 (22) Harness/shield/tether used
 (29) Unknown if harness/shield/tether used

 (99) Unknown if child safety seat used

INJURY CONSEQUENCES34. Injury Severity (Police Rating) 3

- (0) O - No injury
- (1) C - Possible injury
- (2) B - Nonincapacitating injury
- (3) A - Incapacitating injury
- (4) K - Killed
- (5) U - Injury, severity unknown
- (6) Died prior to accident
- (9) Unknown

35. Treatment - Mortality 3

- (0) No treatment
- (1) Fatal
- (2) Fatal - ruled disease (specify):

Nonfatal

- (3) Hospitalization
- (4) Transported and released
- (5) Treatment at scene - nontransported
- (6) Treatment later
- (8) Treatment - other (specify):

(9) Unknown

36. Type Of Medical Facility (for Initial Treatment) 1

- (0) Not treated at a medical facility
- (1) Trauma center
- (2) Hospital
- (3) Medical clinic
- (4) Physician's office
- (5) Treatment later at medical facility
- (8) Other (specify):

(9) Unknown

37. Hospital Stay 1 9

- (00) Not Hospitalized
- _____ Code the number of days (up through 60) that the occupant stayed in hospital.
- (61) 61 days or more
- (99) Unknown

99. Case Occupant φ

- (0) Not Case Occupant
- (1) This is the Case Occupant
- (2) This is the Case Occupant in another case

38. Working Days Lost 9 7

- _____ Code the number of days (up through 60) that the occupant lost from work due to the accident
- (00) No working days lost
- (61) 61 days or more
- (62) Fatally injured
- (97) Not working prior to accident
- (99) Unknown

STOP - GO TO VARIABLE 44 ON PAGE 7**VARIABLES 39 THROUGH 43 ARE COMPLETED BY THE ZONE CENTER**39. Time to Death φ φ

- _____ Code number of hours from time of accident to time of death up through 24 hours. If time of death is greater than 24 hours, code number of days. (Note: 1 day = 31, 2 days = 32, ... n days = 30 + n up through 30 days = 60)
- (00) Not fatal
- (96) Fatal - ruled disease
- (99) Unknown

40. 1st Medically Reported Cause of Death φ φ41. 2nd Medically Reported Cause of Death φ φ42. 3rd Medically Reported Cause of Death φ φ

- _____ Code the Occupant Injury from line number(s) for the medically reported injury(s) which reportedly contributed to this occupant's death
- (00) Not fatal or no additional causes
- (96) Mode of death given but specific injuries are not linked to cause of death. (specify):

(97) Other result (includes fatal ruled disease) (specify):

(99) Unknown

43. Number of Recorded Injuries for This Occupant φ 6

- _____ Code the actual number of injuries recorded for this occupant.
- (00) No recorded injuries
- (97) Injured, details unknown
- (99) Unknown if injured

AUTOMATIC BELT SYSTEM44. Automatic (Passive) Belt System Availability/Function φ

- (0) Not equipped/not available
- (1) 2 point automatic belts
- (2) 3 point automatic belts
- (3) Automatic belts - type unknown

Non-functional

- (4) Automatic belts destroyed or rendered inoperative
- (9) Unknown

45. Automatic (Passive) Belt System Use φ

- (0) Not equipped/not available/destroyed or rendered inoperative
- (1) Automatic belt in use
- (2) Automatic belt not in use (manually disconnected, motorized track inoperative) (specify): _____

- (3) Automatic belt use unknown
- (9) Unknown

46. Automatic (Passive) Belt System Type φ

- (0) Not equipped/not available
- (1) Non-motorized system
- (2) Motorized system
- (9) Unknown

47. Proper Use of Automatic (Passive) Belt System φ

- (0) Not equipped/not available/not used
- (1) Automatic belt used properly
- (2) Automatic belt used properly with child safety seat

Automatic Belt Used Improperly

- (3) Automatic shoulder belt worn under arm
- (4) Automatic shoulder belt worn behind back
- (5) Automatic belt worn around more than one person
- (6) Lap portion of automatic belt worn on abdomen
- (7) Automatic lap and shoulder belt or automatic shoulder belt used improperly with child safety seat (specify): _____

- (8) Other improper use of automatic belt system (specify): _____
- (9) Unknown

48. Automatic (Passive) Belt Failure Modes During Accident φ

- (0) Not equipped/not available/not in use
- (1) No automatic belt failure(s)
- (2) Torn webbing (stretched webbing not included)
- (3) Broken buckle or latchplate
- (4) Upper anchorage separated
- (5) Other anchorage separated (specify): _____

- (6) Broken retractor
- (7) Combination of above (specify): _____
- (8) Other automatic belt failure (specify): _____

- (9) Unknown

49. Seat Orientation (this Occupant Position) 1

- (0) Occupant not seated or no seat
- (1) Forward facing seat
- (2) Rear facing seat
- (3) Side facing seat (inward)
- (4) Side facing seat (outward)
- (8) Other (specify): _____

- (9) Unknown

Check the Primary Source Used In Determining Belt Use.

- [] Not equipped/not available/destroyed or rendered inoperative
- ☒ Vehicle inspection
- [] Official injury data
- [] Driver/occupant interview
- [] Other (specify): _____

- [] Unknown if belt used

ARE ALL APPLICABLE MEDICAL RECORDS INCLUDED WITH INITIAL SUBMISSION?

NO [X] YES []

UPDATE CANDIDATE?

NO [X] YES []

**STOP - VARIABLES 50 THROUGH 53 ARE
COMPLETED BY THE ZONE CENTER****TRAUMA DATA**

50. Glasgow Coma Scale (GCS) Score 1 5
(at Medical Facility)
(00) Not injured
(01) Injured - not treated at medical facility
(02) No GCS Score at medical facility
(03-15) Code the actual value of the
initial GCS Score recorded at medical
facility.
(97) Injured, details unknown
(99) Unknown if injured
51. Was the Occupant Given Blood? 9
(1) No - blood not given
(2) Yes - blood given
(specify units): _____
(9) Unknown if blood given
52. Arterial Blood Gases (ABG) - HCO_3 ϕ 1
(00) Not injured
(01) Injured, ABGs not measured or reported
(02-50) Code the actual value of the HCO_3
(96) ABGs reported, HCO_3 unknown
(97) Injured, details unknown
(99) Unknown if injured

BELT USE DETERMINATION

53. Primary Source of Belt Use Determination 1
(0) Not equipped/not available/destroyed
or rendered inoperative
(1) Vehicle inspection
(2) Official injury data
(3) Driver/occupant interview
(8) Other (specify): _____
(9) Unknown if belt used



OCCUPANT INJURY FORM

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

1. Primary Sampling Unit Number _____

3. Vehicle Number 012. Case Number - Stratum DSI-94-AB-0064. Occupant Number 02

INJURY DATA

Record below the actual injuries sustained by this occupant that were identified from the official and unofficial data sources. Remember not to double count an injury just because it was identified from two different sources. If greater than ten injuries have been documented, encode the balance on the Occupant Injury Supplement.



	Source of Injury Data	Body Region	Type of Anatomic Structure	Specific Anatomic Structure	Level of Injury	A.I.S. Severity	Aspect	Injury Source	Injury Source Confidence Level	Direct/ Indirect Injury	Occupant Area Intrusion Number	ICD-9
1st	5. <u>2</u>	6. <u>5</u>	7. <u>4</u>	8. <u>42</u>	9. <u>26</u>	10. <u>4</u>	11. <u>2</u>	12. <u>11</u>	13. <u>1</u>	14. <u>1</u>	15. <u>00</u>	865.04
2nd	16. <u>2</u>	17. <u>4</u>	18. <u>5</u>	19. <u>02</u>	20. <u>20</u>	21. <u>2</u>	22. <u>2</u>	23. <u>11</u>	24. <u>1</u>	25. <u>1</u>	26. <u>00</u>	847.09
3rd	27. <u>2</u>	28. <u>1</u>	29. <u>6</u>	30. <u>04</u>	31. <u>06</u>	32. <u>2</u>	33. <u>0</u>	34. <u>11</u>	35. <u>1</u>	36. <u>1</u>	37. <u>00</u>	850.5
4th	38. <u>2</u>	39. <u>2</u>	40. <u>9</u>	41. <u>02</u>	42. <u>02</u>	43. <u>1</u>	44. <u>7</u>	45. <u>11</u>	46. <u>1</u>	47. <u>1</u>	48. <u>00</u>	910.0
5th	49. <u>2</u>	50. <u>5</u>	51. <u>9</u>	52. <u>04</u>	53. <u>02</u>	54. <u>1</u>	55. <u>9</u>	56. <u>11</u>	57. <u>1</u>	58. <u>1</u>	59. <u>00</u>	860.03
6th	60. <u>2</u>	61. <u>6</u>	62. <u>4</u>	63. <u>04</u>	64. <u>78</u>	65. <u>1</u>	66. <u>7</u>	67. <u>92</u>	68. <u>1</u>	69. <u>3</u>	70. <u>00</u>	847.1
7th	71. ____	72. ____	73. ____	74. ____	75. ____	76. ____	77. ____	78. ____	79. ____	80. ____	81. ____	
8th	82. ____	83. ____	84. ____	85. ____	86. ____	87. ____	88. ____	89. ____	90. ____	91. ____	92. ____	
9th	93. ____	94. ____	95. ____	96. ____	97. ____	98. ____	99. ____	100. ____	101. ____	102. ____	103. ____	
0th	104. ____	105. ____	106. ____	107. ____	108. ____	109. ____	110. ____	111. ____	112. ____	113. ____	114. ____	

.I.S. - 90

ICD-9

OFFICIAL INJURY DATA — SOFT TISSUE INJURIES

Indicate the Location, Specific Anatomic Structure, Detail (size, depth, fracture type, head injury clinical signs and neurological deficits), and Source of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)



SOURCE OF INJURY DATA

OFFICIAL

- (1) Autopsy records with or without hospital/medical records
- (2) Hospital/medical records other than emergency room (e.g., discharge summary)
- (3) Emergency room records only (including associated X-rays or other lab reports)
- (4) Private physician, walk-in or emergency clinic

UNOFFICIAL

- (5) Lay coroner report
- (6) E.M.S. personnel
- (7) Interviewee
- (8) Other source (specify): _____
- (9) Police

INJURY SOURCE

FRONT

- (01) Windshield
- (02) Mirror
- (03) Sunvisor
- (04) Steering wheel rim
- (05) Steering wheel hub/spoke
- (06) Steering wheel (combination of codes 04 and 05)
- (07) Steering column, transmission selector lever, other attachment
- (08) Add on equipment (e.g., CB, tape deck, air conditioner)
- (09) Left instrument panel and below
- (10) Center instrument panel and below
- (11) Right instrument panel and below
- (12) Glove compartment door
- (13) Knee bolster
- (14) Windshield including one or more of the following: front header, A (A1/A2)-pillar, instrument panel, mirror, or steering assembly (driver side only)
- (15) Windshield including one or more of the following: front header, A (A1/A2)-pillar, instrument panel, or mirror (passenger side only)
- (16) Driver side air bag compartment cover
- (17) Passenger side air bag compartment cover
- (18) Windshield reinforced by exterior object (specify): _____
- (19) Other front object (specify): _____

LEFT SIDE

- (20) Left side interior surface, excluding hardware or armrests
- (21) Left side hardware or armrest
- (22) Left A (A1/A2)-pillar
- (23) Left B-pillar
- (24) Other left pillar (specify): _____

- (25) Left side window glass or frame
- (26) Left side window glass including one or more of the following: frame, window sill, A (A1/A2)-pillar, B-pillar, or roof side rail.
- (27) Other left side object (specify): _____

- (28) Left side window sill

RIGHT SIDE

- (30) Right side interior surface, excluding hardware or armrests
- (31) Right side hardware or armrest
- (32) Right A (A1/A2)-pillar
- (33) Right B-pillar
- (34) Other right pillar (specify): _____

- (35) Right side window glass or frame
- (36) Right side window glass including one or more of the following: frame, window sill, A (A1/A2)-pillar, B-pillar, or roof side rail.
- (37) Other right side object (specify): _____

- (38) Right side window sill

INTERIOR

- (40) Seat, back support
- (41) Belt restraint webbing/buckle
- (42) Belt restraint B-pillar or door frame attachment point
- (43) Other restraint system component (specify): _____
- (44) Head restraint system
- (45) Air bag (use codes "16" and "17" for injuries sustained from air bag compartment covers)
- (46) Other occupants (specify): _____
- (47) Interior loose objects
- (48) Child safety seat (specify): _____
- (49) Other interior object (specify): _____

ROOF

- (50) Front header
- (51) Rear header
- (52) Roof left side rail
- (53) Roof right side rail
- (54) Roof or convertible top

FLOOR

- (56) Floor (including toe pan)
- (57) Floor or console mounted transmission lever, including console
- (58) Parking brake handle
- (59) Foot controls including parking brake

REAR

- (60) Backlight (rear window)

- (61) Backlight storage rack, door, etc.
- (62) Other rear object (specify): _____

EXTERIOR of OCCUPANT'S VEHICLE

- (65) Hood
- (66) Outside hardware (e.g., outside mirror, antenna)
- (67) Other exterior surface or tires (specify): _____
- (68) Unknown exterior objects

EXTERIOR OF OTHER MOTOR VEHICLE

- (70) Front bumper
- (71) Hood edge
- (72) Other front of vehicle (specify): _____

- (73) Hood
- (74) Hood ornament
- (75) Windshield, roof rail, A-pillar
- (76) Side surface
- (77) Side mirrors
- (78) Other side protrusions (specify): _____

- (79) Rear surface
- (80) Undercarriage
- (81) Tires and wheels
- (82) Other exterior of other motor vehicle (specify): _____
- (83) Unknown exterior of other motor vehicle

OTHER VEHICLE OR OBJECT IN THE ENVIRONMENT

- (84) Ground
- (85) Other vehicle or object (specify): _____
- (86) Unknown vehicle or object

NONCONTACT INJURY

- (90) Fire in vehicle
- (91) Flying glass
- (92) Other noncontact injury source (specify): _____
- (93) Air bag exhaust gases
- (97) Injured, unknown source

INJURY SOURCE CONFIDENCE LEVEL

- (1) Certain
- (2) Probable
- (3) Possible
- (9) Unknown

DIRECT/INDIRECT INJURY

- (1) Direct contact injury
- (2) Indirect contact injury
- (3) Noncontact injury
- (7) Injured, unknown source

OCCUPANT INJURY CLASSIFICATION

Body Region

- (1) Head
- (2) Face
- (3) Neck
- (4) Thorax
- (5) Abdomen
- (6) Spine
- (7) Upper Extremity
- (8) Lower Extremity
- (9) Unspecified

Type of Anatomic Structure

- (1) Whole Area
- (2) Vessels
- (3) Nerves
- (4) Organs (includes muscles/ligaments)
- (5) Skeletal (includes joints)
- (6) Head - LOC
- (9) Skin

Specific Anatomic Structure

Whole Area

- (02) Skin - Abrasion
- (04) Skin - Contusion
- (06) Skin - Laceration
- (08) Skin - Avulsion
- (10) Amputation
- (20) Burn
- (30) Crush
- (40) Degloving
- (50) Injury - NFS
- (90) Trauma, other than mechanical

Head - LOC

- (02) Length of LOC
- (04, 06, 08) Level of Consciousness
- (10) Concussion

Spine

- (02) Cervical
- (04) Thoracic
- (06) Lumbar

Vessels, Nerves, Organs, Bones, Joints are assigned consecutive two digit numbers beginning with 02

Level of Injury

Specific injuries are assigned consecutive two-digit numbers beginning with 02.

To the extent possible, within the organizational framework of the AIS, 00 is assigned to an injury NFS as to severity or where only one injury is given in the dictionary for that anatomic structure. 99 is assigned to any injury NFS as to lesion or severity.

Abbreviated Injury Scale

- (1) Minor injury
- (2) Moderate injury
- (3) Serious injury
- (4) Severe injury
- (5) Critical injury
- (6) Maximum (untreatable)
- (7) Injured, unknown severity

Aspect

- (1) Right
- (2) Left
- (3) Bilateral
- (4) Central
- (5) Anterior
- (6) Posterior
- (7) Superior
- (8) Inferior
- (9) Unknown
- (0) Whole region

OFFICIAL INJURY DATA — SKELETAL INJURIES

Restrained?

☒ No

☐ Yes

Blood Alcohol Level
(mg/dl)

BAL = 0

Glasgow Coma
Scale Score

GCSS = 15

Units of Blood
Given

Units = UNK

Arterial Blood Gases


pH = 7.35

PO₂ = 100


PCO₂ = 40

HCO₃ = 24

Indicate the Location, Specific Anatomic Structure, Detail (size, depth, fracture type, head injury clinical signs and neurological deficits), and Source of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)




FRACTURES (MULTIPLE)
L. RIBS
R. INST RIB CAGE



OFFICIAL INJURY DATA — INTERNAL INJURIES

Indicate the Location, Specific Anatomic Structure, Detail (size, depth, fracture type, head injury clinical signs and neurological deficits), and Source of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)





GENERAL VEHICLE FORM

1. Primary Sampling Unit Number

2. Case Number - Stratum DSI-94-AB-00663. Vehicle Number 02

VEHICLE IDENTIFICATION

4. Vehicle Model Year 9 1
Code the last two digits of the model year
(99) Unknown5. Vehicle Make (specify): 4 9
TOYOTA
Applicable codes are found in your
NASS Data Collection, Coding and
Editing Manual.
(99) Unknown6. Vehicle Model (specify): 4 7 1
SR-5 4x4
Applicable codes are found in your
NASS Data Collection, Coding and
Editing Manual.
(999) Unknown7. Body Type 3 0
Note: Applicable codes may be found on
the back of this page.

8. Vehicle Identification Number

J T 4 V N 1 3 9 7 M 5
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17Left justify; Slash zeros and letter Z (0 and Z)
No VIN—Code all zeros
Unknown—Code all nines

OFFICIAL RECORDS

9. Police Reported Vehicle Disposition 1
(0) Not towed due to vehicle damage
(1) Towed due to vehicle damage
(9) Unknown10. Police Reported Travel Speed 9 9 9
Code to the nearest kph (NOTE: 000 means
less than 0.5 kph)
(160) 159.5 kph and above
(999) Unknown mph X 1.6093 = kph11. Police Reported Alcohol Presence 0
(0) No alcohol present
(1) Yes (alcohol present)
(7) Not reported
(8) No driver present
(9) UnknownNote: See variables 37 through 55
(Page 4) for information on Other Drugs12. Alcohol Test Result For Driver 9 6
Code actual value (decimal implied
before first digit—0.xx)
(95) Test refused
(96) None given
(97) AC test performed, results unknown
(98) No driver present
(99) UnknownSource: PAR

ACCIDENT RELATED

13. Speed Limit 0 6 4
(000) No statutory limit
Code posted or statutory speed limit
in kph
(999) Unknown4 0 mph X 1.6093 = 0 6 4 kph14. Attempted Avoidance Maneuver 0 1
(01) No avoidance actions
(02) Braking (no lockup)
(03) Braking (lockup)
(04) Braking (lockup unknown)
(05) Releasing brakes
(06) Steering left
(07) Steering right
(08) Braking and steering left
(09) Braking and steering right
(10) Accelerating
(11) Accelerating and steering left
(12) Accelerating and steering right
(97) No driver present
(98) Other action (specify):
(99) Unknown15. Accident Type 5 1
Applicable codes may be found on the
back of page two of this field form
(00) No impact
Code the number of the diagram that
best describes the accident circumstance
(98) Other accident type (specify):
(99) Unknown

**** SKIP TO VARIABLE GV37 IF GV07 DOES NOT EQUAL 01-49 ****

CODES FOR BODY TYPE

CDS APPLICABLE VEHICLES

Automobiles

- (01) Convertible (excludes sun-roof, t-bar)
- (02) 2-door sedan, hardtop, coupe
- (03) 3-door/2-door hatchback
- (04) 4-door sedan, hardtop
- (05) 5-door/4-door hatchback
- (06) Station wagon (excluding van and truck based)
- (07) Hatchback, number of doors unknown
- (08) Other automobile type (specify): _____
- (09) Unknown automobile type

Automobile Derivatives

- (10) Auto based pickup (includes El Camino, Caballero, Ranchero, Brat, and Rabbit pickup)
- (11) Auto based panel (cargo station wagon, auto based ambulance/hearse)
- (12) Large limousine - more than four side doors or stretched chassis
- (13) Three-wheel automobile or automobile derivative

Utility Vehicles ($\leq 4,500$ kgs GVWR)

- (14) Compact utility (Jeep CJ-2 - CJ-7, Scrambler, Golden Eagle, Renegade, Laredo, Wrangler, Cherokee [84 and after], Dispatcher, Raider, Bronco II, Bronco [76 and before], Explorer, S-10 Blazer, Geo Tracker, Bravada, S-15 Jimmy, Thing, Pathfinder, Trooper, Trooper II, Rodeo, Amigo, Navajo, 4-Runner, Montero, Samurai, Sidekick, Rocky)
- (15) Large utility (includes Jeep Cherokee [83 and before], Ramcharger, Trailduster, Bronco-fullsize [78 and after], fullsize Blazer, fullsize Jimmy, Landcruiser, Rover, Scout)
- (16) Utility station wagon (Chevy Suburban, GMC Suburban, Travelall, Grand Wagoneer, includes suburban limousine)
- (19) Utility, unknown body type

Van Based Light Trucks ($\leq 4,500$ kgs GVWR)

- (20) Minivan (Chrysler Town and Country, Caravan, Grand Caravan, Voyager, Grand Voyager, Mini-Ram, Dodge/Plymouth Vista, Aerostar, Villager, Lumina APV, Trans Sport, Silhouette, Astro, Safari, Toyota Van, Toyota Minivan, Previa, Nissan Minivan, Quest, Mitsubishi Minivan, Vanagon/Camper.)
- (21) Large van (B150-B350, Sportsman, Royal, Maxiwagon, Ram, Tradesman, Voyager [83 and before], E150-E350, Econoline, Clubwagon, Chateau, G10-G30, Chevy Van, Beauville, Sport Van, G15-G35, Rally Van, Vandura.)
- (22) Step van or walk-in van ($\leq 4,500$ kgs GVWR)
- (23) Van based motorhome ($\leq 4,500$ kgs GVWR)
- (24) Van based school bus ($\leq 4,500$ kgs GVWR)
- (25) Van based other bus ($\leq 4,500$ kgs GVWR)
- (28) Other van type (Hi-Cube Van, Kary) (specify): _____
- (29) Unknown van type

Light Conventional Trucks (Pickup style cab, $\leq 4,500$ kgs GVWR)

- (30) Compact pickup (D50, Colt P/U, Ram 50, Dakota, Arrow Pickup [foreign], Ranger, Courier, S-10, T-10, LUV, S-15, T-15, Sonoma, Datsun/Nissan Pickup, P'up, Mazda Pickup, Toyota Pickup, Mitsubishi Pickup)
- (31) Large Pickup (Jeep Pickup, Comanche, Ram Pickup, D100-D350, W100-W350, F100-F350, C10-C35, K10-K35, R10-R35, V10-V35, Silverado, Sierra, R100-R500,)

- (32) Pickup with slide-in camper
- (33) Convertible pickup
- (39) Unknown pickup style light conventional truck type

Other Light Trucks ($\leq 4,500$ kgs GVWR)

- (40) Cab chassis based (includes rescue vehicles, light stake, dump, and tow truck)
- (41) Truck based panel
- (42) Light truck based motorhome (chassis mounted)
- (45) Other light conventional truck type
- (48) Unknown light truck type
- (49) Unknown light vehicle type (automobile, utility, van, or light truck)

OTHER VEHICLES

Buses (Excludes Van Based)

- (50) School bus (designed to carry students, not cross country or transit)
- (58) Other bus type (e.g., transit, intercity, bus based motorhome) (specify): _____
- (59) Unknown bus type

Medium/Heavy Trucks ($> 4,500$ kgs GVWR)

- (60) Step van ($> 4,500$ kgs GVWR)
- (61) Single unit straight truck ($4,500$ kgs $<$ GVWR $\leq 8,850$ kgs)
- (62) Single unit straight truck ($8,850$ kgs $<$ GVWR $\leq 12,000$ kgs)
- (63) Single unit straight truck ($> 12,000$ kgs GVWR)
- (64) Single unit straight truck, GVWR unknown
- (65) Medium/heavy truck based motorhome
- (67) Truck-tractor with no cargo trailer
- (68) Truck-tractor pulling one trailer
- (69) Truck-tractor pulling two or more trailers
- (70) Truck-tractor (unknown if pulling trailer)
- (78) Unknown medium/heavy truck type
- (79) Unknown truck type (light/medium/heavy)

Motored Cycles (Does Not Include All-Terrain Vehicles/Cycles)

- (80) Motorcycle
- (81) Moped (motorized bicycle)
- (82) Three-wheel motorcycle or moped
- (88) Other motored cycle (minibike, motorscooter) (specify): _____
- (89) Unknown motored cycle type

Other Vehicles

- (90) ATV (All-Terrain Vehicle) and ATC (All-Terrain Cycle)
- (91) Snowmobile
- (92) Farm equipment other than trucks
- (93) Construction equipment other than trucks
- (97) Other vehicle type
- (99) Unknown body type

OCCUPANT RELATED

16. Driver Presence in Vehicle 1
 (0) Driver not present
 (1) Driver present
 (9) Unknown
17. Number of Occupants This Vehicle 3
 (00-96) Code actual number of occupants for this vehicle
 (97) 97 or more
 (99) Unknown
18. Number of Occupant Forms Submitted 3

VEHICLE WEIGHT ITEMS

19. Vehicle Curb Weight 1,680
 Code weight to nearest 10 kilograms.
 (045) Less than 450 kilograms
 (610) 6,100 kilograms or more
 (999) Unknown
3,695 lbs X .4536 = 1,676 kgs
 Source: [REDACTED]
20. Vehicle Cargo Weight 0
 Code weight to nearest 10 kilograms.
 (000) Less than 5 kilograms
 (450) 4,500 kilograms or more
 (999) Unknown
 _____ lbs X .4536 = _____ kgs

RECONSTRUCTION DATA

21. Towed Trailing Unit 0
 (0) No towed unit
 (1) Yes—towed trailing unit
 (9) Unknown
22. Documentation of Trajectory Data for This Vehicle 1
 (0) No
 (1) Yes
23. Post Collision Condition of Tree or Pole (For Highest Delta V) 0
 (0) Not collision (for highest delta V) with tree or pole
 (1) Not damaged
 (2) Cracked/sheared
 (3) Tilted < 45 degrees
 (4) Tilted ≥ 45 degrees
 (5) Uprooted tree
 (6) Separated pole from base
 (7) Pole replaced
 (8) Other (specify): _____
 (9) Unknown





































24. Rollover 0
 (0) No rollover (no overturning)
Rollover (primarily about the longitudinal axis)
 (1) Rollover, 1 quarter turn only
 (2) Rollover, 2 quarter turns
 (3) Rollover, 3 quarter turns
 (4) Rollover, 4 or more quarter turns (specify): _____
 (5) Rollover--end-over-end (i.e., primarily about the lateral axis)
 (9) Rollover (overturn), details unknown

OVERRIDE/UNDERRIDE (THIS VEHICLE)

25. Front Override/Underride (this Vehicle) 0
26. Rear Override/Underride (this Vehicle) 0
 (0) No override/underride, or not an end-to-end impact
Override (see specific CDC)
 (1) 1st CDC
 (2) 2nd CDC
 (3) Other not automated CDC (specify): _____
Underride (see specific CDC)
 (4) 1st CDC
 (5) 2nd CDC
 (6) Other not automated CDC (specify): _____
 (7) Medium/heavy truck or bus override
 (9) Unknown

HEADING ANGLE AT IMPACT FOR HIGHEST DELTA V

- Values: (000)-(359) Code actual value
 (997) Noncollision
 (998) Impact with object
 (999) Unknown
27. Heading Angle For This Vehicle 300
28. Heading Angle For Other Vehicle 210

Category	Configuration	ACCIDENT TYPES (Includes Intent)				
I. Single Driver	A. Right Roadside Departure	 01 DRIVE OFF ROAD	 02 CONTROL/ TRACTION LOSS	 03 AVOID COLLISION WITH VEH., PED., ANIM.	04 SPECIFICS OTHER	05 SPECIFICS UNKNOWN
	B. Left Roadside Departure	 06 DRIVE OFF ROAD	 07 CONTROL/ TRACTION LOSS	 08 AVOID COLLISION WITH VEH., PED., ANIM.	09 SPECIFICS OTHER	10 SPECIFICS UNKNOWN
	C. Forward Impact	 11 PARKED VEH.	 12 STA. OBJECT	 13 PEDESTRIAN/ ANIMAL	 14 END DEPARTURE	15 SPECIFICS OTHER 16 SPECIFICS UNKNOWN
II Same Trafficway Same Direction	D. Rear-End	 20 STOPPED 21, 22, 23	 22 SLOWER 24, 25, 26, 27	 26 DECEL. 28, 29, 30, 31	 30 SPECIFICS OTHER	 31 SPECIFICS UNKNOWN
	E. Forward Impact	 34 CONTROL/ TRACTION LOSS	 36 CONTROL/ TRACTION LOSS	 38 AVOID COLLISION WITH VEH.	 40 AVOID COLLISION WITH OBJECT	(EACH • 32) (EACH • 33) SPECIFICS OTHER SPECIFICS UNKNOWN
	F. Sideswipe Angle	 44 LATERAL MOVE	 46 LATERAL MOVE	(EACH • 48) SPECIFICS OTHER	(EACH • 49) SPECIFICS UNKNOWN	
III Same Trafficway Opposite Direction	G. Head-On	 50 LATERAL MOVE	(EACH • 52) SPECIFICS OTHER	(EACH • 53) SPECIFICS UNKNOWN		
	H. Forward Impact	 54 CONTROL/ TRACTION LOSS	 56 CONTROL/ TRACTION LOSS	 58 AVOID COLLISION WITH VEH.	 60 AVOID COLLISION WITH OBJECT	(EACH • 62) (EACH • 63) SPECIFICS OTHER SPECIFICS UNKNOWN
	I. Sideswipe Angle	 64 LATERAL MOVE	(EACH • 66) SPECIFICS OTHER	(EACH • 67) SPECIFICS UNKNOWN		
IV. Change Trafficway Vehicle Turning	J. Turn Across Path	 68 INITIAL OPPOSITE DIRECTIONS	 71 INITIAL SAME DIRECTIONS	 73 SPECIFICS OTHER	(EACH • 74) (EACH • 75) SPECIFICS UNKNOWN	
	K. Turn Into Path	 77 TURN INTO SAME DIRECTION	 79 TURN INTO OPPOSITE DIRECTIONS	 81 SPECIFICS OTHER	(EACH • 84) (EACH • 85) SPECIFICS UNKNOWN	
V. Intersecting Paths (Vehicle Damage)	L. Straight Paths	 86 SPECIFICS OTHER	 88 SPECIFICS UNKNOWN	(EACH • 90) SPECIFICS OTHER	(EACH • 91) SPECIFICS UNKNOWN	
VI. Miscellaneous	M. Backing Etc.	 92 BACKING VEH.	93 OTHER VEH. OR OBJECT	98 Other Accident Type 99 Unknown Accident Type 00 No Impact		

29. Basis for Total Delta V (highest) 1*Delta V Calculated*

- (1) CRASH program—damage only routine
- (2) CRASH program—damage and trajectory routine
- (3) Missing vehicle algorithm

Delta V Not Calculated

- (4) At least one vehicle (which may be this vehicle) is beyond the scope of an acceptable reconstruction program, regardless of collision conditions.
- (5) All vehicles within scope (CDC applicable) of CRASH program but one of the collision conditions is beyond the scope of the CRASH program or other acceptable reconstruction technique, regardless of adequacy of damage data.
- (6) All vehicle and collision conditions are within scope of one of the acceptable reconstruction programs, but there is insufficient data available.

Highest

32. Lateral Component of Delta V \oplus - 0 0 3(+ 0 0 2 mph)3.2 Nearest kph (highest)
(2.0 mph)999 Nearest kph (secondary)

(NOTE: __000 means greater than
-0.5 kph and less than +0.5 kph)
(±160) ±159.5 kph and above
(__999) Unknown

33. Energy Absorption 0 8 7 1 0 0(64,200 ft/lbs)87,076.3 Nearest 100 joules (highest)
(64,256 ft/lbs) Nearest 100 joules (secondary)

(NOTE: 0000 means less than 50 joules)
(9997) 999,650 joules or more
(9999) Unknown

COMPUTER GENERATED DELTA V

30. Total Delta V

Highest

37.2 Nearest kph (highest)
(23.1 mph)999 Nearest kph (secondary)

(NOTE: 000 means less than
0.5 kph)
(160) 159.5 kph and above
(999) Unknown

31. Longitudinal Component of Delta V \oplus - 0 3 737.1 Nearest kph (highest)
(23.0 mph)999 Nearest kph (secondary)

(NOTE: __000 means greater than
-0.5 kph and less than +0.5 kph)
(±160) ±159.5 kph and above
(__999) Unknown

34. Confidence In Reconstruction Program Results (For Highest Delta V) 1

- (0) No reconstruction
- (1) Collision fits model — results appear reasonable
- (2) Collision fits model — results appear high
- (3) Collision fits model — results appear low
- (4) Borderline reconstruction — results appear reasonable

35. Type of Vehicle Inspection 1

- (0) No inspection
- (1) Complete inspection
- (2) Partial inspection (specify):

36. Is this an AOPS Vehicle? 0

- (0) No
- (1) Yes - researcher determined
- (2) VIN determined air bag system
- (3) VIN determined automatic (passive) belts
- (4) VIN determined air bag and automatic (passive) belts

IS OLDMISS APPLICABLE FOR THIS VEHICLE? [] YES [X] NO

IF YES: IS A COMPLETED OLDMISS PROGRAM SUMMARY INCLUDED? [] YES [] NO

37. Police Reported Other Drug Presence ϕ

- (0) No other drug(s) present
- (1) Yes [other drug(s) present]
- (7) Not reported
- (8) No driver present
- (9) Unknown

38. Police Reported Drug Evaluation Classification (DEC) Test For Driver ϕ

- (0) No DEC process available or given
- (1) DEC process given, results known
- (2) DEC process given, results unknown
- (3) DEC process available, unknown if given
- (8) No driver present

39. Other Drug Specimen Test Type For Driver ϕ

- (0) No specimen test given
- (1) Blood test
- (2) Urine test
- (3) Other specimen tests (specify): _____
- (7) Unspecified specimen test
- (8) No driver present
- (9) Unknown if specimen test given

DRUG EVALUATION CLASSIFICATION

OTHER DRUGS TEST RESULTS FOR DRIVER

	DEC Test Results	Specimen Test Results
Narcotic Drug	40. <u> ϕ </u>	41. <u> ϕ </u>
Depressant Drug	42. <u> ϕ </u>	43. <u> ϕ </u>
Stimulant Drug	44. <u> ϕ </u>	45. <u> ϕ </u>
Hallucinogen Drug	46. <u> ϕ </u>	47. <u> ϕ </u>
Cannabinoid Drug	48. <u> ϕ </u>	49. <u> ϕ </u>
Phencyclidine (PCP)	50. <u> ϕ </u>	51. <u> ϕ </u>
Inhalant Drug	52. <u> ϕ </u>	53. <u> ϕ </u>
Other Drug (Excluding Nicotine, Aspirin, Alcohol, Drugs Administered Post-Crash)	54. <u> ϕ </u>	55. <u> ϕ </u>

Codes For DEC Test Results

- (0) No DEC test given
- (1) Passed DEC test
- (2) Failed DEC test
- (3) DEC test given—results unknown
- (8) No driver present
- (9) Unknown if DEC test given

Codes for Specimen Test Results

- (0) No specimen test given
- (1) Drug not found in specimen
- (2) Drug found in specimen
- (7) Specimen test given, results unknown or not obtained
- (8) No driver present
- (9) Unknown if specimen test given

OTHER DATA

56. Driver's Zip Code

- (00000) Driver not present
 (00001) Driver not a resident of U.S. or territories
 _____ Code actual 5-digit zip code
 (99999) Unknown

57. Driver's Race/Ethnic Origin

- (0) Driver not present
 (1) White (non-Hispanic)
 (2) Black (non-Hispanic)
 (3) White (Hispanic)
 (4) Black (Hispanic)
 (5) American Indian, Eskimo or Aleut
 (6) Asian or Pacific Islander
 (8) Other (specify): _____
 (9) Unknown

58. Vehicle Special Use (This Trip)

- (0) No special use
 (1) Taxi
 (2) Vehicle used as school bus
 (3) Vehicle used as other bus
 (4) Military
 (5) Police
 (6) Ambulance
 (7) Fire truck or car
 (8) Other (specify): _____
 (9) Unknown

ROLLOVER DATA

If GV07 (Body Type) \neq 1-49, leave GV59-GV63 blank.
 If GV24 (Rollover) = 0, then GV59-GV63 must equal 0.
 If GV24 = 9, then GV59-GV63 must equal 9.

59. Rollover Initiation Type

- (0) No rollover
 (1) Trip-over
 (2) Flip-over
 (3) Turn-over
 (4) Climb-over
 (5) Fall-over
 (6) Bounce-over
 (7) Collision with another vehicle
 (8) Other rollover initiation type specify): _____
 (9) Unknown rollover initiation type

60. Location of Rollover Initiation

- (0) No rollover
 (1) On roadway
 (2) On shoulder—paved
 (3) On shoulder—unpaved
 (4) On roadside or divided trafficway median
 (9) Unknown

61. Rollover Initiation Object Contacted

62. Location on Vehicle Where Initial Principal Tripping Force Is Applied

- (0) No rollover
 (1) Wheels/tires
 (2) Side plane
 (3) End plane
 (4) Undercarriage
 (5) Other location on vehicle (specify): _____
 (8) Non-contact rollover forces (specify): _____
 (9) Unknown

63. Direction of Initial Roll

- (0) No rollover
 (1) Roll right - primarily about the longitudinal axis
 (2) Roll left - primarily about the longitudinal axis
 (5) End-over-end (i.e., primarily about the lateral axis)
 (9) Unknown roll direction

PRECRASH DATA

64. Pre-Event Movement (Prior to Recognition of Critical Event)

- (01) Going straight
 (02) Slowing or stopping in traffic lane
 (03) Starting in traffic lane
 (04) Stopped in traffic lane
 (05) Passing or overtaking another vehicle
 (06) Disabled or parked in travel lane
 (07) Leaving a parking position
 (08) Entering a parking position
 (09) Turning right
 (10) Turning left
 (11) Making a U-turn
 (12) Backing up (other than for parking position)
 (13) Negotiating a curve
 (14) Changing lanes
 (15) Merging
 (16) Successful avoidance maneuver to a previous critical event
 (97) Other (specify): _____
 (98) No driver present
 (99) Unknown

CODES FOR ROLLOVER INITIATION OBJECT CONTACTED

- (00) No rollover
- (01-30) — Vehicle Number

Noncollision

- (31) Turn-over — fall-over
- (33) Jackknife

Collision With Fixed Object

- (41) Tree (≤ 10 cm in diameter)
- (42) Tree (> 10 cm in diameter)
- (43) Shrubbery or bush
- (44) Embankment

- (45) Breakaway pole or post (any diameter)

Nonbreakaway Pole or Post

- (50) Pole or post (≤ 10 cm in diameter)
- (51) Pole or post (> 10 cm but ≤ 30 cm in diameter)
- (52) Pole or post (> 30 cm in diameter)
- (53) Pole or post (diameter unknown)

- (54) Concrete traffic barrier
- (55) Impact attenuator
- (56) Other traffic barrier (includes guardrail)
(specify): _____

- (57) Fence
- (58) Wall
- (59) Building
- (60) Ditch or culvert
- (61) Ground
- (62) Fire hydrant
- (63) Curb
- (64) Bridge
- (68) Other fixed object (specify): _____

- (69) Unknown fixed object

Collision with Nonfixed Object

- (71) Motor vehicle not in-transport
- (76) Animal
- (77) Train
- (78) Trailer, disconnected in transport
- (79) Object fell from vehicle in-transport
- (88) Other nonfixed object (specify): _____

- (89) Unknown nonfixed object

- (98) Other event (specify): _____

- (99) Unknown event or object

PRECRASH DATA (Continued)

65. Critical Precrash Event 62*This Vehicle Loss of Control Due To:*

- (01) Blow out or flat tire
- (02) Stalled engine
- (03) Disabling vehicle failure (e.g., wheel fell off)
(specify): _____
- (04) Non-disabling vehicle problem (e.g., hood flew up) (specify): _____
- (05) Poor road conditions (puddle, pot hole, ice, etc.)
(specify): _____
- (06) Traveling too fast for conditions
- (08) Other cause of control loss (specify): _____
- (09) Unknown cause of control loss

This Vehicle Traveling

- (10) Over the lane line on left side of travel lane
- (11) Over the lane line on right side of travel lane
- (12) Off the edge of the road on the left side
- (13) Off the edge of the road on the right side
- (14) End departure
- (15) Turning left at intersection
- (16) Turning right at intersection
- (17) Crossing over (passing through) intersection
- (19) Unknown travel direction

Other Motor Vehicle In Lane

- (50) Stopped
- (51) Traveling in same direction with lower speed
(i.e., lower steady speed or decelerating)
- (52) Traveling in same direction with higher speed
- (53) Traveling in opposite direction
- (54) In crossover
- (55) Backing
- (59) Unknown travel direction of other motor vehicle in lane

Other Motor Vehicle Encroaching Into Lane

- (60) From adjacent lane (same direction)—over left lane line
- (61) From adjacent lane (same direction)—over right lane line
- (62) From opposite direction—over left lane line
- (63) From opposite direction—over right lane line
- (64) From parking lane
- (65) From crossing street, turning into same direction
- (66) From crossing street, across path
- (67) From crossing street, turning into opposite direction
- (68) From crossing street, intended path not known
- (70) From driveway, turning into same direction
- (71) From driveway, across path
- (72) From driveway, turning into opposite direction
- (73) From driveway, intended path not known
- (74) From entrance to limited access highway
- (78) Encroachment by other vehicle—details unknown

Pedestrian or Pedalcyclist, or Other Nonmotorist

- (80) Pedestrian in roadway
- (81) Pedestrian approaching roadway
- (82) Pedestrian—unknown location
- (83) Pedalcyclist or other nonmotorist in roadway
(specify): _____
- (84) Pedalcyclist or other nonmotorist approaching roadway (specify): _____
- (85) Pedalcyclist or other nonmotorist—unknown location (specify): _____

Object or Animal

- (87) Animal in roadway
- (88) Animal approaching roadway
- (89) Animal—unknown location
- (90) Object in roadway
- (91) Object approaching roadway
- (92) Object—unknown location
- (98) Other critical precrash event (specify): _____
- (99) Unknown

For Corrective Actions Attempted see variable GV14
(Attempted Avoidance Manuever)

66. Precrash Stability After Avoidance Maneuver 6

- (0) No avoidance maneuver
- (1) Tracking
- (2) Skidding longitudinally—rotation less than 30 degrees
- (3) Skidding laterally—clockwise rotation
- (4) Skidding laterally—counterclockwise rotation
- (7) Other vehicle loss-of-control (specify): _____
- (8) No driver present
- (9) Precrash stability unknown

67. Precrash Directional Consequences of Avoidance Maneuver (Corrective Action) 6

- (0) No avoidance maneuver
- (1) Vehicle stayed in travel lane where avoidance maneuver was initiated
- (2) Vehicle stayed on roadway but left travel lane where avoidance maneuver was initiated
- (3) Vehicle stayed on roadway, not known if left travel lane where avoidance maneuver was initiated
- (4) Vehicle departed roadway
- (5) Avoidance maneuver initiated off roadway
- (8) No driver present
- (9) Directional consequences unknown

*** IF THE CDS APPLICABLE VEHICLE WAS NOT INSPECTED (I.E., GV35 = 0), ***
DO NOT COMPLETE THE EXTERIOR AND INTERIOR VEHICLE FORMS.

*** IF GV07 DOES NOT EQUAL 01-49, DO NOT COMPLETE ***
THE EXTERIOR VEHICLE, INTERIOR VEHICLE,
OCCUPANT ASSESSMENT, AND OCCUPANT INJURY FORMS.



EXTERIOR VEHICLE FORM

1. Primary Sampling Unit Number _____	3. Vehicle Number <u>02</u>
2. Case Number - Stratum <u>DSI-94-AB-006</u>	

VEHICLE IDENTIFICATION

VIN J T 4 V N 1 3 G 7 M 5 -x-x-x-x-x-x-x Model Year 9 1
 Vehicle Make (specify): TOYOTA Vehicle Model (specify): SA5 4x4 PICKUP

LOCATOR

Locate the end of the damage with respect to the vehicle longitudinal center line or bumper corner for end impacts or an undamaged axle for side impacts.

Specific Impact No.	Location of Direct Damage	Location of Field L
<u>01</u>	<u>BEGINS LEFT FRONT BUMPER CORNER</u>	<u>FULL FRONTAL</u>
<u>02</u>	<u>L. SIDE AT L. REAR BUMPER CORNER</u>	<u>NOT MEASURED - CDC ONLY</u>

CRUSH PROFILE IN CENTIMETERS

NOTES: Identify the plane at which the C-measurements are taken (e.g., at bumper, above bumper, at sill, above sill, etc.) and label adjustments (e.g., free space).

Measure and document on the vehicle diagram the location of maximum crush.

Measure C1 to C6 from driver to passenger side in front or rear impacts and rear to front in side impacts.

Free space value is defined as the distance between the baseline and the original body contour taken at the individual C locations. This may include the following: bumper lead, bumper taper, side protrusion, side taper, etc. Record the value for each C-measurement and maximum crush.

Use as many lines/columns as necessary to describe each damage profile.

Specific Impact Number	Plane of Impact C-Measurements	Direct Damage		Field L	C ₁	C ₂	C ₃	C ₄	C ₅	<u>PULLED</u> C ₆	± D	
		Width (CDC)	Max Crush									
01	FRONT BUMPER	75.0	85.1	124.0	85.1	51.1	32.2	18.9	8.0	2.8	-44.0	
	- FREE SPACE		8.0		8.0	4.0	0	0	4.0	8.0		
	RESULTANT		77.1		77.1	47.1	32.2	18.9	4.0	0		
			@ C ₁									
02	L/R BUMPER CORNER	17.0	4.0		NOT MEASURED - CDC ONLY - ZONE 1							
				U.S. EQUIVALENTS								
01	FRONT BUMPER	29.5"	33.5"	48.8"	33.5"	20.1"	12.7"	7.4"	3.1"	1.1"	-15.8"	
	- FREE SPACE		3.1"		3.1"	1.6"	0	0	1.6"	3.1"		
	RESULTANT		30.4"		30.4"	18.5"	12.7"	7.4"	1.5"	0		
			@ C ₁									
02	L/R BUMPER CORNER	6.7"	1.6"		NOT MEASURED - CDC ONLY - ZONE 1							


ORIGINAL SPECIFICATIONS WORK SHEET

Wheelbase	<u>1</u> <u>2</u> <u>2</u> . <u>0</u> inches	x 2.54 =	<u>3</u> <u>1</u> <u>0</u> cm
Overall Length	<u>2</u> <u>0</u> <u>0</u> . <u>0</u> inches	x 2.54 =	<u>5</u> <u>0</u> <u>8</u> cm
Maximum Width	<u>0</u> <u>6</u> <u>6</u> . <u>5</u> inches	x 2.54 =	<u>1</u> <u>6</u> <u>9</u> cm
Curb Weight	<u>0</u> <u>3</u> , <u>6</u> <u>9</u> <u>5</u> pounds	x .4536 =	<u>1</u> . <u>6</u> <u>7</u> <u>6</u> kg
Average Track	<u>0</u> <u>6</u> <u>5</u> . <u>5</u> inches	x 2.54 =	<u>1</u> <u>6</u> <u>6</u> cm
Front Overhang	<u>0</u> <u>2</u> <u>9</u> . <u>5</u> inches	x 2.54 =	<u>0</u> <u>7</u> <u>5</u> cm
Rear Overhang	<u>0</u> <u>4</u> <u>8</u> . <u>4</u> inches	x 2.54 =	<u>1</u> <u>2</u> <u>3</u> cm
Undeformed End Width	<u>0</u> <u>6</u> <u>1</u> . <u>4</u> inches	x 2.54 =	<u>1</u> <u>5</u> <u>6</u> cm
Engine Size: cyl./displ.	<u>3</u> <u>0</u> <u>0</u> <u>0</u> cc	x .001 =	<u>3</u> . <u>0</u> L
	<u>1</u> <u>8</u> <u>3</u> CID	x .0164 =	<u>3</u> . <u>0</u> L





VEHICLE DAMAGE SKETCH

TIRE—WHEEL DAMAGE a. Rotation physically restricted RF <u>2</u> LF <u>1</u> RR <u>2</u> LR <u>2</u> (1) Yes (2) No (8) NA (9) Unk.		b. Tire deflated RF <u>2</u> LF <u>1</u> RR <u>2</u> LR <u>2</u>		ORIGINAL SPECIFICATIONS Wheelbase <u>314</u> cm Overall Length <u>568</u> cm Maximum Width <u>169</u> cm Curb Weight <u>1,676</u> kg Average Track _____ cm Front Overhang <u>75</u> cm Rear Overhang <u>123</u> cm Undeformed End Width <u>156</u> cm Engine Size: cyl./displ. <u>V6/3.0</u> L		WHEEL STEER ANGLES (For locked front wheels or displaced rear axles only) RF \pm _____ ° LF \pm <u>0</u> ° RR \pm _____ ° LR \pm <u>7</u> ° Within \pm 5 degrees	
TYPE OF TRANSMISSION <input checked="" type="checkbox"/> Manual <input type="checkbox"/> Automatic				DRIVE WHEELS <input type="checkbox"/> FWD <input type="checkbox"/> RWD <input checked="" type="checkbox"/> 4WD			
				Approximate Cargo Weight <u>0</u> kg			

GAUGE STANDS ADJ.



MEASUREMENTS IN CENTIMETERS



END SHET
LEFT
> 10 cm
(4.0")

NOTES: Sketch new perimeter and cross hatch direct damage and single hatch induced damage on all views. Annotate observations which might be useful in reconstructing the accident (e.g., grass in tire bead, direction of striations, scuff on sidewalls, etc.). If pulling trailer, sketch type of trailer and damage received on the back of this page.

Annotate any damage caused by extrication such as component removal by torching, prying, or hydraulic shears.

CODES FOR OBJECT CONTACTED

(99) Unknown event or object

[illegible]

COLLISION DEFORMATION CLASSIFICATION

HIGHEST DELTA "V"

Accident Event Sequence Number	Object Contacted	(1) (2) Direction of Force	(3) Deformation Location	(4) Longitudinal or Lateral Location	(5) Vertical or Lateral Location	(6) Type of Damage Distribution	(7) Deformation Extent
4. <u>φ 1</u>	5. <u>φ 1</u>	6. <u>9 2</u>	7. <u>F</u>	8. <u>Y</u>	9. <u>E</u>	10. <u>W</u>	11. <u>φ 4</u>

Second Highest Delta "V"

12. <u>φ 2</u>	13. <u>φ 3</u>	14. <u>φ 9</u>	15. <u>L</u>	16. <u>B</u>	17. <u>L</u>	18. <u>E</u>	19. <u>φ 1</u>
----------------	----------------	----------------	--------------	--------------	--------------	--------------	----------------

CRUSH PROFILE IN CENTIMETERS

The crush profile for the damage described in the CDC(s) above should be documented in the appropriate space below. (ALL MEASUREMENTS ARE IN CENTIMETERS.)

HIGHEST DELTA "V"

20. <u>L</u>	21. <u>C₁</u>	<u>C₂</u>	<u>C₃</u>	<u>C₄</u>	<u>C₅</u>	<u>C₆</u>	22. <u>± D</u>
<u>1 5 6</u> (6")	<u>φ 7 7</u> (3φ")	<u>φ 4 7</u> (19")	<u>φ 3 2</u> (13")	<u>φ 1 9</u> (67")	<u>φ φ 4</u> (42")	<u>φ φ φ</u> (4)	<u>⊖ φ 4 φ</u> (-16")

Second Highest Delta "V"

23. <u>L</u>	24. <u>C₁</u>	<u>C₂</u>	<u>C₃</u>	<u>C₄</u>	<u>C₅</u>	<u>C₆</u>	25. <u>± D</u>
<u>NOT MEASURED - CDC ONLY ZONE 1</u>							<u>+</u> <u>-</u>

26. Are CDCs Documented but Not Coded on The Automated File? φ
(0) No
(1) Yes

27. Researcher's Assessment of Vehicle Disposition 1
(0) Not towed due to vehicle damage
(1) Towed due to vehicle damage
(9) Unknown

28. Original Wheelbase 3 1 φ
Code to the nearest centimeter
(999) Unknown

1 2 2 . φ inches X 2.54 = 3 1 φ centimeters

29. Is This A Multi-Stage Manufactured Vehicle
And/Or A Certified Altered Vehicle? φ

- (0) No post manufacturer modifications
(1) Yes - post manufacturer modifications
(specify): _____

(Include photograph of CERTIFICATION
PLACARD in case report)

(9) Unknown if vehicle is modified

30. Fire Occurrence φ

(0) No fire

Yes, fire occurred

- (1) Minor
(2) Major
(9) Unknown

31. Origin of Fire φ

- (0) No fire
(1) Vehicle exterior (front, side, back, top)
(2) Exhaust system
(3) Fuel tank (and other fuel retention
system parts)
(4) Engine compartment
(5) Cargo/trunk compartment
(6) Instrument panel
(7) Passenger compartment area
(8) Other location (specify): _____

(9) Unknown

32. Type of Fuel Tank-1 1

33. Type of Fuel Tank-2 φ

- (0) No fuel tank (electrical vehicle)
(1) Metallic
(2) Non-metallic
(9) Unknown

34. Fuel Tank-1 Location 4

35. Fuel Tank-2 Location φ

- (0) No fuel tank
(1) Aft of center of the rear wheels (rear axle)
centered
(2) Aft of center of the rear wheels (rear axle) left
side
(3) Aft of center of the rear wheels (rear axle)
right side
(4) Forward of center of the rear wheels (rear
axle) centered
(5) Forward of center of the rear wheels (rear
axle) left side
(6) Forward of center of the rear wheels (rear
axle) right side
(7) Over center of the rear wheels (rear axle)
(8) Other (specify): _____
(9) Unknown

36. Fuel Tank-1 Filler Cap Location 5

37. Fuel Tank-2 Filler Cap Location φ

- (0) No fuel tank
(1) On back plane
(2) Aft of center of the rear wheels (rear axle) on
left side plane
(3) Aft of center of the rear wheels (rear axle) on
right side plane
(4) Forward of center of the rear wheels (rear
axle) on left side plane
(5) Forward of center of the rear wheels (rear
axle) on right side plane
(6) Over the center of the rear wheels (rear axle)
on left side plane
(7) Over the center of the rear wheels (rear axle)
on right side plane
(8) Other (specify): _____
(9) Unknown

38. Fuel Tank-1 Damage 1

39. Fuel Tank-2 Damage φ

- (0) No fuel tank
(1) No damage to fuel tank
(2) Deformed, no seam failure
(3) Deformed, with a seam failure
(4) Punctured
(5) Lacerated (ripped)
(6) Abraded (scraped)
(7) Filler neck separation from the fuel tank
(8) Other damage (specify): _____
(9) Unknown

<p>40. Location of Fuel System-1 Leakage <u> 1 </u></p> <p>41. Location of Fuel System-2 Leakage <u> 0 </u></p> <p style="padding-left: 20px;">(0) No fuel tank</p> <p style="padding-left: 20px;">(1) No fuel leakage</p> <p style="padding-left: 20px;"><i>Primary Area Of Leakage</i></p> <p style="padding-left: 20px;">(2) Tank</p> <p style="padding-left: 20px;">(3) Filler neck</p> <p style="padding-left: 20px;">(4) Cap</p> <p style="padding-left: 20px;">(5) Lines/pump/filter</p> <p style="padding-left: 20px;">(6) Vent/emission recovery</p> <p style="padding-left: 20px;">(8) Other (specify): _____</p> <p style="padding-left: 20px;">(9) Unknown _____</p> <p>42. Fuel Type-1 <u> 0 1 </u></p> <p>43. Fuel Type-2 <u> 0 0 </u></p> <p style="padding-left: 20px;"><i>Single Fuel Type</i></p> <p style="padding-left: 20px;">(00) No fuel tank</p> <p style="padding-left: 20px;">(01) Gasoline</p> <p style="padding-left: 20px;">(02) Diesel</p> <p style="padding-left: 20px;">(03) CNG (Compressed Natural Gas)</p> <p style="padding-left: 20px;">(04) LPG (Liquid Petroleum Gas) also known as Propane</p> <p style="padding-left: 20px;">(05) LNG (Liquid Natural Gas)</p> <p style="padding-left: 20px;">(06) Methanol (M100 or M85)</p> <p style="padding-left: 20px;">(07) Ethanol (E100 or E85)</p> <p style="padding-left: 20px;">(08) Other (Hydrogen or others) (specify): _____</p> <p style="padding-left: 20px;"><i>Electric Powered or Electric/Solar Powered Vehicles</i></p> <p style="padding-left: 20px;">(10) Lead Acid Battery</p> <p style="padding-left: 20px;">(11) Nickel-Iron Battery</p> <p style="padding-left: 20px;">(12) Nickel-Cadmium Battery</p> <p style="padding-left: 20px;">(13) Sodium Metal Chloride Battery</p> <p style="padding-left: 20px;">(14) Sodium Sulfur Battery</p> <p style="padding-left: 20px;">(18) Other (Specify): _____</p> <p style="padding-left: 20px;">(98) Other Hybrid (specify): _____</p> <p style="padding-left: 20px;">(99) Unknown fuel type</p>	<p>44. Is This Vehicle Equipped With More Than Two Fuel Tanks? <u> 0 </u></p> <p style="padding-left: 20px;">(0) No (one or two tanks only)</p> <p style="padding-left: 20px;"><i>Yes - More Than Two Tanks</i></p> <p style="padding-left: 20px;">(1) Yes -- <u>no damage</u> to any tank or filler cap and <u>no fuel system leakage</u></p> <p style="padding-left: 20px;">(2) Yes -- <u>no damage</u> to any tank or filler cap but <u>there is fuel system leakage</u> (specify leakage location): _____</p> <p style="padding-left: 20px;">(3) Yes -- <u>damage</u> to an additional tank or filler cap and <u>there is fuel system leakage</u> (specify the following):</p> <p style="padding-left: 40px;">Type of tank _____</p> <p style="padding-left: 40px;">Tank location _____</p> <p style="padding-left: 40px;">Filler cap location _____</p> <p style="padding-left: 40px;">Tank damage _____</p> <p style="padding-left: 40px;">Location of leakage _____</p> <p style="padding-left: 40px;">Type of fuel _____</p> <p style="padding-left: 20px;">(9) Unknown if more than two tanks</p> <div style="text-align: center; border: 1px solid black; padding: 10px; min-height: 200px;"> <p>COMMENTS</p> <p>_____</p> <p>_____</p> <p>_____</p> <p>_____</p> <p>_____</p> <p>_____</p> <p>_____</p> <p>_____</p> <p>_____</p> </div>
--	---

*** STOP: IF THE CDS APPLICABLE VEHICLE WAS NOT TOWED AND WAS NOT AN AOPS ***

(I.E., GV09 = 0 OR 9 AND GV36 = 0), DO NOT COMPLETE THE INTERIOR VEHICLE FORM.



INTERIOR VEHICLE FORM

1. Primary Sampling Unit Number _____

2. Case Number - Stratum DSI-24-AB-0063. Vehicle Number 02

INTEGRITY

4. Passenger Compartment Integrity 06
(00) No integrity loss

Yes, Integrity Was Lost Through

- (01) Windshield
(02) Door (side)
(03) Door/hatch (back door)
(04) Roof
(05) Roof glass
(06) Side window
(07) Rear window (backlight)
(08) Roof and roof glass
(09) Windshield and door (side)
(10) Windshield and roof
(11) Side and rear window (side window and backlight)
(12) Windshield and side window
(13) Door and side window
(98) Other combination of above (specify):

(99) Unknown

Door, Tailgate or Hatch Opening

5. LF 3 6. RF 3 7. LR 0 8. RR 0 9. TG/H 0

- (0) No door/gate/hatch
(1) Door/gate/hatch remained closed and operational
(2) Door/gate/hatch came open during collision
(3) Door/gate/hatch jammed shut
(8) Other (specify):

(9) Unknown

Damage/Failure Associated with Door, Tailgate or Hatch
Opening in Collision. If IV05-IV09 \neq 2, Then code 010. LF 0 11. RF 0 12. LR 0 13. RR 0 14. TG/H 0

- (0) No door/gate/hatch or door not opened

Door, Tailgate or Hatch Came Open During Collision

- (1) Door operational (no damage)
(2) Latch/striker failure due to damage
(3) Hinge failure due to damage
(4) Door structure failure due to damage
(5) Door support (i.e., pillar, sill, roof side rail,
etc.) failure due to damage
(6) Latch/striker and hinge failure due to damage
(8) Other failure (specify):

(9) Unknown

GLAZING

Glazing Damage from Impact Forces

15. WS 2 16. LF 6 17. RF 6 18. LR 0 19. RR 0
20. BL 0 21. Roof 0 22. Other 0

- (0) No glazing damage from impact forces
(2) Glazing in place and cracked from impact forces
(3) Glazing in place and holed from impact forces
(4) Glazing out-of-place (cracked or not) and not holed from
impact forces
(5) Glazing out-of-place and holed from impact forces
(6) Glazing disintegrated from impact forces
(7) Glazing removed prior to accident
(8) No glazing
(9) Unknown if damaged

Glazing Damage from Occupant Contact

23. WS 0 24. LF 0 25. RF 0 26. LR 0 27. RR 0
28. BL 0 29. Roof 0 30. Other 0

- (0) No occupant contact to glazing or no glazing
(1) Glazing contacted by occupant but no glazing damage
(2) Glazing in place and cracked by occupant contact
(3) Glazing in place and holed by occupant contact
(4) Glazing out-of-place (cracked or not) by occupant
contact and not holed by occupant contact
(5) Glazing out-of-place by occupant contact and holed by
occupant contact
(6) Glazing disintegrated by occupant contact
(9) Unknown if contacted by occupant

If No Glazing Damage *And* No Occupant Contact or No
Glazing, Then Code IV31 Through IV46 As 0

Type of Window/Windshield Glazing

31. WS 1 32. LF 2 33. RF 2 34. LR 0 35. RR 0
36. BL 0 37. Roof 0 38. Other 0

- (0) No glazing contact and no damage, or no glazing
(1) AS-1 — Laminated
(2) AS-2 — Tempered
(3) AS-3 — Tempered-tinted
(4) AS-14 — Glass/Plastic
(8) Other (specify):

(9) Unknown


Window Precrash Glazing Status

39. WS 1 40. LF 2 41. RF 2 42. LR 0 43. RR 0
44. BL 0 45. Roof 0 46. Other 0

- (0) No glazing contact and no damage, or no glazing
(1) Fixed
(2) Closed
(3) Partially opened
(4) Fully opened
(9) Unknown

INTRUSION WORKSHEET

Note: Sketch intruded areas

[illegible]

Document no more than the 15 most severe intrusions

OCCUPANT AREA INTRUSION

Note: If no intrusions, leave variables IV47-IV86 blank.

INTRUDING COMPONENT

Interior Components

- (01) Steering assembly
- (02) Instrument panel left
- (03) Instrument panel center
- (04) Instrument panel right
- (05) Toe pan
- (06) A (A1/A2)-pillar
- (07) B-pillar
- (08) C-pillar
- (09) D-pillar
- (10) Door panel (side)
- (12) Roof (or convertible top)
- (13) Roof side rail
- (14) Windshield
- (15) Windshield header
- (16) Window frame
- (17) Floor pan (includes sill)
- (18) Backlight header
- (19) Front seat back
- (20) Second seat back
- (21) Third seat back
- (22) Fourth seat back
- (23) Fifth seat back
- (24) Seat cushion
- (25) Back door/panel (e.g., tailgate)
- (26) Other interior component (specify):

- (27) Side panel - forward of the A (A2)-pillar
- (28) Side panel - rear of the A (A2)-pillar

Exterior Components

- (30) Hood
- (31) Outside surface of this vehicle (specify):
- (32) Other exterior object in the environment (specify):
- (33) Unknown exterior object
- (97) Catastrophic
- (98) Intrusion of unlisted component(s) (specify):
- (99) Unknown

LOCATION OF INTRUSION

Front Seat

- (11) Left
- (12) Middle
- (13) Right

Fourth Seat

- (41) Left
- (42) Middle
- (43) Right

Second Seat

- (21) Left
- (22) Middle
- (23) Right

- (97) Catastrophic
- (98) Other enclosed area (specify)

(99) Unknown

Third Seat

- (31) Left
- (32) Middle
- (33) Right

MAGNITUDE OF INTRUSION

- (1) ≥ 3 centimeters but < 8 centimeters
- (2) ≥ 8 centimeters but < 15 centimeters
- (3) ≥ 15 centimeters but < 30 centimeters
- (4) ≥ 30 centimeters but < 46 centimeters
- (5) ≥ 46 centimeters but < 61 centimeters
- (6) ≥ 61 centimeters
- (7) Catastrophic
- (9) Unknown













DOMINANT CRUSH DIRECTION

- (1) Vertical
- (2) Longitudinal
- (3) Lateral
- (7) Catastrophic
- (9) Unknown

STEERING RIM/SPOKE DEFORMATION

(All Measurements Are in Centimeters)

COMPARISON VALUE — DAMAGE VALUE = DEFORMATION

	—		=	
	—		=	
0	—	0	=	0
	—		=	
	—		=	

STEERING COLUMN87. Steering Column Type 2

- (1) Fixed column
 (2) Tilt column
 (3) Telescoping column
 (4) Tilt and telescoping column
 (8) Other column type (specify): _____

(9) Unknown

88. Blank X X

(This variable is left blank so that numbering consistency can be maintained with the 1988-94 CDS.

89. Blank X X X

(This variable is left blank so that numbering consistency can be maintained with the 1988-94 CDS.

90. Blank X X X

(This variable is left blank so that numbering consistency can be maintained with the 1988-94 CDS.

91. Blank X X X

(This variable is left blank so that numbering consistency can be maintained with the 1988-94 CDS.

92. Steering Rim/Spoke Deformation φ φ

Code actual measured

deformation to the nearest centimeter

- (00) No steering rim deformation
 (01-14) Actual measured value in centimeters
 (15) 15 centimeters or more
 (98) Observed deformation cannot be measured
 (99) Unknown


93. Location of Steering Rim/Spoke Deformation φ φ*Quarter Sections*

- (01) Section A
 (02) Section B
 (03) Section C
 (04) Section D

Half Sections

- (05) Upper half of rim/spoke
 (06) Lower half of rim/spoke
 (07) Left half of rim/spoke
 (08) Right half of rim/spoke

- (09) Complete steering wheel collapse
 (10) Undetermined location
 (99) Unknown

**INSTRUMENT PANEL**94. Odometer Reading φ 5 φ,000

_____kilometers—Code to the nearest 1,000 kilometers

- (000) No odometer
 (001) Less than 1,500 kilometers
 (500) 499,500 kilometers or more
 (999) Unknown

φ 3 1 1 2 2 miles X 1.6093 = φ 5 φ φ 8 5 kilometers

Source: INSPECTION95. Instrument Panel Damage from Occupant Contact? φ

- (0) No
 (1) Yes
 (9) Unknown

96. Knee Bolsters Deformed from Occupant Contact? 8


- (0) No
 (1) Yes
 (8) Not present
 (9) Unknown

97. Did Glove Compartment Door Open During Collision(s)? φ

- (0) No
 (1) Yes
 (8) Not present
 (9) Unknown

VEHICLE INTERIOR SKETCHES

Note area of ejection/entrapment



Sketch windshield contact(s) and the damaged area(s) on the instrument panel outline (e.g., radio, glove compartment, damage to instrument panel structure).

Cross hatch contact points, draw spider webs or use other annotation as may be appropriate.

Annotate the contacted area with a letter (begin with A) and list on the Points of Occupant Contact page.

POINTS OF OCCUPANT CONTACT

Contact	Interior Component Contacted	Occupant No. If Known	Body Region If Known	Supporting Physical Evidence	Confidence Level of Contact Point
A	59	01	R. & L. FEET	DEFORMATION	1
B					
C					
D					
E					
F					
G					
H					
I					
J					
K					
L					
M					
N					

CODES FOR INTERIOR COMPONENTS

FRONT

- (01) Windshield
- (02) Mirror
- (03) Sunvisor
- (04) Steering wheel rim
- (05) Steering wheel hub/spoke
- (06) Steering wheel (combination of codes 04 and 05)
- (07) Steering column, transmission selector lever, other attachment
- (08) Add on equipment (e.g., CB, tape deck, air conditioner)
- (09) Left instrument panel and below
- (10) Center instrument panel and below
- (11) Right instrument panel and below
- (12) Glove compartment door
- (13) Knee bolster
- (14) Windshield including one or more of the following: front header, A (A1/A2)-pillar, instrument panel, mirror, or steering assembly (driver side only)
- (15) Windshield including one or more of the following: front header, A (A1/A2)-pillar, instrument panel, or mirror (passenger side only)
- (16) Driver side air bag compartment cover
- (17) Passenger side air bag compartment cover
- (18) Windshield reinforced by exterior object (specify): _____
- (19) Other front object (specify): _____

LEFT SIDE

- (20) Left side interior surface, excluding hardware or armrests
- (21) Left side hardware or armrest
- (22) Left A (A1/A2)-pillar

(23) Left B-pillar

(24) Other left pillar (specify): _____

- (25) Left side window glass or frame
- (26) Left side window glass including one or more of the following: frame, window sill, A (A1/A2)-pillar, B-pillar, or roof side rail.
- (27) Other left side object (specify): _____
- (28) Left side window sill

RIGHT SIDE

- (30) Right side interior surface, excluding hardware or armrests
- (31) Right side hardware or armrest
- (32) Right A (A1/A2)-pillar
- (33) Right B-pillar
- (34) Other right pillar (specify): _____
- (35) Right side window glass or frame
- (36) Right side window glass including one or more of the following: frame, window sill, A (A1/A2)-pillar, B pillar, or roof side rail.
- (37) Other right side object (specify): _____
- (38) Right side window sill

INTERIOR

- (40) Seat, back support
- (41) Belt restraint webbing/buckle
- (42) Belt restraint B-pillar attachment point
- (43) Other restraint system component (specify): _____
- (44) Head restraint system
- (45) Air bag (use codes "16" and "17" for injuries sustained from air bag compartment covers)

(46) Other occupants (specify): _____

(47) Interior loose objects

(48) Child safety seat (specify): _____

(49) Other interior object (specify): _____

ROOF

- (50) Front header
- (51) Rear header
- (52) Roof left side rail
- (53) Roof right side rail
- (54) Roof or convertible top

FLOOR

- (56) Floor (including toe pan)
- (57) Floor or console mounted transmission lever, including console
- (58) Parking brake handle
- (59) Foot controls including parking brake

REAR

- (60) Backlight (rear window)
- (61) Backlight storage rack, door, etc.
- (62) Other rear object (specify): _____

CONFIDENCE LEVEL OF CONTACT POINT

- (1) Certain
- (2) Probable
- (3) Possible
- (9) Unknown

AUTOMATIC RESTRAINTS

NOTES: Encode the data for each applicable front seat position. The attribute for the variables may be found below. Restraint systems should be assessed during the vehicle inspection then coded on the Occupant Assessment Form.

AIR BAGS

		Left	Right
F I R S T	Availability/Function	ϕ	ϕ
	Deployment	ϕ	ϕ
	Failure	ϕ	ϕ

Air Bag System Availability/Function

- (0) Not equipped/not available
(1) Air bag

Non-functional

- (2) Air bag disconnected (specify):

(3) Air bag not reinstalled
(9) Unknown

Air Bag System Deployment

- (0) Not equipped/not available
(1) Air bag deployed during accident (as a result of impact)
(2) Air bag deployed inadvertently just prior to accident
(3) Air bag deployed, accident sequence undetermined
(4) Nondeployed
(5) Unknown if deployed
(6) Air bag deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)
(9) Unknown

Are There Indications of Air Bag System Failure?

- (0) Not equipped/not available
(1) No
(2) Yes (specify):

(9) Unknown

AUTOMATIC BELTS

		Left	Right
F I R S T	Availability/Function	ϕ	ϕ
	Use	ϕ	ϕ
	Type	ϕ	ϕ
	Proper Use	ϕ	ϕ
	Failure Modes	ϕ	ϕ

Automatic (Passive) Belt System Availability/Function

- (0) Not equipped/not available
(1) 2 point automatic belts
(2) 3 point automatic belts
(3) Automatic belts - type unknown

Non-functional

- (4) Automatic belts destroyed or rendered inoperative
(9) Unknown

Automatic (Passive) Belt System Use

- (0) Not equipped/not available/destroyed or rendered inoperative
(1) Automatic belt in use
(2) Automatic belt not in use (manually disconnected, motorized track inoperative)
(3) Automatic belt use unknown
(9) Unknown

Automatic (Passive) Belt System Type

- (0) Not equipped/not available
(1) Non-motorized system
(2) Motorized system
(9) Unknown

Proper Use of Automatic (Passive) Belt System

- (0) Not equipped/not available/not used
(1) Automatic belt used properly
(2) Automatic belt used properly with child safety seat

Automatic Belt Used Improperly

- (3) Automatic shoulder belt worn under arm
(4) Automatic shoulder belt worn behind back
(5) Automatic belt worn around more than one person
(6) Lap portion of automatic belt worn on abdomen
(7) Automatic lap and shoulder belt or automatic shoulder belt used improperly with child safety seat (specify):

(8) Other improper use of automatic belt system (specify):

(9) Unknown

Automatic (Passive) Belt Failure Modes During Accident

- (0) Not equipped/not available/not in use
(1) No automatic belt failure(s)
(2) Torn webbing (stretched webbing not included)
(3) Broken buckle or latchplate
(4) Upper anchorage separated
(5) Other anchorage separated (specify):

(6) Broken retractor
(7) Combination of above (specify):

(8) Other automatic belt failure (specify):

(9) Unknown

MANUAL RESTRAINTS

NOTES: Encode the applicable data for each seat position in the vehicle. The attribute for the variable may be found below. Restraint systems should be assessed during the vehicle inspection then coded on the Occupant Assessment Form.

If a Child safety seat is present, encode the data on the back of this page.

If the vehicle has automatic restraints available, encode the appropriate data on the back of the previous page.

		Left	Center	Right
F I R S T	Availability	4	φ	4
	Evidence of usage	NONE	—	NONE
	Used in this crash?	φ4	φφ	14
	Proper Use	1	φ	1
	Failure Modes	1	φ	1
S E C O N D	Availability	4	φ	4
	Evidence of usage	NONE	—	NONE
	Used in this crash?	φ4	φφ	φφ
	Proper Use	1	φ	φ
	Failure Modes	1	φ	φ
O T H E R	Availability			
	Evidence of usage			
	Used in this crash?			
	Proper Use			
	Failure Modes			

Manual (Active) Belt System Availability

- (0) None available
- (1) Belt removed/destroyed
- (2) Shoulder belt
- (3) Lap belt
- (4) Lap and shoulder belt
- (5) Belt available - type unknown

Integral Belt Partially Destroyed

- (6) Shoulder belt (lap belt destroyed/removed)
- (7) Lap belt (shoulder belt destroyed/removed)

(8) Other belt (specify): _____

(9) Unknown

Manual (Active) Belt System Use

- (00) None used, not available, or belt removed/destroyed
- (01) Inoperable (specify): _____
- (02) Shoulder belt
- (03) Lap belt
- (04) Lap and shoulder belt
- (05) Belt used - type unknown
- (08) Other belt used (specify): _____
- (12) Shoulder belt used with child safety seat
- (13) Lap belt used with child safety seat
- (14) Lap and shoulder belt used with child safety seat
- (15) Belt used with child safety seat - type unknown
- (18) Other belt used with child safety seat (specify): _____
- (99) Unknown if belt used

Proper Use of Manual (Active) Belts

- (0) None used or not available
- (1) Belt used properly
- (2) Belt used properly with child safety seat

Belt Used Improperly

- (3) Shoulder belt worn under arm
- (4) Shoulder belt worn behind back or seat
- (5) Belt worn around more than one person
- (6) Lap belt worn on abdomen
- (7) Lap belt or lap and shoulder belt used improperly with child safety seat (specify): _____

(8) Other improper use of manual belt system (specify): _____

(9) Unknown

Manual (Active) Belt Failure Modes During Accident

- (0) No manual belt used or not available
- (1) No manual belt failure(s)
- (2) Torn webbing (stretched webbing not included)
- (3) Broken buckle or latchplate
- (4) Upper anchorage separated
- (5) Other anchorage separated (specify): _____

(6) Broken retractor

(7) Combination of above (specify): _____

(8) Other manual belt failure (specify): _____

(9) Unknown

CHILD SAFETY SEAT FIELD ASSESSMENT

When a child safety seat is present enter the occupant's number in the first row and complete the column below the occupant's number using the codes listed below. Complete a column for each child safety seat present.

Occupant Number	02					
1. Type of Child Safety Seat	3					
2. Child Safety Seat Orientation	12					
3. Child Safety Seat Harness Usage	12					
4. Child Safety Seat Shield Usage	12					
5. Child Safety Seat Tether Usage	03					
6. Child Safety Seat Make/Model		Specify Below for Each Child Safety Seat				

1. Type of Child Safety Seat

- (0) No child safety seat
- (1) Infant seat
- (2) Toddler seat
- (3) Convertible seat
- (4) Booster seat
- (7) Other type child safety seat (specify): _____
- (8) Unknown child safety seat type
- (9) Unknown if child safety seat used

2. Child Safety Seat Orientation

- (00) No child safety seat
- Designed for Rear Facing for This Age/Weight
 - (01) Rear facing
 - (02) Forward facing
 - (08) Other orientation (specify): _____
- (09) Unknown orientation
- Designed for Forward Facing for This Age/Weight
 - (11) Rear facing
 - (12) Forward facing
 - (18) Other orientation (specify): _____
- (19) Unknown orientation
- Unknown Design or Orientation For This Age/Weight, or Unknown Age/Weight
 - (21) Rear facing
 - (22) Forward facing
 - (28) Other orientation (specify): _____
- (29) Unknown orientation
- (99) Unknown if child safety seat used

3. Child Safety Seat Harness Usage

- 4. Child Safety Seat Shield Usage
- 5. Child Safety Seat Tether Usage
- Note: Options Below Are Used for Variables 3-5.
- (00) No child safety seat

Not Designed with Harness/Shield/Tether

- (01) After market harness/shield/tether added, not used
- (02) After market harness/shield/tether used
- (03) Child safety seat used, but no after market harness/shield/tether added
- (09) Unknown if harness/shield/tether added or used

Designed With Harness/Shield/Tether

- (11) Harness/shield/tether not used
- (12) Harness/shield/tether used
- (19) Unknown if harness/shield/tether used

Unknown If Designed With Harness/Shield/Tether

- (21) Harness/shield/tether not used
- (22) Harness/shield/tether used
- (29) Unknown if harness/shield/tether used
- (99) Unknown if child safety seat used

- 6. Child Safety Seat Make/Model
- (Specify make/model and occupant number)

EVENFLO CHAMPION I

MODEL NUMBER 224187

OCCUPANT #2

HEAD RESTRAINTS/SEAT EVALUATION

NOTES: Encode the applicable data for each seat position in the vehicle. The attribute for these variables may be found at the bottom of the page. Head restraint type/damage and seat type/performance should be assessed during the vehicle inspection then coded on the Occupant Assessment Form.

		Left	Center	Right
FIRST	Head Restraint Type/Damage	3	φ	3
	Seat Type	φ2	φ φ	φ2
	Seat Performance	6	φ	1
	Seat Orientation	1	φ	1
SECOND	Head Restraint Type/Damage	φ	φ	φ
	Seat Type	φ9	φ φ	φ9
	Seat Performance	1	φ	1
	Seat Orientation	1	φ	1
THIRD	Head Restraint Type/Damage			
	Seat Type			
	Seat Performance			
	Seat Orientation			
OTHER	Head Restraint Type/Damage			
	Seat Type			
	Seat Performance			
	Seat Orientation			

Head Restraint Type/Damage by Occupant at This Occupant Position

- (0) No head restraints
- (1) Integral — no damage
- (2) Integral — damaged during accident
- (3) Adjustable — no damage
- (4) Adjustable — damaged during accident
- (5) Add-on — no damage
- (6) Add-on — damaged during accident
- (8) Other Specify: _____
- (9) Unknown

Seat Type (this Occupant Position)

- (00) Occupant not seated or no seat
- (01) Bucket
- (02) Bucket with folding back
- (03) Bench
- (04) Bench with separate back cushions
- (05) Bench with folding back(s)
- (06) Split bench with separate back cushions
- (07) Split bench with folding back(s)
- (08) Pedestal (i.e., column supported)
- (09) Other seat type (specify):
FOLDING "JUMP" SEAT
- (10) Box mounted seat (i.e., van type)
- (99) Unknown

Seat Performance (this Occupant Position)

- (0) Occupant not seated or no seat
- (1) No seat performance failure(s)
- (2) Seat adjusters failed
- (3) Seat back folding locks or "seat back" failed specify: _____
- (4) Seat tracks/anchors failed
- (5) Deformed by impact of occupant
- (6) Deformed by passenger compartment intrusion (specify):
LIF FLOOR AND SILL
- (7) Combination of above (specify): _____
- (8) Other (specify): _____
- (9) Unknown

Seat Orientation (this Occupant Position)

- (0) Occupant not seated or no seat
- (1) Forward facing seat
- (2) Rear facing seat
- (3) Side facing seat (inward)
- (4) Side facing seat (outward)
- (8) Other (specify): _____
- (9) Unknown

DESCRIBE ANY INDICATION OF ABNORMAL OCCUPANT POSTURE (I.E., UNUSUAL OCCUPANT CONTACT PATTERN)

EJECTION/ENTRAPMENT DATA

Complete the following if the researcher has any indication that an occupant was either ejected from or entrapped in the vehicle. Code the appropriate data on the Occupant Assessment Form.

EJECTION No [☒] Yes []

Describe indications of ejection and body parts involved in partial ejection(s):

Occupant Number						
Ejection						
(Note on Vehicle Interior Sketch) Ejection Area						
Ejection Medium						
Medium Status						

Ejection

- (1) Complete ejection
- (2) Partial ejection
- (3) Ejection, Unknown degree
- (9) Unknown

Ejection Area

- (1) Windshield
- (2) Left front
- (3) Right front
- (4) Left rear
- (5) Right rear
- (6) Rear

(7) Roof

- (8) Other area (e.g., back of pickup, etc.) (specify):

(9) Unknown**Ejection Medium**

- (1) Door/hatch/tailgate
- (2) Nonfixed roof structure
- (3) Fixed glazing
- (4) Nonfixed glazing (specify):

(5) Integral structure

- (8) Other medium (specify):

(9) Unknown**Medium Status (Immediately Prior to Impact)**

- (1) Open
- (2) Closed
- (3) Integral structure
- (9) Unknown

ENTRAPMENT No [☒] Yes []

Describe entrapment mechanism: _____

Component(s): _____

(Note in vehicle interior diagram)

National Highway Traffic Safety
Administration

OCCUPANT ASSESSMENT FORM

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

OCCUPANT'S SEATING

1. Primary Sampling Unit Number _____
2. Case Number - Stratum DSI-94-AB-006
3. Vehicle Number 02
4. Occupant Number 01

OCCUPANT'S CHARACTERISTICS

5. Occupant's Age 26
Code actual age at time of accident.
(00) Less than one year old (specify by month):
(97) 97 years and older
(99) Unknown

6. Occupant's Sex 1
(1) Male
(2) Female
(9) Unknown

7. Occupant's Height 183
Code actual height to the nearest
centimeter.
(999) Unknown

72 inches X 2.54 = 183 centimeters

8. Occupant's Weight 082
Code actual weight to the nearest
kilogram.
(999) Unknown

180 pounds X .4536 = 82 kilograms

9. Occupant's Role 1
(1) Driver
(2) Passenger
(9) Unknown

10. Occupant's Seat Position 11
Front Seat
(11) Left side
(12) Middle
(13) Right side
(14) Other (specify): _____
(15) On or in the lap of another occupant

- Second Seat*
(21) Left side
(22) Middle
(23) Right side
(24) Other (specify): _____
(25) On or in the lap of another occupant

- Third Seat*
(31) Left side
(32) Middle
(33) Right side
(34) Other (specify): _____
(35) On or in the lap of another occupant

- Fourth Seat*
(41) Left side
(42) Middle
(43) Right side
(44) Other (specify): _____
(45) On or in the lap of another occupant

- (97) In or on unenclosed area
(98) Other seat (specify): _____
(99) Unknown

11. Occupant's Posture 0
(0) Normal posture

- Abnormal posture*
(1) Kneeling or standing on seat
(2) Lying on or across seat
(3) Kneeling, standing or sitting in front of seat
(4) Sitting sideways or turned to talk with another occupant or to look out a rear window
(5) Sitting on a console
(6) Lying back in a reclined seat position
(7) Bracing with feet or hands on a surface in front of seat
(8) Other abnormal posture (specify): _____
(9) Unknown

EJECTION/ENTRAPMENT

12. Ejection

φ

- (0) No ejection
- (1) Complete ejection
- (2) Partial ejection
- (3) Ejection, unknown degree
- (9) Unknown

13. Ejection Area

φ

- (0) No ejection
- (1) Windshield
- (2) Left front
- (3) Right front
- (4) Left rear
- (5) Right rear
- (6) Rear
- (7) Roof
- (8) Other area (e.g., back of pickup, etc.)
(specify): _____
- (9) Unknown

14. Ejection Medium

φ

- (0) No ejection
- (1) Door/hatch/tailgate
- (2) Nonfixed roof structure
- (3) Fixed glazing
- (4) Nonfixed glazing (specify): _____
- (5) Integral structure
- (8) Other medium (specify): _____
- (9) Unknown

15. Medium Status (Immediately Prior To Impact)

φ

- (0) No ejection
- (1) Open
- (2) Closed
- (3) Integral structure
- (9) Unknown

16. Entrapment

φ

(NOTE: Entrapped means that part of the person was in the vehicle and mechanically restrained; jammed doors and immobilizing injuries by themselves are not sufficient to constitute entrapment.)

- (0) Not entrapped
- (1) Entrapped
- (9) Unknown

RESTRAINT SYSTEM EVALUATION

17. Manual (Active) Belt System Availability 4

- (0) None available
- (1) Belt removed/destroyed
- (2) Shoulder belt
- (3) Lap belt
- (4) Lap and shoulder belt
- (5) Belt available—type unknown

Integral Belt Partially Destroyed

- (6) Shoulder belt (lap belt destroyed/removed)
- (7) Lap belt (shoulder belt destroyed/removed)

(8) Other belt (specify): _____

(9) Unknown _____

18. Manual (Active) Belt System Use φ 4

- (00) None used, not available, or belt removed/destroyed
- (01) Inoperative (specify): _____

(02) Shoulder belt _____

(03) Lap belt _____

(04) Lap and shoulder belt _____

(05) Belt used—type unknown _____

(08) Other belt used (specify): _____

(12) Shoulder belt used with child safety seat _____

(13) Lap belt used with child safety seat _____

(14) Lap and shoulder belt used with child safety seat _____

(15) Belt used with child safety seat—type unknown _____

(18) Other belt used with child safety seat (specify): _____

(99) Unknown if belt used _____

19. Proper Use of Manual (Active) Belts 1

- (0) None used or not available
- (1) Belt used properly
- (2) Belt used properly with child safety seat

Belt Used Improperly

- (3) Shoulder belt worn under arm
- (4) Shoulder belt worn behind back or seat
- (5) Belt worn around more than one person
- (6) Lap belt worn on abdomen
- (7) Lap belt or lap and shoulder belt used improperly with child safety seat (specify): _____

(8) Other improper use of manual belt system (specify): _____

(9) Unknown _____

20. Manual (Active) Belt Failure Modes During Accident 1

- (0) No manual belt used
- (1) No manual belt failure(s)
- (2) Torn webbing (stretched webbing not included)
- (3) Broken buckle or latchplate
- (4) Upper anchorage separated
- (5) Other anchorage separated (specify): _____

(6) Broken retractor _____

(7) Combination of above (specify): _____

(8) Other manual belt failure (specify): _____

(9) Unknown _____

21. Air Bag System Availability/Function φ

- (0) Not equipped/not available
- (1) Air bag

Non-functional

(2) Air bag disconnected (specify): _____

(3) Air bag not reinstalled _____

(9) Unknown _____

22. Air Bag System Deployment φ

- (0) Not equipped/not available
- (1) Air bag deployed during accident (as a result of impact)
- (2) Air bag deployed inadvertently just prior to accident
- (3) Air bag deployed, accident sequence undetermined
- (4) Nondeployed
- (5) Unknown if deployed
- (6) Air bag deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)
- (9) Unknown

23. Are There Indications of Air Bag System Failure? φ

- (0) Not equipped/not available
- (1) No
- (2) Yes (specify): _____

(9) Unknown _____

Note: See Variables 44 through 48 (Page 5) for Information on Automatic Belts

24. Police Reported Restraint Use φ

- (0) None used
- (1) Police did not indicate restraint use
- (2) Shoulder belt
- (3) Lap belt
- (4) Lap and shoulder belt
- (5) Belt used, type not specified
- (6) Child safety seat
- (7) Other or automatic restraint (specify): _____

(8) Restrained, type unknown _____

(9) Police indicated "unknown" _____

HEAD RESTRAINT AND SEAT EVALUATION

25. Head Restraint Type/Damage by Occupant at This Occupant Position

3

- (0) No head restraints
- (1) Integral—no damage
- (2) Integral—damaged during accident
- (3) Adjustable—no damage
- (4) Adjustable—damaged during accident
- (5) Add-on—no damage
- (6) Add-on—damaged during accident
- (8) Other (specify): _____
- (9) Unknown

26. Seat Type (this Occupant Position)

φ 2

- (00) Occupant not seated or no seat
- (01) Bucket
- (02) Bucket with folding back
- (03) Bench
- (04) Bench with separate back cushions
- (05) Bench with folding back(s)
- (06) Split bench with separate back cushions
- (07) Split bench with folding back(s)
- (08) Pedestal (i.e., column supported)
- (09) Other seat type (specify): _____
- (10) Box mounted seat (i.e., van type)
- (99) Unknown

27. Seat Performance (this Occupant Position)

6

- (0) Occupant not seated or no seat
- (1) No seat performance failure(s)
- (2) Seat adjusters failed
- (3) Seat back folding locks or "seat back" failed (specify): _____
- (4) Seat track/anchors failed
- (5) Deformed by impact of occupant
- (6) Deformed by passenger compartment intrusion (specify): L/F FLOOR AND SILL
- (7) Combination of above (specify): _____
- (8) Other (specify): _____
- (9) Unknown

CHILD SAFETY SEAT

28. Child Safety Seat Make/Model ϕ ϕ ϕ

(000) No child safety seat

Applicable codes are found in your NASS CDS
Data Collection, Coding and Editing

(950) Built-in child safety seat

(997) Other make/model (specify):

(998) Unknown make/model

(999) Unknown if child safety seat used

29. Type of Child Safety Seat ϕ

(0) No child safety seat

(1) Infant seat

(2) Toddler seat

(3) Convertible seat

(4) Booster seat

(7) Other type child safety seat (specify):

(8) Unknown child safety seat type

(9) Unknown if child safety seat used

30. Child Safety Seat Orientation ϕ ϕ

(00) No child safety seat

Designed for Rear Facing for This Age/Weight

(01) Rear facing

(02) Forward facing

(08) Other orientation (specify):

(09) Unknown orientation*Designed For Forward Facing for This Age/Weight*

(11) Rear facing

(12) Forward facing

(18) Other orientation (specify):

(19) Unknown orientation*Unknown Design or Orientation For This
Age/Weight, or Unknown Age/Weight*

(21) Rear facing

(22) Forward facing

(28) Other orientation (specify):

(29) Unknown orientation

(99) Unknown if child safety seat used

31. Child Safety Seat Harness Usage ϕ ϕ 32. Child Safety Seat Shield Usage ϕ ϕ 33. Child Safety Seat Tether Usage ϕ ϕ Note: Options below applicable to
Variables OA31-OA33.

(00) No child safety seat

Not Designed With Harness/Shield/Tether(01) After market harness/shield/tether
added, not used

(02) After market harness/shield/tether used

(03) Child safety seat used, but no after market
harness/shield/tether added(09) Unknown if harness/shield/tether
added or used*Designed With Harness/Shield/Tether*

(11) Harness/shield/tether not used

(12) Harness/shield/tether used

(19) Unknown if harness/shield/tether used

Unknown If Designed With Harness/Shield/Tether

(21) Harness/shield/tether not used

(22) Harness/shield/tether used

(29) Unknown if harness/shield/tether used

(99) Unknown if child safety seat used

INJURY CONSEQUENCES34. Injury Severity (Police Rating) 3

- (0) O - No injury
- (1) C - Possible injury
- (2) B - Nonincapacitating injury
- (3) A - Incapacitating injury
- (4) K - Killed
- (5) U - Injury, severity unknown
- (6) Died prior to accident
- (9) Unknown

35. Treatment - Mortality 3

- (0) No treatment
- (1) Fatal
- (2) Fatal - ruled disease (specify):

Nonfatal

- (3) Hospitalization
- (4) Transported and released
- (5) Treatment at scene - nontransported
- (6) Treatment later
- (8) Treatment - other (specify):

(9) Unknown

36. Type Of Medical Facility (for Initial Treatment) 2

- (0) Not treated at a medical facility
- (1) Trauma center
- (2) Hospital
- (3) Medical clinic
- (4) Physician's office
- (5) Treatment later at medical facility
- (8) Other (specify):

(9) Unknown

37. Hospital Stay φ 3

- (00) Not Hospitalized
- _____ Code the number of days (up through 60) that the occupant stayed in hospital.
- (61) 61 days or more
- (99) Unknown

99. Case Occupant φ

- (0) Not Case Occupant
- (1) This is the Case Occupant
- (2) This is the Case Occupant in another case

38. Working Days Lost 6 1

- _____ Code the number of days (up through 60) that the occupant lost from work due to the accident
- (00) No working days lost
- (61) 61 days or more
- (62) Fatally injured
- (97) Not working prior to accident
- (99) Unknown

STOP - GO TO VARIABLE 44 ON PAGE 7**VARIABLES 39 THROUGH 43 ARE COMPLETED BY THE ZONE CENTER**39. Time to Death φ φ

- _____ Code number of hours from time of accident to time of death up through 24 hours. If time of death is greater than 24 hours, code number of days. (Note: 1 day = 31, 2 days = 32, ... n days = 30 + n up through 30 days = 60)
- (00) Not fatal
- (96) Fatal - ruled disease
- (99) Unknown

40. 1st Medically Reported Cause of Death φ φ41. 2nd Medically Reported Cause of Death φ φ42. 3rd Medically Reported Cause of Death φ φ

- _____ Code the Occupant Injury from line number(s) for the medically reported injury(s) which reportedly contributed to this occupant's death
- (00) Not fatal or no additional causes
- (96) Mode of death given but specific injuries are not linked to cause of death. (specify):

(97) Other result (includes fatal ruled disease) (specify):

(99) Unknown

43. Number of Recorded Injuries for This Occupant φ 4

- _____ Code the actual number of injuries recorded for this occupant.
- (00) No recorded injuries
- (97) Injured, details unknown
- (99) Unknown if injured

AUTOMATIC BELT SYSTEM44. Automatic (Passive) Belt System Availability/Function φ

- (0) Not equipped/not available
- (1) 2 point automatic belts
- (2) 3 point automatic belts
- (3) Automatic belts - type unknown

Non-functional

- (4) Automatic belts destroyed or rendered inoperative
- (9) Unknown

45. Automatic (Passive) Belt System Use φ

- (0) Not equipped/not available/destroyed or rendered inoperative
- (1) Automatic belt in use
- (2) Automatic belt not in use (manually disconnected, motorized track inoperative) (specify): _____
- (3) Automatic belt use unknown
- (9) Unknown

46. Automatic (Passive) Belt System Type φ

- (0) Not equipped/not available
- (1) Non-motorized system
- (2) Motorized system
- (9) Unknown

47. Proper Use of Automatic (Passive) Belt System φ

- (0) Not equipped/not available/not used
- (1) Automatic belt used properly
- (2) Automatic belt used properly with child safety seat

Automatic Belt Used Improperly

- (3) Automatic shoulder belt worn under arm
- (4) Automatic shoulder belt worn behind back
- (5) Automatic belt worn around more than one person
- (6) Lap portion of automatic belt worn on abdomen
- (7) Automatic lap and shoulder belt or automatic shoulder belt used improperly with child safety seat (specify): _____
- (8) Other improper use of automatic belt system (specify): _____
- (9) Unknown

48. Automatic (Passive) Belt Failure Modes During Accident φ

- (0) Not equipped/not available/not in use
- (1) No automatic belt failure(s)
- (2) Torn webbing (stretched webbing not included)
- (3) Broken buckle or latchplate
- (4) Upper anchorage separated
- (5) Other anchorage separated (specify): _____
- (6) Broken retractor
- (7) Combination of above (specify): _____
- (8) Other automatic belt failure (specify): _____
- (9) Unknown

49. Seat Orientation (this Occupant Position) 1

- (0) Occupant not seated or no seat
- (1) Forward facing seat
- (2) Rear facing seat
- (3) Side facing seat (inward)
- (4) Side facing seat (outward)
- (8) Other (specify): _____
- (9) Unknown

Check the Primary Source Used In Determining Belt Use.

- [] Not equipped/not available/destroyed or rendered inoperative
- [X] Vehicle inspection
- [] Official injury data
- [] Driver/occupant interview
- [] Other (specify): _____
- [] Unknown if belt used

ARE ALL APPLICABLE MEDICAL RECORDS INCLUDED WITH INITIAL SUBMISSION?

NO [X] YES []

UPDATE CANDIDATE?

NO [X] YES []

**STOP - VARIABLES 50 THROUGH 53 ARE
COMPLETED BY THE ZONE CENTER****TRAUMA DATA**

50. Glasgow Coma Scale (GCS) Score 0 2
(at Medical Facility)
(00) Not injured
(01) Injured - not treated at medical facility
(02) No GCS Score at medical facility
(03-15) Code the actual value of the
initial GCS Score recorded at medical
facility.
(97) Injured, details unknown
(99) Unknown if injured
51. Was the Occupant Given Blood? 1
(1) No - blood not given
(2) Yes - blood given
(specify units): _____
(9) Unknown if blood given
52. Arterial Blood Gases (ABG) - HCO_3 0 1
(00) Not injured
(01) Injured, ABGs not measured or reported
(02-50) Code the actual value of the HCO_3
(96) ABGs reported, HCO_3 unknown
(97) Injured, details unknown
(99) Unknown if injured

BELT USE DETERMINATION

53. Primary Source of Belt Use Determination 1
(0) Not equipped/not available/destroyed
or rendered inoperative
(1) Vehicle inspection
(2) Official injury data
(3) Driver/occupant interview
(8) Other (specify): _____
(9) Unknown if belt used

National Highway Traffic Safety
Administration

OCCUPANT INJURY FORM

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

1. Primary Sampling Unit Number _____

3. Vehicle Number 022. Case Number - Stratum DSI-94-AB-0064. Occupant Number 01

INJURY DATA

Record below the actual injuries sustained by this occupant that were identified from the official and unofficial data sources. Remember not to double count an injury just because it was identified from two different sources. If greater than ten injuries have been documented, encode the balance on the Occupant Injury Supplement.



	Source of Injury Data	Body Region	Type of Anatomic Structure	Specific Anatomic Structure	Level of Injury	A.I.S. Severity	Aspect	Injury Source	Injury Source Confidence Level	Direct/ Indirect Injury	Occupant Area Intrusion Number	ICD-9
1st	5. <u>7</u>	6. <u>1</u>	7. <u>4</u>	8. <u>06</u>	9. <u>29</u>	10. <u>4</u>	11. <u>2</u>	12. <u>04</u>	13. <u>1</u>	14. <u>1</u>	15. <u>00</u>	853.06
2nd	16. <u>7</u>	17. <u>2</u>	18. <u>9</u>	19. <u>06</u>	20. <u>02</u>	21. <u>1</u>	22. <u>2</u>	23. <u>04</u>	24. <u>1</u>	25. <u>1</u>	26. <u>00</u>	873.42
3rd	27. <u>7</u>	28. <u>6</u>	29. <u>4</u>	30. <u>02</u>	31. <u>7B</u>	32. <u>1</u>	33. <u>6</u>	34. <u>92</u>	35. <u>1</u>	36. <u>3</u>	37. <u>00</u>	847.0
4th	38. <u>7</u>	39. <u>6</u>	40. <u>4</u>	41. <u>04</u>	42. <u>7B</u>	43. <u>1</u>	44. <u>7</u>	45. <u>92</u>	46. <u>1</u>	47. <u>3</u>	48. <u>00</u>	847.1
5th	49. ____	50. ____	51. ____	52. ____	53. ____	54. ____	55. ____	56. ____	57. ____	58. ____	59. ____	
6th	60. ____	61. ____	62. ____	63. ____	64. ____	65. ____	66. ____	67. ____	68. ____	69. ____	70. ____	
7th	71. ____	72. ____	73. ____	74. ____	75. ____	76. ____	77. ____	78. ____	79. ____	80. ____	81. ____	
8th	82. ____	83. ____	84. ____	85. ____	86. ____	87. ____	88. ____	89. ____	90. ____	91. ____	92. ____	
9th	93. ____	94. ____	95. ____	96. ____	97. ____	98. ____	99. ____	100. ____	101. ____	102. ____	103. ____	
10th	104. ____	105. ____	106. ____	107. ____	108. ____	109. ____	110. ____	111. ____	112. ____	113. ____	114. ____	

OCCUPANT INJURY DATA

[illegible]

OFFICIAL INJURY DATA — SOFT TISSUE INJURIES

Indicate the Location, Specific Anatomic Structure, Detail (size, depth, fracture type, head injury clinical signs and neurological deficits), and Source of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)



SOURCE OF INJURY DATA

OFFICIAL

- (1) Autopsy records with or without hospital/medical records
- (2) Hospital/medical records other than emergency room (e.g., discharge summary)
- (3) Emergency room records only (including associated X-rays or other lab reports)
- (4) Private physician, walk-in or emergency clinic

UNOFFICIAL

- (5) Lay coroner report
- (6) E.M.S. personnel
- (7) Interviewee
- (8) Other source (specify): _____
- (9) Police

INJURY SOURCE

FRONT

- (01) Windshield
- (02) Mirror
- (03) Sunvisor
- (04) Steering wheel rim
- (05) Steering wheel hub/spoke
- (06) Steering wheel (combination of codes 04 and 05)
- (07) Steering column, transmission selector lever, other attachment
- (08) Add on equipment (e.g., CB, tape deck, air conditioner)
- (09) Left instrument panel and below
- (10) Center instrument panel and below
- (11) Right instrument panel and below
- (12) Glove compartment door
- (13) Knee bolster
- (14) Windshield including one or more of the following: front header, A (A1/A2)-pillar, instrument panel, mirror, or steering assembly (driver side only)
- (15) Windshield including one or more of the following: front header, A (A1/A2)-pillar, instrument panel, or mirror (passenger side only)
- (16) Driver side air bag compartment cover
- (17) Passenger side air bag compartment cover
- (18) Windshield reinforced by exterior object (specify): _____
- (19) Other front object (specify): _____

LEFT SIDE

- (20) Left side interior surface, excluding hardware or armrests
- (21) Left side hardware or armrest
- (22) Left A (A1/A2)-pillar
- (23) Left B-pillar
- (24) Other left pillar (specify): _____

- (25) Left side window glass or frame
- (26) Left side window glass including one or more of the following: frame, window sill, A (A1/A2)-pillar, B-pillar, or roof side rail.
- (27) Other left side object (specify): _____

- (28) Left side window sill

RIGHT SIDE

- (30) Right side interior surface, excluding hardware or armrests
- (31) Right side hardware or armrest
- (32) Right A (A1/A2)-pillar
- (33) Right B-pillar
- (34) Other right pillar (specify): _____

- (35) Right side window glass or frame
- (36) Right side window glass including one or more of the following: frame, window sill, A (A1/A2)-pillar, B-pillar, or roof side rail.
- (37) Other right side object (specify): _____

- (38) Right side window sill

INTERIOR

- (40) Seat, back support
- (41) Belt restraint webbing/buckle
- (42) Belt restraint B-pillar or door frame attachment point
- (43) Other restraint system component (specify): _____
- (44) Head restraint system
- (45) Air bag (use codes "16" and "17" for injuries sustained from air bag compartment covers)
- (46) Other occupants (specify): _____
- (47) Interior loose objects
- (48) Child safety seat (specify): _____
- (49) Other interior object (specify): _____

ROOF

- (50) Front header
- (51) Rear header
- (52) Roof left side rail
- (53) Roof right side rail
- (54) Roof or convertible top

FLOOR

- (56) Floor (including toe pan)
- (57) Floor or console mounted transmission lever, including console
- (58) Parking brake handle
- (59) Foot controls including parking brake

REAR

- (60) Backlight (rear window)

- (61) Backlight storage rack, door, etc.
- (62) Other rear object (specify): _____

EXTERIOR of OCCUPANT'S VEHICLE

- (65) Hood
- (66) Outside hardware (e.g., outside mirror, antenna)
- (67) Other exterior surface or tires (specify): _____
- (68) Unknown exterior objects

EXTERIOR OF OTHER MOTOR VEHICLE

- (70) Front bumper
- (71) Hood edge
- (72) Other front of vehicle (specify): _____

- (73) Hood
- (74) Hood ornament
- (75) Windshield, roof rail, A-pillar
- (76) Side surface
- (77) Side mirrors
- (78) Other side protrusions (specify) _____

- (79) Rear surface
- (80) Undercarriage
- (81) Tires and wheels
- (82) Other exterior of other motor vehicle (specify): _____

- (83) Unknown exterior of other motor vehicle

OTHER VEHICLE OR OBJECT IN THE ENVIRONMENT

- (84) Ground
- (85) Other vehicle or object (specify) _____
- (86) Unknown vehicle or object

NONCONTACT INJURY

- (90) Fire in vehicle
- (91) Flying glass
- (92) Other noncontact injury source (specify): Inertial Force
- (93) Air bag exhaust gases
- (97) Injured, unknown source

INJURY SOURCE CONFIDENCE LEVEL

- (1) Certain
- (2) Probable
- (3) Possible
- (9) Unknown

DIRECT/INDIRECT INJURY

- (1) Direct contact injury
- (2) Indirect contact injury
- (3) Noncontact injury
- (7) Injured, unknown source

OCCUPANT INJURY CLASSIFICATION

Body Region

- (1) Head
- (2) Face
- (3) Neck
- (4) Thorax
- (5) Abdomen
- (6) Spine
- (7) Upper Extremity
- (8) Lower Extremity
- (9) Unspecified

Type of Anatomic Structure

- (1) Whole Area
- (2) Vessels
- (3) Nerves
- (4) Organs (includes muscles/ligaments)
- (5) Skeletal (includes joints)
- (6) Head - LOC
- (9) Skin

Specific Anatomic Structure

Whole Area

- (02) Skin - Abrasion
- (04) Skin - Contusion
- (06) Skin - Laceration
- (08) Skin - Avulsion
- (10) Amputation
- (20) Burn
- (30) Crush
- (40) Degloving
- (50) Injury - NFS
- (90) Trauma, other than mechanical

Head - LOC

- (02) Length of LOC
- (04, 06, 08) Level of Consciousness
- (10) Concussion

Spine

- (02) Cervical
- (04) Thoracic
- (06) Lumbar

Vessels, Nerves, Organs, Bones,
Joints are assigned consecutive two digit numbers beginning with 02

Level of Injury

Specific injuries are assigned consecutive two-digit numbers beginning with 02.

To the extent possible, within the organizational framework of the AIS, 00 is assigned to an injury NFS as to severity or where only one injury is given in the dictionary for that anatomic structure. 99 is assigned to any injury NFS as to lesion or severity.

Abbreviated Injury Scale

- (1) Minor injury
- (2) Moderate injury
- (3) Serious injury
- (4) Severe injury
- (5) Critical injury
- (6) Maximum (untreatable)
- (7) Injured, unknown severity

Aspect

- (1) Right
- (2) Left
- (3) Bilateral
- (4) Central
- (5) Anterior
- (6) Posterior
- (7) Superior
- (8) Inferior
- (9) Unknown
- (0) Whole region

OFFICIAL INJURY DATA — SKELETAL INJURIES

Restrained?

☐ No

☒ Yes

Blood Alcohol Level
(mg/dl)

BAL = ϕ

Glasgow Coma
Scale Score

GCSS = ϕ

Units of Blood
Given

Units = ϕ

Arterial Blood Gases



pH = ϕ

PO₂ = ϕ

PCO₂ = ϕ


HCO₃ = ϕ

Indicate the Location, Specific Anatomic Structure, Detail (size, depth, fracture type, head injury clinical signs and neurological deficits), and Source of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)



OFFICIAL INJURY DATA —INTERNAL INJURIES

Indicate the Location, Specific Anatomic Structure, Detail (size, depth, fracture type, head injury clinical signs and neurological deficits), and Source of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)



National Highway Traffic Safety
Administration

OCCUPANT ASSESSMENT FORM

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

OCCUPANT'S SEATING

1. Primary Sampling Unit Number _____
2. Case Number - Stratum DSI-94-AB-006
3. Vehicle Number 02
4. Occupant Number 02

OCCUPANT'S CHARACTERISTICS

5. Occupant's Age 01
Code actual age at time of accident.
(00) Less than one year old (specify by month): _____
(97) 97 years and older _____
(99) Unknown
6. Occupant's Sex 1
(1) Male
(2) Female
(9) Unknown
7. Occupant's Height 079
Code actual height to the nearest centimeter.
(999) Unknown
31 inches X 2.54 = 079 centimeters
8. Occupant's Weight 015
Code actual weight to the nearest kilogram.
(999) Unknown
032 pounds X .4536 = 015 kilograms
9. Occupant's Role 2
(1) Driver
(2) Passenger
(9) Unknown

10. Occupant's Seat Position 13
Front Seat
(11) Left side
(12) Middle
(13) Right side
(14) Other (specify): _____
(15) On or in the lap of another occupant
- Second Seat*
(21) Left side
(22) Middle
(23) Right side
(24) Other (specify): _____
(25) On or in the lap of another occupant
- Third Seat*
(31) Left side
(32) Middle
(33) Right side
(34) Other (specify): _____
(35) On or in the lap of another occupant
- Fourth Seat*
(41) Left side
(42) Middle
(43) Right side
(44) Other (specify): _____
(45) On or in the lap of another occupant
(97) In or on unenclosed area
(98) Other seat (specify): _____
(99) Unknown
11. Occupant's Posture 0
(0) Normal posture
- Abnormal posture*
(1) Kneeling or standing on seat
(2) Lying on or across seat
(3) Kneeling, standing or sitting in front of seat
(4) Sitting sideways or turned to talk with another occupant or to look out a rear window
(5) Sitting on a console
(6) Lying back in a reclined seat position
(7) Bracing with feet or hands on a surface in front of seat
(8) Other abnormal posture (specify): _____
(9) Unknown

EJECTION/ENTRAPMENT

12. Ejection φ

- (0) No ejection
- (1) Complete ejection
- (2) Partial ejection
- (3) Ejection, unknown degree
- (9) Unknown

13. Ejection Area φ

- (0) No ejection
- (1) Windshield
- (2) Left front
- (3) Right front
- (4) Left rear
- (5) Right rear
- (6) Rear
- (7) Roof
- (8) Other area (e.g., back of pickup, etc.)
(specify): _____
- (9) Unknown

14. Ejection Medium φ

- (0) No ejection
- (1) Door/hatch/tailgate
- (2) Nonfixed roof structure
- (3) Fixed glazing
- (4) Nonfixed glazing (specify): _____
- (5) Integral structure
- (8) Other medium (specify): _____
- (9) Unknown

15. Medium Status (Immediately Prior To Impact) φ

- (0) No ejection
- (1) Open
- (2) Closed
- (3) Integral structure
- (9) Unknown

16. Entrapment φ

- (NOTE: Entrapped means that part of the person was in the vehicle and mechanically restrained; jammed doors and immobilizing injuries by themselves are not sufficient to constitute entrapment.)
- (0) Not entrapped
 - (1) Entrapped
 - (9) Unknown

RESTRAINT SYSTEM EVALUATION

17. Manual (Active) Belt System Availability 4

- (0) None available
- (1) Belt removed/destroyed
- (2) Shoulder belt
- (3) Lap belt
- (4) Lap and shoulder belt
- (5) Belt available—type unknown

Integral Belt Partially Destroyed

- (6) Shoulder belt (lap belt destroyed/removed)
- (7) Lap belt (shoulder belt destroyed/removed)

(8) Other belt (specify): _____

(9) Unknown _____

18. Manual (Active) Belt System Use 1 4

- (00) None used, not available, or belt removed/destroyed
- (01) Inoperative (specify): _____

(02) Shoulder belt _____

(03) Lap belt _____

(04) Lap and shoulder belt _____

(05) Belt used—type unknown _____

(08) Other belt used (specify): _____

(12) Shoulder belt used with child safety seat _____

(13) Lap belt used with child safety seat _____

(14) Lap and shoulder belt used with child safety seat _____

(15) Belt used with child safety seat—type unknown _____

(18) Other belt used with child safety seat (specify): _____

(99) Unknown if belt used _____

19. Proper Use of Manual (Active) Belts 1

- (0) None used or not available
- (1) Belt used properly
- (2) Belt used properly with child safety seat

Belt Used Improperly

- (3) Shoulder belt worn under arm
- (4) Shoulder belt worn behind back or seat
- (5) Belt worn around more than one person
- (6) Lap belt worn on abdomen
- (7) Lap belt or lap and shoulder belt used improperly with child safety seat (specify): _____

(8) Other improper use of manual belt system (specify): _____

(9) Unknown _____

20. Manual (Active) Belt Failure Modes During Accident 1

- (0) No manual belt used
- (1) No manual belt failure(s)
- (2) Torn webbing (stretched webbing not included)
- (3) Broken buckle or latchplate
- (4) Upper anchorage separated
- (5) Other anchorage separated (specify): _____

(6) Broken retractor _____

(7) Combination of above (specify): _____

(8) Other manual belt failure (specify): _____

(9) Unknown _____

21. Air Bag System Availability/Function φ

- (0) Not equipped/not available
- (1) Air bag

Non-functional

(2) Air bag disconnected (specify): _____

(3) Air bag not reinstalled _____

(9) Unknown _____

22. Air Bag System Deployment φ

- (0) Not equipped/not available
- (1) Air bag deployed during accident (as a result of impact)
- (2) Air bag deployed inadvertently just prior to accident
- (3) Air bag deployed, accident sequence undetermined
- (4) Nondeployed
- (5) Unknown if deployed
- (6) Air bag deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)
- (9) Unknown

23. Are There Indications of Air Bag System Failure? φ

- (0) Not equipped/not available
- (1) No
- (2) Yes (specify): _____

(9) Unknown _____

Note: See Variables 44 through 48 (Page 5) for Information on Automatic Belts

24. Police Reported Restraint Use 6

- (0) None used
- (1) Police did not indicate restraint use
- (2) Shoulder belt
- (3) Lap belt
- (4) Lap and shoulder belt
- (5) Belt used, type not specified
- (6) Child safety seat
- (7) Other or automatic restraint (specify): _____

(8) Restrained, type unknown _____

(9) Police indicated "unknown" _____

HEAD RESTRAINT AND SEAT EVALUATION

25. Head Restraint Type/Damage by Occupant at This Occupant Position 3

- (0) No head restraints
- (1) Integral—no damage
- (2) Integral—damaged during accident
- (3) Adjustable—no damage
- (4) Adjustable—damaged during accident
- (5) Add-on—no damage
- (6) Add-on—damaged during accident
- (8) Other (specify): _____

(9) Unknown

26. Seat Type (this Occupant Position) φ 2

- (00) Occupant not seated or no seat
- (01) Bucket
- (02) Bucket with folding back
- (03) Bench
- (04) Bench with separate back cushions
- (05) Bench with folding back(s)
- (06) Split bench with separate back cushions
- (07) Split bench with folding back(s)
- (08) Pedestal (i.e., column supported)
- (09) Other seat type (specify): _____

(10) Box mounted seat (i.e., van type)

(99) Unknown

27. Seat Performance (this Occupant Position) 1

- (0) Occupant not seated or no seat
- (1) No seat performance failure(s)
- (2) Seat adjusters failed
- (3) Seat back folding locks or "seat back" failed (specify): _____
- (4) Seat track/anchors failed
- (5) Deformed by impact of occupant
- (6) Deformed by passenger compartment intrusion (specify): _____

(7) Combination of above (specify): _____

(8) Other (specify): _____

(9) Unknown

CHILD SAFETY SEAT

28. Child Safety Seat Make/Model 9 9 7

(000) No child safety seat

Applicable codes are found in your NASS CDS
Data Collection, Coding and Editing

(950) Built-in child safety seat

(997) Other make/model (specify):

EVENFLO CHAMPION I

(998) Unknown make/model

(999) Unknown if child safety seat used

29. Type of Child Safety Seat 3

(0) No child safety seat

(1) Infant seat

(2) Toddler seat

(3) Convertible seat

(4) Booster seat

(7) Other type child safety seat (specify):

(8) Unknown child safety seat type

(9) Unknown if child safety seat used

30. Child Safety Seat Orientation 1 2

(00) No child safety seat

Designed for Rear Facing for This Age/Weight

(01) Rear facing

(02) Forward facing

(08) Other orientation (specify):

(09) Unknown orientation*Designed For Forward Facing for This Age/Weight*

(11) Rear facing

(12) Forward facing

(18) Other orientation (specify):

(19) Unknown orientation*Unknown Design or Orientation For This
Age/Weight, or Unknown Age/Weight*

(21) Rear facing

(22) Forward facing

(28) Other orientation (specify):

(29) Unknown orientation

(99) Unknown if child safety seat used

31. Child Safety Seat Harness Usage 1 232. Child Safety Seat Shield Usage 1 233. Child Safety Seat Tether Usage 0 3Note: Options below applicable to
Variables OA31-OA33.

(00) No child safety seat

Not Designed With Harness/Shield/Tether(01) After market harness/shield/tether
added, not used

(02) After market harness/shield/tether used

(03) Child safety seat used, but no after market
harness/shield/tether added(09) Unknown if harness/shield/tether
added or used*Designed With Harness/Shield/Tether*

(11) Harness/shield/tether not used

(12) Harness/shield/tether used

(19) Unknown if harness/shield/tether used

Unknown If Designed With Harness/Shield/Tether

(21) Harness/shield/tether not used

(22) Harness/shield/tether used

(29) Unknown if harness/shield/tether used

(99) Unknown if child safety seat used

INJURY CONSEQUENCES34. Injury Severity (Police Rating) 3

- (0) O - No injury
- (1) C - Possible injury
- (2) B - Nonincapacitating injury
- (3) A - Incapacitating injury
- (4) K - Killed
- (5) U - Injury, severity unknown
- (6) Died prior to accident
- (9) Unknown

35. Treatment - Mortality 4

- (0) No treatment
- (1) Fatal
- (2) Fatal - ruled disease (specify):

Nonfatal

- (3) Hospitalization
- (4) Transported and released
- (5) Treatment at scene - nontransported
- (6) Treatment later
- (8) Treatment - other (specify):

- (9) Unknown

36. Type Of Medical Facility (for Initial Treatment) 2

- (0) Not treated at a medical facility
- (1) Trauma center
- (2) Hospital
- (3) Medical clinic
- (4) Physician's office
- (5) Treatment later at medical facility
- (8) Other (specify):

- (9) Unknown

37. Hospital Stay φ φ

- (00) Not Hospitalized
_____ Code the number of days (up through 60)
that the occupant stayed in hospital.
- (61) 61 days or more
- (99) Unknown

99. Case Occupant φ

- (0) Not Case Occupant
- (1) This is the Case Occupant
- (2) This is the Case Occupant
in another case

38. Working Days Lost 9 7

- _____ Code the number of days
(up through 60) that the occupant
lost from work due to the accident
- (00) No working days lost
- (61) 61 days or more
- (62) Fatally injured
- (97) Not working prior to accident
- (99) Unknown

STOP - GO TO VARIABLE 44 ON PAGE 7**VARIABLES 39 THROUGH 43 ARE
COMPLETED BY THE ZONE CENTER**39. Time to Death φ φ

- _____ Code number of hours from time of
accident to time of death up through 24
hours. If time of death is greater than 24
hours, code number of days. (Note: 1 day =
31, 2 days = 32, ... n days = 30 + n up
through 30 days = 60)
- (00) Not fatal
- (96) Fatal - ruled disease
- (99) Unknown

40. 1st Medically Reported Cause of Death φ φ41. 2nd Medically Reported Cause of Death φ φ42. 3rd Medically Reported Cause of Death φ φ

- _____ Code the Occupant Injury from line
number(s) for the medically reported
injury(s) which reportedly contributed to
this occupant's death
- (00) Not fatal or no additional causes
- (96) Mode of death given but specific
injuries are not linked to cause
of death. (specify):

(97) Other result (includes fatal ruled
disease) (specify):

(99) Unknown

43. Number of Recorded Injuries for
This Occupant φ 1

- _____ Code the actual number of
injuries recorded for this occupant.
- (00) No recorded injuries
- (97) Injured, details unknown
- (99) Unknown if injured

AUTOMATIC BELT SYSTEM44. Automatic (Passive) Belt System Availability/Function φ

- (0) Not equipped/not available
- (1) 2 point automatic belts
- (2) 3 point automatic belts
- (3) Automatic belts - type unknown

Non-functional

- (4) Automatic belts destroyed or rendered inoperative
- (9) Unknown

45. Automatic (Passive) Belt System Use φ

- (0) Not equipped/not available/destroyed or rendered inoperative
- (1) Automatic belt in use
- (2) Automatic belt not in use (manually disconnected, motorized track inoperative) (specify): _____

- (3) Automatic belt use unknown
- (9) Unknown

46. Automatic (Passive) Belt System Type φ

- (0) Not equipped/not available
- (1) Non-motorized system
- (2) Motorized system
- (9) Unknown

47. Proper Use of Automatic (Passive) Belt System φ

- (0) Not equipped/not available/not used
- (1) Automatic belt used properly
- (2) Automatic belt used properly with child safety seat

Automatic Belt Used Improperly

- (3) Automatic shoulder belt worn under arm
- (4) Automatic shoulder belt worn behind back
- (5) Automatic belt worn around more than one person
- (6) Lap portion of automatic belt worn on abdomen
- (7) Automatic lap and shoulder belt or automatic shoulder belt used improperly with child safety seat (specify): _____

- (8) Other improper use of automatic belt system (specify): _____
- (9) Unknown

48. Automatic (Passive) Belt Failure Modes During Accident φ

- (0) Not equipped/not available/not in use
- (1) No automatic belt failure(s)
- (2) Torn webbing (stretched webbing not included)
- (3) Broken buckle or latchplate
- (4) Upper anchorage separated
- (5) Other anchorage separated (specify): _____

- (6) Broken retractor
- (7) Combination of above (specify): _____
- (8) Other automatic belt failure (specify): _____

- (9) Unknown

49. Seat Orientation (this Occupant Position) 1

- (0) Occupant not seated or no seat
- (1) Forward facing seat
- (2) Rear facing seat
- (3) Side facing seat (inward)
- (4) Side facing seat (outward)
- (8) Other (specify): _____

- (9) Unknown

Check the Primary Source Used In Determining Belt Use.

- [] Not equipped/not available/destroyed or rendered inoperative
- [X] Vehicle inspection
- [] Official injury data
- [] Driver/occupant interview
- [] Other (specify): _____

- [] Unknown if belt used

ARE ALL APPLICABLE MEDICAL RECORDS INCLUDED WITH INITIAL SUBMISSION?

NO [X] YES []

UPDATE CANDIDATE?

NO [X] YES []

STOP - VARIABLES 50 THROUGH 53 ARE COMPLETED BY THE ZONE CENTER**TRAUMA DATA**

50. Glasgow Coma Scale (GCS) Score 0 2
(at Medical Facility)
(00) Not injured
(01) Injured - not treated at medical facility
(02) No GCS Score at medical facility
(03-15) Code the actual value of the initial GCS Score recorded at medical facility.
(97) Injured, details unknown
(99) Unknown if injured
51. Was the Occupant Given Blood? 1
(1) No - blood not given
(2) Yes - blood given
(specify units): _____
(9) Unknown if blood given
52. Arterial Blood Gases (ABG) - HCO_3 0 1
(00) Not injured
(01) Injured, ABGs not measured or reported
(02-50) Code the actual value of the HCO_3
(96) ABGs reported, HCO_3 unknown
(97) Injured, details unknown
(99) Unknown if injured

BELT USE DETERMINATION

53. Primary Source of Belt Use Determination 1
(0) Not equipped/not available/destroyed or rendered inoperative
(1) Vehicle inspection
(2) Official injury data
(3) Driver/occupant interview
(8) Other (specify): _____
(9) Unknown if belt used



OCCUPANT INJURY FORM

1. Primary Sampling Unit Number _____

3. Vehicle Number 622. Case Number - Stratum DSI-94-AB-6664. Occupant Number 62

INJURY DATA

Record below the actual injuries sustained by this occupant that were identified from the official and unofficial data sources. Remember not to double count an injury just because it was identified from two different sources. If greater than ten injuries have been documented, encode the balance on the Occupant Injury Supplement.



	Source of Injury Data	Body Region	Type of Anatomic Structure	Specific Anatomic Structure	Level of Injury	A.I.S. Severity	Aspect	Injury Source	Injury Source Confidence Level	Direct/ Indirect Injury	Occupant Area Intrusion Number
1st	5. <u>7</u>	6. <u>1</u>	7. <u>6</u>	8. <u>64</u>	9. <u>99</u>	10. <u>1</u>	11. <u>6</u>	12. <u>48</u>	13. <u>1</u>	14. <u>1</u>	15. <u>66</u>
2nd	16. ____	17. ____	18. ____	19. ____	20. ____	21. ____	22. ____	23. ____	24. ____	25. ____	26. ____
3rd	27. ____	28. ____	29. ____	30. ____	31. ____	32. ____	33. ____	34. ____	35. ____	36. ____	37. ____
4th	38. ____	39. ____	40. ____	41. ____	42. ____	43. ____	44. ____	45. ____	46. ____	47. ____	48. ____
5th	49. ____	50. ____	51. ____	52. ____	53. ____	54. ____	55. ____	56. ____	57. ____	58. ____	59. ____
6th	60. ____	61. ____	62. ____	63. ____	64. ____	65. ____	66. ____	67. ____	68. ____	69. ____	70. ____
7th	71. ____	72. ____	73. ____	74. ____	75. ____	76. ____	77. ____	78. ____	79. ____	80. ____	81. ____
8th	82. ____	83. ____	84. ____	85. ____	86. ____	87. ____	88. ____	89. ____	90. ____	91. ____	92. ____
9th	93. ____	94. ____	95. ____	96. ____	97. ____	98. ____	99. ____	100. ____	101. ____	102. ____	103. ____
10th	104. ____	105. ____	106. ____	107. ____	108. ____	109. ____	110. ____	111. ____	112. ____	113. ____	114. ____

ICD-9

856.9

OFFICIAL INJURY DATA — SOFT TISSUE INJURIES

Indicate the Location, Specific Anatomic Structure, Detail (size, depth, fracture type, head injury clinical signs and neurological deficits), and Source of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)



SOURCE OF INJURY DATA

OFFICIAL

- (1) Autopsy records with or without hospital/medical records
- (2) Hospital/medical records other than emergency room (e.g., discharge summary)
- (3) Emergency room records only (including associated X-rays or other lab reports)
- (4) Private physician, walk-in or emergency clinic

UNOFFICIAL

- (5) Lay coroner report
- (6) E.M.S. personnel
- (7) Interviewee
- (8) Other source (specify): _____
- (9) Police

INJURY SOURCE

FRONT

- (01) Windshield
- (02) Mirror
- (03) Sunvisor
- (04) Steering wheel rim
- (05) Steering wheel hub/spoke
- (06) Steering wheel (combination of codes 04 and 05)
- (07) Steering column, transmission selector lever, other attachment
- (08) Add on equipment (e.g., CB, tape deck, air conditioner)
- (09) Left instrument panel and below
- (10) Center instrument panel and below
- (11) Right instrument panel and below
- (12) Glove compartment door
- (13) Knee bolster
- (14) Windshield including one or more of the following: front header, A (A1/A2)-pillar, instrument panel, mirror, or steering assembly (driver side only)
- (15) Windshield including one or more of the following: front header, A (A1/A2)-pillar, instrument panel, or mirror (passenger side only)
- (16) Driver side air bag compartment cover
- (17) Passenger side air bag compartment cover
- (18) Windshield reinforced by exterior object (specify): _____
- (19) Other front object (specify): _____

LEFT SIDE

- (20) Left side interior surface, excluding hardware or armrests
- (21) Left side hardware or armrest
- (22) Left A (A1/A2)-pillar
- (23) Left B-pillar
- (24) Other left pillar (specify): _____

- (25) Left side window glass or frame
- (26) Left side window glass including one or more of the following: frame, window sill, A (A1/A2)-pillar, B-pillar, or roof side rail.
- (27) Other left side object (specify): _____

- (28) Left side window sill

RIGHT SIDE

- (30) Right side interior surface, excluding hardware or armrests
- (31) Right side hardware or armrest
- (32) Right A (A1/A2)-pillar
- (33) Right B-pillar
- (34) Other right pillar (specify): _____

- (35) Right side window glass or frame
- (36) Right side window glass including one or more of the following: frame, window sill, A (A1/A2)-pillar, B-pillar, or roof side rail.
- (37) Other right side object (specify): _____

- (38) Right side window sill

INTERIOR

- (40) Seat, back support
- (41) Belt restraint webbing/buckle
- (42) Belt restraint B-pillar or door frame attachment point
- (43) Other restraint system component (specify): _____
- (44) Head restraint system
- (45) Air bag (use codes "16" and "17" for injuries sustained from air bag compartment covers)
- (46) Other occupants (specify): _____
- (47) Interior loose objects
- (48) Child safety seat (specify): _____
- (49) Other interior object (specify): _____

ROOF

- (50) Front header
- (51) Rear header
- (52) Roof left side rail
- (53) Roof right side rail
- (54) Roof or convertible top

FLOOR

- (56) Floor (including toe pan)
- (57) Floor or console mounted transmission lever, including console
- (58) Parking brake handle
- (59) Foot controls including parking brake

REAR

- (60) Backlight (rear window)

- (61) Backlight storage rack, door, etc.
- (62) Other rear object (specify): _____

EXTERIOR of OCCUPANT'S VEHICLE

- (65) Hood
- (66) Outside hardware (e.g., outside mirror, antenna)
- (67) Other exterior surface or tires (specify): _____
- (68) Unknown exterior objects

EXTERIOR of OTHER MOTOR VEHICLE

- (70) Front bumper
- (71) Hood edge
- (72) Other front of vehicle (specify): _____

- (73) Hood
- (74) Hood ornament
- (75) Windshield, roof rail, A-pillar
- (76) Side surface
- (77) Side mirrors
- (78) Other side protrusions (specify): _____

- (79) Rear surface
- (80) Undercarriage
- (81) Tires and wheels
- (82) Other exterior of other motor vehicle (specify): _____

- (83) Unknown exterior of other motor vehicle

OTHER VEHICLE or OBJECT in THE ENVIRONMENT

- (84) Ground
- (85) Other vehicle or object (specify): _____
- (86) Unknown vehicle or object

NONCONTACT INJURY

- (90) Fire in vehicle
- (91) Flying glass
- (92) Other noncontact injury source (specify): _____
- (93) Air bag exhaust gases
- (97) Injured, unknown source

INJURY SOURCE CONFIDENCE LEVEL

- (1) Certain
- (2) Probable
- (3) Possible
- (9) Unknown

DIRECT/INDIRECT INJURY

- (1) Direct contact injury
- (2) Indirect contact injury
- (3) Noncontact injury
- (7) Injured, unknown source

OCCUPANT INJURY CLASSIFICATION

Body Region

- (1) Head
- (2) Face
- (3) Neck
- (4) Thorax
- (5) Abdomen
- (6) Spine
- (7) Upper Extremity
- (8) Lower Extremity
- (9) Unspecified

Type of Anatomic Structure

- (1) Whole Area
- (2) Vessels
- (3) Nerves
- (4) Organs (includes muscles/ligaments)
- (5) Skeletal (includes joints)
- (6) Head - LOC
- (9) Skin

Specific Anatomic Structure

Whole Area

- (02) Skin - Abrasion
- (04) Skin - Contusion
- (06) Skin - Laceration
- (08) Skin - Avulsion
- (10) Amputation
- (20) Burn
- (30) Crush
- (40) Degloving
- (50) Injury - NFS
- (90) Trauma, other than mechanical

Head - LOC

- (02) Length of LOC
- (04, 06, 08) Level of Consciousness
- (10) Concussion

Spine

- (02) Cervical
- (04) Thoracic
- (06) Lumbar

Vessels, Nerves, Organs, Bones, Joints are assigned consecutive two digit numbers beginning with 02

Level of Injury

Specific injuries are assigned consecutive two-digit numbers beginning with 02.

To the extent possible, within the organizational framework of the AIS, 00 is assigned to an injury NFS as to severity or where only one injury is given in the dictionary for that anatomic structure. 99 is assigned to any injury NFS as to lesion or severity.

Abbreviated Injury Scale

- (1) Minor injury
- (2) Moderate injury
- (3) Serious injury
- (4) Severe injury
- (5) Critical injury
- (6) Maximum (untreatable)
- (7) Injured, unknown severity

Aspect

- (1) Right
- (2) Left
- (3) Bilateral
- (4) Central
- (5) Anterior
- (6) Posterior
- (7) Superior
- (8) Inferior
- (9) Unknown
- (0) Whole region

OFFICIAL INJURY DATA — SKELETAL INJURIES

Restrained?

☐ No
☐ Yes

Blood Alcohol Level
(mg/dl)

BAL = ____

Glasgow Coma
Scale Score

GCSS = ____

Units of Blood
Given

Units = ____

Arterial Blood Gases



pH = ____

PO₂ = ____

PCO₂ = ____



HCO₃ = ____

Indicate the Location, Specific Anatomic Structure, Detail (size, depth, fracture type, head injury clinical signs and neurological deficits), and Source of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)



OFFICIAL INJURY DATA — INTERNAL INJURIES

Indicate the Location, Specific Anatomic Structure, Detail (size, depth, fracture type, head injury clinical signs and neurological deficits), and Source of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)



National Highway Traffic Safety
Administration

OCCUPANT ASSESSMENT FORM

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

OCCUPANT'S SEATING

1. Primary Sampling Unit Number 2. Case Number - Stratum DSI-94-AB-01663. Vehicle Number 024. Occupant Number 03

OCCUPANT'S CHARACTERISTICS

5. Occupant's Age 11

Code actual age at time of accident.

(00) Less than one year old (specify by month):

(97) 97 years and older

(99) Unknown

6. Occupant's Sex 2

(1) Male

(2) Female

(9) Unknown

7. Occupant's Height 137Code actual height to the nearest
centimeter.

(999) Unknown

54 inches X 2.54 = 137 centimeters8. Occupant's Weight 041Code actual weight to the nearest
kilogram.

(999) Unknown

090 pounds X .4536 = 041 kilograms9. Occupant's Role 2

(1) Driver

(2) Passenger

(9) Unknown

10. Occupant's Seat Position 21

Front Seat

(11) Left side

(12) Middle

(13) Right side

(14) Other (specify):

(15) On or in the lap of another occupant

Second Seat

(21) Left side

(22) Middle

(23) Right side

(24) Other (specify):

(25) On or in the lap of another occupant

Third Seat

(31) Left side

(32) Middle

(33) Right side

(34) Other (specify):

(35) On or in the lap of another occupant

Fourth Seat

(41) Left side

(42) Middle

(43) Right side

(44) Other (specify):

(45) On or in the lap of another occupant

(97) In or on unenclosed area

(98) Other seat (specify):

(99) Unknown

11. Occupant's Posture 0

(0) Normal posture

Abnormal posture

(1) Kneeling or standing on seat

(2) Lying on or across seat

(3) Kneeling, standing or sitting in front of seat

(4) Sitting sideways or turned to talk with another
occupant or to look out a rear window

(5) Sitting on a console

(6) Lying back in a reclined seat position

(7) Bracing with feet or hands on a surface in front
of seat

(8) Other abnormal posture (specify):

(9) Unknown

EJECTION/ENTRAPMENT

12. Ejection φ

- (0) No ejection
- (1) Complete ejection
- (2) Partial ejection
- (3) Ejection, unknown degree
- (9) Unknown

13. Ejection Area φ

- (0) No ejection
- (1) Windshield
- (2) Left front
- (3) Right front
- (4) Left rear
- (5) Right rear
- (6) Rear
- (7) Roof
- (8) Other area (e.g., back of pickup, etc.)
(specify): _____
- (9) Unknown

14. Ejection Medium φ

- (0) No ejection
- (1) Door/hatch/tailgate
- (2) Nonfixed roof structure
- (3) Fixed glazing
- (4) Nonfixed glazing (specify): _____
- (5) Integral structure
- (8) Other medium (specify): _____
- (9) Unknown

15. Medium Status (Immediately Prior To Impact) φ

- (0) No ejection
- (1) Open
- (2) Closed
- (3) Integral structure
- (9) Unknown

16. Entrapment φ

(NOTE: Entrapped means that part of the person was in the vehicle and mechanically restrained; jammed doors and immobilizing injuries by themselves are not sufficient to constitute entrapment.)

- (0) Not entrapped
- (1) Entrapped
- (9) Unknown

RESTRAINT SYSTEM EVALUATION

17. Manual (Active) Belt System Availability 4

- (0) None available
- (1) Belt removed/destroyed
- (2) Shoulder belt
- (3) Lap belt
- (4) Lap and shoulder belt
- (5) Belt available—type unknown

Integral Belt Partially Destroyed

- (6) Shoulder belt (lap belt destroyed/removed)
- (7) Lap belt (shoulder belt destroyed/removed)

(8) Other belt (specify): _____

(9) Unknown _____

18. Manual (Active) Belt System Use 4

- (00) None used, not available, or belt removed/destroyed
- (01) Inoperative (specify): _____

(02) Shoulder belt _____

(03) Lap belt _____

(04) Lap and shoulder belt _____

(05) Belt used—type unknown _____

(08) Other belt used (specify): _____

(12) Shoulder belt used with child safety seat _____

(13) Lap belt used with child safety seat _____

(14) Lap and shoulder belt used with child safety seat _____

(15) Belt used with child safety seat—type unknown _____

(18) Other belt used with child safety seat (specify): _____

(99) Unknown if belt used _____

19. Proper Use of Manual (Active) Belts 1

- (0) None used or not available
- (1) Belt used properly
- (2) Belt used properly with child safety seat

Belt Used Improperly

- (3) Shoulder belt worn under arm
- (4) Shoulder belt worn behind back or seat
- (5) Belt worn around more than one person
- (6) Lap belt worn on abdomen
- (7) Lap belt or lap and shoulder belt used improperly with child safety seat (specify): _____

(8) Other improper use of manual belt system (specify): _____

(9) Unknown _____

20. Manual (Active) Belt Failure Modes During Accident 1

- (0) No manual belt used
- (1) No manual belt failure(s)
- (2) Torn webbing (stretched webbing not included)
- (3) Broken buckle or latchplate
- (4) Upper anchorage separated
- (5) Other anchorage separated (specify): _____

(6) Broken retractor _____

(7) Combination of above (specify): _____

(8) Other manual belt failure (specify): _____

(9) Unknown _____

21. Air Bag System Availability/Function 4

- (0) Not equipped/not available
- (1) Air bag

Non-functional

(2) Air bag disconnected (specify): _____

(3) Air bag not reinstalled _____

(9) Unknown _____

22. Air Bag System Deployment 4

- (0) Not equipped/not available
- (1) Air bag deployed during accident (as a result of impact)
- (2) Air bag deployed inadvertently just prior to accident
- (3) Air bag deployed, accident sequence undetermined
- (4) Nondeployed
- (5) Unknown if deployed
- (6) Air bag deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)
- (9) Unknown

23. Are There Indications of Air Bag System Failure? 4

- (0) Not equipped/not available
- (1) No
- (2) Yes (specify): _____

(9) Unknown _____

Note: See Variables 44 through 48 (Page 5) for Information on Automatic Belts

24. Police Reported Restraint Use 4

- (0) None used
- (1) Police did not indicate restraint use
- (2) Shoulder belt
- (3) Lap belt
- (4) Lap and shoulder belt
- (5) Belt used, type not specified
- (6) Child safety seat
- (7) Other or automatic restraint (specify): _____

(8) Restrained, type unknown _____

(9) Police indicated "unknown" _____

HEAD RESTRAINT AND SEAT EVALUATION

25. Head Restraint Type/Damage by Occupant at This Occupant Position ϕ

- (0) No head restraints
- (1) Integral—no damage
- (2) Integral—damaged during accident
- (3) Adjustable—no damage
- (4) Adjustable—damaged during accident
- (5) Add-on—no damage
- (6) Add-on—damaged during accident
- (8) Other (specify): _____

(9) Unknown

26. Seat Type (this Occupant Position) ϕ 9

- (00) Occupant not seated or no seat
- (01) Bucket
- (02) Bucket with folding back
- (03) Bench
- (04) Bench with separate back cushions
- (05) Bench with folding back(s)
- (06) Split bench with separate back cushions
- (07) Split bench with folding back(s)
- (08) Pedestal (i.e., column supported)
- (09) Other seat type (specify):

FOLDING "JUMP" SEAT

- (10) Box mounted seat (i.e., van type)
- (99) Unknown

27. Seat Performance (this Occupant Position) 1

- (0) Occupant not seated or no seat
- (1) No seat performance failure(s)
- (2) Seat adjusters failed
- (3) Seat back folding locks or "seat back" failed (specify): _____
- (4) Seat track/anchors failed
- (5) Deformed by impact of occupant
- (6) Deformed by passenger compartment intrusion (specify): _____

(7) Combination of above (specify): _____

(8) Other (specify): _____

(9) Unknown

CHILD SAFETY SEAT

28. Child Safety Seat Make/Model ϕ ϕ ϕ
 (000) No child safety seat
 Applicable codes are found in your NASS CDS
 Data Collection, Coding and Editing
 (950) Built-in child safety seat
 (997) Other make/model (specify):

(998) Unknown make/model
 (999) Unknown if child safety seat used

29. Type of Child Safety Seat ϕ
 (0) No child safety seat
 (1) Infant seat
 (2) Toddler seat
 (3) Convertible seat
 (4) Booster seat
 (7) Other type child safety seat (specify):

(8) Unknown child safety seat type
 (9) Unknown if child safety seat used

30. Child Safety Seat Orientation ϕ ϕ
 (00) No child safety seat

Designed for Rear Facing for This Age/Weight

(01) Rear facing
 (02) Forward facing
 (08) Other orientation (specify):

(09) Unknown orientation

Designed For Forward Facing for This Age/Weight

(11) Rear facing
 (12) Forward facing
 (18) Other orientation (specify):

(19) Unknown orientation

Unknown Design or Orientation For This Age/Weight, or Unknown Age/Weight

(21) Rear facing
 (22) Forward facing
 (28) Other orientation (specify):

(29) Unknown orientation

(99) Unknown if child safety seat used

31. Child Safety Seat Harness Usage ϕ ϕ

32. Child Safety Seat Shield Usage ϕ ϕ

33. Child Safety Seat Tether Usage ϕ ϕ

Note: Options below applicable to
 Variables OA31-OA33.

(00) No child safety seat

Not Designed With Harness/Shield/Tether

(01) After market harness/shield/tether
 added, not used
 (02) After market harness/shield/tether used
 (03) Child safety seat used, but no after market
 harness/shield/tether added
 (09) Unknown if harness/shield/tether
 added or used

Designed With Harness/Shield/Tether

(11) Harness/shield/tether not used
 (12) Harness/shield/tether used
 (19) Unknown if harness/shield/tether used

Unknown If Designed With Harness/Shield/Tether

(21) Harness/shield/tether not used
 (22) Harness/shield/tether used
 (29) Unknown if harness/shield/tether used

(99) Unknown if child safety seat used

INJURY CONSEQUENCES34. Injury Severity (Police Rating) 3

- (0) O - No injury
- (1) C - Possible injury
- (2) B - Nonincapacitating injury
- (3) A - Incapacitating injury
- (4) K - Killed
- (5) U - Injury, severity unknown
- (6) Died prior to accident
- (9) Unknown

35. Treatment - Mortality 4

- (0) No treatment
- (1) Fatal
- (2) Fatal - ruled disease (specify):

Nonfatal

- (3) Hospitalization
- (4) Transported and released
- (5) Treatment at scene - nontransported
- (6) Treatment later
- (8) Treatment - other (specify):

(9) Unknown

36. Type Of Medical Facility (for Initial Treatment) 2

- (0) Not treated at a medical facility
- (1) Trauma center
- (2) Hospital
- (3) Medical clinic
- (4) Physician's office
- (5) Treatment later at medical facility
- (8) Other (specify):

(9) Unknown

37. Hospital Stay φ φ

- (00) Not Hospitalized
- _____ Code the number of days (up through 60) that the occupant stayed in hospital.
- (61) 61 days or more
- (99) Unknown

99. Case Occupant φ

- (0) Not Case Occupant
- (1) This is the Case Occupant
- (2) This is the Case Occupant in another case

38. Working Days Lost 9 7

- _____ Code the number of days (up through 60) that the occupant lost from work due to the accident
- (00) No working days lost
- (61) 61 days or more
- (62) Fatally injured
- (97) Not working prior to accident
- (99) Unknown

STOP - GO TO VARIABLE 44 ON PAGE 7**VARIABLES 39 THROUGH 43 ARE COMPLETED BY THE ZONE CENTER**39. Time to Death φ φ

- _____ Code number of hours from time of accident to time of death up through 24 hours. If time of death is greater than 24 hours, code number of days. (Note: 1 day = 31, 2 days = 32, ... n days = 30 + n up through 30 days = 60)
- (00) Not fatal
- (96) Fatal - ruled disease
- (99) Unknown

40. 1st Medically Reported Cause of Death φ φ41. 2nd Medically Reported Cause of Death φ φ42. 3rd Medically Reported Cause of Death φ φ

- _____ Code the Occupant Injury from line number(s) for the medically reported injury(s) which reportedly contributed to this occupant's death
- (00) Not fatal or no additional causes
- (96) Mode of death given but specific injuries are not linked to cause of death. (specify):

(97) Other result (includes fatal ruled disease) (specify):

(99) Unknown

43. Number of Recorded Injuries for This Occupant φ 1

- _____ Code the actual number of injuries recorded for this occupant.
- (00) No recorded injuries
- (97) Injured, details unknown
- (99) Unknown if injured

AUTOMATIC BELT SYSTEM44. Automatic (Passive) Belt System Availability/Function ϕ

- (0) Not equipped/not available
- (1) 2 point automatic belts
- (2) 3 point automatic belts
- (3) Automatic belts - type unknown

Non-functional

- (4) Automatic belts destroyed or rendered inoperative
- (9) Unknown

45. Automatic (Passive) Belt System Use ϕ

- (0) Not equipped/not available/destroyed or rendered inoperative
- (1) Automatic belt in use
- (2) Automatic belt not in use (manually disconnected, motorized track inoperative) (specify): _____
- (3) Automatic belt use unknown
- (9) Unknown

46. Automatic (Passive) Belt System Type ϕ

- (0) Not equipped/not available
- (1) Non-motorized system
- (2) Motorized system
- (9) Unknown

47. Proper Use of Automatic (Passive) Belt System ϕ

- (0) Not equipped/not available/not used
- (1) Automatic belt used properly
- (2) Automatic belt used properly with child safety seat

Automatic Belt Used Improperly

- (3) Automatic shoulder belt worn under arm
- (4) Automatic shoulder belt worn behind back
- (5) Automatic belt worn around more than one person
- (6) Lap portion of automatic belt worn on abdomen
- (7) Automatic lap and shoulder belt or automatic shoulder belt used improperly with child safety seat (specify): _____
- (8) Other improper use of automatic belt system (specify): _____
- (9) Unknown

48. Automatic (Passive) Belt Failure Modes During Accident ϕ

- (0) Not equipped/not available/not in use
- (1) No automatic belt failure(s)
- (2) Torn webbing (stretched webbing not included)
- (3) Broken buckle or latchplate
- (4) Upper anchorage separated
- (5) Other anchorage separated (specify): _____
- (6) Broken retractor
- (7) Combination of above (specify): _____
- (8) Other automatic belt failure (specify): _____
- (9) Unknown

49. Seat Orientation (this Occupant Position) 1

- (0) Occupant not seated or no seat
- (1) Forward facing seat
- (2) Rear facing seat
- (3) Side facing seat (inward)
- (4) Side facing seat (outward)
- (8) Other (specify): _____
- (9) Unknown

Check the Primary Source Used In Determining Belt Use.

- [] Not equipped/not available/destroyed or rendered inoperative
- [X] Vehicle inspection
- [] Official injury data
- [] Driver/occupant interview
- [] Other (specify): _____

[] Unknown if belt used

ARE ALL APPLICABLE MEDICAL RECORDS INCLUDED WITH INITIAL SUBMISSION?

NO [X] YES []

UPDATE CANDIDATE?

NO [X] YES []

**STOP - VARIABLES 50 THROUGH 53 ARE
COMPLETED BY THE ZONE CENTER****TRAUMA DATA**

50. Glasgow Coma Scale (GCS) Score ϕ 2
(at Medical Facility)
(00) Not injured
(01) Injured - not treated at medical facility
(02) No GCS Score at medical facility
(03-15) Code the actual value of the
initial GCS Score recorded at medical
facility.
(97) Injured, details unknown
(99) Unknown if injured
51. Was the Occupant Given Blood? 1
(1) No - blood not given
(2) Yes - blood given
(specify units): _____
(9) Unknown if blood given
52. Arterial Blood Gases (ABG) - HCO_3 ϕ 1
(00) Not injured
(01) Injured, ABGs not measured or reported
(02-50) Code the actual value of the HCO_3
(96) ABGs reported , HCO_3 unknown
(97) Injured, details unknown
(99) Unknown if injured

BELT USE DETERMINATION

53. Primary Source of Belt Use Determination 1
(0) Not equipped/not available/destroyed
or rendered inoperative
(1) Vehicle inspection
(2) Official injury data
(3) Driver/occupant interview
(8) Other (specify): _____
(9) Unknown if belt used



OCCUPANT INJURY FORM

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

1. Primary Sampling Unit Number _____

3. Vehicle Number 022. Case Number - Stratum DSI-94-AB-0064. Occupant Number 03

INJURY DATA

Record below the actual injuries sustained by this occupant that were identified from the official and unofficial data sources. Remember not to double count an injury just because it was identified from two different sources. If greater than ten injuries have been documented, encode the balance on the Occupant Injury Supplement.



	Source of Injury Data	Body Region	Type of Anatomic Structure	Specific Anatomic Structure	Level of Injury	A.I.S. Severity	Aspect	Injury Source	Injury Source Confidence Level	Direct/ Indirect Injury	Occupant Area Intrusion Number	ICD-9
1st	5. <u>7</u>	6. <u>2</u>	7. <u>5</u>	8. <u>10</u>	9. <u>02</u>	10. <u>1</u>	11. <u>4</u>	12. <u>40</u>	13. <u>1</u>	14. <u>1</u>	15. <u>00</u>	<u>802.0</u>
2nd	16. ____	17. ____	18. ____	19. ____	20. ____	21. ____	22. ____	23. ____	24. ____	25. ____	26. ____	
3rd	27. ____	28. ____	29. ____	30. ____	31. ____	32. ____	33. ____	34. ____	35. ____	36. ____	37. ____	
4th	38. ____	39. ____	40. ____	41. ____	42. ____	43. ____	44. ____	45. ____	46. ____	47. ____	48. ____	
5th	49. ____	50. ____	51. ____	52. ____	53. ____	54. ____	55. ____	56. ____	57. ____	58. ____	59. ____	
6th	60. ____	61. ____	62. ____	63. ____	64. ____	65. ____	66. ____	67. ____	68. ____	69. ____	70. ____	
7th	71. ____	72. ____	73. ____	74. ____	75. ____	76. ____	77. ____	78. ____	79. ____	80. ____	81. ____	
8th	82. ____	83. ____	84. ____	85. ____	86. ____	87. ____	88. ____	89. ____	90. ____	91. ____	92. ____	
9th	93. ____	94. ____	95. ____	96. ____	97. ____	98. ____	99. ____	100. ____	101. ____	102. ____	103. ____	
10th	104. ____	105. ____	106. ____	107. ____	108. ____	109. ____	110. ____	111. ____	112. ____	113. ____	114. ____	

.I.S. - 90

ICD-9

OFFICIAL INJURY DATA — SOFT TISSUE INJURIES

Indicate the Location, Specific Anatomic Structure, Detail (size, depth, fracture type, head injury clinical signs and neurological deficits), and Source of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)



SOURCE OF INJURY DATA**OFFICIAL**

- (1) Autopsy records with or without hospital/medical records
- (2) Hospital/medical records other than emergency room (e.g., discharge summary)
- (3) Emergency room records only (including associated X-rays or other lab reports)
- (4) Private physician, walk-in or emergency clinic

UNOFFICIAL

- (5) Lay coroner report
- (6) E.M.S. personnel
- (7) Interviewee
- (8) Other source (specify): _____
- (9) Police

INJURY SOURCE**FRONT**

- (01) Windshield
- (02) Mirror
- (03) Sunvisor
- (04) Steering wheel rim
- (05) Steering wheel hub/spoke
- (06) Steering wheel (combination of codes 04 and 05)
- (07) Steering column, transmission selector lever, other attachment
- (08) Add on equipment (e.g., CB, tape deck, air conditioner)
- (09) Left instrument panel and below
- (10) Center instrument panel and below
- (11) Right instrument panel and below
- (12) Glove compartment door
- (13) Knee bolster
- (14) Windshield including one or more of the following: front header, A (A1/A2)-pillar, instrument panel, mirror, or steering assembly (driver side only)
- (15) Windshield including one or more of the following: front header, A (A1/A2)-pillar, instrument panel, or mirror (passenger side only)
- (16) Driver side air bag compartment cover
- (17) Passenger side air bag compartment cover
- (18) Windshield reinforced by exterior object (specify): _____
- (19) Other front object (specify): _____

LEFT SIDE

- (20) Left side interior surface, excluding hardware or armrests
- (21) Left side hardware or armrest
- (22) Left A (A1/A2)-pillar
- (23) Left B-pillar
- (24) Other left pillar (specify): _____

- (25) Left side window glass or frame
- (26) Left side window glass including one or more of the following: frame, window sill, A (A1/A2)-pillar, B-pillar, or roof side rail.
- (27) Other left side object (specify): _____
- (28) Left side window sill

RIGHT SIDE

- (30) Right side interior surface, excluding hardware or armrests
 - (31) Right side hardware or armrest
 - (32) Right A (A1/A2)-pillar
 - (33) Right B-pillar
 - (34) Other right pillar (specify): _____
 - (35) Right side window glass or frame
 - (36) Right side window glass including one or more of the following: frame, window sill, A (A1/A2)-pillar, B-pillar, or roof side rail.
 - (37) Other right side object (specify): _____
 - (38) Right side window sill
- INTERIOR**
- (40) Seat, back support
 - (41) Belt restraint webbing/buckle
 - (42) Belt restraint B-pillar or door frame attachment point
 - (43) Other restraint system component (specify): _____
 - (44) Head restraint system
 - (45) Air bag (use codes "16" and "17" for injuries sustained from air bag compartment covers)
 - (46) Other occupants (specify): _____
 - (47) Interior loose objects
 - (48) Child safety seat (specify): _____
 - (49) Other interior object (specify): _____

ROOF

- (50) Front header
- (51) Rear header
- (52) Roof left side rail
- (53) Roof right side rail
- (54) Roof or convertible top

FLOOR

- (56) Floor (including toe pan)
- (57) Floor or console mounted transmission lever, including console
- (58) Parking brake handle
- (59) Foot controls including parking brake

REAR

- (60) Backlight (rear window)

- (61) Backlight storage rack, door, etc.
- (62) Other rear object (specify): _____

EXTERIOR of OCCUPANT'S VEHICLE

- (65) Hood
- (66) Outside hardware (e.g., outside mirror, antenna)
- (67) Other exterior surface or tires (specify): _____
- (68) Unknown exterior objects

EXTERIOR of OTHER MOTOR VEHICLE

- (70) Front bumper
- (71) Hood edge
- (72) Other front of vehicle (specify): _____
- (73) Hood
- (74) Hood ornament
- (75) Windshield, roof rail, A-pillar
- (76) Side surface
- (77) Side mirrors
- (78) Other side protrusions (specify) _____
- (79) Rear surface
- (80) Undercarriage
- (81) Tires and wheels
- (82) Other exterior of other motor vehicle (specify): _____
- (83) Unknown exterior of other motor vehicle

OTHER VEHICLE OR OBJECT IN THE ENVIRONMENT

- (84) Ground
- (85) Other vehicle or object (specify) _____
- (86) Unknown vehicle or object

NONCONTACT INJURY

- (90) Fire in vehicle
- (91) Flying glass
- (92) Other noncontact injury source (specify): _____
- (93) Air bag exhaust gases
- (97) Injured, unknown source

INJURY SOURCE CONFIDENCE LEVEL

- (1) Certain
- (2) Probable
- (3) Possible
- (9) Unknown

DIRECT/INDIRECT INJURY

- (1) Direct contact injury
- (2) Indirect contact injury
- (3) Noncontact injury
- (7) Injured, unknown source

OCCUPANT INJURY CLASSIFICATION

Body Region	Specific Anatomic Structure	Spine	Abbreviated Injury Scale
(1) Head	<u>Whole Area</u>	(02) Cervical	(1) Minor injury
(2) Face	(02) Skin - Abrasion	(04) Thoracic	(2) Moderate injury
(3) Neck	(04) Skin - Contusion	(06) Lumbar	(3) Serious injury
(4) Thorax	(06) Skin - Laceration	<u>Vessels, Nerves, Organs, Bones,</u>	(4) Severe injury
(5) Abdomen	(08) Skin - Avulsion	<u>Joints are assigned consecutive</u>	(5) Critical injury
(6) Spine	(10) Amputation	two digit numbers beginning with 02	(6) Maximum (untreatable)
(7) Upper Extremity	(20) Burn	Level of Injury	(7) Injured, unknown severity
(8) Lower Extremity	(30) Crush	Specific injuries are assigned consecutive two-digit numbers beginning with 02.	Aspect
(9) Unspecified	(40) Degloving		
Type of Anatomic Structure	(50) Injury - NFS	To the extent possible, within the organizational framework of the AIS, 00 is assigned to an injury NFS as to severity or where only one injury is given in the dictionary for that anatomic structure. 99 is assigned to any injury NFS as to lesion or severity.	(1) Right
	(90) Trauma, other than mechanical		(2) Left
	<u>Head - LOC</u>		(3) Bilateral
	(02) Length of LOC		(4) Central
	(04, 06, 08) Level of Consciousness		(5) Anterior
(1) Whole Area	(10) Concussion		(6) Posterior
(2) Vessels			(7) Superior
(3) Nerves			(8) Inferior
(4) Organs (includes muscles/ligaments)			(9) Unknown
(5) Skeletal (includes joints)			(0) Whole region
(6) Head - LOC			
(9) Skin			

OFFICIAL INJURY DATA — SKELETAL INJURIES

Restrained?

— No

X Yes

Blood Alcohol Level
(mg/dl)

BAL = ϕ

Glasgow Coma
Scale Score

GCSS = ϕ

Units of Blood
Given

Units = ϕ

Arterial Blood Gases



pH = ϕ

PO₂ = ϕ

PCO₂ = ϕ



HCO₃ = ϕ

Indicate the Location, Specific Anatomic Structure, Detail (size, depth, fracture type, head injury clinical signs and neurological deficits), and Source of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)



OFFICIAL INJURY DATA — INTERNAL INJURIES

Indicate the Location, Specific Anatomic Structure, Detail (size, depth, fracture type, head injury clinical signs and neurological deficits), and Source of all injuries indicated by official sources (or from PAR or other unofficial sources if medical records and interviewee data are unavailable.)





GENERAL VEHICLE FORM

1. Primary Sampling Unit Number _____
2. Case Number - Stratum DSI-94-AB-φφ6
3. Vehicle Number φ 3

VEHICLE IDENTIFICATION

4. Vehicle Model Year 9 φ
Code the last two digits of the model year
(99) Unknown
5. Vehicle Make (specify): 1 4
MERCURY
Applicable codes are found in your
NASS Data Collection, Coding and
Editing Manual.
(99) Unknown
6. Vehicle Model (specify): φ φ 4
COUGAR
Applicable codes are found in your
NASS Data Collection, Coding and
Editing Manual.
(999) Unknown
7. Body Type φ 2
Note: Applicable codes may be found on
the back of this page.
8. Vehicle Identification Number
1 M E P M 6 φ 4 φ L H Y Y Y Y Y Y
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17
Left justify; Slash zeros and letter Z (0 and Z)
No VIN—Code all zeros
Unknown—Code all nines

OFFICIAL RECORDS

9. Police Reported Vehicle Disposition 1
(0) Not towed due to vehicle damage
(1) Towed due to vehicle damage
(9) Unknown
10. Police Reported Travel Speed 9 9 9
Code to the nearest kph (NOTE: 000 means
less than 0.5 kph)
(160) 159.5 kph and above
(999) Unknown
____ mph X 1.6093 = ____ kph

11. Police Reported Alcohol Presence φ
(0) No alcohol present
(1) Yes (alcohol present)
(7) Not reported
(8) No driver present
(9) Unknown

Note: See variables 37 through 55
(Page 4) for information on Other Drugs

12. Alcohol Test Result For Driver 9 6
Code actual value (decimal implied
before first digit—0.xx)
(95) Test refused
(96) None given
(97) AC test performed, results unknown
(98) No driver present
(99) Unknown

Source: PAR

ACCIDENT RELATED

13. Speed Limit φ 6 4
(000) No statutory limit
Code posted or statutory speed limit
in kph
(999) Unknown
4 φ mph X 1.6093 = φ 6 4 kph
14. Attempted Avoidance Maneuver φ 4
(01) No avoidance actions
(02) Braking (no lockup)
(03) Braking (lockup)
(04) Braking (lockup unknown)
(05) Releasing brakes
(06) Steering left
(07) Steering right
(08) Braking and steering left
(09) Braking and steering right
(10) Accelerating
(11) Accelerating and steering left
(12) Accelerating and steering right
(97) No driver present
(98) Other action (specify):
(99) Unknown
15. Accident Type 9 8
Applicable codes may be found on the
back of page two of this field form
(00) No impact
Code the number of the diagram that
best describes the accident circumstance
(98) Other accident type (specify):
THIRD VEHICLE IN THREE VEHICLE CRASH
(99) Unknown

**** SKIP TO VARIABLE GV37 IF GV07 DOES NOT EQUAL 01-49 ****

CODES FOR BODY TYPE

CDS APPLICABLE VEHICLES

Automobiles

- (01) Convertible (excludes sun-roof, t-bar)
- (02) 2-door sedan, hardtop, coupe
- (03) 3-door/2-door hatchback
- (04) 4-door sedan, hardtop
- (05) 5-door/4-door hatchback
- (06) Station wagon (excluding van and truck based)
- (07) Hatchback, number of doors unknown
- (08) Other automobile type (specify): _____
- (09) Unknown automobile type

Automobile Derivatives

- (10) Auto based pickup (includes El Camino, Caballero, Ranchero, Brat, and Rabbit pickup)
- (11) Auto based panel (cargo station wagon, auto based ambulance/hearse)
- (12) Large limousine - more than four side doors or stretched chassis
- (13) Three-wheel automobile or automobile derivative

Utility Vehicles ($\leq 4,500$ kgs GVWR)

- (14) Compact utility (Jeep CJ-2 - CJ-7, Scrambler, Golden Eagle, Renegade, Laredo, Wrangler, Cherokee [84 and after], Dispatcher, Raider, Bronco II, Bronco [76 and before], Explorer, S-10 Blazer, Geo Tracker, Bravada, S-15 Jimmy, Thing, Pathfinder, Trooper, Trooper II, Rodeo, Amigo, Navajo, 4-Runner, Montero, Samurai, Sidekick, Rocky)
- (15) Large utility (includes Jeep Cherokee [83 and before], Ramcharger, Trailduster, Bronco-fullsize [78 and after], fullsize Blazer, fullsize Jimmy, Landcruiser, Rover, Scout)
- (16) Utility station wagon (Chevy Suburban, GMC Suburban, Travelall, Grand Wagoneer, includes suburban limousine)
- (19) Utility, unknown body type

Van Based Light Trucks ($\leq 4,500$ kgs GVWR)

- (20) Minivan (Chrysler Town and Country, Caravan, Grand Caravan, Voyager, Grand Voyager, Mini-Ram, Dodge/Plymouth Vista, Aerostar, Villager, Lumina APV, Trans Sport, Silhouette, Astro, Safari, Toyota Van, Toyota Minivan, Previa, Nissan Minivan, Quest, Mitsubishi Minivan, Vanagon/Camper.)
- (21) Large van (B150-B350, Sportsman, Royal, Maxiwagon, Ram, Tradesman, Voyager [83 and before], E150-E350, Econoline, Clubwagon, Chateau, G10-G30, Chevy Van, Beauville, Sport Van, G15-G35, Rally Van, Vandura.)
- (22) Step van or walk-in van ($\leq 4,500$ kgs GVWR)
- (23) Van based motorhome ($\leq 4,500$ kgs GVWR)
- (24) Van based school bus ($\leq 4,500$ kgs GVWR)
- (25) Van based other bus ($\leq 4,500$ kgs GVWR)
- (28) Other van type (Hi-Cube Van, Kary) (specify): _____
- (29) Unknown van type

Light Conventional Trucks (Pickup style cab, $\leq 4,500$ kgs GVWR)

- (30) Compact pickup (D50, Colt P/U, Ram 50, Dakota, Arrow Pickup [foreign], Ranger, Courier, S-10, T-10, LUV, S-15, T-15, Sonoma, Datsun/Nissan Pickup, P'up, Mazda Pickup, Toyota Pickup, Mitsubishi Pickup)
- (31) Large Pickup (Jeep Pickup, Comanche, Ram Pickup, D100-D350, W100-W350, F100-F350, C10-C35, K10-K35, R10-R35, V10-V35, Silverado, Sierra, R100-R500,)

- (32) Pickup with slide-in camper
- (33) Convertible pickup
- (39) Unknown pickup style light conventional truck type

Other Light Trucks ($\leq 4,500$ kgs GVWR)

- (40) Cab chassis based (includes rescue vehicles, light stake, dump, and tow truck)
- (41) Truck based panel
- (42) Light truck based motorhome (chassis mounted)
- (45) Other light conventional truck type
- (48) Unknown light truck type
- (49) Unknown light vehicle type (automobile, utility, van, or light truck)

OTHER VEHICLES

Buses (Excludes Van Based)

- (50) School bus (designed to carry students, not cross country or transit)
- (58) Other bus type (e.g., transit, intercity, bus based motorhome) (specify): _____
- (59) Unknown bus type

Medium/Heavy Trucks ($> 4,500$ kgs GVWR)

- (60) Step van ($> 4,500$ kgs GVWR)
- (61) Single unit straight truck ($4,500$ kgs $<$ GVWR $\leq 8,850$ kgs)
- (62) Single unit straight truck ($8,850$ kgs $<$ GVWR $\leq 12,000$ kgs)
- (63) Single unit straight truck ($> 12,000$ kgs GVWR)
- (64) Single unit straight truck, GVWR unknown
- (65) Medium/heavy truck based motorhome
- (67) Truck-tractor with no cargo trailer
- (68) Truck-tractor pulling one trailer
- (69) Truck-tractor pulling two or more trailers
- (70) Truck-tractor (unknown if pulling trailer)
- (78) Unknown medium/heavy truck type
- (79) Unknown truck type (light/medium/heavy)

Motored Cycles (Does Not Include All-Terrain Vehicles/Cycles)

- (80) Motorcycle
- (81) Moped (motorized bicycle)
- (82) Three-wheel motorcycle or moped
- (88) Other motored cycle (minibike, motorscooter) (specify): _____
- (89) Unknown motored cycle type

Other Vehicles

- (90) ATV (All-Terrain Vehicle) and ATC (All-Terrain Cycle)
- (91) Snowmobile
- (92) Farm equipment other than trucks
- (93) Construction equipment other than trucks
- (97) Other vehicle type
- (99) Unknown body type

OCCUPANT RELATED

16. Driver Presence in Vehicle 1
 (0) Driver not present
 (1) Driver present
 (9) Unknown
17. Number of Occupants This Vehicle 2
 (00-96) Code actual number of occupants for this vehicle
 (97) 97 or more
 (99) Unknown
18. Number of Occupant Forms Submitted 2

24. Rollover 0
 (0) No rollover (no overturning)
- Rollover (primarily about the longitudinal axis)*
 (1) Rollover, 1 quarter turn only
 (2) Rollover, 2 quarter turns
 (3) Rollover, 3 quarter turns
 (4) Rollover, 4 or more quarter turns (specify):

- (5) Rollover--end-over-end (i.e., primarily about the lateral axis)
 (9) Rollover (overturn), details unknown

VEHICLE WEIGHT ITEMS

19. Vehicle Curb Weight 1,640
 _____ Code weight to nearest 10 kilograms.
 (045) Less than 450 kilograms
 (610) 6,100 kilograms or more
 (999) Unknown
- 3,600 lbs X .4536 = 1,631 kgs
- Source: _____
20. Vehicle Cargo Weight 9,990
 _____ Code weight to nearest 10 kilograms.
 (000) Less than 5 kilograms
 (450) 4,500 kilograms or more
 (999) Unknown
- _____ lbs X .4536 = _____ kgs

OVERRIDE/UNDERRIDE (THIS VEHICLE)

25. Front Override/Underride (this Vehicle) 0
26. Rear Override/Underride (this Vehicle) 0
- (0) No override/underride, or not an end-to-end impact
- Override (see specific CDC)*
 (1) 1st CDC
 (2) 2nd CDC
 (3) Other not automated CDC (specify):

- Underride (see specific CDC)*
 (4) 1st CDC
 (5) 2nd CDC
 (6) Other not automated CDC (specify):

- (7) Medium/heavy truck or bus override
 (9) Unknown




























































RECONSTRUCTION DATA

21. Towed Trailing Unit 0
 (0) No towed unit
 (1) Yes--towed trailing unit
 (9) Unknown
22. Documentation of Trajectory Data for This Vehicle 0
 (0) No
 (1) Yes
23. Post Collision Condition of Tree or Pole (For Highest Delta V) 0
 (0) Not collision (for highest delta V) with tree or pole
 (1) Not damaged
 (2) Cracked/sheared
 (3) Tilted < 45 degrees
 (4) Tilted ≥ 45 degrees
 (5) Uprooted tree
 (6) Separated pole from base
 (7) Pole replaced
 (8) Other (specify):

 (9) Unknown

HEADING ANGLE AT IMPACT FOR HIGHEST DELTA V

- Values: (000)-(359) Code actual value
 (997) Noncollision
 (998) Impact with object
 (999) Unknown
27. Heading Angle For This Vehicle 050
28. Heading Angle For Other Vehicle 340

Category	Configuration	ACCIDENT TYPES (Includes Intent)				
I. Single Driver	A. Right Roadside Departure	 01 DRIVE OFF ROAD	 02 CONTROL/ TRACTION LOSS	 03 AVOID COLLISION WITH VEH., PED., ANIM.	04 SPECIFICS OTHER	05 SPECIFICS UNKNOWN
	B. Left Roadside Departure	 06 DRIVE OFF ROAD	 07 CONTROL/ TRACTION LOSS	 08 AVOID COLLISION WITH VEH., PED., ANIM.	09 SPECIFICS OTHER	10 SPECIFICS UNKNOWN
	C. Forward Impact	 11 PARKED VEH.	 12 STA. OBJECT	 13 PEDESTRIAN/ ANIMAL	 14 END DEPARTURE	15 SPECIFICS OTHER 16 SPECIFICS UNKNOWN
II Same Trafficway Same Direction	D. Rear-End	 20 STOPPED 21, 22, 23	 24 SLOWER 25, 26, 27	 28 DECEL. 29, 30, 31	 30 SPECIFICS OTHER	 31 SPECIFICS UNKNOWN
	E. Forward Impact	 34 CONTROL/ TRACTION LOSS	 36 CONTROL/ TRACTION LOSS	 38 AVOID COLLISION WITH VEH.	 40 AVOID COLLISION WITH OBJECT	 41 SPECIFICS OTHER  42 SPECIFICS UNKNOWN
	F. Sideswipe Angle	 44 SPECIFICS OTHER	 45 SPECIFICS OTHER	 46 SPECIFICS OTHER	 47 SPECIFICS OTHER	(EACH • 48) SPECIFICS UNKNOWN (EACH • 49) SPECIFICS UNKNOWN
III Same Trafficway Opposite Direction	G. Head-On	 50 LATERAL MOVE	 51 SPECIFICS OTHER	 52 SPECIFICS UNKNOWN	 53 SPECIFICS UNKNOWN	
	H. Forward Impact	 54 CONTROL/ TRACTION LOSS	 56 CONTROL/ TRACTION LOSS	 58 AVOID COLLISION WITH VEH.	 60 AVOID COLLISION WITH OBJECT	 61 SPECIFICS OTHER  62 SPECIFICS UNKNOWN
	I. Sideswipe Angle	 64 LATERAL MOVE	 65 SPECIFICS OTHER	 66 SPECIFICS UNKNOWN	 67 SPECIFICS UNKNOWN	
IV. Change Trafficway Vehicle Turning	J. Turn Across Path	 68 INITIAL OPPOSITE DIRECTIONS	 71 INITIAL SAME DIRECTIONS	 73 SPECIFICS OTHER	 74 SPECIFICS UNKNOWN	 75 SPECIFICS UNKNOWN
	K. Turn Into Path	 76 TURN INTO SAME DIRECTION	 79 TURN INTO OPPOSITE DIRECTIONS	 81 SPECIFICS OTHER	 82 SPECIFICS UNKNOWN	 83 SPECIFICS UNKNOWN
V. Intersecting Paths (Vehicle Damage)	L. Straight Paths	 87 SPECIFICS OTHER	 88 SPECIFICS OTHER	 89 SPECIFICS OTHER	 90 SPECIFICS UNKNOWN	 91 SPECIFICS UNKNOWN
VI. Miscellaneous	M. Backing Etc.	 92 BACKING VEH.	 93 OTHER VEH. OR OBJECT	 98 Other Accident Type	 99 Unknown Accident Type	 00 No Impact

29. Basis for Total Delta V (highest)

6*Delta V Calculated*

- (1) CRASH program—damage only routine
- (2) CRASH program—damage and trajectory routine
- (3) Missing vehicle algorithm

Delta V Not Calculated

- (4) At least one vehicle (which may be this vehicle) is beyond the scope of an acceptable reconstruction program, regardless of collision conditions.
- (5) All vehicles within scope (CDC applicable) of CRASH program but one of the collision conditions is beyond the scope of the CRASH program or other acceptable reconstruction technique, regardless of adequacy of damage data.
- (6) All vehicle and collision conditions are within scope of one of the acceptable reconstruction programs, but there is insufficient data available.

Highest

32. Lateral Component of Delta V

+
- 9 9 9

____ Nearest kph (highest)

____ Nearest kph (secondary)

(NOTE: __000 means greater than
-0.5 kph and less than +0.5 kph)
(±160) ±159.5 kph and above
(__999) Unknown

33. Energy Absorption

9 9 9 , 9 0 0

____ Nearest 100 joules (highest)

____ Nearest 100 joules (secondary)

(NOTE: 0000 means less than 50 joules)
(9997) 999,650 joules or more
(9999) Unknown

COMPUTER GENERATED DELTA V

30. Total Delta V

Highest
9 9 9

____ Nearest kph (highest)

____ Nearest kph (secondary)

(NOTE: 000 means less than
0.5 kph)
(160) 159.5 kph and above
(999) Unknown

31. Longitudinal Component of
Delta V+
- 9 9 9

____ Nearest kph (highest)

____ Nearest kph (secondary)

(NOTE: __000 means greater than
-0.5 kph and less than +0.5 kph)
(±160) ±159.5 kph and above
(__999) Unknown

34. Confidence In Reconstruction Program
Results (For Highest Delta V)

- (0) No reconstruction φ
- (1) Collision fits model — results appear reasonable
- (2) Collision fits model — results appear high
- (3) Collision fits model — results appear low
- (4) Borderline reconstruction — results appear reasonable

35. Type of Vehicle Inspection

- (0) No inspection φ
- (1) Complete inspection
- (2) Partial inspection (specify):

36. Is this an AOPS Vehicle?

- (0) No φ
- (1) Yes - researcher determined
- (2) VIN determined air bag system
- (3) VIN determined automatic (passive) belts
- (4) VIN determined air bag and automatic (passive) belts

IS OLDMISS APPLICABLE FOR THIS VEHICLE? [] YES [X] NO**IF YES: IS A COMPLETED OLDMISS PROGRAM SUMMARY INCLUDED? [] YES [] NO**

37. Police Reported Other Drug Presence ϕ

- (0) No other drug(s) present
- (1) Yes [other drug(s) present]
- (7) Not reported
- (8) No driver present
- (9) Unknown

38. Police Reported Drug Evaluation Classification (DEC) Test For Driver ϕ

- (0) No DEC process available or given
- (1) DEC process given, results known
- (2) DEC process given, results unknown
- (3) DEC process available, unknown if given
- (8) No driver present

39. Other Drug Specimen Test Type For Driver ϕ

- (0) No specimen test given
- (1) Blood test
- (2) Urine test
- (3) Other specimen tests (specify): _____
- (7) Unspecified specimen test
- (8) No driver present
- (9) Unknown if specimen test given

DRUG EVALUATION CLASSIFICATION**OTHER DRUGS TEST RESULTS FOR DRIVER**

	DEC Test Results	Specimen Test Results
Narcotic Drug	40. <u> ϕ </u>	41. <u> ϕ </u>
Depressant Drug	42. <u> ϕ </u>	43. <u> ϕ </u>
Stimulant Drug	44. <u> ϕ </u>	45. <u> ϕ </u>
Hallucinogen Drug	46. <u> ϕ </u>	47. <u> ϕ </u>
Cannabinoid Drug	48. <u> ϕ </u>	49. <u> ϕ </u>
Phencyclidine (PCP)	50. <u> ϕ </u>	51. <u> ϕ </u>
Inhalant Drug	52. <u> ϕ </u>	53. <u> ϕ </u>
Other Drug (Excluding Nicotine, Aspirin, Alcohol, Drugs Administered Post-Crash)	54. <u> ϕ </u>	55. <u> ϕ </u>

Codes For DEC Test Results

- (0) No DEC test given
- (1) Passed DEC test
- (2) Failed DEC test
- (3) DEC test given—results unknown
- (8) No driver present
- (9) Unknown if DEC test given

Codes for Specimen Test Results

- (0) No specimen test given
- (1) Drug not found in specimen
- (2) Drug found in specimen
- (7) Specimen test given, results unknown or not obtained
- (8) No driver present
- (9) Unknown if specimen test given

OTHER DATA

56. Driver's Zip Code

- (00000) Driver not present
 (00001) Driver not a resident of U.S. or territories
 Code actual 5-digit zip code
 (99999) Unknown

57. Driver's Race/Ethnic Origin

9

- (0) Driver not present
 (1) White (non-Hispanic)
 (2) Black (non-Hispanic)
 (3) White (Hispanic)
 (4) Black (Hispanic)
 (5) American Indian, Eskimo or Aleut
 (6) Asian or Pacific Islander
 (8) Other (specify): _____
 (9) Unknown

58. Vehicle Special Use (This Trip)

φ

- (0) No special use
 (1) Taxi
 (2) Vehicle used as school bus
 (3) Vehicle used as other bus
 (4) Military
 (5) Police
 (6) Ambulance
 (7) Fire truck or car
 (8) Other (specify): _____
 (9) Unknown

ROLLOVER DATA

If GV07 (Body Type) ≠ 1-49, leave GV59-GV63 blank.
 If GV24 (Rollover) = 0, then GV59-GV63 must equal 0.
 If GV24 = 9, then GV59-GV63 must equal 9.

59. Rollover Initiation Type

φ

- (0) No rollover
 (1) Trip-over
 (2) Flip-over
 (3) Turn-over
 (4) Climb-over
 (5) Fall-over
 (6) Bounce-over
 (7) Collision with another vehicle
 (8) Other rollover initiation type specify): _____
 (9) Unknown rollover initiation type

60. Location of Rollover Initiation

φ

- (0) No rollover
 (1) On roadway
 (2) On shoulder—paved
 (3) On shoulder—unpaved
 (4) On roadside or divided trafficway median
 (9) Unknown

61. Rollover Initiation Object Contacted

φ φ

62. Location on Vehicle Where Initial Principal Tripping Force Is Applied

φ

- (0) No rollover
 (1) Wheels/tires
 (2) Side plane
 (3) End plane
 (4) Undercarriage
 (5) Other location on vehicle (specify): _____
 (8) Non-contact rollover forces (specify): _____
 (9) Unknown

63. Direction of Initial Roll

φ

- (0) No rollover
 (1) Roll right - primarily about the longitudinal axis
 (2) Roll left - primarily about the longitudinal axis
 (5) End-over-end (i.e., primarily about the lateral axis)
 (9) Unknown roll direction

PRECRAASH DATA

64. Pre-Event Movement (Prior to Recognition of Critical Event)

1 3

- (01) Going straight
 (02) Slowing or stopping in traffic lane
 (03) Starting in traffic lane
 (04) Stopped in traffic lane
 (05) Passing or overtaking another vehicle
 (06) Disabled or parked in travel lane
 (07) Leaving a parking position
 (08) Entering a parking position
 (09) Turning right
 (10) Turning left
 (11) Making a U-turn
 (12) Backing up (other than for parking position)
 (13) Negotiating a curve
 (14) Changing lanes
 (15) Merging
 (16) Successful avoidance maneuver to a previous critical event
 (97) Other (specify): _____
 (98) No driver present
 (99) Unknown

CODES FOR ROLLOVER INITIATION OBJECT CONTACTED

- (00) No rollover
- (01-30) — Vehicle Number

Noncollision

- (31) Turn-over — fall-over
- (33) Jackknife

Collision With Fixed Object

- (41) Tree (≤ 10 cm in diameter)
- (42) Tree (> 10 cm in diameter)
- (43) Shrubbery or bush
- (44) Embankment

- (45) Breakaway pole or post (any diameter)

Nonbreakaway Pole or Post

- (50) Pole or post (≤ 10 cm in diameter)
- (51) Pole or post (> 10 cm but ≤ 30 cm in diameter)
- (52) Pole or post (> 30 cm in diameter)
- (53) Pole or post (diameter unknown)

- (54) Concrete traffic barrier
- (55) Impact attenuator
- (56) Other traffic barrier (includes guardrail)
(specify): _____

- (57) Fence
- (58) Wall
- (59) Building
- (60) Ditch or culvert
- (61) Ground
- (62) Fire hydrant
- (63) Curb
- (64) Bridge
- (68) Other fixed object (specify): _____

- (69) Unknown fixed object

Collision with Nonfixed Object

- (71) Motor vehicle not in-transport
- (76) Animal
- (77) Train
- (78) Trailer, disconnected in transport
- (79) Object fell from vehicle in-transport
- (88) Other nonfixed object (specify): _____

- (89) Unknown nonfixed object

- (98) Other event (specify): _____

- (99) Unknown event or object

PRECRASH DATA (Continued)

65. Critical Precrash Event 1 1*This Vehicle Loss of Control Due To:*

- (01) Blow out or flat tire
- (02) Stalled engine
- (03) Disabling vehicle failure (e.g., wheel fell off) (specify): _____
- (04) Non-disabling vehicle problem (e.g., hood flew up) (specify): _____
- (05) Poor road conditions (puddle, pot hole, ice, etc.) (specify): _____
- (06) Traveling too fast for conditions
- (08) Other cause of control loss (specify): _____
- (09) Unknown cause of control loss

This Vehicle Traveling

- (10) Over the lane line on left side of travel lane
- (11) Over the lane line on right side of travel lane
- (12) Off the edge of the road on the left side
- (13) Off the edge of the road on the right side
- (14) End departure
- (15) Turning left at intersection
- (16) Turning right at intersection
- (17) Crossing over (passing through) intersection
- (19) Unknown travel direction

Other Motor Vehicle In Lane

- (50) Stopped
- (51) Traveling in same direction with lower speed (i.e., lower steady speed or decelerating)
- (52) Traveling in same direction with higher speed
- (53) Traveling in opposite direction
- (54) In crossover
- (55) Backing
- (59) Unknown travel direction of other motor vehicle in lane

Other Motor Vehicle Encroaching Into Lane

- (60) From adjacent lane (same direction)—over left lane line
- (61) From adjacent lane (same direction)—over right lane line
- (62) From opposite direction—over left lane line
- (63) From opposite direction—over right lane line
- (64) From parking lane
- (65) From crossing street, turning into same direction
- (66) From crossing street, across path
- (67) From crossing street, turning into opposite direction
- (68) From crossing street, intended path not known
- (70) From driveway, turning into same direction
- (71) From driveway, across path
- (72) From driveway, turning into opposite direction
- (73) From driveway, intended path not known
- (74) From entrance to limited access highway
- (78) Encroachment by other vehicle—details unknown

Pedestrian or Pedalcyclist, or Other Nonmotorist

- (80) Pedestrian in roadway
- (81) Pedestrian approaching roadway
- (82) Pedestrian—unknown location
- (83) Pedalcyclist or other nonmotorist in roadway (specify): _____
- (84) Pedalcyclist or other nonmotorist approaching roadway (specify): _____
- (85) Pedalcyclist or other nonmotorist—unknown location (specify): _____

Object or Animal

- (87) Animal in roadway
- (88) Animal approaching roadway
- (89) Animal—unknown location
- (90) Object in roadway
- (91) Object approaching roadway
- (92) Object—unknown location

(98) Other critical precrash event (specify): _____

(99) Unknown

For Corrective Actions Attempted see variable GV14 (Attempted Avoidance Manuever)

66. Precrash Stability After Avoidance Maneuver 1

- (0) No avoidance maneuver
- (1) Tracking
- (2) Skidding longitudinally—rotation less than 30 degrees
- (3) Skidding laterally—clockwise rotation
- (4) Skidding laterally—counterclockwise rotation
- (7) Other vehicle loss-of-control (specify): _____
- (8) No driver present
- (9) Precrash stability unknown

67. Precrash Directional Consequences of Avoidance Maneuver (Corrective Action) 2

- (0) No avoidance maneuver
- (1) Vehicle stayed in travel lane where avoidance maneuver was initiated
- (2) Vehicle stayed on roadway but left travel lane where avoidance maneuver was initiated
- (3) Vehicle stayed on roadway, not known if left travel lane where avoidance maneuver was initiated
- (4) Vehicle departed roadway
- (5) Avoidance maneuver initiated off roadway
- (8) No driver present
- (9) Directional consequences unknown

*** IF THE CDS APPLICABLE VEHICLE WAS NOT INSPECTED (I.E., GV35 = 0), ***
DO NOT COMPLETE THE EXTERIOR AND INTERIOR VEHICLE FORMS.

*** IF GV07 DOES NOT EQUAL 01-49, DO NOT COMPLETE ***
THE EXTERIOR VEHICLE, INTERIOR VEHICLE,
OCCUPANT ASSESSMENT, AND OCCUPANT INJURY FORMS.

National Highway Traffic Safety
Administration

OCCUPANT ASSESSMENT FORM

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

OCCUPANT'S SEATING

1. Primary Sampling Unit Number _____
2. Case Number - Stratum DSI-94-AB-φφφ
3. Vehicle Number φ 3
4. Occupant Number φ 1

OCCUPANT'S CHARACTERISTICS

5. Occupant's Age 2 2
Code actual age at time of accident.
(00) Less than one year old (specify by month): _____
(97) 97 years and older _____
(99) Unknown
6. Occupant's Sex 2
(1) Male
(2) Female
(9) Unknown
7. Occupant's Height 9 9 9
Code actual height to the nearest centimeter.
(999) Unknown

_____ inches X 2.54 = _____ centimeters
8. Occupant's Weight 9 9 9
Code actual weight to the nearest kilogram.
(999) Unknown

_____ pounds X .4536 = _____ kilograms
9. Occupant's Role 1
(1) Driver
(2) Passenger
(9) Unknown

10. Occupant's Seat Position 1 1
Front Seat
(11) Left side
(12) Middle
(13) Right side
(14) Other (specify): _____
(15) On or in the lap of another occupant
- Second Seat*
(21) Left side
(22) Middle
(23) Right side
(24) Other (specify): _____
(25) On or in the lap of another occupant
- Third Seat*
(31) Left side
(32) Middle
(33) Right side
(34) Other (specify): _____
(35) On or in the lap of another occupant
- Fourth Seat*
(41) Left side
(42) Middle
(43) Right side
(44) Other (specify): _____
(45) On or in the lap of another occupant

(97) In or on unenclosed area
(98) Other seat (specify): _____
(99) Unknown
11. Occupant's Posture 9
(0) Normal posture
- Abnormal posture*
(1) Kneeling or standing on seat
(2) Lying on or across seat
(3) Kneeling, standing or sitting in front of seat
(4) Sitting sideways or turned to talk with another occupant or to look out a rear window
(5) Sitting on a console
(6) Lying back in a reclined seat position
(7) Bracing with feet or hands on a surface in front of seat
(8) Other abnormal posture (specify): _____
(9) Unknown

EJECTION/ENTRAPMENT

12. Ejection

φ

- (0) No ejection
- (1) Complete ejection
- (2) Partial ejection
- (3) Ejection, unknown degree
- (9) Unknown

13. Ejection Area

φ

- (0) No ejection
- (1) Windshield
- (2) Left front
- (3) Right front
- (4) Left rear
- (5) Right rear
- (6) Rear
- (7) Roof
- (8) Other area (e.g., back of pickup, etc.)
(specify): _____
- (9) Unknown

14. Ejection Medium

φ

- (0) No ejection
- (1) Door/hatch/tailgate
- (2) Nonfixed roof structure
- (3) Fixed glazing
- (4) Nonfixed glazing (specify): _____
- (5) Integral structure
- (8) Other medium (specify): _____
- (9) Unknown

15. Medium Status (Immediately Prior To Impact) φ

- (0) No ejection
- (1) Open
- (2) Closed
- (3) Integral structure
- (9) Unknown

16. Entrapment

φ

(NOTE: Entrapped means that part of the person was in the vehicle and mechanically restrained; jammed doors and immobilizing injuries by themselves are not sufficient to constitute entrapment.)

- (0) Not entrapped
- (1) Entrapped
- (9) Unknown

RESTRAINT SYSTEM EVALUATION

17. Manual (Active) Belt System Availability 9

- (0) None available
- (1) Belt removed/destroyed
- (2) Shoulder belt
- (3) Lap belt
- (4) Lap and shoulder belt
- (5) Belt available—type unknown

Integral Belt Partially Destroyed

- (6) Shoulder belt (lap belt destroyed/removed)
- (7) Lap belt (shoulder belt destroyed/removed)

(8) Other belt (specify): _____

(9) Unknown _____

18. Manual (Active) Belt System Use 9 9

- (00) None used, not available, or belt removed/destroyed
- (01) Inoperative (specify): _____

(02) Shoulder belt _____

(03) Lap belt _____

(04) Lap and shoulder belt _____

(05) Belt used—type unknown _____

(08) Other belt used (specify): _____

(12) Shoulder belt used with child safety seat _____

(13) Lap belt used with child safety seat _____

(14) Lap and shoulder belt used with child safety seat _____

(15) Belt used with child safety seat—type unknown _____

(18) Other belt used with child safety seat (specify): _____

(99) Unknown if belt used _____

19. Proper Use of Manual (Active) Belts 9

- (0) None used or not available
- (1) Belt used properly
- (2) Belt used properly with child safety seat

Belt Used Improperly

- (3) Shoulder belt worn under arm
- (4) Shoulder belt worn behind back or seat
- (5) Belt worn around more than one person
- (6) Lap belt worn on abdomen
- (7) Lap belt or lap and shoulder belt used improperly with child safety seat (specify): _____

(8) Other improper use of manual belt system (specify): _____

(9) Unknown _____

20. Manual (Active) Belt Failure Modes During Accident 9

- (0) No manual belt used
- (1) No manual belt failure(s)
- (2) Torn webbing (stretched webbing not included)
- (3) Broken buckle or latchplate
- (4) Upper anchorage separated
- (5) Other anchorage separated (specify): _____

(6) Broken retractor _____

(7) Combination of above (specify): _____

(8) Other manual belt failure (specify): _____

(9) Unknown _____

21. Air Bag System Availability/Function φ

- (0) Not equipped/not available
- (1) Air bag

Non-functional

(2) Air bag disconnected (specify): _____

(3) Air bag not reinstalled _____

(9) Unknown _____

22. Air Bag System Deployment φ

- (0) Not equipped/not available
- (1) Air bag deployed during accident (as a result of impact)
- (2) Air bag deployed inadvertently just prior to accident
- (3) Air bag deployed, accident sequence undetermined
- (4) Nondeployed
- (5) Unknown if deployed
- (6) Air bag deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)
- (9) Unknown

23. Are There Indications of Air Bag System Failure? φ

- (0) Not equipped/not available
- (1) No
- (2) Yes (specify): _____

(9) Unknown _____

Note: See Variables 44 through 48 (Page 5) for Information on Automatic Belts

24. Police Reported Restraint Use 4

- (0) None used
- (1) Police did not indicate restraint use
- (2) Shoulder belt
- (3) Lap belt
- (4) Lap and shoulder belt
- (5) Belt used, type not specified
- (6) Child safety seat
- (7) Other or automatic restraint (specify): _____

(8) Restrained, type unknown _____

(9) Police indicated "unknown" _____

HEAD RESTRAINT AND SEAT EVALUATION

25. Head Restraint Type/Damage by Occupant
at This Occupant Position9

- (0) No head restraints
- (1) Integral—no damage
- (2) Integral—damaged during accident
- (3) Adjustable—no damage
- (4) Adjustable—damaged during accident
- (5) Add-on—no damage
- (6) Add-on—damaged during accident
- (8) Other (specify): _____
- (9) Unknown

26. Seat Type (this Occupant Position)

9 9

- (00) Occupant not seated or no seat
- (01) Bucket
- (02) Bucket with folding back
- (03) Bench
- (04) Bench with separate back cushions
- (05) Bench with folding back(s)
- (06) Split bench with separate back cushions
- (07) Split bench with folding back(s)
- (08) Pedestal (i.e., column supported)
- (09) Other seat type (specify): _____
- (10) Box mounted seat (i.e., van type)
- (99) Unknown

27. Seat Performance (this Occupant Position)

9

- (0) Occupant not seated or no seat
- (1) No seat performance failure(s)
- (2) Seat adjusters failed
- (3) Seat back folding locks or "seat back" failed (specify): _____
- (4) Seat track/anchors failed
- (5) Deformed by impact of occupant
- (6) Deformed by passenger compartment intrusion (specify): _____
- (7) Combination of above (specify): _____
- (8) Other (specify): _____
- (9) Unknown

CHILD SAFETY SEAT

28. Child Safety Seat Make/Model φ φ φ
 (000) No child safety seat

Applicable codes are found in your NASS CDS
 Data Collection, Coding and Editing
 (950) Built-in child safety seat
 (997) Other make/model (specify):

(998) Unknown make/model
 (999) Unknown if child safety seat used

29. Type of Child Safety Seat φ
 (0) No child safety seat

(1) Infant seat
 (2) Toddler seat
 (3) Convertible seat
 (4) Booster seat
 (7) Other type child safety seat (specify):

(8) Unknown child safety seat type
 (9) Unknown if child safety seat used

30. Child Safety Seat Orientation φ φ
 (00) No child safety seat

Designed for Rear Facing for This Age/Weight

(01) Rear facing
 (02) Forward facing
 (08) Other orientation (specify):

(09) Unknown orientation

Designed For Forward Facing for This Age/Weight

(11) Rear facing
 (12) Forward facing
 (18) Other orientation (specify):

(19) Unknown orientation

Unknown Design or Orientation For This Age/Weight, or Unknown Age/Weight

(21) Rear facing
 (22) Forward facing
 (28) Other orientation (specify):

(29) Unknown orientation

(99) Unknown if child safety seat used

31. Child Safety Seat Harness Usage φ φ

32. Child Safety Seat Shield Usage φ φ

33. Child Safety Seat Tether Usage φ φ

Note: Options below applicable to
 Variables OA31-OA33.
 (00) No child safety seat

Not Designed With Harness/Shield/Tether

(01) After market harness/shield/tether
 added, not used
 (02) After market harness/shield/tether used
 (03) Child safety seat used, but no after market
 harness/shield/tether added
 (09) Unknown if harness/shield/tether
 added or used

Designed With Harness/Shield/Tether

(11) Harness/shield/tether not used
 (12) Harness/shield/tether used
 (19) Unknown if harness/shield/tether used

Unknown If Designed With Harness/Shield/Tether

(21) Harness/shield/tether not used
 (22) Harness/shield/tether used
 (29) Unknown if harness/shield/tether used

(99) Unknown if child safety seat used

INJURY CONSEQUENCES34. Injury Severity (Police Rating) 2

- (0) O - No injury
- (1) C - Possible injury
- (2) B - Nonincapacitating injury
- (3) A - Incapacitating injury
- (4) K - Killed
- (5) U - Injury, severity unknown
- (6) Died prior to accident
- (9) Unknown

35. Treatment - Mortality 9

- (0) No treatment
- (1) Fatal
- (2) Fatal - ruled disease (specify):

Nonfatal

- (3) Hospitalization
- (4) Transported and released
- (5) Treatment at scene - nontransported
- (6) Treatment later
- (8) Treatment - other (specify):

- (9) Unknown

36. Type Of Medical Facility (for Initial Treatment) 9

- (0) Not treated at a medical facility
- (1) Trauma center
- (2) Hospital
- (3) Medical clinic
- (4) Physician's office
- (5) Treatment later at medical facility
- (8) Other (specify):

- (9) Unknown

37. Hospital Stay 9 9

- (00) Not Hospitalized
_____ Code the number of days (up through 60)
that the occupant stayed in hospital.
- (61) 61 days or more
- (99) Unknown

99. Case Occupant φ

- (0) Not Case Occupant
- (1) This is the Case Occupant
- (2) This is the Case Occupant
in another case

38. Working Days Lost 9 9

- _____ Code the number of days
(up through 60) that the occupant
lost from work due to the accident
- (00) No working days lost
- (61) 61 days or more
- (62) Fatally injured
- (97) Not working prior to accident
- (99) Unknown

STOP - GO TO VARIABLE 44 ON PAGE 7**VARIABLES 39 THROUGH 43 ARE
COMPLETED BY THE ZONE CENTER**39. Time to Death φ φ

- _____ Code number of hours from time of
accident to time of death up through 24
hours. If time of death is greater than 24
hours, code number of days. (Note: 1 day =
31, 2 days = 32, ... n days = 30 + n up
through 30 days = 60)
- (00) Not fatal
- (96) Fatal - ruled disease
- (99) Unknown

40. 1st Medically Reported Cause of Death φ φ41. 2nd Medically Reported Cause of Death φ φ42. 3rd Medically Reported Cause of Death φ φ

- _____ Code the Occupant Injury from line
number(s) for the medically reported
injury(s) which reportedly contributed to
this occupant's death
- (00) Not fatal or no additional causes
- (96) Mode of death given but specific
injuries are not linked to cause
of death. (specify):

(97) Other result (includes fatal ruled
disease) (specify):

(99) Unknown

43. Number of Recorded Injuries for
This Occupant 9 1

- _____ Code the actual number of
injuries recorded for this occupant.
- (00) No recorded injuries
- (97) Injured, details unknown
- (99) Unknown if injured

AUTOMATIC BELT SYSTEM44. Automatic (Passive) Belt System Availability/Function φ

- (0) Not equipped/not available
- (1) 2 point automatic belts
- (2) 3 point automatic belts
- (3) Automatic belts - type unknown

Non-functional

- (4) Automatic belts destroyed or rendered inoperative
- (9) Unknown

45. Automatic (Passive) Belt System Use φ

- (0) Not equipped/not available/destroyed or rendered inoperative
- (1) Automatic belt in use
- (2) Automatic belt not in use (manually disconnected, motorized track inoperative) (specify): _____

- (3) Automatic belt use unknown
- (9) Unknown

46. Automatic (Passive) Belt System Type φ

- (0) Not equipped/not available
- (1) Non-motorized system
- (2) Motorized system
- (9) Unknown

47. Proper Use of Automatic (Passive) Belt System φ

- (0) Not equipped/not available/not used
- (1) Automatic belt used properly
- (2) Automatic belt used properly with child safety seat

Automatic Belt Used Improperly

- (3) Automatic shoulder belt worn under arm
- (4) Automatic shoulder belt worn behind back
- (5) Automatic belt worn around more than one person
- (6) Lap portion of automatic belt worn on abdomen
- (7) Automatic lap and shoulder belt or automatic shoulder belt used improperly with child safety seat (specify): _____

- (8) Other improper use of automatic belt system (specify): _____
- (9) Unknown

48. Automatic (Passive) Belt Failure Modes During Accident φ

- (0) Not equipped/not available/not in use
- (1) No automatic belt failure(s)
- (2) Torn webbing (stretched webbing not included)
- (3) Broken buckle or latchplate
- (4) Upper anchorage separated
- (5) Other anchorage separated (specify): _____

- (6) Broken retractor
- (7) Combination of above (specify): _____
- (8) Other automatic belt failure (specify): _____

- (9) Unknown

49. Seat Orientation (this Occupant Position) L

- (0) Occupant not seated or no seat
- (1) Forward facing seat
- (2) Rear facing seat
- (3) Side facing seat (inward)
- (4) Side facing seat (outward)
- (8) Other (specify): _____

- (9) Unknown

Check the Primary Source Used In Determining Belt Use.

- [] Not equipped/not available/destroyed or rendered inoperative
- [] Vehicle inspection
- [] Official injury data
- [] Driver/occupant interview
- [] Other (specify): _____

- [X] Unknown if belt used

ARE ALL APPLICABLE MEDICAL RECORDS INCLUDED WITH INITIAL SUBMISSION?

NO [X] YES []

UPDATE CANDIDATE?

NO [X] YES []

**STOP - VARIABLES 50 THROUGH 53 ARE
COMPLETED BY THE ZONE CENTER****TRAUMA DATA**

50. Glasgow Coma Scale (GCS) Score 9 7
(at Medical Facility)
(00) Not injured
(01) Injured - not treated at medical facility
(02) No GCS Score at medical facility
(03-15) Code the actual value of the
initial GCS Score recorded at medical
facility.
(97) Injured, details unknown
(99) Unknown if injured
51. Was the Occupant Given Blood? 9
(1) No - blood not given
(2) Yes - blood given
(specify units): _____
(9) Unknown if blood given
52. Arterial Blood Gases (ABG) - HCO_3 9 7
(00) Not injured
(01) Injured, ABGs not measured or reported
(02-50) Code the actual value of the HCO_3
(96) ABGs reported, HCO_3 unknown
(97) Injured, details unknown
(99) Unknown if injured

BELT USE DETERMINATION

53. Primary Source of Belt Use Determination 9
(0) Not equipped/not available/destroyed
or rendered inoperative
(1) Vehicle inspection
(2) Official injury data
(3) Driver/occupant interview
(8) Other (specify): _____
(9) Unknown if belt used

National Highway Traffic Safety
Administration

OCCUPANT ASSESSMENT FORM

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

OCCUPANT'S SEATING

1. Primary Sampling Unit Number _____
2. Case Number - Stratum DSI-94-AB-006
3. Vehicle Number 03
4. Occupant Number 02

OCCUPANT'S CHARACTERISTICS

5. Occupant's Age 21
Code actual age at time of accident.
(00) Less than one year old (specify by month):
(97) 97 years and older
(99) Unknown

6. Occupant's Sex 2
(1) Male
(2) Female
(9) Unknown

7. Occupant's Height 999
Code actual height to the nearest
centimeter.
(999) Unknown

____ inches X 2.54 = ____ centimeters

8. Occupant's Weight 999
Code actual weight to the nearest
kilogram.
(999) Unknown

____ pounds X .4536 = ____ kilograms

9. Occupant's Role 2
(1) Driver
(2) Passenger
(9) Unknown

10. Occupant's Seat Position 13
Front Seat
(11) Left side
(12) Middle
(13) Right side
(14) Other (specify): _____
(15) On or in the lap of another occupant

- Second Seat*
(21) Left side
(22) Middle
(23) Right side
(24) Other (specify): _____
(25) On or in the lap of another occupant

- Third Seat*
(31) Left side
(32) Middle
(33) Right side
(34) Other (specify): _____
(35) On or in the lap of another occupant

- Fourth Seat*
(41) Left side
(42) Middle
(43) Right side
(44) Other (specify): _____
(45) On or in the lap of another occupant

- (97) In or on unenclosed area
(98) Other seat (specify): _____
(99) Unknown

11. Occupant's Posture 9
(0) Normal posture

- Abnormal posture*
(1) Kneeling or standing on seat
(2) Lying on or across seat
(3) Kneeling, standing or sitting in front of seat
(4) Sitting sideways or turned to talk with another
occupant or to look out a rear window
(5) Sitting on a console
(6) Lying back in a reclined seat position
(7) Bracing with feet or hands on a surface in front
of seat
(8) Other abnormal posture (specify): _____
(9) Unknown

EJECTION/ENTRAPMENT

12. Ejection ϕ

- (0) No ejection
- (1) Complete ejection
- (2) Partial ejection
- (3) Ejection, unknown degree
- (9) Unknown

13. Ejection Area ϕ

- (0) No ejection
- (1) Windshield
- (2) Left front
- (3) Right front
- (4) Left rear
- (5) Right rear
- (6) Rear
- (7) Roof
- (8) Other area (e.g., back of pickup, etc.)
(specify): _____
- (9) Unknown

14. Ejection Medium ϕ

- (0) No ejection
- (1) Door/hatch/tailgate
- (2) Nonfixed roof structure
- (3) Fixed glazing
- (4) Nonfixed glazing (specify): _____
- (5) Integral structure
- (8) Other medium (specify): _____
- (9) Unknown

15. Medium Status (Immediately Prior To Impact) ϕ

- (0) No ejection
- (1) Open
- (2) Closed
- (3) Integral structure
- (9) Unknown

16. Entrapment ϕ

(NOTE: Entrapped means that part of the person was in the vehicle and mechanically restrained; jammed doors and immobilizing injuries by themselves are not sufficient to constitute entrapment.)

- (0) Not entrapped
- (1) Entrapped
- (9) Unknown

RESTRAINT SYSTEM EVALUATION

17. Manual (Active) Belt System Availability 9

- (0) None available
- (1) Belt removed/destroyed
- (2) Shoulder belt
- (3) Lap belt
- (4) Lap and shoulder belt
- (5) Belt available—type unknown

Integral Belt Partially Destroyed

- (6) Shoulder belt (lap belt destroyed/removed)
- (7) Lap belt (shoulder belt destroyed/removed)

(8) Other belt (specify): _____

(9) Unknown _____

18. Manual (Active) Belt System Use 9 9

- (00) None used, not available, or belt removed/destroyed
- (01) Inoperative (specify): _____

(02) Shoulder belt _____

(03) Lap belt _____

(04) Lap and shoulder belt _____

(05) Belt used—type unknown _____

(08) Other belt used (specify): _____

(12) Shoulder belt used with child safety seat _____

(13) Lap belt used with child safety seat _____

(14) Lap and shoulder belt used with child safety seat _____

(15) Belt used with child safety seat—type unknown _____

(18) Other belt used with child safety seat (specify): _____

(99) Unknown if belt used _____

19. Proper Use of Manual (Active) Belts 9

- (0) None used or not available
- (1) Belt used properly
- (2) Belt used properly with child safety seat

Belt Used Improperly

- (3) Shoulder belt worn under arm
- (4) Shoulder belt worn behind back or seat
- (5) Belt worn around more than one person
- (6) Lap belt worn on abdomen
- (7) Lap belt or lap and shoulder belt used improperly with child safety seat (specify): _____

(8) Other improper use of manual belt system (specify): _____

(9) Unknown _____

20. Manual (Active) Belt Failure Modes During Accident 2

- (0) No manual belt used
- (1) No manual belt failure(s)
- (2) Torn webbing (stretched webbing not included)
- (3) Broken buckle or latchplate
- (4) Upper anchorage separated
- (5) Other anchorage separated (specify): _____

(6) Broken retractor _____

(7) Combination of above (specify): _____

(8) Other manual belt failure (specify): _____

(9) Unknown _____

21. Air Bag System Availability/Function φ

- (0) Not equipped/not available
- (1) Air bag

Non-functional

(2) Air bag disconnected (specify): _____

(3) Air bag not reinstalled _____

(9) Unknown _____

22. Air Bag System Deployment φ

- (0) Not equipped/not available
- (1) Air bag deployed during accident (as a result of impact)
- (2) Air bag deployed inadvertently just prior to accident
- (3) Air bag deployed, accident sequence undetermined
- (4) Nondeployed
- (5) Unknown if deployed
- (6) Air bag deployed as a result of a noncollision event during accident sequence (e.g., fire, explosion, electrical)
- (9) Unknown

23. Are There Indications of Air Bag System Failure? φ

- (0) Not equipped/not available
- (1) No
- (2) Yes (specify): _____

(9) Unknown _____

Note: See Variables 44 through 48 (Page 5) for Information on Automatic Belts

24. Police Reported Restraint Use φ

- (0) None used
- (1) Police did not indicate restraint use
- (2) Shoulder belt
- (3) Lap belt
- (4) Lap and shoulder belt
- (5) Belt used, type not specified
- (6) Child safety seat
- (7) Other or automatic restraint (specify): _____

(8) Restrained, type unknown _____

(9) Police indicated "unknown" _____

HEAD RESTRAINT AND SEAT EVALUATION

25. Head Restraint Type/Damage by Occupant at This Occupant Position 9

- (0) No head restraints
- (1) Integral—no damage
- (2) Integral—damaged during accident
- (3) Adjustable—no damage
- (4) Adjustable—damaged during accident
- (5) Add-on—no damage
- (6) Add-on—damaged during accident
- (8) Other (specify): _____

(9) Unknown

26. Seat Type (this Occupant Position) 9 9

- (00) Occupant not seated or no seat
- (01) Bucket
- (02) Bucket with folding back
- (03) Bench
- (04) Bench with separate back cushions
- (05) Bench with folding back(s)
- (06) Split bench with separate back cushions
- (07) Split bench with folding back(s)
- (08) Pedestal (i.e., column supported)
- (09) Other seat type (specify): _____

(10) Box mounted seat (i.e., van type)

(99) Unknown

27. Seat Performance (this Occupant Position) 9

- (0) Occupant not seated or no seat
- (1) No seat performance failure(s)
- (2) Seat adjusters failed
- (3) Seat back folding locks or "seat back" failed (specify): _____
- (4) Seat track/anchors failed
- (5) Deformed by impact of occupant
- (6) Deformed by passenger compartment intrusion (specify): _____

(7) Combination of above (specify): _____

(8) Other (specify): _____

(9) Unknown

CHILD SAFETY SEAT

28. Child Safety Seat Make/Model φ φ φ
 (000) No child safety seat
 Applicable codes are found in your NASS CDS
 Data Collection, Coding and Editing
 (950) Built-in child safety seat
 (997) Other make/model (specify):

 (998) Unknown make/model
 (999) Unknown if child safety seat used

29. Type of Child Safety Seat φ
 (0) No child safety seat
 (1) Infant seat
 (2) Toddler seat
 (3) Convertible seat
 (4) Booster seat
 (7) Other type child safety seat (specify):

 (8) Unknown child safety seat type
 (9) Unknown if child safety seat used

30. Child Safety Seat Orientation φ φ
 (00) No child safety seat

Designed for Rear Facing for This Age/Weight
 (01) Rear facing
 (02) Forward facing
 (08) Other orientation (specify):

 (09) Unknown orientation

Designed For Forward Facing for This Age/Weight
 (11) Rear facing
 (12) Forward facing
 (18) Other orientation (specify):

 (19) Unknown orientation

Unknown Design or Orientation For This Age/Weight, or Unknown Age/Weight
 (21) Rear facing
 (22) Forward facing
 (28) Other orientation (specify):

 (29) Unknown orientation

 (99) Unknown if child safety seat used

31. Child Safety Seat Harness Usage φ φ

32. Child Safety Seat Shield Usage φ φ

33. Child Safety Seat Tether Usage φ φ

Note: Options below applicable to
 Variables OA31-OA33.
 (00) No child safety seat

Not Designed With Harness/Shield/Tether

(01) After market harness/shield/tether
 added, not used
 (02) After market harness/shield/tether used
 (03) Child safety seat used, but no after market
 harness/shield/tether added
 (09) Unknown if harness/shield/tether
 added or used

Designed With Harness/Shield/Tether

(11) Harness/shield/tether not used
 (12) Harness/shield/tether used
 (19) Unknown if harness/shield/tether used

Unknown If Designed With Harness/Shield/Tether

(21) Harness/shield/tether not used
 (22) Harness/shield/tether used
 (29) Unknown if harness/shield/tether used

 (99) Unknown if child safety seat used

INJURY CONSEQUENCES34. Injury Severity (Police Rating) 3

- (0) O - No injury
- (1) C - Possible injury
- (2) B - Nonincapacitating injury
- (3) A - Incapacitating injury
- (4) K - Killed
- (5) U - Injury, severity unknown
- (6) Died prior to accident
- (9) Unknown

35. Treatment - Mortality 9

- (0) No treatment
- (1) Fatal
- (2) Fatal - ruled disease (specify):

Nonfatal

- (3) Hospitalization
- (4) Transported and released
- (5) Treatment at scene - nontransported
- (6) Treatment later
- (8) Treatment - other (specify):

(9) Unknown

36. Type Of Medical Facility (for Initial Treatment) 9

- (0) Not treated at a medical facility
- (1) Trauma center
- (2) Hospital
- (3) Medical clinic
- (4) Physician's office
- (5) Treatment later at medical facility
- (8) Other (specify):

(9) Unknown

37. Hospital Stay 9 9

- (00) Not Hospitalized
- _____ Code the number of days (up through 60) that the occupant stayed in hospital.
- (61) 61 days or more
- (99) Unknown

99. Case Occupant φ

- (0) Not Case Occupant
- (1) This is the Case Occupant
- (2) This is the Case Occupant in another case

38. Working Days Lost 9 9

- _____ Code the number of days (up through 60) that the occupant lost from work due to the accident
- (00) No working days lost
- (61) 61 days or more
- (62) Fatally injured
- (97) Not working prior to accident
- (99) Unknown

STOP - GO TO VARIABLE 44 ON PAGE 7**VARIABLES 39 THROUGH 43 ARE COMPLETED BY THE ZONE CENTER**39. Time to Death φ φ

- _____ Code number of hours from time of accident to time of death up through 24 hours. If time of death is greater than 24 hours, code number of days. (Note: 1 day = 31, 2 days = 32, ... n days = 30 + n up through 30 days = 60)
- (00) Not fatal
- (96) Fatal - ruled disease
- (99) Unknown

40. 1st Medically Reported Cause of Death φ φ41. 2nd Medically Reported Cause of Death φ φ42. 3rd Medically Reported Cause of Death φ φ

- _____ Code the Occupant Injury from line number(s) for the medically reported injury(s) which reportedly contributed to this occupant's death
- (00) Not fatal or no additional causes
- (96) Mode of death given but specific injuries are not linked to cause of death. (specify):

(97) Other result (includes fatal ruled disease) (specify):

(99) Unknown

43. Number of Recorded Injuries for This Occupant 9 7

- _____ Code the actual number of injuries recorded for this occupant.
- (00) No recorded injuries
- (97) Injured, details unknown
- (99) Unknown if injured

AUTOMATIC BELT SYSTEM44. Automatic (Passive) Belt System Availability/ Function φ

- (0) Not equipped/not available
- (1) 2 point automatic belts
- (2) 3 point automatic belts
- (3) Automatic belts - type unknown

Non-functional

- (4) Automatic belts destroyed or rendered inoperative
- (9) Unknown

45. Automatic (Passive) Belt System Use φ

- (0) Not equipped/not available/destroyed or rendered inoperative
- (1) Automatic belt in use
- (2) Automatic belt not in use (manually disconnected, motorized track inoperative) (specify):

- (3) Automatic belt use unknown
- (9) Unknown

46. Automatic (Passive) Belt System Type φ

- (0) Not equipped/not available
- (1) Non-motorized system
- (2) Motorized system
- (9) Unknown

47. Proper Use of Automatic (Passive) Belt System φ

- (0) Not equipped/not available/not used
- (1) Automatic belt used properly
- (2) Automatic belt used properly with child safety seat

Automatic Belt Used Improperly

- (3) Automatic shoulder belt worn under arm
- (4) Automatic shoulder belt worn behind back
- (5) Automatic belt worn around more than one person
- (6) Lap portion of automatic belt worn on abdomen
- (7) Automatic lap and shoulder belt or automatic shoulder belt used improperly with child safety seat (specify):

- (8) Other improper use of automatic belt system (specify):
- (9) Unknown

48. Automatic (Passive) Belt Failure Modes During Accident φ

- (0) Not equipped/not available/not in use
- (1) No automatic belt failure(s)
- (2) Torn webbing (stretched webbing not included)
- (3) Broken buckle or latchplate
- (4) Upper anchorage separated
- (5) Other anchorage separated (specify):

- (6) Broken retractor
- (7) Combination of above (specify):
- (8) Other automatic belt failure (specify):

- (9) Unknown

49. Seat Orientation (this Occupant Position) 1

- (0) Occupant not seated or no seat
- (1) Forward facing seat
- (2) Rear facing seat
- (3) Side facing seat (inward)
- (4) Side facing seat (outward)
- (8) Other (specify):

- (9) Unknown

Check the Primary Source Used In Determining Belt Use.

- [] Not equipped/not available/destroyed or rendered inoperative
- [] Vehicle inspection
- [] Official injury data
- [] Driver/occupant interview
- [] Other (specify):

- [X] Unknown if belt used

ARE ALL APPLICABLE MEDICAL RECORDS INCLUDED WITH INITIAL SUBMISSION?

NO [X] YES []

UPDATE CANDIDATE?

NO [X] YES []

**STOP - VARIABLES 50 THROUGH 53 ARE
COMPLETED BY THE ZONE CENTER****TRAUMA DATA**

50. Glasgow Coma Scale (GCS) Score 9 1
(at Medical Facility)
(00) Not injured
(01) Injured - not treated at medical facility
(02) No GCS Score at medical facility
(03-15) Code the actual value of the
initial GCS Score recorded at medical
facility.
(97) Injured, details unknown
(99) Unknown if injured
51. Was the Occupant Given Blood? 9
(1) No - blood not given
(2) Yes - blood given
(specify units): _____
(9) Unknown if blood given
52. Arterial Blood Gases (ABG) - HCO_3 9 1
(00) Not injured
(01) Injured, ABGs not measured or reported
(02-50) Code the actual value of the HCO_3
(96) ABGs reported, HCO_3 unknown
(97) Injured, details unknown
(99) Unknown if injured

BELT USE DETERMINATION

53. Primary Source of Belt Use Determination 9
(0) Not equipped/not available/destroyed
or rendered inoperative
(1) Vehicle inspection
(2) Official injury data
(3) Driver/occupant interview
(8) Other (specify): _____
(9) Unknown if belt used



U.S. Department of Transportation

National Highway Traffic Safety
Administration

CRASHPC PROGRAM SUMMARY

(All Measurements in Metric)

NATIONAL ACCIDENT SAMPLING SYSTEM
CRASHWORTHINESS DATA SYSTEM

Identifying Title

Primary Sampling Unit DSI-94-AB-006
Case No.-Stratum

01
Accident Event
Sequence No.

9 4
Date (Month, day, year) of Run

CRASHPC Vehicle Identification

Vehicle 1	<u>1990</u>	<u>CADILLAC</u>	<u>SEDAN DEVILLE</u>	<u>01</u>
Vehicle 2	<u>1991</u>	<u>TOYOTA</u>	<u>SRS 4WD PICKUP TRUCK</u>	<u>02</u>
	Year	Make	Model	NASS Veh. No.

GENERAL INFORMATION

VEHICLE 1		VEHICLE 2	
Size	<u>4</u>	Size	<u>5</u>
Weight		Weight	
<u>1608</u> + <u>143</u> + <u>0</u> = <u>1751</u> kg		<u>1676</u> + <u>137</u> + <u>0</u> = <u>1813</u> kg	
Curb Occupant(s) Cargo		Curb Occupant(s) Cargo	
CDC	<u>9 2 F Y E W 4</u>	CDC	<u>9 2 F Y E W 4</u>
PDOF (-180 to +180)	<u>0 0 5</u> °	PDOF (-180 to +180)	<u>0 0 5</u> °
Stiffness	<u>9</u>	Stiffness	<u>8</u>

SCENE INFORMATION

Rest and Impact Positions [] No, Go To Damage Information [] Yes

VEHICLE 1		VEHICLE 2	
Rest Position	X _____ m Y _____ m PSI _____ °	Rest Position	X _____ m Y _____ m PSI _____ °
Impact Position	X _____ m Y _____ m PSI _____ °	Impact Position	X _____ m Y _____ m PSI _____ °
Slip Angle (-180 to +180)	_____ °	Slip Angle (-180 to +180)	_____ °

VEHICLE MOTION

Sustained Contact [] No [] Yes

VEHICLE 1		VEHICLE 2	
Skidding (Rotation)	[] No [] Yes	Skidding (Rotation)	[] No [] Yes
Skidding Stop Before Rest	[] No [] Yes	Skidding Stop Before Rest	[] No [] Yes
End of Rotation Position	X _____ m Y _____ m PSI _____ °	End of Rotation Position	X _____ m Y _____ m PSI _____ °
Curved Path	[] No [] Yes	Curved Path	[] No [] Yes
Point on Path	X _____ m Y _____ m	Point on Path	X _____ m Y _____ m
Rotation Direction	[] None [] CW [] CCW	Rotation Direction	[] None [] CW [] CCW
Rotation >360°	[] No [] Yes	Rotation >360°	[] No [] Yes

National Accident Sampling System-Crashworthiness Data System: CRASHPC Program Summary

FRICTION INFORMATION

Coefficient of Friction . _____
Rolling Resistance Option _____

Vehicle 1 Rolling Resistance

LF _____ RF _____
LR _____ RR _____

Vehicle 2 Rolling Resistance

LF _____ RF _____
LR _____ RR _____

TRAJECTORY INFORMATION

Trajectory Data [] No [] Yes
If No, Go To Damage Information

Vehicle 1 Steer Angles

LF _____ ° RF _____ °
LR _____ ° RR _____ °

Vehicle 2 Steer Angles

LF _____ ° RF _____ °
LR _____ ° RR _____ °

Terrain Boundary [] No [] Yes

First Point

X _____ . _____ m Y _____ . _____ m

Second Point

X _____ . _____ m Y _____ . _____ m

Secondary Coefficient of Friction . _____

DAMAGE INFORMATION

VEHICLE 1

Damage Length L 1 6 0 cm

Crush Depths
C₁ 1 0 5 cm
C₂ 0 8 1 cm
C₃ 0 5 5 cm
C₄ 0 3 9 cm
C₅ 0 1 4 cm
C₆ 0 0 0 cm

Damage Offset D ⊕ 0 4 3 cm

VEHICLE 2

Damage Length L 1 5 5 cm

Crush Depths
C₁ 0 7 7 cm
C₂ 0 4 7 cm
C₃ 0 3 2 cm
C₄ 0 1 9 cm
C₅ 0 0 4 cm
C₆ 0 0 0 cm

Damage Offset D ⊕ 0 4 0 cm

IF THIS COMMON IMPACT WAS WITH A MOTOR VEHICLE *NOT IN TRANSPORT*, FILL IN THE INFORMATION BELOW.

Model Year: _____
Make: _____
Model: _____
VIN: _____

The Weight, CDC, Scene Data and Damage Information for this vehicle should be recorded above.

Complete and ATTACH the appropriate vehicle damage sketch and dimensions to the Form.

DSI-94-AB-006

SUMMARY OF CRASHPC RESULTS (USING SPINOUT)

CRASH3 RECONSTRUCTION

SPEED CHANGE (DAMAGE)		TOTAL(KPH)	LONG.(KPH)	LAT.(KPH)	ANG.(DEG)
	VEH #1	38.5	-38.4	3.4	-5.0
	VEH #2	37.2	-37.1	3.2	-5.0

ENERGY DISSIPATED BY DAMAGE VEH#1:133340.0 JOULES VEH#2: 87076.3 JOULES

SUMMARY OF DAMAGE DATA
VEHICLE # 1

(* INDICATES DEFAULT VALUE)
VEHICLE # 2

TYPE-----CATEGORY 4
STIFFNESS---CATEGORY 9
WEIGHT----- 1751.3 KGS
CDC-----12FYEW4
L----- 160.0 CM.
C1----- 104.6 CM.
C2----- 81.3 CM.
C3----- 55.4 CM.
C4----- 38.6 CM.
C5----- 14.5 CM.
C6----- .0 CM.
D----- -42.7 CM.
RHO----- 1.00 *
ANG----- -5.0 DEG.
D'----- -72.0 CM.

TYPE-----CATEGORY 5
STIFFNESS---CATEGORY 8
WEIGHT----- 1813.0 KGS
CDC-----12FYEW4
L----- 154.9 CM.
C1----- 77.2 CM.
C2----- 47.0 CM.
C3----- 32.3 CM.
C4----- 18.8 CM.
C5----- 3.8 CM.
C6----- .0 CM.
D----- -40.1 CM.
RHO----- 1.00 *
ANG----- -5.0 DEG.
D'----- -74.4 CM.

DIMENSIONS AND INERTIAL PROPERTIES

A1 = 138.9 CM.
B1 = 150.4 CM.
TR1 = 157.0 CM.
I1 = 424303.6 NEWT-SEC**2-CM
M1 = 17.580 NEWT-SEC**2/CM
XF1 = 251.0 CM.
XR1 = -289.6 CM.
YS1 = 97.8 CM.

A2 = 142.5 CM.
B2 = 160.0 CM.
TR2 = 161.8 CM.
I2 = 474356.3 NEWT-SEC**2-CM
M2 = 18.200 NEWT-SEC**2/CM
XF2 = 258.6 CM.
XR2 = -309.6 CM.
YS2 = 101.3 CM.

DSI-94-AB-006

SUMMARY OF CRASHPC RESULTS (USING SPINOUT)

CRASH3 RECONSTRUCTION

SPEED CHANGE (DAMAGE)		TOTAL(MPH)	LONG.(MPH)	LAT.(MPH)	ANG.(DEG)
	VEH #1	23.9	-23.9	2.1	-5.0
	VEH #2	23.1	-23.0	2.0	-5.0

ENERGY DISSIPATED BY DAMAGE VEH#1: 98333.3 FT-LB VEH#2: 64215.6 FT-LB

SUMMARY OF DAMAGE DATA
VEHICLE # 1

(* INDICATES DEFAULT VALUE)
VEHICLE # 2

TYPE-----CATEGORY 4
STIFFNESS---CATEGORY 9
WEIGHT----- 3861.0 LBS.
CDC-----12FYEW4
L----- 63.0 IN.
C1----- 41.2 IN.
C2----- 32.0 IN.
C3----- 21.8 IN.
C4----- 15.2 IN.
C5----- 5.7 IN.
C6----- .0 IN.
D----- -16.8
RHO----- 1.00 *
ANG----- -5.0 DEG.
D'----- -28.4 IN.

TYPE-----CATEGORY 5
STIFFNESS---CATEGORY 8
WEIGHT----- 3997.0 LBS.
CDC-----12FYEW4
L----- 61.0 IN.
C1----- 30.4 IN.
C2----- 18.5 IN.
C3----- 12.7 IN.
C4----- 7.4 IN.
C5----- 1.5 IN.
C6----- .0 IN.
D----- -15.8
RHO----- 1.00 *
ANG----- -5.0 DEG.
D'----- -29.3 IN.

DIMENSIONS AND INERTIAL PROPERTIES

A1	=	54.7	IN.	A2	=	56.1	IN.
B1	=	59.2	IN.	B2	=	63.0	IN.
TR1	=	61.8	IN.	TR2	=	63.7	IN.
I1	=	37555.9	LB-SEC**2-IN	I2	=	41986.2	LB-SEC**2-IN
M1	=	10.039	LB-SEC**2/IN	M2	=	10.393	LB-SEC**2/IN
XF1	=	98.8	IN.	XF2	=	101.8	IN.
XR1	=	-114.0	IN.	XR2	=	-121.9	IN.
YS1	=	38.5	IN.	YS2	=	39.9	IN.

AIRBAG SUPPLEMENT

1

ACCIDENT SUMMARY

1. Accident Date: [REDACTED] 94

2. Police Investigated

1

- (1) Yes
- (2) No
- (3) Unknown

Agency: [REDACTED] Police

City:

County:

3. General Locality

2

- (1) Freeway, Limited Access
- (2) Urban (City)
- (3) Urban-Rural (mixed)
- (4) Rural, Fields

4. Configuration (First Harm)

2

- (0) Struck Object or Ped
- (1) Rear-End
- (2) Head-On
- (3) Rear-to-Rear
- (4) Angle
- (5) Sideswipe-Same Direction
- (6) Sideswipe-Opposite Dir.
- (7) Noncollision
- (8) Nonimpact Deployment
- (9) Unknown

5. Fire Involved

0

- (0) None
- (1) Airbag Vehicle
- (2) Other Vehicle
- (3) Both Vehicles
- (9) Unknown

6. Vehicles Involved

3

7. Persons Involved

7

8. Injured Persons

7

9. Maximum AIS in Accident

4

AIRBAG VEHICLE INSPECTION

10. Date Vehicle Inspected:

11. Reason Vehicle Note Inspected

1

- (0) Not Required
- (1) Inspection Completed
- (2) Cannot be Located
- (3) Repaired or Destroyed
- (5) Refusal or Impounded
- (7) Other:

12. Impact Data Obtained

4

- (0) No Data Obtained
- (1) CDC Only
- (2) Crush Profile Only
- (3) Trajectory Data Only
- (4) CDC and Crush Profile
- (5) CDC and Trajectory
- (6) Crush and Trajectory
- (7) CDC, Crush, and Trajectory

13. Basis of Delta-V

1

- (0) Not Computed (Unknown why)
- (1) CRASH - Damage Only
- (2) CRASH - Damage + Traj
- (3) OLDMISS
- (4) POLES
- (5) Unknown Basis
- (6) One Vehicle Beyond Scope
- (7) Collision Beyond Scope
- (8) Insufficient Data

VEHICLE HISTORY

14. Prior Impacts for AB Vehicle?

2

- (1) Yes
- (2) No
- (9) Unknown

15. Prior AB Maintenance or Service

2

- (1) Yes, (2) No, (9) Unknown

Describe:

AIRBAG SUPPLEMENT

2

AIRBAG VEHICLE

Fleet: **NONE**

VIN: **1G6CD5338L4XXXXXX**

Mileage: **67,983 mi (42,244 mi)**

SYSTEM READINESS LAMP

16. Pre-Impact Lamp Condition 1
- (1) Functioning/Proved Out
 - (2) Inoperative
 - (9) Unknown
17. Driver's Report of Pre-Impact Flashing 64
- (00) No Flashing Reported
 - (01) Continuous Flashing
 - (02)
 - Number of Flashes: ____
 - (11)
 - (12) Constant Light
 - (19) Flashing, Unknown Number
 - (88) Not Applicable, System Removed
 - (99) Unknown
18. Period of Pre-Impact Flashing 4
- (0) No Flashing
 - (1) Same Day as Impact
 - (2) Prior Day
 - (3) Prior Two Days
 - (4) Prior Week
 - (5) Prior Month
 - (6) Over One Month
 - (9) Unknown
19. Post-Impact Lamp Condition 2
- (1) Functioning/Proved Out
 - (2) Inoperative
 - (9) Unknown
20. Post-Impact Flashing 99
- (00) No Flashing Reported
 - (01) Continuous Flashing
 - (02)
 - Number of Flashes: ____
 - (11)
 - (12) Constant Light
 - (19) Flashing, Unknown Number
 - (88) Not Applicable, System Removed
 - (99) Unknown

21. Airbag Vehicle First Harmful Event 13
- (01) Fire or explosion
 - (02) Immersion
 - (03) Gas Inhalation
 - (04) Fell from vehicle
 - (05) Injured in vehicle
 - (06) Other noncollision (specify):
 - (07) Overturn
 - (08) Jackknife
 - COLLISION WITH:
 - (09) Pedestrian
 - (10) Pedalcyclist
 - (11) Railway train
 - (12) Animal
 - (13) Motor vehicle in transport (same roadway)
 - (14) Motor vehicle in transport (other roadway)
 - (15) Parked motor vehicle
 - (16) Other type nonmotorist (specify):
 - (17) Thrown or falling object
 - (18) Boulder
 - COLLISION WITH FIXED OBJECT
 - (20) Building
 - (21) Impact attenuator/crash cushion
 - (22) Bridge pier or abutment
 - (23) Bridge parapet end
 - (24) Bridge rail
 - (25) Guardrail
 - (26) Concrete traffic barrier
 - (27) Median barrier
 - (28) Other longitudinal barrier (specify):
 - (29) Highway/traffic sign post
 - (30) Overhead sign support
 - (31) Luminaire/light support
 - (32) Utility pole
 - (33) Other post, pole, or support
 - (34) Culvert
 - (35) Curb
 - (36) Ditch
 - (37) Embankment-earth
 - (38) Embankment-rock, stone, or concrete
 - (39) Fence
 - (40) Wall
 - (41) Fire hydrant
 - (42) Shrubbery
 - (43) Tree
 - (44) Other fixed object (specify):
 - (45) Pavement surface irregularity
 - (99) Unknown

AIRBAG SUPPLEMENT

3

AIRBAG VEHICLE IMPACT SUMMARY

22. Vehicle Role 3
(0) Noncollision
(1) Striking unit
(2) Struck unit
(3) Both striking and struck
(9) Unknown
23. Manner of Leaving Scene 2
(1) Driven
(2) Towed-due to damage
(3) Towed-not for damage
(4) Towed-details unknown
(5) Abandoned
(9) Unknown
24. Number of Impact Events 1
(8) 8 or more
(9) Unknown
25. Rollover φ
(0) No rollover
(1) First event
(2) Subsequent event
(3) Yes, Unknown event
(9) Unknown
26. Override/Underride φ
(0) No override/underride
(1) Override - 1st CDC
(2) Override - Other CDC
(3) Underride - 1st CDC
(4) Underride - Other CDC
(9) Unknown

AIRBAG VEHICLE DAMAGE

CODES: (1) Yes, (2) No, (9) Unknown

27. Left Front Fender Damage 1
28. Right Front Fender Damage 1
29. Center Top of Grille Damage 1

FRONT BUMPER E.A. STATUS

30. Left 4
31. Right 2
(1) Normal
(2) Extended
(3) Partial Compression
(4) Complete Compression
(5) Not Applicable
(9) Unknown

FIRST AIRBAG VEHICLE IMPACT:

32. Configuration 2
(0) Struck Object or Ped
(1) Rear-End
(2) Head-On
(3) Rear-to-Rear
(4) Angle
(5) Sideswipe-Same Direction
(6) Sideswipe-Opposite Dir.
(7) Noncollision
(8) Nonimpact Deployment
(9) Unknown
33. CDC:
34. Object Contacted: 1991 TOYOTA 3RS Pickup

PRIMARY/DEPLOYMENT IMPACT:

35. Event Number 1
36. Total Delta-V 39 mph (24 mph)
37. Longitudinal Delta-V 38 mph (-24 mph)
38. Configuration 2
See 32 above for codes
39. CDC: 92 F Y E W 4
40. Object Contacted: 1991 TOYOTA 3RS Pickup

AIRBAG SUPPLEMENT

4

AIRBAG SYSTEM DAMAGE


CODES: (1) Yes, Damaged
(2) No, Intact
(3) Not Applicable
(9) Unknown

- | | |
|---|--|
| 41. Airbag Module | <div style="border: 1px solid black; padding: 2px; display: inline-block;">2</div> |
| 42. Left Front Sensor | <div style="border: 1px solid black; padding: 2px; display: inline-block;">1</div> |
| 43. Center Front Sensor | <div style="border: 1px solid black; padding: 2px; display: inline-block;">9</div> |
| 44. Right Front Sensor | <div style="border: 1px solid black; padding: 2px; display: inline-block;">2</div> |
| 45. Rear Cowl Sensor | <div style="border: 1px solid black; padding: 2px; display: inline-block;">9</div> |
| 46. Diagnostic Module | <div style="border: 1px solid black; padding: 2px; display: inline-block;">9</div> |
| 47. Wiring | <div style="border: 1px solid black; padding: 2px; display: inline-block;">9</div> |
| 48. Knee Diverter | <div style="border: 1px solid black; padding: 2px; display: inline-block;">3</div> |
| 49. Indication of disconnected
or loose electrical
connectors | <div style="border: 1px solid black; padding: 2px; display: inline-block;">2</div> |
| 50. Condition of Deployed Bag | <div style="border: 1px solid black; padding: 2px; display: inline-block;">1</div> |
- (1) Bag intact
(2) Split or torn
(3) Cut by object in impact
(4) Cut after accident
(5) Other
(8) NA (not deployed)
(9) Unknown


DESCRIBE SYSTEM AND BAG DAMAGE:

NOTE DAMAGE AND CONTACT MARKS ON AIRBAG DIAGRAMS
BELOW:

FRONT



BACK



AIRBAG SUPPLEMENT

5

OCCUPANTS OF AIRBAG CAR

51. Number of Occupants in Vehicle 2
52. Number of Injured Persons 2
53. Maximum AIS in Airbag Vehicle 4
(0) No Injury
(1-6) AIS Severity
(7) Injured, unknown severity
(9) Unknown

DRIVER

Age: 77

Sex: FEMALE

54. Number of Driver Injuries 8

55. Source of Best Injury Data 2
(0) Not injured
(1) Autopsy
(2) Hospital Medical Records
(3) Emergency Room only
(4) Private physician, clinic
(5) Lay Coroner Report
(6) EMS Personnel
(7) Interviewee
(8) Police
(9) Unknown

MAXIMUM AIS BY BODY REGION

REGION	MAX AIS	CONTACT
Head/Neck/Face	<u>2</u>	<u>26</u>
Chest	<u>2</u>	<u>11</u>
Abdomen	<u>4</u>	<u>11</u>
Legs/Hips	<u>3</u>	<u>09</u>
Other (Arms)	<u>2</u>	<u>04</u>
Driver Maximum	<u>3</u>	<u>09</u>

EJECTION NONE

Extent: N/A

Portal: N/A

OTHER VEHICLE:

Maximum AIS 4

Prime/Deploy Impact w AB Vehicle
Event Number 1

CDC: 92FYEW4

Total Delta V (13mph) 37 kph

Make: TOYOTA

Model Year: 1991

Model: SR5 4x4

Body Type: PICK UP TRUCK

NOTES:

AIRBAG SUPPLEMENT

6

DRIVER BELT USAGE: (1) Used (2) Not Used (9) Unknown

2

Evidence:

DRIVER POSTURE: Any comments Recorded (1) Yes, (2) No

2

Describe driver's posture and position on seat including specific comments on head, torso, buttocks, legs, and feet. Also note hand and arm position. Did driver brace before crash? Describe:

DRIVER FOREIGN OBJECTS: Comments Recorded (1) Yes, (2) No

2

Was driver wearing contact lenses or eyeglasses? Or holding any foreign object at the time of the impact (packages on lap, pipe, food, bottle, cigarette, etc.)? Did any lenses, objects, or jewelery play any role?:

DRIVER COMMENTS: Comments Recorded (1) Yes, (2) No

2

Was the driver aware that the vehicle was equipped with a supplemental restraint system? Did driver offer any comments on smoke, noise, etc.? Did the driver comment on the airbag as a restraint system? Describe:

PASSENGER-AIRBAG CONTACT: (1) Yes, (2) No, (9) Unknown

2

Describe:



INTERVIEW FORM (A)

1. Primary Sampling Unit Number _____

2. Case Number - Stratum DSI-94-AB-0063. Vehicle Number 02Interviewee(s) Role or Name(s): DRIVER, VEHICLE 2

Review all available information and interview questions prior to conducting interview(s) to ensure the acquisition of all pertinent data.

If the driver was not the person interviewed, was an appointment made for a follow-up interview?

DRIVER'S DESCRIPTION OF ACCIDENT EVENTS

I don't really recall too much - I was following my
Mother to her new home and the next thing I knew
another car was in front of me - coming at me in my
lane - and we hit head on - I don't remember anything
else.

OCCUPANT'S DESCRIPTION OF ACCIDENT EVENTS



INTERVIEW FORM (B)

1. Primary Sampling Unit Number _____

2. Case Number - Stratum DSI-94-AB-006

3. Vehicle Number 02

Interviewee(s) Role or Name(s): DRIVER, VEHICLE 2

ACCIDENT DATA QUESTIONS

1. Can you tell me in which direction you were traveling?

☒ North [] South [] East [] West

(Optional - Where were you coming from or going to?)

2. In which lane were you traveling?

(Note: Lane 1 is designated as the right curb lane.)

☒ (1) [2] [3] [4] [] Other (specify):

3. Can you remember your estimated travel speed (in miles per hour) before the accident?

[] Stopped [] 1-10 [] 10-20
[] 20-30 ☒ 30-40 [] 40-50
[] 50-60 [] 60-70 [] 70+

4. Just before the accident, can you tell me what you were intending to do or were doing?

☒ Going straight [] Stopped
[] slowing [] Accelerating
[] Turning left [] Turning right
[] Changing lanes to left [] Changing lanes to right
[] Backing
[] Other (specify): _____

5. Did you experience any loss of control due to weather conditions or mechanical problems?

☒ No
[] Yes (If yes, describe below)

6. Did you have to take any avoidance actions prior to the accident?

☒ No - Go to question 7
[] Yes - Go to question 6a

6a. What actions did you take?

[] Braking with lock-up
[] Braking without lock-up
[] Releasing brakes
[] Accelerating
[] Steering left
[] Steering right
[] Other (specify):

7. Where was your vehicle at the time of the collision?

☒ Original travel lane [] Different travel lane
[] In intersection [] Off roadway to right
[] Off roadway to left
[] Other (specify): _____

8. Was your travel speed at the time of the collision different from your previous travel speed?

☒ No
[] Lower
[] Higher
[] Unknown

8a. Can you estimate your speed at the time of the collision?

[] Stopped [] 1-10 [] 10-20
[] 20-30 ☒ 30-40 [] 40-50
[] 50-60 [] 60-70 [] 70+

9. Immediately following the collision, can you describe how your vehicle moved to its stopped position?

10. Can you tell me how many collisions your vehicle had during the accident and the source of the collisions?

I only remember one.

1. Primary Sampling Unit Number _____

3. Vehicle Number 022. Case Number - Stratum DSI-94-AB-0464. Occupant Number 01

VEHICLE/DRIVER DATA QUESTIONS

1. Can you tell me the year, make, model of your vehicle?

1991 TOYOTA SRS 4WD P.V.
 Year Make Model

2. Can you describe the damage to your vehicle?

front end

3. Was there any previous damage to your vehicle that is not related to this accident?

☒ No
☐ Yes (If "yes", describe below)

4. Did any of the doors (hatch, tailgate) open during the accident?

☒ No
☐ Yes (If "Yes", describe below)

5. Did any of the windows break during the accident?

☐ No
☐ Yes (If "Yes", describe below)

I don't know

6. Does your vehicle have a glove compartment?

☐ No
☒ Yes

6a. Did the glove compartment door come open during the accident?

☐ No
☐ Yes
☒ Unknown

7. Does your vehicle have "seat belts"?

☐ No (If "No", go to question 7b)
☒ Yes (If "Yes", go to question 7a)

7a. Can you describe the type of seat belt for each seat?

Driver's seat	<input type="checkbox"/> Lap	<input checked="" type="checkbox"/> Lap and shoulder
Front seat middle	<input type="checkbox"/> Lap	<input type="checkbox"/> Lap and shoulder
Front seat right	<input type="checkbox"/> Lap	<input checked="" type="checkbox"/> Lap and shoulder
Rear seat left	<input type="checkbox"/> Lap	<input checked="" type="checkbox"/> Lap and shoulder
Rear seat middle	<input type="checkbox"/> Lap	<input type="checkbox"/> Lap and shoulder
Rear seat right	<input type="checkbox"/> Lap	<input checked="" type="checkbox"/> Lap and shoulder

(Identify seat belts for third row and beyond)

7b. Were any of the belts removed or not functional prior to the accident?

☒ No
☐ Yes (If "Yes", specify which belt and describe problem)

8. Do any of the front belts move along a motorized track when the door is opened or closed?

☒ No (If "No", go to question 9)
☐ Yes (If "Yes", what seat location?)
☐ Left Front
☐ Right-Front

8a. Were the motorized belts working properly before the accident?

☐ No (If "No", describe condition below)

☐ Yes

8b. Were the belts connected to the track prior to the accident?

☐ No
☐ Yes
☐ Unknown

9. Do any of the front "seat" belts attach to the door such that when the door is opened the belt travels with the door?

☒ No (go to question 10)
☐ Yes

9a. Does this belt come across the _____?

☐ Chest only
☐ Lap and chest

9b. Was this belt connected prior to the accident?

☐ No
☐ Yes
☐ Unknown

AIR BAGS

10. Is your vehicle equipped with a driver's side air bag?

☒ No (go to question 11)
☐ Yes (go to question 10a)
☐ Unknown (go to question 11)

10a. Did the air bag inflate during the accident?

☐ No (go to questions 10b and 10c)
☐ Yes (go to question 10e)

1. Primary Sampling Unit Number

3. Vehicle Number

02

2. Case Number - Stratum

DSI-94-AB-006

4. Occupant Number

01

VEHICLE/DRIVER DATA QUESTIONS (CONTINUED)

10b. Was the air bag wiring disconnected prior to the accident?

☐ No☐ Yes (If "Yes", describe previous condition)☐ Unknown

10c. Was your vehicle involved in any accidents prior to this accident which inflated the air bag?

☐ No (go to question 11)☐ Yes (go to question 10d)☐ Unknown

10d. Was the air bag re-installed after the accident?

☐ No (go to question 11)☐ Yes☐ Unknown

10e. Did the air bag inflate as you expected?

☐ No (If "No" describe below)☐ Yes☐ Unknown

11. Is your vehicle equipped with a passenger side air bag?

☒ No (If "No", go to question 12)☐ Yes (If "Yes", go to question 11a)☐ Unknown (If "Unknown", go to question 12)

11a. Did the passenger air bag inflate during the accident?

☐ No (go to question 11b)☐ Yes (go to question 12)

11b. Was the passenger air bag wiring disconnected prior to the accident?

☐ No☐ Yes (If "Yes", describe below)☐ Unknown

11c. Was the passenger air bag inflated in a previous accident?

☐ No (go to question 12)☐ Yes (go to question 11d)☐ Unknown

11d. Was the passenger air bag re-installed after the accident?

☐ No (go to question 12)☐ Yes☐ Unknown

11e. Did the passenger air bag inflate as you expected?

☐ No (If "No" describe below)☐ Yes☐ Unknown

CHILD SAFETY SEAT

12. Was there a person in a child safety seat in your vehicle?

☐ No (If "No", go to question 13)☒ Yes☐ Unknown

12a. Can you tell me the manufacturer and model of the child safety seat?

Evenflo Champion I
224187

12b. Can you describe the type of child safety seat?

☐ Infant☐ Toddler☒ Convertible☐ Booster☐ Other (specify):☐ Unknown

12c. Where was the child safety seat(s) located?

☐ [12] ☒ [13]☐ [21] ☐ [22] ☐ [23]☐ [31] ☐ [32] ☐ [33]☐ [Other] (specify):

12d. Can you tell me which direction the child safety seat was facing prior to the accident?

☐ Rear facing☒ Forward facing,☐ Other (specify):☐ Unknown

12e. Was a seat belt used to hold the child seat in place?

☐ No (If "No", go to question 12g)☒ Yes (If "Yes", go to question 12f)☐ Unknown

12f. Can you describe how the seat belt was secured to the child seat?

☐ Looped through designated rear framing struts?☐ Looped through arm rest slots?☐ Belt across safety shield?☐ Looped through rear frame outside the designated framing struts?☐ Other (specify):☒ Unknown

12g. What was the child safety seat equipped with at the time of purchase? (check all that apply)

☒ Harness☒ Shield☐ Tether strap

If any box is checked, ask questions 12h - 12i.

1. Primary Sampling Unit Number

3. Vehicle Number

02

2. Case Number - Stratum

DSE-94-AB-000

4. Occupant Number

01

VEHICLE/DRIVER DATA QUESTIONS (CONTINUED)

12h. Were any of these items added after you owned the child safety seat?

☐ Yes

(specify _____)

☒ No☐ Unknown

12i. Were any of these items used during the accident?

☒ Yes (If "Yes", check all that apply)☒ Harness☒ Shield☐ Tether strap☐ No☐ Unknown

OPTIONAL

If you do not know where the vehicle is or if the owner's permission is needed for inspection.

15. Do you know where the vehicle is currently located?

16. May I take a look at your vehicle to assess the damage?

☐ No☐ Yes

DRIVER ONLY

17. What race do you consider yourself?

☒ White☐ Black☐ American Indian, Eskimo or Aleut, Asian or Pacific Islander☐ Other (specify: _____)☐ Unknown.

18. Are you of hispanic origin?

☒ No☐ Yes

CARGO WEIGHT AND MILEAGE

13. Was there any cargo in your vehicle?

☒ No (If "No", go to question 14)☐ Yes (If "Yes", go to question 13a)☐ Unknown

13a. Can you estimate the weight of the cargo?

_____ lbs.

Cargo description

14. Can you tell me the mileage on the vehicle?

I Don't know miles

1. Primary Sampling Unit Number _____ 3. Vehicle Number 02
 2. Case Number - Stratum DSF-94AB-000 4. Occupant Number 01

VEHICLE ROLLOVER/FIRE QUESTIONS

ROLLOVER QUESTIONS

FIRE QUESTIONS

1. Did the vehicle rollover during the accident?

☒ No (If "No", go to question 2.)

☐ Yes

☐ Unknown (skip to question 2)

1a. Describe where the rollover began.

☐ On roadway

☐ On shoulder

☐ On roadside or median

☐ Unknown

1b. What caused the vehicle to rollover?

☐ Other vehicle (specify vehicle number): _____

☐ Contacted object (specify): _____

☐ Other cause (specify): _____

☐ Unknown

1c. Describe which direction the vehicle rolled.

☐ Toward the right

☐ Toward the left

☐ End-over-end

☐ Unknown

1d. Estimate the number of sides (including the top and bottom) which contacted the ground during the rollover?

☐ 1 side

☐ 2 sides

☐ 3 sides

☐ 4 sides

☐ Unknown

1e. Did the vehicle roll over more than one complete turn (more than 4 sides)?

☐ No (If "No", go to question 1g.)

☐ Yes

1f. Estimate the number of complete turns.

☐ No

☐ Yes (specify): _____

☐ Unknown

1g. When the vehicle stopped rolling over, which side of the vehicle was in contact with the ground?

☐ Left side

☐ Right side

☐ Top

☐ Wheels

☐ Unknown

2. Did the vehicle experience a fire?

☒ No (If "No", skip to Occupant Data Questions)

☐ Yes

☐ Unknown

2a. Describe where the fire started or where smoke was first seen.

☐ Under the hood

☐ Behind the instrument panel

☐ In the passenger compartment

☐ In the trunk/cargo area

☐ Under the vehicle

☐ From other involved vehicle

☐ Unknown

2b. Did the fire start with the electrical system?

☐ No

☐ Yes (specify): _____

☐ Unknown

2c. Did the fire start with the fuel system?

☐ No (If "No", skip to Occupant Data Questions)

☐ Yes (go to question 2d)

☐ Unknown

2d. Describe which part of the fuel system that may have been involved?

☐ No

☐ Yes (specify): _____

_____ Fuel tank

_____ Fuel lines

_____ Engine compartment (specify component if known)

☐ Unknown

(Go To Occupant Data Questions)

COMMENTS ON ROLLOVERS AND FIRES

1. Primary Sampling Unit Number

3. Vehicle Number

02

2. Case Number - Stratum

DSF 94 AB-016

4. Occupant Number

01

OCCUPANT DATA QUESTIONS

1. Was there anyone else in your vehicle at the time of the accident?

☐ No (If "No", go to question 4)☒ Yes (If "Yes", specify number in question 2 below and then go to question 3)☐ Unknown

2. How many?

☐ One other person☒ Two other persons☐ Three other persons☐ Four other persons☐ Five other persons☐ Six other persons☐ Seven or more other persons
(specify number:)

3. Where was this person sitting? (Circle seating positions)

<input checked="" type="checkbox"/> (21)	<input type="checkbox"/> (12)	<input checked="" type="checkbox"/> (13)
<input type="checkbox"/> (31)	<input type="checkbox"/> (22)	<input type="checkbox"/> (23)
	<input type="checkbox"/> (32)	<input type="checkbox"/> (33)

☐ Other (specify:)

OCCUPANT CHARACTERISTICS

4. Can I have your (his/her) height, weight, age, and sex?

1-6.6' 160 26 m
 Height 3' 3" Weight 32 Age 1 m
3-4.6' 90 11 F
 Sex: ☐ Male ☐ Female

OCCUPANT POSTURE

5. Can you tell me how you (he/she was) were sitting in your vehicle?

I don't recall

5a. Can you describe the location of your (his/her) feet just prior to the collision?

L. foot on floor - R. foot on accel.

5b. Can you describe the location of your (his/her) arms?

I don't recall

5c. Was your (his/her) back resting against the seat back rest?

☐ No (If "No", describe the position)☒ Yes☐ Unknown

5d. Were you (Was he/she)

☒ Sitting upright or☐ Leaning to left side, or☐ Leaning to right side?

OCCUPANT EJECTION

6. Were you (Was he/she) or any part of your (his/her) body thrown from the vehicle during the accident?

☒ No (If "No", go to question 7)☐ Yes (If "Yes", go to question 6a)☐ Unknown

6a. Can you remember out of what area of the vehicle you were (he/she was) thrown?

☐ No☐ Yes (Describe:)

OCCUPANT RESTRAINT

7. Were you (Was he/she) wearing a seat belt just before the accident?

☐ No (If "No", go to question 8)☐ Yes☒ Unknown - I don't recall

7a. Were you (Was he/she) wearing the

☐ Lap belt?☐ Lap and Shoulder belt?☐ Shoulder belt?

7b. Can you describe how you were (he/she was) wearing the lap belt?

☐ Across the stomach☐ Low on lap☐ Other (specify:)☒ Unknown

7c. Can you describe how you were (he/she was) wearing the shoulder belt?

☐ Over the shoulder☐ Under the arm☐ Behind the back☐ Behind the seat☐ Other (specify:)

7d. Did any part of the belt system break or tear?

☐ No☐ Yes (If "Yes", describe)☒ Unknown

OCCUPANT ENTRAPMENT

8. Were you (Was he/she) trapped in the vehicle?

☒ No☐ Yes (If "Yes", describe)☐ Unknown

1. Primary Sampling Unit Number

3. Vehicle Number

02

2. Case Number - Stratum

DSE-94-AB-006

4. Occupant Number

01

OCCUPANT INJURY DATA QUESTIONS

1. Were you (Was he/she) injured?

☐ No (If "No", skip to question 7)☒ Yes (If "Yes", complete Occupant Injury Questions)☐ Unknown

2. Did you (he/she) receive any cuts, abrasions, or bruises?

☐ No (go to question 3)☒ Yes (If "Yes", record the exact location(s) and size on the manikin(s).)☐ Unknown

2a. Do you know what caused your (his/her) injury(s)?

☒ No☐ Yes (If "Yes", specify the component(s) or object(s) on the manikin(s).)☐ Unknown

3. Did you (he/she) experience any broken bones?

☒ No (If "No", go to question 4)☐ Yes (If "Yes", record the exact location(s) and type of fracture(s) on the manikin(s), and then go to question 3a.)☐ Unknown

3a. Do you know what caused the injury(s)?

☒ No☐ Yes (If "Yes", specify the component(s) or object(s) on the manikin(s).)☐ Unknown

4. Did you (he/she) injure your (his/her) head? (skull/brain?)

☐ No (If "No", go to question 5)☒ Yes (If "Yes", describe the type of injury(s) on the manikin(s), then go to question 4a.)☐ Unknown

4a. Do you know what caused the injury(s)?

☒ No☐ Yes (If "Yes", specify the component(s) on the manikin(s).)☐ Unknown

5. Were any of your (his/her) internal organs injured?

☒ No (If "No", go to question 6)☐ Yes (If "Yes", thoroughly describe the type of injury(s) and specify the internal organ(s) injured on the manikin(s), and then go to question 5a.)☐ Unknown

5a. Do you know what caused this injury?

☒ No☐ Yes (If "Yes", specify the component(s) on the manikin(s).)☐ Unknown

6. Did you (he/she) suffer any joint sprains or muscle strains?

☐ No (If "No", go to question 7)☒ Yes (If "Yes", specify on the manikin(s), and then go to question 6a.)☐ Unknown

6a. Do you know what caused the injury(s)?

☒ No☐ Yes (If "Yes", specify the component(s) on the manikin(s).)☐ Unknown

7. Did you (he/she) receive any treatment?

☐ No (If "No", go to question 8)☒ Yes (If "Yes", go to question 7a or return to question 2.)

7a. Were you (Was he/she) treated by (check all that apply):

☒ Hospital/trauma center? (specify hospital name):refused☐ Medical clinic☐ Out patient surgery? (specify medical facility:)☐ Paramedics or first aid at the scene?☐ A doctor in his/her office?☐ Treated at home?☐ None of the above, go to question 8.

7b. Were you (Was he/she) treated and released from the emergency room?

☒ No (If "No", go to question 7c.)☐ Yes (If "Yes", go to question 7e.)

7c. Were you (Was he/she) hospitalized?

☐ No (If "No", give an explanation)☒ Yes (If "Yes", go to question 7d.)

7d. How many days were you (was he/she) in the hospital?

3 days

1. Primary Sampling Unit Number

3. Vehicle Number

02

2. Case Number - Stratum

DSI-94RB-066

4. Occupant Number

01

OCCUPANT INJURY DATA QUESTIONS (CONTINUED)

7e. Have you (Has he/she) received any follow-up treatment?

☐ No☒ Yes (If "Yes", describe:)3 times a week since
accident.☐ Unknown

8. Have you (he/she) lost any days from work or school (college)?

☐ No☒ Yes (If "Yes", determine the number of days lost)
(Specify:) over 90 days☐ Not working prior to the accident☐ Unknown

7f. In order to achieve the best possible scientific data regarding your (his/her) injury(s), we need to obtain a copy of your (his/her) medical reports. Would you (he/she) sign a medical release form?

☒ No☐ Yes (If "Yes", mail or present the form for signature.)

REPORT NO.	PAGE NO. 12	ACCIDENT DATE 94	ACCIDENT TIME 4	REPORT TYPE <input type="checkbox"/> FATAL <input checked="" type="checkbox"/> INJURY <input type="checkbox"/> PDD <input type="checkbox"/> HIT & RUN <input type="checkbox"/> NON-TRAFFIC	RESEARCH	LOCAL CASE NUMBER	LOCAL CODES	PLACES <input type="checkbox"/> NO <input checked="" type="checkbox"/> YES
INVESTIGATING OFFICER ID	10	AGENCY AND AREA	11	REVIEWER ID	13	CODE AND NAME OF MUNICIPALITY	14	COUNTY 12
RD CHAS 03	RTE NUM Accident Occurred On 17	ROAD NAME	18	IN LANE N/A	TRAF SIG <input checked="" type="checkbox"/> NO <input type="checkbox"/> YES 20	ON RAMP <input checked="" type="checkbox"/> NO <input type="checkbox"/> YES 21	Ramp Number (Direction) 1 N-W 2 W-N 3 E-N 4 N-E 5 S-E 6 E-S 7 W-S 8 S-W 9 Other	IN INTERSECTION <input type="checkbox"/> NO <input checked="" type="checkbox"/> YES 22
RD COND 01	INT-RTE 25	INTERSECTING ROAD NAME or Log Mile Reference Manual description	26	MILEPT	77 DIR	Dist at Acc 101 RT-Ret & Dir	29	30
RD DIV 01	ACCIDENT DIAGRAM	31	NORTH 32	DESCRIBE ACCIDENT briefly: identify units by numbers. Also identify the following: a) the OBJECT DAMAGED & NATURE OF DAMAGE (Property other than vehicle) and b) the NAME & ADDRESS OF OWNER when applicable.				
SRT COND 02	Show & Label: Roads, Traffic Units, the Travel Direction consistent with the Log Mile Reference Manual, and Movement of Traffic Units.							
CAN ZONE <input type="checkbox"/> NO <input checked="" type="checkbox"/> YES 35	VEHICLE "1" WAS TRAVELING SOUTHBOUND RD 5000 DR. CROSSED CENTERLINE AND COLLIDED WITH VEHICLE "2". VEHICLE "3" COLLIDED WITH VEHICLE "2".							
UNION 01								
EVENT-1 01								
EVENT-2 01								
FIX OBJ 00								
COLL TY 01								
LIGHT 01								
WEATHER 01								
UNIT # 01	NAME (First, Middle, Last)	44	SEX 45	UNIT # 02	NAME (First, Middle, Last)	44	SEX 45	01
TYPE 46	ADDRESS (Hm, Street, City, State, Zip)	47	TEL <input type="checkbox"/> Work <input checked="" type="checkbox"/> Res	UNIT # 02	ADDRESS (Hm, Street, City, State, Zip)	47	TEL <input type="checkbox"/> Work <input checked="" type="checkbox"/> Res	01
UNIT 01	DRIVER <input checked="" type="checkbox"/> "PED"	48	INS 49	UNIT # 02	DRIVER <input checked="" type="checkbox"/> "PED"	48	INS 49	01
MOVEMENT 01	CONDITN 01	SUBST 01	TEST 01	RESULT 00	FOR PEDS ONLY 0	AGE 55	TYPE 56	LOCATN 57
SPEED LIMIT 40	SAF. EQU 99	EQ PROB 99	EJECT 01	CITATION NUMBER (S)	64	FAULT <input type="checkbox"/> NO <input checked="" type="checkbox"/> YES 65	66	67
GOING 02	DRIVER'S LICENSE NUMBER	67	STATE	CLASS 69	GOING 01	DRIVER'S LICENSE NUMBER	67	STATE
CONTINU 02	DR DATE OF BIRTH 16	IRREGULAR CONDITION <input type="checkbox"/> PARKED <input type="checkbox"/> CAUGHT FIRE <input type="checkbox"/> HIT & RUN <input type="checkbox"/> DRIVERLESS <input type="checkbox"/> N O Y	72	HMI SPILL 73	HAZ MAT NUMBER 74	CONTINU 01	DR DATE OF BIRTH 67	IRREGULAR CONDITION <input type="checkbox"/> PARKED <input type="checkbox"/> CAUGHT FIRE <input type="checkbox"/> HIT & RUN <input type="checkbox"/> DRIVERLESS <input type="checkbox"/> N O Y
BODY TY 02	COMMER. VEHICLE ONLY	U. S. DOT NUMBER 76	ICC NUMBER 77	BODY TY 78	CDL? <input type="checkbox"/> NO <input checked="" type="checkbox"/> YES 79	BODY TY 01	COMMER. VEHICLE ONLY	U. S. DOT NUMBER 76
MOST HE 01	OWNER OR CARRIER NAME (Write "SAME" if Driver)	TEL <input type="checkbox"/> Work <input checked="" type="checkbox"/> Res	81	MOST HE 01	OWNER OR CARRIER NAME (Write "SAME" if Driver)	TEL <input type="checkbox"/> Work <input checked="" type="checkbox"/> Res	81	
CONTRIB CIRCUMSTANCES 15	OWNER/CARRIER ADDRESS	83	84	CONTRIB CIRCUMSTANCES 00	OWNER/CARRIER ADDRESS	83	84	
82-2	YEAR & MAKE OF VEHICLE 90 CADILLAC	85	MODEL 86 SEDAN DEVILLE	82-2	YEAR & MAKE OF VEHICLE 90 TOYT	85	MODEL 86 SRS	
82-3	EXP YR & REGISR # STATE 16011230	AREAS DAMAGED	INSURER	82-3	EXP YR & REGISR # STATE 16011230	AREAS DAMAGED	INSURER	
82-4	VEHICLE ID NUMBER 00 1G6CD533814	92	POLICY NUMBER 3	82-4	VEHICLE ID NUMBER 00 JT4VN13E7M5	92	POLICY NUMBER 2	
DAM EXT 03	VEHICLE REMOVED BY	95	VEHICLE REMOVED TO	DAM EXT 04	VEHICLE REMOVED BY	95	VEHICLE REMOVED TO	
TRAFFIC UNIT #	SEATING POSITION	CODE all injured & uninjured PASSENGERS below. Use "W" for witness in TRAF UNIT and SEAT columns. WRITE NAME & ADDRESS of Injured Passengers and Witnesses.				Witness telephone #	SEX	AGE
01	03	SAME				99	01	07
02	03	SAME					01	01
02	05						02	01
03	05						02	02
W							01	
W							02	
							0	
107	INJURED TAKEN BY	108	INJURED TAKEN TO	109	INJURED TAKEN BY	110	INJURED TAKEN TO	111

